



**THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA**  
MATERIALS MANAGEMENT DEPARTMENT  
101 OLD VENICE ROAD • OSPREY, FLORIDA 34229  
TELEPHONE (941) 486-2183 • FAX (941) 486-2188

**MEMORANDUM**

**TO: Members of the School Board**  
**Lori White, Superintendent**  
**Mitsi Corcoran, Chief Financial Officer**

**FROM: Pat Black, CPPB, Director of Materials Management**

**TITLE: APPROVAL TO AWARD BID #15-0130 FOR HVAC FILTER**  
**REPLACEMENT SERVICE**

Bids to provide 'HVAC Filter Replacement Service' were received from two vendors on July 15, 2014. The bid of Kleen Air Research was the best low bid meeting the advertised specifications. This bid is for a period of one year with the option to renew for two additional one-year periods. Funds for these purchases are contained in the transfer from capital budget allocated to the Facilities Services Department.

**Requested by:**  
Jody Dumas

"Failure to file a protest within the time prescribed in Section 120.57(3), Florida Statutes, or failure to post the protest bond or other security required by law within the time allowed for filing a bond shall constitute a waiver of proceedings under Chapter 120, Florida Statutes."

Posting Date: 08/12/2014

**Fiscal Impact:**

Not to exceed  
\$225,000.00

**Recommended Motion:** That the bid of Kleen Air Research, to provide 'HVAC Filter Replacement Service' in an amount not to exceed \$225,000.00, be approved as presented.

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
ALTA VISTA ELEMENTARY	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ALTA VISTA ELEMENTARY	1	PBYP1	16.0 X 039.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ALTA VISTA ELEMENTARY	1	PBYP1	16.2 X 030.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ALTA VISTA ELEMENTARY	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ALTA VISTA ELEMENTARY	1	PBYP2	12.0 X 017.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ALTA VISTA ELEMENTARY	2	PBYP2	12.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ALTA VISTA ELEMENTARY	1	PBYP2	13.6 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ALTA VISTA ELEMENTARY	1	PBYP2	14.2 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ALTA VISTA ELEMENTARY	1	PBYP2	14.2 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ALTA VISTA ELEMENTARY	6	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
ALTA VISTA ELEMENTARY	2	PBYP2	16.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ALTA VISTA ELEMENTARY	6	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
ALTA VISTA ELEMENTARY	1	PBYP2	17.6 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ALTA VISTA ELEMENTARY	3	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
ALTA VISTA ELEMENTARY	2	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ALTA VISTA ELEMENTARY	2	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ALTA VISTA ELEMENTARY	1	PBYP2	20.0 X 027.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ALTA VISTA ELEMENTARY	1	PBYP2	20.0 X 028.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ALTA VISTA ELEMENTARY	2	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ALTA VISTA ELEMENTARY	1	PYD-P	09.0 X 040.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
ALTA VISTA ELEMENTARY	2	WSHMF	10.0 X 010.0 X 00.4	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ALTA VISTA ELEMENTARY	2	WSHMF	12.0 X 013.0 X 00.4	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ALTA VISTA ELEMENTARY	2	WSHMF	12.0 X 016.0 X 00.4	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ALTA VISTA (PRIOR - PHOENIX LOCATION)	1	PBYP1	20.0 X 025.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ALTA VISTA (PRIOR - PHOENIX LOCATION)	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ALTA VISTA (PRIOR - PHOENIX LOCATION)	2	WSHMF	10.0 X 012.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ASHTON ELEMENTARY	1	PBYP1	15.0 X 030.5 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ASHTON ELEMENTARY	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ASHTON ELEMENTARY	1	PBYP1	16.2 X 030.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ASHTON ELEMENTARY	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ASHTON ELEMENTARY	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ASHTON ELEMENTARY	1	PBYP1	22.0 X 022.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ASHTON ELEMENTARY	1	PBYP2	13.6 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ASHTON ELEMENTARY	2	PBYP2	16.0 X 016.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ASHTON ELEMENTARY	2	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ASHTON ELEMENTARY	2	PBYP2	16.0 X 020.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ASHTON ELEMENTARY	2	PBYP2	16.0 X 021.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
ASHTON ELEMENTARY	2	PBYP2	16.0 X 021.2 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ASHTON ELEMENTARY	2	PBYP2	16.0 X 021.3 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ASHTON ELEMENTARY	1	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ASHTON ELEMENTARY	4	PBYP2	16.0 X 021.6 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
ASHTON ELEMENTARY	4	PBYP2	16.0 X 023.3 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
ASHTON ELEMENTARY	4	PBYP2	16.0 X 023.6 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
ASHTON ELEMENTARY	2	PBYP2	16.0 X 024.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ASHTON ELEMENTARY	2	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ASHTON ELEMENTARY	2	PBYP2	16.0 X 025.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ASHTON ELEMENTARY	4	PBYP2	16.0 X 025.6 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
ASHTON ELEMENTARY	2	PBYP2	16.0 X 027.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ASHTON ELEMENTARY	2	PBYP2	16.0 X 027.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ASHTON ELEMENTARY	4	PBYP2	17.0 X 020.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
ASHTON ELEMENTARY	1	PBYP2	17.3 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ASHTON ELEMENTARY	4	PBYP2	19.0 X 025.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
ASHTON ELEMENTARY	2	PBYP2	20.0 X 020.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ASHTON ELEMENTARY	1	PBYP2	20.0 X 021.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ASHTON ELEMENTARY	1	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ASHTON ELEMENTARY	1	PBYP2	20.0 X 027.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ASHTON ELEMENTARY	2	PBYP2	22.4 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
ASHTON ELEMENTARY	1	WSHMF	08.0 X 014.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ASHTON ELEMENTARY	1	WSHMF	10.0 X 028.4 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ASHTON ELEMENTARY	1	WSHMF	12.0 X 026.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ATWATER ELEMENTARY	6	PBYP1	16.0 X 020.0 X 01.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
ATWATER ELEMENTARY	2	PBYP1	16.0 X 025.0 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ATWATER ELEMENTARY	4	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
ATWATER ELEMENTARY	4	PBYP1	20.0 X 024.0 X 01.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
ATWATER ELEMENTARY	6	PBYP1	20.0 X 025.0 X 01.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
ATWATER ELEMENTARY	4	PBYP1	24.0 X 024.0 X 01.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
ATWATER ELEMENTARY	1	PL13H	16.0 X 020.0 X 02.0	\$7.27	\$43.62	\$7.27	\$8.53	\$51.18	\$7.53
ATWATER ELEMENTARY	2	PL13H	16.0 X 025.0 X 02.0	\$7.99	\$95.88	\$7.99	\$9.87	\$118.44	\$8.87
ATWATER ELEMENTARY	1	PL13H	20.0 X 020.0 X 02.0	\$8.04	\$48.24	\$8.04	\$9.79	\$58.74	\$8.79
ATWATER ELEMENTARY	4	PL13H	20.0 X 024.0 X 02.0	\$9.04	\$216.96	\$9.04	\$11.33	\$271.92	\$10.33
ATWATER ELEMENTARY	2	PL13H	20.0 X 025.0 X 02.0	\$8.96	\$107.52	\$8.96	\$11.25	\$135.00	\$10.25
ATWATER ELEMENTARY	4	PL13H	24.0 X 024.0 X 02.0	\$9.74	\$233.76	\$9.74	\$12.78	\$306.72	\$11.78
ATWATER ELEMENTARY	1	WASH	WASH OUT FILTER	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BAY HAVEN	4	PBYP1	09.4 X 028.6 X 01.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
BAY HAVEN	4	PBYP1	11.4 X 028.0 X 01.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
BAY HAVEN	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BAY HAVEN	1	PBYP1	17.0 X 021.5 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
BAY HAVEN	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BAY HAVEN	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BAY HAVEN	1	PBYP1	20.2 X 021.5 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BAY HAVEN	4	PBYP2	11.6 X 037.1 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
BAY HAVEN	4	PBYP2	11.6 X 039.1 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
BAY HAVEN	3	PBYP2	12.0 X 024.0 X 02.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
BAY HAVEN	1	PBYP2	14.4 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BAY HAVEN	2	PBYP2	15.6 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BAY HAVEN	2	PBYP2	15.6 X 023.2 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BAY HAVEN	2	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BAY HAVEN	2	PBYP2	16.0 X 021.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BAY HAVEN	4	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
BAY HAVEN	4	PBYP2	16.0 X 023.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
BAY HAVEN	8	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
BAY HAVEN	1	PBYP2	25.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BAY HAVEN	1	PBYP2	25.0 X 025.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BAY HAVEN	4	PLPS4	16.0 X 025.0 X 04.0	\$7.91	\$189.84	\$7.91	\$7.00	\$168.00	\$6.75
BAY HAVEN	1	PLPS4	20.0 X 025.0 X 04.0	\$8.11	\$48.66	\$8.11	\$7.00	\$42.00	\$7.00
BAY HAVEN	1	PYD-P	09.4 X 017.4 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BAY HAVEN	1	WSHMF	09.0 X 012.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
BAY HAVEN	1	WSHMF	10.0 X 018.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BAY HAVEN	1	WSHMF	10.0 X 041.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BAY HAVEN	2	WSHMF	12.0 X 012.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BOOKER HIGH	5	PBYP1	10.0 X 025.0 X 01.0	\$2.93	\$87.90	\$2.93	\$2.95	\$88.50	\$1.95
BOOKER HIGH	1	PBYP1	16.0 X 016.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER HIGH	1	PBYP1	16.0 X 017.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER HIGH	1	PBYP1	16.0 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER HIGH	1	PBYP1	16.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER HIGH	1	PBYP1	16.0 X 020.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER HIGH	1	PBYP1	17.0 X 019.6 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER HIGH	1	PBYP1	18.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER HIGH	1	PBYP1	20.0 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER HIGH	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER HIGH	1	PBYP1	20.0 X 022.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER HIGH	1	PBYP1	20.0 X 022.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER HIGH	8	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
BOOKER HIGH	2	PBYP2	16.0 X 021.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BOOKER HIGH	4	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
BOOKER HIGH	2	PBYP2	16.2 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BOOKER HIGH	1	PBYP2	17.6 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
BOOKER HIGH	4	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
BOOKER HIGH	2	PBYP2	20.0 X 021.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BOOKER HIGH	4	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
BOOKER HIGH	4	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
BOOKER HIGH	1	PBYP2	20.0 X 027.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER HIGH	1	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER HIGH	1	PYD-P	09.0 X 020.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER MIDDLE	1	PBYP1	16.0 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER MIDDLE	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER MIDDLE	6	PBYP2	12.0 X 024.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
BOOKER MIDDLE	1	PBYP2	12.4 X 016.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER MIDDLE	1	PBYP2	14.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER MIDDLE	4	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
BOOKER MIDDLE	2	PBYP2	16.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BOOKER MIDDLE	4	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
BOOKER MIDDLE	1	PBYP2	16.0 X 027.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER MIDDLE	12	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$210.96	\$2.93	\$2.95	\$212.40	\$1.95
BOOKER MIDDLE	1	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER MIDDLE	2	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BOOKER MIDDLE	1	PBYP2	20.0 X 027.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95



THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
BOOKER MIDDLE	2	PBYP2	21.0 X 021.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BOOKER MIDDLE	2	PBYP2	21.4 X 042.0 X 02.0	\$4.35	\$52.20	\$4.35	\$2.95	\$35.40	\$1.95
BOOKER MIDDLE	1	PBYP2	22.4 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER MIDDLE	1	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER MIDDLE	2	PLPS1	24.0 X 024.0 X 01.0	\$5.87	\$70.44	\$5.87	\$4.45	\$53.40	\$4.45
BOOKER MIDDLE	2	PLTDC	24.0 X 024.0 X 01.0	\$14.00	\$168.00	\$14.00	\$14.48	\$173.76	\$13.00
BOOKER MIDDLE	1	SLEVE	14.2 X 020.2	\$3.50	\$21.00	\$3.50	\$3.65	\$21.90	\$2.65
BOOKER MIDDLE	2	WSHMF	12.0 X 013.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BOOKER MIDDLE	1	WSHMF	12.4 X 016.4 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BOOKER MIDDLE	2	WSHMF	13.0 X 017.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BRENTWOOD ELEMENTARY	1	PBYP1	16.0 X 025.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BRENTWOOD ELEMENTARY	1	PBYP2	09.2 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BRENTWOOD ELEMENTARY	1	PBYP2	09.2 X 020.5 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BRENTWOOD ELEMENTARY	1	PBYP2	12.4 X 017.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BRENTWOOD ELEMENTARY	1	PBYP2	13.6 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BRENTWOOD ELEMENTARY	1	PBYP2	14.2 X 025.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BRENTWOOD ELEMENTARY	2	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BRENTWOOD ELEMENTARY	1	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BRENTWOOD ELEMENTARY	1	PBYP2	16.0 X 025.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BRENTWOOD ELEMENTARY	1	PBYP2	18.2 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
BRENTWOOD ELEMENTARY	6	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
BRENTWOOD ELEMENTARY	1	PBYP2	20.0 X 020.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BRENTWOOD ELEMENTARY	2	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BRENTWOOD ELEMENTARY	2	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BRENTWOOD ELEMENTARY	1	PBYP2	20.0 X 025.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BRENTWOOD ELEMENTARY	1	PBYP2	20.0 X 028.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BRENTWOOD ELEMENTARY	2	PBYP2	20.5 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BRENTWOOD ELEMENTARY	1	PLPS4	16.0 X 025.0 X 04.0	\$7.91	\$47.46	\$7.91	\$7.00	\$42.00	\$6.75
BRENTWOOD ELEMENTARY	3	PLPS4	20.0 X 025.0 X 04.0	\$8.11	\$145.98	\$8.11	\$7.00	\$126.00	\$7.00
BRENTWOOD ELEMENTARY	1	PYD-P	10.4 X 019.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BRENTWOOD ELEMENTARY	1	WSHMF	08.0 X 012.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BRENTWOOD ELEMENTARY	1	WSHMF	10.4 X 017.2 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BRENTWOOD ELEMENTARY	1	WSHMF	11.4 X 018.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BRENTWOOD ELEMENTARY	2	WSHMF	12.0 X 012.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BRENTWOOD ELEMENTARY	2	WSHMF	12.0 X 012.0 X 00.4	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BRENTWOOD ELEMENTARY	2	WSHMF	12.4 X 013.6 X 00.4	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BROOKSIDE MIDDLE	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BROOKSIDE MIDDLE	2	PBYP2	12.2 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BROOKSIDE MIDDLE	1	PBYP2	12.4 X 017.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BROOKSIDE MIDDLE	1	PBYP2	13.6 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
BROOKSIDE MIDDLE	2	PBYP2	14.2 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BROOKSIDE MIDDLE	2	PBYP2	14.2 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BROOKSIDE MIDDLE	1	PBYP2	14.2 X 025.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BROOKSIDE MIDDLE	2	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BROOKSIDE MIDDLE	2	PBYP2	16.0 X 021.2 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BROOKSIDE MIDDLE	2	PBYP2	16.0 X 021.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BROOKSIDE MIDDLE	2	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BROOKSIDE MIDDLE	1	PBYP2	16.0 X 025.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BROOKSIDE MIDDLE	2	PBYP2	16.0 X 027.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BROOKSIDE MIDDLE	2	PBYP2	17.6 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BROOKSIDE MIDDLE	1	PBYP2	17.6 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BROOKSIDE MIDDLE	2	PBYP2	19.4 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BROOKSIDE MIDDLE	1	PBYP2	19.4 X 025.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BROOKSIDE MIDDLE	2	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BROOKSIDE MIDDLE	2	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
BROOKSIDE MIDDLE	1	PBYP2	20.0 X 025.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BROOKSIDE MIDDLE	1	PBYP2	20.0 X 027.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BROOKSIDE MIDDLE	6	PBYP2	25.0 X 025.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
BROOKSIDE MIDDLE	1	WSHMF	08.0 X 024.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
BROOKSIDE MIDDLE	2	WSHMF	12.0 X 012.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
BROOKSIDE MIDDLE	2	WSHMF	12.0 X 012.0 X 00.4	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
CRANBERRY ELEMENTARY	1	PBYP1	16.0 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
CRANBERRY ELEMENTARY	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
CRANBERRY ELEMENTARY	1	PBYP1	16.2 X 030.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
CRANBERRY ELEMENTARY	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
CRANBERRY ELEMENTARY	4	PBYP2	13.4 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
CRANBERRY ELEMENTARY	4	PBYP2	14.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
CRANBERRY ELEMENTARY	4	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
CRANBERRY ELEMENTARY	4	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
CRANBERRY ELEMENTARY	4	PBYP2	16.0 X 023.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
CRANBERRY ELEMENTARY	8	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
CRANBERRY ELEMENTARY	4	PBYP2	16.0 X 025.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
CRANBERRY ELEMENTARY	2	PBYP2	16.0 X 027.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
CRANBERRY ELEMENTARY	2	PBYP2	17.4 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
CRANBERRY ELEMENTARY	2	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
CRANBERRY ELEMENTARY	2	PBYP2	20.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
CRANBERRY ELEMENTARY	16	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$281.28	\$2.93	\$2.95	\$283.20	\$1.95
CRANBERRY ELEMENTARY	10	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$175.80	\$2.93	\$2.95	\$177.00	\$1.95
CRANBERRY ELEMENTARY	4	PBYP2	20.0 X 025.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
CRANBERRY ELEMENTARY	1	WSHMF	11.0 X 028.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
CRANBERRY ELEMENTARY	1	WSHMF	11.0 X 038.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
CRANBERRY ELEMENTARY	2	WSHMF	12.0 X 012.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
CRANBERRY ELEMENTARY	1	WSHMF	16.0 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
EMMA BOOKER ELEMENTARY	1	PBYP1	12.0 X 024.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
EMMA BOOKER ELEMENTARY	1	PBYP1	15.0 X 030.5 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
EMMA BOOKER ELEMENTARY	1	PBYP1	16.2 X 030.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
EMMA BOOKER ELEMENTARY	1	PBYP1	18.0 X 024.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
EMMA BOOKER ELEMENTARY	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
EMMA BOOKER ELEMENTARY	2	PBYP1	21.4 X 021.4 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
EMMA BOOKER ELEMENTARY	2	PBYP2	07.4 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
EMMA BOOKER ELEMENTARY	4	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
EMMA BOOKER ELEMENTARY	1	PBYP2	16.0 X 020.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
EMMA BOOKER ELEMENTARY	2	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
EMMA BOOKER ELEMENTARY	2	PBYP2	16.0 X 021.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
EMMA BOOKER ELEMENTARY	2	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
EMMA BOOKER ELEMENTARY	2	PBYP2	16.0 X 027.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
EMMA BOOKER ELEMENTARY	1	PBYP2	16.2 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
EMMA BOOKER ELEMENTARY	1	PBYP2	17.6 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
EMMA BOOKER ELEMENTARY	1	PBYP2	20.0 X 021.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
EMMA BOOKER ELEMENTARY	1	PBYP2	20.0 X 023.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
EMMA BOOKER ELEMENTARY	1	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
EMMA BOOKER ELEMENTARY	1	PBYP2	20.0 X 027.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
EMMA BOOKER ELEMENTARY	1	PBYP2	25.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
EMMA BOOKER ELEMENTARY	1	PBYP2	25.0 X 025.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
EMMA BOOKER ELEMENTARY	1	WSHMF	10.0 X 040.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
EMMA BOOKER ELEMENTARY	1	WSHMF	10.0 X 040.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
EMMA BOOKER ELEMENTARY	1	WSHMF	10.0 X 047.4 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP1	08.0 X 012.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP1	11.2 X 018.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP1	12.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP1	12.0 X 036.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP1	12.2 X 018.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP1	16.2 X 030.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	8	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	4	PBYP2	16.0 X 023.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
ENGLEWOOD ELEMENTARY	2	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
ENGLEWOOD ELEMENTARY	4	PBYP2	16.0 X 025.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
ENGLEWOOD ELEMENTARY	2	PBYP2	16.0 X 027.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP2	17.6 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	5	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$87.90	\$2.93	\$2.95	\$88.50	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP2	20.0 X 021.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP2	20.0 X 021.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP2	20.0 X 021.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	2	PBYP2	20.0 X 021.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP2	20.0 X 027.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	1	PBYP2	25.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
ENGLEWOOD ELEMENTARY	2	WSHMF	12.0 X 012.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
ENGLEWOOD ELEMENTARY	1	WSHMF	16.0 X 016.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
FACILITIES SERVICES	3	PBYP1	16.0 X 025.0 X 01.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
FACILITIES SERVICES	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
FACILITIES SERVICES	1	PBYP1	17.4 X 025.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
FACILITIES SERVICES	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
FACILITIES SERVICES	1	PBYP1	22.0 X 022.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
FACILITIES SERVICES	1	PYD-P	09.0 X 020.4 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
FACILITIES SERVICES	1	PYD-P	10.0 X 018.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
FACILITIES SERVICES	1	PYD-P	12.0 X 016.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
FACILITIES SERVICES	1	WSHMF	09.0 X 030.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
FACILITIES SERVICES	1	WSHMF	10.0 X 018.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
FACILITIES SERVICES	2	WSHMF	16.0 X 020.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
FLORIDA CENTER PORTABLE	1	PBYP1	15.0 X 030.5 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
FRUITVILLE ELEMENTARY	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
FRUITVILLE ELEMENTARY	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
FRUITVILLE ELEMENTARY	4	PBYP2	10.4 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
FRUITVILLE ELEMENTARY	1	PBYP2	12.4 X 017.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
FRUITVILLE ELEMENTARY	2	PBYP2	13.2 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
FRUITVILLE ELEMENTARY	1	PBYP2	14.2 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
FRUITVILLE ELEMENTARY	2	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
FRUITVILLE ELEMENTARY	2	PBYP2	16.0 X 021.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
FRUITVILLE ELEMENTARY	2	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
FRUITVILLE ELEMENTARY	4	PBYP2	16.0 X 023.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
FRUITVILLE ELEMENTARY	2	PBYP2	16.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
FRUITVILLE ELEMENTARY	8	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
FRUITVILLE ELEMENTARY	2	PBYP2	16.0 X 027.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
FRUITVILLE ELEMENTARY	2	PBYP2	17.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
FRUITVILLE ELEMENTARY	2	PBYP2	17.4 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95



THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
FRUITVILLE ELEMENTARY	4	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
FRUITVILLE ELEMENTARY	2	PBYP2	20.0 X 023.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
FRUITVILLE ELEMENTARY	6	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
FRUITVILLE ELEMENTARY	4	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
FRUITVILLE ELEMENTARY	16	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$281.28	\$2.93	\$2.95	\$283.20	\$1.95
FRUITVILLE ELEMENTARY	1	PYD-P	11.0 X 022.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
FRUITVILLE ELEMENTARY	2	WSHMF	14.0 X 017.4 X 00.4	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GARDEN ELEMENTARY	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GARDEN ELEMENTARY	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GARDEN ELEMENTARY	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GARDEN ELEMENTARY	6	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
GARDEN ELEMENTARY	2	PBYP2	16.0 X 021.2 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GARDEN ELEMENTARY	4	PBYP2	16.0 X 025.6 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
GARDEN ELEMENTARY	6	PBYP2	17.2 X 020.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
GARDEN ELEMENTARY	2	PBYP2	19.2 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GARDEN ELEMENTARY	4	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
GARDEN ELEMENTARY	2	PBYP2	20.0 X 021.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GARDEN ELEMENTARY	2	PBYP2	20.0 X 023.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GARDEN ELEMENTARY	6	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
GARDEN ELEMENTARY	1	PBYP2	20.0 X 027.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
GARDEN ELEMENTARY	2	PBYP2	23.4 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GARDEN ELEMENTARY	1	WSHMF	12.0 X 036.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	1	PBYP1	12.0 X 024.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	1	PBYP1	15.0 X 030.5 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	1	PBYP1	16.2 X 030.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	1	PBYP1	20.2 X 044.2 X 01.0	\$4.35	\$26.10	\$4.35	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	1	PBYP1	21.6 X 021.6 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	1	PBYP2	12.0 X 016.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	4	PBYP2	13.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
GLENALLEN ELEMENTARY	1	PBYP2	15.0 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	1	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	4	PBYP2	16.0 X 021.2 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
GLENALLEN ELEMENTARY	1	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	2	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GLENALLEN ELEMENTARY	4	PBYP2	16.0 X 025.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
GLENALLEN ELEMENTARY	2	PBYP2	16.0 X 027.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GLENALLEN ELEMENTARY	2	PBYP2	16.0 X 040.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GLENALLEN ELEMENTARY	1	PBYP2	17.3 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
GLENALLEN ELEMENTARY	1	PBYP2	18.2 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	1	PBYP2	19.0 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	2	PBYP2	19.4 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GLENALLEN ELEMENTARY	4	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
GLENALLEN ELEMENTARY	1	PBYP2	20.0 X 021.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	1	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	1	WSHMF	09.0 X 018.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GLENALLEN ELEMENTARY	1	WSHMF	13.0 X 026.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GOCIO ELEMENTARY	1	PBYP1	15.6 X 066.0 X 01.0	\$4.35	\$26.10	\$4.35	\$2.95	\$17.70	\$1.95
GOCIO ELEMENTARY	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GOCIO ELEMENTARY	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GOCIO ELEMENTARY	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GOCIO ELEMENTARY	2	PBYP2	09.3 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GOCIO ELEMENTARY	2	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GOCIO ELEMENTARY	4	PBYP2	16.0 X 021.6 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
GOCIO ELEMENTARY	3	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
GOCIO ELEMENTARY	2	PBYP2	19.6 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GOCIO ELEMENTARY	1	PBYP2	19.6 X 025.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GOCIO ELEMENTARY	2	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GOCIO ELEMENTARY	1	PBYP2	20.0 X 021.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
GOCIO ELEMENTARY	1	PBYP2	20.0 X 021.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GOCIO ELEMENTARY	2	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GOCIO ELEMENTARY	2	PBYP2	20.0 X 025.2 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GOCIO ELEMENTARY	2	PBYP2	23.6 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GOCIO ELEMENTARY	1	PBYP2	23.6 X 025.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GOCIO ELEMENTARY	6	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
GOCIO ELEMENTARY	1	WSHMF	12.0 X 016.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GOCIO ELEMENTARY	1	WSHMF	12.4 X 013.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GOCIO ELEMENTARY	2	WSHMF	14.0 X 014.0 X 00.4	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GOCIO ELEMENTARY	1	WSHMF	16.0 X 020.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GULF GATE ELEMENTARY	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GULF GATE ELEMENTARY	2	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GULF GATE ELEMENTARY	1	PBYP2	16.0 X 025.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GULF GATE ELEMENTARY	2	PBYP2	16.0 X 027.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GULF GATE ELEMENTARY	1	PBYP2	16.0 X 028.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GULF GATE ELEMENTARY	1	PBYP2	17.6 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GULF GATE ELEMENTARY	2	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GULF GATE ELEMENTARY	1	PBYP2	20.0 X 021.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GULF GATE ELEMENTARY	2	PBYP2	20.0 X 021.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
GULF GATE ELEMENTARY	2	PBYP2	20.0 X 023.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
GULF GATE ELEMENTARY	1	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GULF GATE ELEMENTARY	1	PBYP2	20.0 X 025.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GULF GATE ELEMENTARY	1	PBYP2	20.0 X 027.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GULF GATE ELEMENTARY	1	PBYP2	25.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GULF GATE ELEMENTARY	1	PBYP2	25.0 X 025.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
GULF GATE ELEMENTARY	1	WSHMF	09.0 X 025.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
HERON CREEK MIDDLE	1	PBYP1	15.0 X 030.5 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
HERON CREEK MIDDLE	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
HERON CREEK MIDDLE	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
HERON CREEK MIDDLE	4	PBYP2	14.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
HERON CREEK MIDDLE	6	PBYP2	16.0 X 016.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
HERON CREEK MIDDLE	2	PBYP2	16.0 X 018.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
HERON CREEK MIDDLE	2	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
HERON CREEK MIDDLE	2	PBYP2	16.0 X 021.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
HERON CREEK MIDDLE	2	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
HERON CREEK MIDDLE	2	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
HERON CREEK MIDDLE	2	PBYP2	16.0 X 025.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
HERON CREEK MIDDLE	2	PBYP2	16.0 X 027.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
HERON CREEK MIDDLE	2	PBYP2	16.0 X 030.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
HERON CREEK MIDDLE	2	PBYP2	16.0 X 030.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
HERON CREEK MIDDLE	1	PBYP2	17.4 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
HERON CREEK MIDDLE	2	PBYP2	17.5 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
HERON CREEK MIDDLE	2	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
HERON CREEK MIDDLE	1	PBYP2	20.0 X 021.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
HERON CREEK MIDDLE	1	PBYP2	20.0 X 021.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
HERON CREEK MIDDLE	2	PBYP2	20.0 X 023.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
HERON CREEK MIDDLE	2	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
HERON CREEK MIDDLE	4	PBYP2	20.0 X 025.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
HERON CREEK MIDDLE	1	PBYP2	20.0 X 027.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
HERON CREEK MIDDLE	1	PBYP2	25.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
HERON CREEK MIDDLE	1	WSHMF	11.0 X 028.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
HERON CREEK MIDDLE	2	WSHMF	12.0 X 012.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
HERON CREEK MIDDLE	4	WSHMM	16.0 X 030.0 X 01.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
LAKEVIEW ELEMENTARY	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAKEVIEW ELEMENTARY	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAKEVIEW ELEMENTARY	2	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
LAKEVIEW ELEMENTARY	1	PBYP2	16.0 X 021.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAKEVIEW ELEMENTARY	2	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
LAKEVIEW ELEMENTARY	2	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
LAKEVIEW ELEMENTARY	2	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
LAKEVIEW ELEMENTARY	2	PBYP2	20.0 X 021.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
LAKEVIEW ELEMENTARY	2	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
LAKEVIEW ELEMENTARY	1	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAKEVIEW ELEMENTARY	1	PBYP2	25.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAKEVIEW ELEMENTARY	1	PYD-P	16.2 X 030.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAKEVIEW ELEMENTARY	1	PYD-P	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAKEVIEW ELEMENTARY	1	WSHMF	10.0 X 014.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAKEVIEW ELEMENTARY	2	WSHMF	12.0 X 014.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
LAMARQUE ELEMENTARY	4	CHPYP	06.4 X 024.0 X 00.2	\$4.50	\$108.00	\$4.50	\$6.50	\$156.00	\$6.50
LAMARQUE ELEMENTARY	4	CHPYP	07.0 X 024.0 X 00.2	\$4.50	\$108.00	\$4.50	\$6.50	\$156.00	\$6.50
LAMARQUE ELEMENTARY	4	CHPYP	13.0 X 020.0 X 00.2	\$5.25	\$126.00	\$5.25	\$6.50	\$156.00	\$6.50
LAMARQUE ELEMENTARY	4	CHPYP	13.0 X 024.0 X 00.2	\$6.00	\$144.00	\$6.00	\$6.50	\$156.00	\$6.50
LAMARQUE ELEMENTARY	4	CHPYP	13.4 X 020.0 X 00.2	\$5.25	\$126.00	\$5.25	\$6.50	\$156.00	\$6.50
LAMARQUE ELEMENTARY	4	CHPYP	16.0 X 020.0 X 00.2	\$6.00	\$144.00	\$6.00	\$6.50	\$156.00	\$6.50
LAMARQUE ELEMENTARY	2	CHPYP	16.0 X 021.2 X 00.2	\$6.00	\$72.00	\$6.00	\$6.50	\$78.00	\$6.50
LAMARQUE ELEMENTARY	4	CHPYP	16.0 X 021.4 X 00.2	\$6.00	\$144.00	\$6.00	\$6.50	\$156.00	\$6.50
LAMARQUE ELEMENTARY	4	CHPYP	16.0 X 021.6 X 00.2	\$6.00	\$144.00	\$6.00	\$6.50	\$156.00	\$6.50
LAMARQUE ELEMENTARY	8	CHPYP	16.0 X 025.0 X 00.2	\$6.75	\$324.00	\$6.75	\$6.50	\$312.00	\$6.50
LAMARQUE ELEMENTARY	2	CHPYP	16.0 X 025.2 X 00.2	\$6.75	\$81.00	\$6.75	\$6.50	\$78.00	\$6.50
LAMARQUE ELEMENTARY	2	CHPYP	16.0 X 025.4 X 00.2	\$6.75	\$81.00	\$6.75	\$6.50	\$78.00	\$6.50

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
LAMARQUE ELEMENTARY	4	CHPYP	16.0 X 025.5 X 00.2	\$6.75	\$162.00	\$6.75	\$6.50	\$156.00	\$6.50
LAMARQUE ELEMENTARY	1	CHPYP	17.0 X 025.0 X 00.2	\$6.75	\$40.50	\$6.75	\$6.50	\$39.00	\$6.50
LAMARQUE ELEMENTARY	1	CHPYP	17.2 X 025.0 X 00.2	\$6.75	\$40.50	\$6.75	\$6.50	\$39.00	\$6.50
LAMARQUE ELEMENTARY	1	CHPYP	17.4 X 025.0 X 00.2	\$6.75	\$40.50	\$6.75	\$6.50	\$39.00	\$6.50
LAMARQUE ELEMENTARY	1	CHPYP	18.0 X 020.0 X 00.2	\$6.00	\$36.00	\$6.00	\$6.50	\$39.00	\$6.50
LAMARQUE ELEMENTARY	4	CHPYP	20.0 X 020.0 X 00.2	\$6.75	\$162.00	\$6.75	\$6.50	\$156.00	\$6.50
LAMARQUE ELEMENTARY	1	CHPYP	20.0 X 021.0 X 00.2	\$6.75	\$40.50	\$6.75	\$6.50	\$39.00	\$6.50
LAMARQUE ELEMENTARY	2	CHPYP	20.0 X 021.4 X 00.2	\$6.75	\$81.00	\$6.75	\$6.50	\$78.00	\$6.50
LAMARQUE ELEMENTARY	20	CHPYP	20.0 X 024.0 X 00.2	\$6.75	\$810.00	\$6.75	\$6.50	\$780.00	\$6.50
LAMARQUE ELEMENTARY	2	CHPYP	20.0 X 025.0 X 00.2	\$7.50	\$90.00	\$7.50	\$6.50	\$78.00	\$6.50
LAMARQUE ELEMENTARY	1	CHPYP	20.0 X 027.6 X 00.2	\$7.50	\$45.00	\$7.50	\$6.50	\$39.00	\$6.50
LAMARQUE ELEMENTARY	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAMARQUE ELEMENTARY	1	PBYP1	18.0 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAMARQUE ELEMENTARY	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAMARQUE ELEMENTARY	4	PBYP2	06.4 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
LAMARQUE ELEMENTARY	4	PBYP2	07.0 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
LAMARQUE ELEMENTARY	4	PBYP2	13.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
LAMARQUE ELEMENTARY	4	PBYP2	13.0 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
LAMARQUE ELEMENTARY	4	PBYP2	13.4 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
LAMARQUE ELEMENTARY	4	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95



THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
LAMARQUE ELEMENTARY	2	PBYP2	16.0 X 021.2 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
LAMARQUE ELEMENTARY	4	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
LAMARQUE ELEMENTARY	4	PBYP2	16.0 X 021.6 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
LAMARQUE ELEMENTARY	8	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
LAMARQUE ELEMENTARY	2	PBYP2	16.0 X 025.2 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
LAMARQUE ELEMENTARY	2	PBYP2	16.0 X 025.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
LAMARQUE ELEMENTARY	4	PBYP2	16.0 X 025.5 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
LAMARQUE ELEMENTARY	1	PBYP2	17.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAMARQUE ELEMENTARY	1	PBYP2	17.2 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAMARQUE ELEMENTARY	1	PBYP2	17.4 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAMARQUE ELEMENTARY	4	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
LAMARQUE ELEMENTARY	1	PBYP2	20.0 X 021.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAMARQUE ELEMENTARY	2	PBYP2	20.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
LAMARQUE ELEMENTARY	20	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$351.60	\$2.93	\$2.95	\$354.00	\$1.95
LAMARQUE ELEMENTARY	2	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
LAMARQUE ELEMENTARY	1	PBYP2	20.0 X 027.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAMARQUE ELEMENTARY	4	WSHMF	10.0 X 011.0 X 00.5	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
LAMARQUE ELEMENTARY	1	WSHMF	10.0 X 026.4 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAMARQUE ELEMENTARY	1	WSHMF	11.4 X 013.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	1	PBYP1	13.6 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
LAUREL NOKOMIS	1	PBYP1	14.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	1	PBYP1	15.0 X 030.5 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	1	PBYP1	20.2 X 020.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	1	PBYP1	21.6 X 021.6 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	1	PBYP2	12.0 X 015.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	1	PBYP2	12.0 X 023.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	1	PBYP2	12.0 X 023.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	6	PBYP2	12.0 X 024.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
LAUREL NOKOMIS	1	PBYP2	14.4 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	1	PBYP2	15.6 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	1	PBYP2	16.0 X 025.0 X 01.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	1	PBYP2	17.0 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	2	PBYP2	18.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
LAUREL NOKOMIS	1	PBYP2	19.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	4	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
LAUREL NOKOMIS	2	PBYP2	20.0 X 023.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
LAUREL NOKOMIS	4	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
LAUREL NOKOMIS	2	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
LAUREL NOKOMIS	1	PBYP2	21.4 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	1	PBYP2	23.2 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	1	PBYP2	23.3 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	1	PBYP2	23.4 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	6	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
LAUREL NOKOMIS	1	PBYP2	24.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
LAUREL NOKOMIS	2	WASH	13.0 X 021.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
LAUREL NOKOMIS	1	WSHMF	10.0 X 014.4 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
MCINTOSH MIDDLE	1	PBYP1	15.0 X 030.5 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
MCINTOSH MIDDLE	1	PBYP1	16.0 X 025.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
MCINTOSH MIDDLE	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
MCINTOSH MIDDLE	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
MCINTOSH MIDDLE	1	PBYP1	21.6 X 021.6 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
MCINTOSH MIDDLE	4	PBYP2	13.4 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
MCINTOSH MIDDLE	2	PBYP2	13.4 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
MCINTOSH MIDDLE	4	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
MCINTOSH MIDDLE	1	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
MCINTOSH MIDDLE	4	PBYP2	16.0 X 023.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
MCINTOSH MIDDLE	2	PBYP2	16.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
MCINTOSH MIDDLE	2	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
MCINTOSH MIDDLE	2	PBYP2	16.2 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
MCINTOSH MIDDLE	2	PBYP2	17.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
MCINTOSH MIDDLE	1	PBYP2	17.4 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
MCINTOSH MIDDLE	1	PBYP2	18.2 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
MCINTOSH MIDDLE	1	PBYP2	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
MCINTOSH MIDDLE	1	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
MCINTOSH MIDDLE	1	PBYP2	20.0 X 021.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
MCINTOSH MIDDLE	1	PBYP2	20.0 X 021.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
MCINTOSH MIDDLE	2	PBYP2	20.0 X 023.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
MCINTOSH MIDDLE	16	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$281.28	\$2.93	\$2.95	\$283.20	\$1.95
MCINTOSH MIDDLE	2	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
MCINTOSH MIDDLE	1	PBYP2	20.0 X 027.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
MCINTOSH MIDDLE	6	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
MCINTOSH MIDDLE	1	PBYP2	25.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
MCINTOSH MIDDLE	1	WSHMF	13.0 X 017.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
NORTH PORT HIGH	1	PBYP1	15.0 X 030.5 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
NORTH PORT HIGH	2	PBYP1	16.0 X 025.0 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
NORTH PORT HIGH	3	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
NORTH PORT HIGH	1	PBYP1	17.0 X 025.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
NORTH PORT HIGH	1	PBYP1	19.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
NORTH PORT HIGH	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
NORTH PORT HIGH	3	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
NORTH PORT HIGH	2	PBYP2	08.2 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
NORTH PORT HIGH	4	PBYP2	13.4 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
NORTH PORT HIGH	4	PBYP2	14.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
NORTH PORT HIGH	4	PBYP2	14.5 X 025.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
NORTH PORT HIGH	2	PBYP2	14.6 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
NORTH PORT HIGH	6	PBYP2	15.0 X 020.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
NORTH PORT HIGH	2	PBYP2	15.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
NORTH PORT HIGH	4	PBYP2	15.6 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
NORTH PORT HIGH	4	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
NORTH PORT HIGH	4	PBYP2	16.0 X 021.6 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
NORTH PORT HIGH	4	PBYP2	16.0 X 023.6 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
NORTH PORT HIGH	8	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
NORTH PORT HIGH	2	PBYP2	16.2 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
NORTH PORT HIGH	2	PBYP2	17.2 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
NORTH PORT HIGH	2	PBYP2	17.4 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
NORTH PORT HIGH	1	PBYP2	17.6 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
NORTH PORT HIGH	16	PBYP2	18.0 X 024.0 X 02.0	\$2.93	\$281.28	\$2.93	\$2.95	\$283.20	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
NORTH PORT HIGH	4	PBYP2	19.1 X 025.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
NORTH PORT HIGH	1	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
NORTH PORT HIGH	1	PBYP2	20.0 X 021.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
NORTH PORT HIGH	2	PBYP2	20.0 X 021.2 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
NORTH PORT HIGH	2	PBYP2	20.0 X 021.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
NORTH PORT HIGH	2	PBYP2	20.0 X 023.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
NORTH PORT HIGH	16	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$281.28	\$2.93	\$2.95	\$283.20	\$1.95
NORTH PORT HIGH	8	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
NORTH PORT HIGH	4	PBYP2	20.0 X 025.2 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
NORTH PORT HIGH	4	PBYP2	20.0 X 025.6 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
NORTH PORT HIGH	1	PBYP2	20.0 X 027.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
NORTH PORT HIGH	1	PBYP2	20.0 X 027.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
NORTH PORT HIGH	1	PBYP2	20.0 X 030.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
NORTH PORT HIGH	1	PBYP2	20.2 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
NORTH PORT HIGH	4	PBYP2	20.6 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
NORTH PORT HIGH	1	PBYP2	25.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
NORTH PORT HIGH	1	PYD-P	11.0 X 017.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
NORTH PORT HIGH	1	PYD-P	11.0 X 022.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
NORTH PORT HIGH	1	WSHMF	08.0 X 020.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
NORTH PORT HIGH	1	WSHMF	08.0 X 024.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
NORTH PORT HIGH	2	WSHMF	12.0 X 012.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
NORTH PORT HIGH	2	WSHMF	13.0 X 015.0 X 00.4	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
OAK PARK	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	4	PBYP1	16.2 X 030.2 X 01.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
OAK PARK	6	PBYP1	20.0 X 025.0 X 01.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
OAK PARK	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	5	PBYP2	09.4 X 020.0 X 02.0	\$2.93	\$87.90	\$2.93	\$2.95	\$88.50	\$1.95
OAK PARK	1	PBYP2	12.0 X 016.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	1	PBYP2	12.0 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	1	PBYP2	12.4 X 016.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	1	PBYP2	14.4 X 023.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	4	PBYP2	15.4 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
OAK PARK	2	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
OAK PARK	1	PBYP2	16.0 X 020.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	2	PBYP2	16.0 X 021.1 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
OAK PARK	2	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
OAK PARK	8	PBYP2	16.0 X 023.6 X 01.4	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
OAK PARK	2	PBYP2	16.0 X 025.3 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
OAK PARK	2	PBYP2	16.0 X 025.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
OAK PARK	2	PBYP2	16.0 X 026.7 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
OAK PARK	2	PBYP2	16.0 X 027.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
OAK PARK	1	PBYP2	16.0 X 038.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	1	PBYP2	16.2 X 033.6 X 01.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	3	PBYP2	17.0 X 023.4 X 02.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
OAK PARK	1	PBYP2	17.0 X 023.5 X 01.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	1	PBYP2	17.2 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	1	PBYP2	17.4 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	3	PBYP2	18.0 X 024.0 X 02.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
OAK PARK	1	PBYP2	19.4 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	1	PBYP2	19.6 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	1	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	1	PBYP2	20.0 X 020.2 X 01.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	1	PBYP2	20.0 X 023.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	5	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$87.90	\$2.93	\$2.95	\$88.50	\$1.95
OAK PARK	1	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	1	PBYP2	20.0 X 027.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	1	PBYP2	20.0 X 027.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	1	PBYP2	22.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	4	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
OAK PARK	2	PBYP2	24.0 X 027.2 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95



THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
OAK PARK	1	PBYP2	25.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	1	PYD-P	11.0 X 023.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK	1	WSHMF	10.0 X 016.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK SOUTH	9	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$158.22	\$2.93	\$2.95	\$159.30	\$1.95
OAK PARK SOUTH	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK SOUTH	2	PBYP2	20.0 X 027.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
OAK PARK SOUTH	1	PBYP2	21.4 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
OAK PARK SOUTH	2	WSHMF	12.0 X 012.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
PHILLIPPI SHORES ELEMENTARY	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PHILLIPPI SHORES ELEMENTARY	2	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
PHILLIPPI SHORES ELEMENTARY	2	PBYP2	16.0 X 021.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
PHILLIPPI SHORES ELEMENTARY	4	PBYP2	16.0 X 021.3 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
PHILLIPPI SHORES ELEMENTARY	4	PBYP2	16.0 X 023.3 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
PHILLIPPI SHORES ELEMENTARY	4	PBYP2	16.0 X 023.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
PHILLIPPI SHORES ELEMENTARY	8	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
PHILLIPPI SHORES ELEMENTARY	4	PBYP2	16.0 X 025.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
PHILLIPPI SHORES ELEMENTARY	2	PBYP2	16.0 X 027.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
PHILLIPPI SHORES ELEMENTARY	4	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
PHILLIPPI SHORES ELEMENTARY	2	PBYP2	20.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
PHILLIPPI SHORES ELEMENTARY	8	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
PHILLIPPI SHORES ELEMENTARY	4	PBYP2	20.0 X 025.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
PHILLIPPI SHORES ELEMENTARY	1	PBYP2	20.0 X 027.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PHILLIPPI SHORES ELEMENTARY	1	PBYP2	20.0 X 027.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PHILLIPPI SHORES ELEMENTARY	1	WSHMF	10.0 X 028.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
PHILLIPPI SHORES ELEMENTARY	1	WSHMF	10.0 X 042.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	1	PBYP1	15.0 X 030.5 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	7	PBYP1	16.2 X 030.2 X 01.0	\$2.93	\$123.06	\$2.93	\$2.95	\$123.90	\$1.95
PINE VIEW	1	PBYP1	18.0 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	7	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$123.06	\$2.93	\$2.95	\$123.90	\$1.95
PINE VIEW	1	PBYP2	08.0 X 016.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	3	PBYP2	09.0 X 016.0 X 02.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
PINE VIEW	1	PBYP2	09.4 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	2	PBYP2	10.0 X 016.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
PINE VIEW	3	PBYP2	10.0 X 020.0 X 02.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
PINE VIEW	1	PBYP2	10.4 X 016.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	1	PBYP2	12.4 X 017.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	1	PBYP2	14.2 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	2	PBYP2	14.6 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
PINE VIEW	1	PBYP2	15.6 X 027.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	2	PBYP2	16.0 X 017.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
PINE VIEW	2	PBYP2	16.0 X 018.2 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
PINE VIEW	2	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
PINE VIEW	2	PBYP2	16.0 X 023.2 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
PINE VIEW	1	PBYP2	16.0 X 023.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	2	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
PINE VIEW	1	PBYP2	16.0 X 027.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	1	PBYP2	16.0 X 036.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	2	PBYP2	16.2 X 023.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
PINE VIEW	2	PBYP2	16.2 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
PINE VIEW	1	PBYP2	19.2 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	1	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	1	PBYP2	20.0 X 023.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	8	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
PINE VIEW	1	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	1	PBYP2	20.0 X 026.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
PINE VIEW	1	PBYP2	20.0 X 038.0 X 02.0	\$4.35	\$26.10	\$4.35	\$2.95	\$17.70	\$1.95
PINE VIEW	1	SLEVE	10.4 X 022.0	\$3.50	\$21.00	\$3.50	\$3.65	\$21.90	\$2.65
PINE VIEW	1	SLEVE	13.0 X 026.0	\$3.50	\$21.00	\$3.50	\$3.65	\$21.90	\$2.65
PINE VIEW	1	SLEVE	14.2 X 021.2	\$3.50	\$21.00	\$3.50	\$3.65	\$21.90	\$2.65
PINE VIEW	2	WSHMF	12.0 X 012.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
RIVERVIEW HIGH	1	PBYP1	10.0 X 061.6 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
RIVERVIEW HIGH	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
RIVERVIEW HIGH	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
RIVERVIEW HIGH	2	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
RIVERVIEW HIGH	2	PBYP1	21.6 X 021.6 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
RIVERVIEW HIGH	4	PBYP2	10.2 X 020.0 X 01.4	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
RIVERVIEW HIGH	1	PBYP2	12.0 X 024.0 X 01.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
RIVERVIEW HIGH	14	PBYP2	16.0 X 020.0 X 01.4	\$2.93	\$246.12	\$2.93	\$2.95	\$247.80	\$1.95
RIVERVIEW HIGH	2	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
RIVERVIEW HIGH	1	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
RIVERVIEW HIGH	1	PBYP2	16.0 X 021.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
RIVERVIEW HIGH	2	PBYP2	16.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
RIVERVIEW HIGH	2	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
RIVERVIEW HIGH	8	PBYP2	20.0 X 020.0 X 01.4	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
RIVERVIEW HIGH	2	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
RIVERVIEW HIGH	1	PBYP2	20.0 X 021.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
RIVERVIEW HIGH	2	PBYP2	20.0 X 021.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
RIVERVIEW HIGH	2	PBYP2	20.0 X 023.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
RIVERVIEW HIGH	6	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
RIVERVIEW HIGH	1	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
RIVERVIEW HIGH	16	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$281.28	\$2.93	\$2.95	\$283.20	\$1.95
RIVERVIEW HIGH	1	PBYP2	25.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
RIVERVIEW HIGH	1	WASH	WASH OUT FILTER	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
RIVERVIEW HIGH	1	WSHMF	12.0 X 030.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI SOUTH	2	PBYP1	14.0 X 028.0 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI SOUTH	1	PBYP1	15.0 X 030.5 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI SOUTH	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI SOUTH	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI SOUTH	1	WSHMF	10.0 X 016.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	1	PBYP1	09.2 X 043.6 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	1	PBYP1	09.4 X 021.6 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	1	PBYP1	10.4 X 061.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	2	PBYP1	15.6 X 042.0 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	1	PBYP1	15.6 X 078.0 X 01.0	\$4.35	\$26.10	\$4.35	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	2	PBYP1	16.0 X 025.0 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	1	PBYP1	16.2 X 066.4 X 01.0	\$4.35	\$26.10	\$4.35	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	1	PBYP1	17.0 X 025.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	2	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	4	PBYP2	10.4 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	1	PBYP2	12.0 X 012.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	1	PBYP2	12.0 X 016.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	6	PBYP2	15.0 X 020.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	2	PBYP2	15.0 X 021.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	8	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	4	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	4	PBYP2	16.0 X 023.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	13	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$228.54	\$2.93	\$2.95	\$230.10	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	4	PBYP2	16.0 X 025.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	2	PBYP2	16.0 X 027.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	6	PBYP2	17.4 X 020.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	2	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	2	PBYP2	20.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	1	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95



THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	1	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	1	PBYP2	20.0 X 027.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	4	PBYP2	21.0 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	1	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	1	WSHMF	12.0 X 030.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	1	WSHMF	12.0 X 030.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	1	WSHMF	13.0 X 021.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECHNICAL INSTITUTE - SCTI - SARASOTA	1	WSHMF	13.0 X 030.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	PBYP1	08.7 X 061.2 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	2	PBYP1	10.2 X 023.0 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	2	PBYP1	10.2 X 025.0 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	1	PBYP1	11.6 X 021.6 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
SARASOTA HIGH	1	PBYP1	12.2 X 012.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	PBYP1	12.2 X 024.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	2	PBYP1	15.0 X 030.2 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	1	PBYP1	15.0 X 030.5 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	2	PBYP1	15.5 X 078.0 X 01.0	\$4.35	\$52.20	\$4.35	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	1	PBYP1	15.6 X 066.0 X 01.0	\$4.35	\$26.10	\$4.35	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	PBYP1	15.6 X 078.0 X 01.0	\$4.35	\$26.10	\$4.35	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	4	PBYP1	16.0 X 025.0 X 01.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
SARASOTA HIGH	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	PBYP1	16.2 X 028.3 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	PBYP1	16.6 X 025.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	PBYP1	16.6 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	PBYP1	17.4 X 025.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	PBYP1	20.0 X 022.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	2	PBYP1	20.0 X 022.2 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	2	PBYP1	20.0 X 025.0 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	PBYP1	21.6 X 021.6 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	PBYP1	21.6 X 032.5 X 01.0	\$4.35	\$26.10	\$4.35	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	PBYP1	23.6 X 035.6 X 01.0	\$4.35	\$26.10	\$4.35	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
SARASOTA HIGH	1	PBYP2	04.6 X 016.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	2	PBYP2	09.2 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	4	PBYP2	09.4 X 016.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
SARASOTA HIGH	1	PBYP2	10.2 X 016.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	2	PBYP2	11.6 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	3	PBYP2	12.0 X 024.0 X 02.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
SARASOTA HIGH	1	PBYP2	12.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	PBYP2	13.5 X 019.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	PBYP2	13.5 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	PBYP2	13.5 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	4	PBYP2	13.6 X 016.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
SARASOTA HIGH	2	PBYP2	14.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	4	PBYP2	15.6 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
SARASOTA HIGH	4	PBYP2	16.0 X 016.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
SARASOTA HIGH	2	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	2	PBYP2	16.0 X 021.2 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	2	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	2	PBYP2	16.0 X 023.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	3	PBYP2	16.0 X 023.2 X 02.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
SARASOTA HIGH	2	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
SARASOTA HIGH	2	PBYP2	16.0 X 025.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	1	PBYP2	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	PBYP2	16.1 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	PBYP2	16.1 X 026.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	2	PBYP2	16.4 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	2	PBYP2	17.4 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	2	PBYP2	18.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	2	PBYP2	18.6 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	3	PBYP2	19.4 X 025.0 X 02.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
SARASOTA HIGH	2	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	2	PBYP2	20.0 X 021.2 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	2	PBYP2	20.0 X 021.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	1	PBYP2	20.0 X 023.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	6	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
SARASOTA HIGH	8	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
SARASOTA HIGH	1	PBYP2	20.0 X 025.3 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	9	PBYP2	20.2 X 025.0 X 02.0	\$2.93	\$158.22	\$2.93	\$2.95	\$159.30	\$1.95
SARASOTA HIGH	2	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA HIGH	1	PBYP2	24.0 X 025.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA HIGH	1	WSHMF	11.0 X 011.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
SARASOTA HIGH	1	WSHMF	12.0 X 020.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA MIDDLE	1	PBYP1	16.0 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA MIDDLE	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA MIDDLE	1	PBYP1	20.0 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA MIDDLE	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA MIDDLE	6	PBYP2	12.0 X 024.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
SARASOTA MIDDLE	4	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
SARASOTA MIDDLE	2	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA MIDDLE	4	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
SARASOTA MIDDLE	1	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA MIDDLE	2	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA MIDDLE	2	PBYP2	22.0 X 022.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SARASOTA MIDDLE	1	PBYP2	23.2 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA MIDDLE	1	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA MIDDLE	2	PLPS1	24.0 X 024.0 X 01.0	\$5.87	\$70.44	\$5.87	\$4.45	\$53.40	\$4.45
SARASOTA MIDDLE	2	PLTDC	24.0 X 024.0 X 01.0	\$14.00	\$168.00	\$14.00	\$14.48	\$173.76	\$13.00
SARASOTA MIDDLE	4	WSHMF	10.0 X 012.0 X 00.4	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
SARASOTA CO TECH INSTITUTE - SCTI - FIRE/SCIENCE	1	PBYP1	14.4 X 022.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
SARASOTA CO TECH INSTITUTE - SCTI - FIRE/SCIENCE	1	PBYP1	15.0 X 030.5 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECH INSTITUTE - SCTI - FIRE/SCIENCE	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECH INSTITUTE - SCTI - FIRE/SCIENCE	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECH INSTITUTE - SCTI - FIRE/SCIENCE	1	WSHMF	08.0 X 014.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SARASOTA CO TECH INSTITUTE - SCTI - FIRE/SCIENCE	1	WSHMF	12.0 X 018.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SHERIFF DRIVER TRAINING PORTABLE	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SOUTHSIDE ELEMENTARY	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SOUTHSIDE ELEMENTARY	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SOUTHSIDE ELEMENTARY	6	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
SOUTHSIDE ELEMENTARY	2	PBYP2	16.0 X 020.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SOUTHSIDE ELEMENTARY	2	PBYP2	16.0 X 021.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SOUTHSIDE ELEMENTARY	2	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SOUTHSIDE ELEMENTARY	2	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SOUTHSIDE ELEMENTARY	3	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
SOUTHSIDE ELEMENTARY	2	PBYP2	20.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SOUTHSIDE ELEMENTARY	4	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
SOUTHSIDE ELEMENTARY	3	PLPS2	12.0 X 024.0 X 02.0	\$5.15	\$92.70	\$5.15	\$4.45	\$80.10	\$4.45
SOUTHSIDE ELEMENTARY	2	PLPS2	16.0 X 020.0 X 02.0	\$5.33	\$63.96	\$5.33	\$4.45	\$53.40	\$4.45
SOUTHSIDE ELEMENTARY	2	PLPS2	20.0 X 020.0 X 02.0	\$5.63	\$67.56	\$5.63	\$4.45	\$53.40	\$4.45
SOUTHSIDE ELEMENTARY	1	WSHMF	13.0 X 029.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SUNCOAST POLYTECHNICAL HIGH	1	PBYP2	12.0 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SUNCOAST POLYTECHNICAL HIGH	10	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$175.80	\$2.93	\$2.95	\$177.00	\$1.95
SUNCOAST POLYTECHNICAL HIGH	2	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
SUNCOAST POLYTECHNICAL HIGH	5	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$87.90	\$2.93	\$2.95	\$88.50	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
SUNCOAST POLYTECHNICAL HIGH	1	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SUNCOAST POLYTECHNICAL HIGH	1	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SUNCOAST POLYTECHNICAL HIGH	1	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TATUM RIDGE ELEMENTARY	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TATUM RIDGE ELEMENTARY	1	PBYP1	18.0 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TATUM RIDGE ELEMENTARY	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TATUM RIDGE ELEMENTARY	4	PBYP2	10.2 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
TATUM RIDGE ELEMENTARY	4	PBYP2	10.4 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
TATUM RIDGE ELEMENTARY	1	PBYP2	13.4 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TATUM RIDGE ELEMENTARY	4	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
TATUM RIDGE ELEMENTARY	4	PBYP2	16.0 X 021.2 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
TATUM RIDGE ELEMENTARY	2	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TATUM RIDGE ELEMENTARY	8	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
TATUM RIDGE ELEMENTARY	4	PBYP2	16.0 X 025.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
TATUM RIDGE ELEMENTARY	1	PBYP2	17.4 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TATUM RIDGE ELEMENTARY	1	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TATUM RIDGE ELEMENTARY	1	PBYP2	20.0 X 021.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95



THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
TATUM RIDGE ELEMENTARY	2	PBYP2	20.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TATUM RIDGE ELEMENTARY	1	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TATUM RIDGE ELEMENTARY	1	PBYP2	20.0 X 027.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TATUM RIDGE ELEMENTARY	4	PBYP2	21.0 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
TATUM RIDGE ELEMENTARY	16	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$281.28	\$2.93	\$2.95	\$283.20	\$1.95
TATUM RIDGE ELEMENTARY	1	PBYP2	25.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TATUM RIDGE ELEMENTARY	1	WSHMF	11.0 X 028.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TATUM RIDGE ELEMENTARY	1	WSHMF	11.0 X 037.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TATUM RIDGE ELEMENTARY	2	WSHMF	13.0 X 013.0 X 00.4	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TAYLOR RANCH ELEMENTARY	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	1	PBYP1	16.2 X 030.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	2	PBYP1	21.0 X 021.0 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TAYLOR RANCH ELEMENTARY	1	PBYP1	21.6 X 021.6 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	1	PBYP1	24.0 X 024.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	1	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	2	PBYP2	16.0 X 020.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TAYLOR RANCH ELEMENTARY	2	PBYP2	16.0 X 025.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TAYLOR RANCH ELEMENTARY	2	PBYP2	16.0 X 026.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TAYLOR RANCH ELEMENTARY	2	PBYP2	16.0 X 027.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
TAYLOR RANCH ELEMENTARY	1	PBYP2	17.2 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	1	PBYP2	17.4 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	1	PBYP2	18.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	1	PBYP2	18.2 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	1	PBYP2	20.0 X 020.0 X 01.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	1	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	2	PBYP2	20.0 X 022.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TAYLOR RANCH ELEMENTARY	1	PBYP2	20.0 X 025.0 X 01.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	2	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TAYLOR RANCH ELEMENTARY	1	PBYP2	20.0 X 027.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	1	PBYP2	24.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	1	PBYP2	24.6 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	1	PBYP2	25.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	1	WSHMF	09.0 X 017.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TAYLOR RANCH ELEMENTARY	2	WSHMF	12.0 X 012.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
THE LANDINGS	1	PBYP1	06.2 X 012.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	2	PBYP1	10.2 X 020.0 X 00.5	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
THE LANDINGS	2	PBYP1	10.2 X 020.0 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
THE LANDINGS	1	PBYP1	11.6 X 017.6 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	1	PBYP1	12.2 X 012.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
THE LANDINGS	3	PBYP1	16.0 X 025.0 X 00.5	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
THE LANDINGS	3	PBYP1	16.0 X 025.0 X 01.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
THE LANDINGS	1	PBYP1	16.2 X 016.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	1	PBYP1	17.2 X 022.6 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	1	PBYP1	17.4 X 025.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	1	PBYP1	17.6 X 017.6 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	1	PBYP1	18.2 X 019.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	1	PBYP1	18.2 X 019.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	2	PBYP1	20.0 X 020.0 X 00.5	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
THE LANDINGS	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	1	PBYP1	20.0 X 022.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	1	PBYP1	20.0 X 022.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	1	PBYP1	20.0 X 025.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	2	PBYP1	21.6 X 021.6 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
THE LANDINGS	1	PBYP2	14.4 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	6	PBYP2	15.0 X 020.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
THE LANDINGS	2	PBYP2	15.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
THE LANDINGS	2	PBYP2	15.0 X 022.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
THE LANDINGS	1	PBYP2	15.7 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	1	PBYP2	15.7 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
THE LANDINGS	2	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
THE LANDINGS	3	PBYP2	16.0 X 025.0 X 01.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
THE LANDINGS	1	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	1	PBYP2	20.0 X 020.0 X 01.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	3	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
THE LANDINGS	3	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
THE LANDINGS	4	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
THE LANDINGS	1	PBYP2	23.6 X 024.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
THE LANDINGS	4	PLPS1	16.0 X 025.0 X 01.0	\$5.39	\$129.36	\$5.39	\$4.45	\$106.80	\$4.45
THE LANDINGS	1	PLPS4	16.0 X 025.0 X 04.0	\$7.91	\$47.46	\$7.91	\$7.00	\$42.00	\$6.75
THE LANDINGS	1	SLEVE	20.0 X 020.0	\$3.50	\$21.00	\$3.50	\$3.65	\$21.90	\$2.65
THE LANDINGS	1	SLEVE	20.0 X 022.0	\$3.50	\$21.00	\$3.50	\$3.65	\$21.90	\$2.65
THE LANDINGS	2	WSHMF	12.0 X 012.0 X 00.4	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TOLEDO BLADE ELEMENTARY	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TOLEDO BLADE ELEMENTARY	1	PBYP1	16.0 X 030.6 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TOLEDO BLADE ELEMENTARY	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TOLEDO BLADE ELEMENTARY	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TOLEDO BLADE ELEMENTARY	4	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
TOLEDO BLADE ELEMENTARY	2	PBYP2	16.0 X 021.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TOLEDO BLADE ELEMENTARY	1	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
TOLEDO BLADE ELEMENTARY	2	PBYP2	16.0 X 027.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TOLEDO BLADE ELEMENTARY	1	PBYP2	17.4 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TOLEDO BLADE ELEMENTARY	2	PBYP2	20.0 X 020.0 X 01.4	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TOLEDO BLADE ELEMENTARY	2	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TOLEDO BLADE ELEMENTARY	1	PBYP2	20.0 X 021.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TOLEDO BLADE ELEMENTARY	1	PBYP2	20.0 X 025.0 X 01.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TOLEDO BLADE ELEMENTARY	2	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TOLEDO BLADE ELEMENTARY	1	PBYP2	20.0 X 027.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TOLEDO BLADE ELEMENTARY	1	PBYP2	20.2 X 027.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TOLEDO BLADE ELEMENTARY	1	PBYP2	25.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TOLEDO BLADE ELEMENTARY	1	PBYP2	25.0 X 025.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TOLEDO BLADE ELEMENTARY	2	WSHMF	12.0 X 012.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TOLEDO BLADE ELEMENTARY	1	WSHMF	16.0 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRANSPORTATION 17TH ST	2	PBYP1	16.0 X 025.0 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TRANSPORTATION 17TH ST	1	PBYP1	17.0 X 025.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRANSPORTATION /PURCHASING	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRANSPORTATION /PURCHASING	1	PBYP1	18.0 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
TRANSPORTATION /PURCHASING	1	PBYP1	18.6 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRANSPORTATION /PURCHASING	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRANSPORTATION /PURCHASING	1	PBYP1	20.0 X 025.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRANSPORTATION /PURCHASING	1	PBYP1	20.2 X 031.2 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRANSPORTATION /PURCHASING	1	PBYP1	22.2 X 023.4 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRANSPORTATION /PURCHASING	2	PBYP1	22.2 X 025.0 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TRANSPORTATION /PURCHASING	6	PBYP2	15.0 X 020.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
TRANSPORTATION /PURCHASING	2	PBYP2	15.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TRANSPORTATION /PURCHASING	4	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
TRANSPORTATION /PURCHASING	2	PBYP2	16.2 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
TRANSPORTATION /PURCHASING	2	PBYP2	18.4 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TRANSPORTATION /PURCHASING	2	PBYP2	20.0 X 021.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TRANSPORTATION /PURCHASING	4	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
TRANSPORTATION /PURCHASING	1	PBYP2	20.0 X 027.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRANSPORTATION /PURCHASING	3	PLPS1	16.0 X 025.0 X 01.0	\$5.39	\$97.02	\$5.39	\$4.45	\$80.10	\$4.45
TRANSPORTATION /PURCHASING	2	PLPS2	16.0 X 020.0 X 02.0	\$5.33	\$63.96	\$5.33	\$4.45	\$53.40	\$4.45
TRANSPORTATION /PURCHASING	1	PYD-P	09.0 X 039.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRANSPORTATION /PURCHASING	1	PYD-P	09.0 X 039.4 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRANSPORTATION /PURCHASING	1	PYD-P	11.0 X 017.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRANSPORTATION /PURCHASING	1	PYD-P	11.6 X 017.4 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
TRANSPORTATION /PURCHASING	1	WSHMF	10.0 X 046.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRIAD NORTH	1	PBYP1	15.0 X 030.5 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRIAD NORTH	1	PBYP2	15.4 X 016.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRIAD NORTH	2	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TRIAD NORTH	2	PBYP2	16.0 X 021.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TRIAD NORTH	1	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRIAD NORTH	2	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TRIAD NORTH	1	PBYP2	20.0 X 027.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TRIAD NORTH	1	PBYP2	20.0 X 048.0 X 01.4	\$4.35	\$26.10	\$4.35	\$2.95	\$17.70	\$1.95
TRIAD NORTH	1	WSHMF	24.0 X 024.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TUTTLE ELEMENTARY	1	PBYP1	16.0 X 028.1 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TUTTLE ELEMENTARY	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TUTTLE ELEMENTARY	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TUTTLE ELEMENTARY	4	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
TUTTLE ELEMENTARY	2	PBYP2	16.0 X 021.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TUTTLE ELEMENTARY	2	PBYP2	16.0 X 022.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TUTTLE ELEMENTARY	6	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$105.48	\$2.93	\$2.95	\$106.20	\$1.95
TUTTLE ELEMENTARY	2	PBYP2	16.2 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TUTTLE ELEMENTARY	2	PBYP2	16.4 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95



THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
TUTTLE ELEMENTARY	2	PBYP2	17.4 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TUTTLE ELEMENTARY	1	PBYP2	17.6 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TUTTLE ELEMENTARY	1	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TUTTLE ELEMENTARY	1	PBYP2	20.0 X 021.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TUTTLE ELEMENTARY	1	PBYP2	20.0 X 021.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TUTTLE ELEMENTARY	2	PBYP2	20.0 X 021.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TUTTLE ELEMENTARY	2	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
TUTTLE ELEMENTARY	1	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TUTTLE ELEMENTARY	1	PBYP2	20.0 X 027.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TUTTLE ELEMENTARY	1	PBYP2	25.0 X 025.2 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
TUTTLE ELEMENTARY	2	WSHMF	12.0 X 013.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE ELEMENTARY	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE ELEMENTARY	4	PBYP2	12.2 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
VENICE ELEMENTARY	2	PBYP2	13.4 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE ELEMENTARY	8	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
VENICE ELEMENTARY	2	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE ELEMENTARY	4	PBYP2	16.0 X 025.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
VENICE ELEMENTARY	2	PBYP2	17.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE ELEMENTARY	2	PBYP2	17.4 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE ELEMENTARY	10	PBYP2	18.0 X 025.0 X 02.0	\$2.93	\$175.80	\$2.93	\$2.95	\$177.00	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
VENICE ELEMENTARY	1	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE ELEMENTARY	1	PBYP2	20.0 X 021.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE ELEMENTARY	2	PBYP2	20.0 X 023.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE ELEMENTARY	8	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
VENICE ELEMENTARY	4	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
VENICE ELEMENTARY	1	PBYP2	20.0 X 027.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE ELEMENTARY	1	WSHMF	11.0 X 027.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE ELEMENTARY	1	WSHMF	11.0 X 038.0 X 00.2	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	1	PBYP1	06.2 X 019.4 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	5	PBYP1	10.0 X 025.0 X 01.0	\$2.93	\$87.90	\$2.93	\$2.95	\$88.50	\$1.95
VENICE HIGH	1	PBYP1	10.4 X 019.4 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	1	PBYP1	12.4 X 030.4 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	1	PBYP1	14.0 X 025.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	1	PBYP1	15.0 X 030.5 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	1	PBYP1	16.0 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	1	PBYP1	16.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	4	PBYP1	16.0 X 025.0 X 01.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
VENICE HIGH	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	1	PBYP1	17.0 X 025.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	1	PBYP1	20.0 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
VENICE HIGH	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	1	PBYP1	20.0 X 022.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	1	PBYP2	12.0 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	4	PBYP2	15.4 X 016.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
VENICE HIGH	4	PBYP2	15.6 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
VENICE HIGH	1	PBYP2	15.6 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	1	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	4	PBYP2	16.0 X 021.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
VENICE HIGH	2	PBYP2	16.0 X 021.2 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE HIGH	4	PBYP2	16.0 X 021.6 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
VENICE HIGH	4	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
VENICE HIGH	1	PBYP2	16.0 X 028.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	2	PBYP2	17.6 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE HIGH	4	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
VENICE HIGH	2	PBYP2	20.0 X 021.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE HIGH	8	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
VENICE HIGH	12	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$210.96	\$2.93	\$2.95	\$212.40	\$1.95
VENICE HIGH	2	PBYP2	20.0 X 025.2 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE HIGH	2	PBYP2	20.0 X 032.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE HIGH	2	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
VENICE HIGH	1	WSHMF	08.2 X 016.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE HIGH	2	WSHMF	10.0 X 012.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE HIGH	2	WSHMF	10.0 X 012.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE MIDDLE	2	PBYP1	16.0 X 025.0 X 01.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE MIDDLE	1	PBYP1	16.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE MIDDLE	1	PBYP1	17.0 X 025.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE MIDDLE	1	PBYP1	18.0 X 022.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE MIDDLE	1	PBYP1	20.0 X 020.0 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE MIDDLE	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE MIDDLE	1	PBYP1	20.0 X 030.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE MIDDLE	2	PBYP1	21.2 X 022.7 X 00.5	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE MIDDLE	1	PBYP1	21.6 X 046.0 X 00.5	\$4.35	\$26.10	\$4.35	\$2.95	\$17.70	\$1.95
VENICE MIDDLE	2	PBYP2	11.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE MIDDLE	2	PBYP2	12.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE MIDDLE	2	PBYP2	14.1 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE MIDDLE	1	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE MIDDLE	2	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE MIDDLE	2	PBYP2	18.6 X 030.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE MIDDLE	2	PBYP2	20.0 X 022.6 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE MIDDLE	2	PBYP2	20.0 X 024.0 X 01.4	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
VENICE MIDDLE	2	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE MIDDLE	3	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$52.74	\$2.93	\$2.95	\$53.10	\$1.95
VENICE MIDDLE	2	PBYP2	20.0 X 027.6 X 01.4	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE MIDDLE	1	PBYP2	20.0 X 027.6 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE MIDDLE	2	PBYP2	20.0 X 030.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
VENICE MIDDLE	1	PBYP2	21.4 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
VENICE MIDDLE	4	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
VENICE MIDDLE	2	PLPS2	20.0 X 024.0 X 02.0	\$5.76	\$69.12	\$5.76	\$4.45	\$53.40	\$4.45
VENICE MIDDLE	1	PYD-P	09.0 X 039.4 X 00.5	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
WILKINSON ELEMENTARY	4	PBYP2	13.5 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
WILKINSON ELEMENTARY	8	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
WILKINSON ELEMENTARY	4	PBYP2	16.0 X 021.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
WILKINSON ELEMENTARY	4	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
WILKINSON ELEMENTARY	4	PBYP2	16.0 X 023.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
WILKINSON ELEMENTARY	8	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$140.64	\$2.93	\$2.95	\$141.60	\$1.95
WILKINSON ELEMENTARY	4	PBYP2	16.0 X 025.4 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
WILKINSON ELEMENTARY	2	PBYP2	16.0 X 027.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
WILKINSON ELEMENTARY	2	PBYP2	16.0 X 040.5 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
WILKINSON ELEMENTARY	4	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
WILKINSON ELEMENTARY	2	PBYP2	20.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
WILKINSON ELEMENTARY	2	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
WILKINSON ELEMENTARY	1	PBYP2	20.0 X 027.4 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
WILKINSON ELEMENTARY	4	PBYP2	21.0 X 024.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
WILKINSON ELEMENTARY	12	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$210.96	\$2.93	\$2.95	\$212.40	\$1.95
WILKINSON ELEMENTARY	1	WSHMF	11.0 X 030.0 X 00.4	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
WILKINSON ELEMENTARY	2	WSHMF	12.0 X 012.0 X 00.4	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
WILKINSON ELEMENTARY	2	WSHMF	12.4 X 013.0 X 00.5	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
WOODLAND MIDDLE	1	PBYP1	20.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
WOODLAND MIDDLE	4	PBYP2	16.0 X 020.0 X 02.0	\$2.93	\$70.32	\$2.93	\$2.95	\$70.80	\$1.95
WOODLAND MIDDLE	2	PBYP2	16.0 X 021.4 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
WOODLAND MIDDLE	2	PBYP2	16.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
WOODLAND MIDDLE	1	PBYP2	16.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
WOODLAND MIDDLE	1	PBYP2	17.4 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
WOODLAND MIDDLE	2	PBYP2	20.0 X 020.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
WOODLAND MIDDLE	2	PBYP2	20.0 X 024.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
WOODLAND MIDDLE	2	PBYP2	20.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
WOODLAND MIDDLE	1	PBYP2	24.0 X 024.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
WOODLAND MIDDLE	2	PBYP2	24.0 X 025.0 X 02.0	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95
WOODLAND MIDDLE	1	PBYP2	25.0 X 025.0 X 02.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
WOODLAND MIDDLE	2	WSHMF	10.0 X 012.0 X 00.2	\$2.93	\$35.16	\$2.93	\$2.95	\$35.40	\$1.95

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for HVAC Filter Replacement Service - Bid #15-0130

Opened July 15, 2014 at 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include: (1) provision of all filter media and frames (if required) as indicated in the bid specifications, and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for filter replacement service for those facilities specified within and any locations that may be added by the SBSC.				Kleen Air Research			Pure Air		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name  *See Attachment A for physical addresses	Qty	Filter type *See Bid Specifications for Code	Filter size	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>	Price for each filter change including filter	Total for six (6) filter changes (including filter) Per year (Qty x each price x 6 changes)	Price for each filter material only (delivered to each location) <b>REJECT</b>
WOODLAND MIDDLE	1	WSHMF	10.0 X 020.0 X 01.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
WOODLAND MIDDLE	1	WSHMF	12.0 X 033.0	\$2.93	\$17.58	\$2.93	\$2.95	\$17.70	\$1.95
SERVICE TELEPHONE				256-777-7321			727-528-1700		
The Contractor shall provide a single, local telephone number for the SBSC personnel to call to contact the Contractor's supervisory personnel during standard working hours. Contractor personnel must man this phone on a continuous basis during normal working hours.							Extension corrected on Brentwood Elementary		
Notes									
Contact Name				Dewayne Brock			Magen Shaw		
Address				4510 Hellton Drive Florence, AL 35630			204 Eastman Street Greenwood, MS 38930		
Phone				256-767-5122			800-230-2524		
Fax				256-767-5188			662-453-8199		
Federal ID#				630803993			640655737		
Email				dbrock@filterpro.com			m.shaw@pureairco.com		
Recorded by: Simone Pascarella				Witnessed by: Joyce E. Haney					