



THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

MATERIALS MANAGEMENT DEPARTMENT

101 OLD VENICE ROAD

OSPREY, FLORIDA 34229

TELEPHONE (941) 486-2183 • FAX (941) 486-2188

MEMORANDUM

**TO: Members of the School Board
Lori White, Superintendent
Mitsi Corcoran, Chief Financial Officer**

FROM: Pat Black, CPPB, Director of Materials Management

**TITLE: APPROVAL TO AWARD BID #12-0130 FOR HVAC FILTER
REPLACEMENT**

Bids to provide 'HVAC Filter Replacement' were received from four vendors on June 29, 2011. The bid of Kleen Air Research was the best low bid meeting the advertised specifications. This bid is for a period of one year with the option to renew for two additional one-year periods. The funds for these purchases are contained in the transfer from capital budget allocated to the Facilities Services Department.

Requested by:
Jody Dumas

"Failure to file a protest within the time prescribed in Section 120.57(3), Florida Statutes, or failure to post the protest bond or other security required by law within the time allowed for filing a bond shall constitute a waiver of proceedings under Chapter 120, Florida Statutes."

Posting Date: 07-26-11

Fiscal Impact:

Not to exceed
\$225,000

Funding:

Transfer from
Capital

Recommended Motion: That the bid of Kleen Air Research to provide 'HVAC Filter Replacement' in an amount not to exceed \$225,000, be approved for award and purchase.

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
17TH Steet Bus Barn	2	AM POLY 1"	16.0 X 025.0 X 01.0	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$1.58
17TH Steet Bus Barn	1	AM POLY 1"	17.0 X 025.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.68
Alta Vista Elementary	1	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.81
Alta Vista Elementary	9	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$324.00	\$6.00	\$3.15	\$170.10	\$1.90
Alta Vista Elementary	12	AM POLY 1"	16.0 X 039.0 X 01.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$2.47
Alta Vista Elementary	1	AM POLY 1"	16.2 X 030.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.94
Alta Vista Elementary	11	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$396.00	\$6.00	\$3.15	\$207.90	\$2.38
Alta Vista Elementary	2	AM POLY 2"	12.0 X 017.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.06
Alta Vista Elementary	4	AM POLY 2"	12.0 X 024.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.44
Alta Vista Elementary	1	AM POLY 2"	13.6 X 024.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.63
Alta Vista Elementary	1	AM POLY 2"	14.2 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.42
Alta Vista Elementary	1	AM POLY 2"	14.2 X 024.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.70
Alta Vista Elementary	12	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$1.60
Alta Vista Elementary	2	AM POLY 2"	16.0 X 024.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.92
Alta Vista Elementary	12	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$2.00
Alta Vista Elementary	5	AM POLY 2"	17.6 X 024.0 X 02.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$2.11
Alta Vista Elementary	5	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$2.00
Alta Vista Elementary	9	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$324.00	\$6.00	\$3.15	\$170.10	\$2.40
Alta Vista Elementary	2	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.50
Alta Vista Elementary	13	AM POLY 2"	20.0 X 027.6 X 02.0	\$6.00	\$468.00	\$6.00	\$3.15	\$245.70	\$2.76
Alta Vista Elementary	12	AM POLY 2"	20.0 X 028.0 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$2.80
Alta Vista Elementary	4	AM POLY 2"	24.0 X 024.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.88
Alta Vista Elementary	1	AM POLY 1/2"	09.0 X 040.0 X 00.4	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$1.43
Alta Vista Elementary	2	WASH-OUT	10.0 X 010.0 X 00.4	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$7.09
Alta Vista Elementary	2	WASH-OUT	12.0 X 013.0 X 00.4	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$7.09

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
17TH Steet Bus Barn	2	AM POLY 1"	16.0 X 025.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
17TH Steet Bus Barn	1	AM POLY 1"	17.0 X 025.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Alta Vista Elementary	1	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Alta Vista Elementary	9	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Alta Vista Elementary	12	AM POLY 1"	16.0 X 039.0 X 01.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Alta Vista Elementary	1	AM POLY 1"	16.2 X 030.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Alta Vista Elementary	11	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$198.00	\$2.00	\$3.07	\$202.62	\$3.07
Alta Vista Elementary	2	AM POLY 2"	12.0 X 017.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Alta Vista Elementary	4	AM POLY 2"	12.0 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Alta Vista Elementary	1	AM POLY 2"	13.6 X 024.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Alta Vista Elementary	1	AM POLY 2"	14.2 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Alta Vista Elementary	1	AM POLY 2"	14.2 X 024.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Alta Vista Elementary	12	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Alta Vista Elementary	2	AM POLY 2"	16.0 X 024.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Alta Vista Elementary	12	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Alta Vista Elementary	5	AM POLY 2"	17.6 X 024.0 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Alta Vista Elementary	5	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Alta Vista Elementary	9	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Alta Vista Elementary	2	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Alta Vista Elementary	13	AM POLY 2"	20.0 X 027.6 X 02.0	\$3.00	\$234.00	\$2.00	\$3.07	\$239.46	\$3.07
Alta Vista Elementary	12	AM POLY 2"	20.0 X 028.0 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Alta Vista Elementary	4	AM POLY 2"	24.0 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Alta Vista Elementary	1	AM POLY 1/2"	09.0 X 040.0 X 00.4	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Alta Vista Elementary	2	WASH-OUT	10.0 X 010.0 X 00.4	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Alta Vista Elementary	2	WASH-OUT	12.0 X 013.0 X 00.4	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Alta Vista Elementary	4	WASH-OUT	12.0 X 016.0 X 00.4	\$5.00	\$120.00	\$5.00	\$3.15	\$75.60	\$7.09
Ashton Elementary	3	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.81
Ashton Elementary	2	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.90
Ashton Elementary	9	AM POLY 1"	16.2 X 030.2 X 01.0	\$6.00	\$324.00	\$6.00	\$3.15	\$170.10	\$1.94
Ashton Elementary	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.58
Ashton Elementary	11	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$396.00	\$6.00	\$3.15	\$207.90	\$2.38
Ashton Elementary	1	AM POLY 1"	22.0 X 022.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.92
Ashton Elementary	1	AM POLY 2"	13.6 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.70
Ashton Elementary	4	AM POLY 2"	16.0 X 016.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.28
Ashton Elementary	20	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$720.00	\$6.00	\$3.15	\$378.00	\$1.60
Ashton Elementary	2	AM POLY 2"	16.0 X 020.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.63
Ashton Elementary	2	AM POLY 2"	16.0 X 021.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.68
Ashton Elementary	4	AM POLY 2"	16.0 X 021.2 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.70
Ashton Elementary	2	AM POLY 2"	16.0 X 021.3 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.70
Ashton Elementary	1	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.71
Ashton Elementary	4	AM POLY 2"	16.0 X 021.6 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.73
Ashton Elementary	4	AM POLY 2"	16.0 X 023.3 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.86
Ashton Elementary	4	AM POLY 2"	16.0 X 023.6 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.89
Ashton Elementary	2	AM POLY 2"	16.0 X 024.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.95
Ashton Elementary	32	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$1,152.00	\$6.00	\$3.15	\$604.80	\$2.00
Ashton Elementary	2	AM POLY 2"	16.0 X 025.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.03
Ashton Elementary	4	AM POLY 2"	16.0 X 025.6 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.05
Ashton Elementary	2	AM POLY 2"	16.0 X 027.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.19
Ashton Elementary	4	AM POLY 2"	16.0 X 027.6 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.21
Ashton Elementary	4	AM POLY 2"	17.0 X 020.4 X 02.0	\$3.00	\$72.00	\$5.00	\$3.15	\$75.60	\$1.73

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Alta Vista Elementary	4	WASH-OUT	12.0 X 016.0 X 00.4	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Ashton Elementary	3	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Ashton Elementary	2	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Ashton Elementary	9	AM POLY 1"	16.2 X 030.2 X 01.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Ashton Elementary	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Ashton Elementary	11	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$198.00	\$2.00	\$3.07	\$202.62	\$3.07
Ashton Elementary	1	AM POLY 1"	22.0 X 022.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Ashton Elementary	1	AM POLY 2"	13.6 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Ashton Elementary	4	AM POLY 2"	16.0 X 016.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Ashton Elementary	20	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$360.00	\$2.00	\$3.07	\$368.40	\$3.07
Ashton Elementary	2	AM POLY 2"	16.0 X 020.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Ashton Elementary	2	AM POLY 2"	16.0 X 021.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Ashton Elementary	4	AM POLY 2"	16.0 X 021.2 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Ashton Elementary	2	AM POLY 2"	16.0 X 021.3 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Ashton Elementary	1	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Ashton Elementary	4	AM POLY 2"	16.0 X 021.6 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Ashton Elementary	4	AM POLY 2"	16.0 X 023.3 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Ashton Elementary	4	AM POLY 2"	16.0 X 023.6 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Ashton Elementary	2	AM POLY 2"	16.0 X 024.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Ashton Elementary	32	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$576.00	\$2.00	\$3.07	\$589.44	\$3.07
Ashton Elementary	2	AM POLY 2"	16.0 X 025.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Ashton Elementary	4	AM POLY 2"	16.0 X 025.6 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Ashton Elementary	2	AM POLY 2"	16.0 X 027.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Ashton Elementary	4	AM POLY 2"	16.0 X 027.6 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Ashton Elementary	4	AM POLY 2"	17.0 X 020.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Ashton Elementary	1	AM POLY 2"	17.3 X 025.0 X 02.0	\$3.00	\$18.00	\$5.00	\$3.15	\$18.90	\$2.16
Ashton Elementary	4	AM POLY 2"	19.0 X 025.0 X 02.0	\$4.00	\$96.00	\$5.00	\$3.15	\$75.60	\$2.38
Ashton Elementary	4	AM POLY 2"	20.0 X 020.6 X 02.0	\$4.00	\$96.00	\$5.00	\$3.15	\$75.60	\$2.06
Ashton Elementary	1	AM POLY 2"	20.0 X 021.4 X 02.0	\$4.00	\$24.00	\$5.00	\$3.15	\$18.90	\$2.14
Ashton Elementary	28	AM POLY 2"	20.0 X 025.0 X 02.0	\$4.00	\$672.00	\$5.00	\$3.15	\$529.20	\$2.50
Ashton Elementary	1	AM POLY 2"	20.0 X 027.2 X 02.0	\$6.00	\$36.00	\$5.00	\$3.15	\$18.90	\$2.72
Ashton Elementary	2	AM POLY 2"	22.4 X 025.0 X 02.0	\$6.00	\$72.00	\$5.00	\$3.15	\$37.80	\$2.80
Ashton Elementary	1	MERV 8 SC PLEAT	20.0 X 025.0 X 02.0	\$8.00	\$48.00	\$8.00	\$4.54	\$27.24	\$2.54
Ashton Elementary	1	WASH-OUT	08.0 X 014.0 X 00.5	\$3.00	\$18.00	\$5.00	\$3.15	\$18.90	\$7.09
Ashton Elementary	2	WASH-OUT	10.0 X 028.4 X 00.4	\$3.00	\$36.00	\$5.00	\$3.15	\$37.80	\$11.08
Ashton Elementary	1	WASH-OUT	12.0 X 026.0 X 00.5	\$3.00	\$18.00	\$5.00	\$3.15	\$18.90	\$13.07
Atwater Elementary	31	AM POLY 1"	16.0 X 020.0 X 01.0	\$3.00	\$558.00	\$3.00	\$3.15	\$585.90	\$1.27
Atwater Elementary	32	AM POLY 1"	16.0 X 025.0 X 01.0	\$3.00	\$576.00	\$3.00	\$3.15	\$604.80	\$1.58
Atwater Elementary	15	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$270.00	\$3.00	\$3.15	\$283.50	\$1.58
Atwater Elementary	4	AM POLY 1"	20.0 X 024.0 X 01.0	\$3.00	\$72.00	\$3.00	\$3.15	\$75.60	\$1.90
Atwater Elementary	28	AM POLY 1"	20.0 X 025.0 X 01.0	\$3.00	\$504.00	\$3.00	\$3.15	\$529.20	\$1.98
Atwater Elementary	4	AM POLY 1"	24.0 X 024.0 X 01.0	\$3.00	\$72.00	\$3.00	\$3.15	\$75.60	\$2.28
Atwater Elementary	31	MERV 13 HC PLEAT	16.0 X 020.0 X 02.0	\$10.00	\$1,860.00	\$11.00	\$8.73	\$1,623.78	\$6.73
Atwater Elementary	32	MERV 13 HC PLEAT	16.0 X 025.0 X 02.0	\$12.00	\$2,304.00	\$11.00	\$9.69	\$1,860.48	\$7.69
Atwater Elementary	15	MERV 13 HC PLEAT	20.0 X 020.0 X 02.0	\$12.00	\$1,080.00	\$11.00	\$9.69	\$872.10	\$7.69
Atwater Elementary	4	MERV 13 HC PLEAT	20.0 X 024.0 X 02.0	\$14.00	\$336.00	\$14.00	\$11.19	\$268.56	\$9.19
Atwater Elementary	28	MERV 13 HC PLEAT	20.0 X 025.0 X 02.0	\$14.00	\$2,352.00	\$14.00	\$10.85	\$1,822.80	\$8.85
Atwater Elementary	4	MERV 13 HC PLEAT	24.0 X 024.0 X 02.0	\$16.00	\$384.00	\$21.00	\$11.25	\$270.00	\$9.25
Atwater Elementary	7	WASH-OUT	WASH OUT FILTER	\$3.00	\$126.00	\$6.00	\$3.15	\$132.30	
Bay Haven	2	AM POLY 1"	09.4 X 028.6 X 01.0	\$3.00	\$36.00	\$5.00	\$3.15	\$37.80	\$1.06

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Ashton Elementary	1	AM POLY 2"	17.3 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Ashton Elementary	4	AM POLY 2"	19.0 X 025.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Ashton Elementary	4	AM POLY 2"	20.0 X 020.6 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Ashton Elementary	1	AM POLY 2"	20.0 X 021.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Ashton Elementary	28	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$504.00	\$2.00	\$3.07	\$515.76	\$3.07
Ashton Elementary	1	AM POLY 2"	20.0 X 027.2 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Ashton Elementary	2	AM POLY 2"	22.4 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Ashton Elementary	1	MERV 8 SC PLEAT	20.0 X 025.0 X 02.0	\$5.56	\$33.36	\$2.00	\$5.00	\$30.00	\$5.00
Ashton Elementary	1	WASH-OUT	08.0 X 014.0 X 00.5	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Ashton Elementary	2	WASH-OUT	10.0 X 028.4 X 00.4	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Ashton Elementary	1	WASH-OUT	12.0 X 026.0 X 00.5	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Atwater Elementary	31	AM POLY 1"	16.0 X 020.0 X 01.0	\$3.00	\$558.00	\$2.00	\$3.07	\$571.02	\$3.07
Atwater Elementary	32	AM POLY 1"	16.0 X 025.0 X 01.0	\$3.00	\$576.00	\$2.00	\$3.07	\$589.44	\$3.07
Atwater Elementary	15	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$270.00	\$2.00	\$3.07	\$276.30	\$3.07
Atwater Elementary	4	AM POLY 1"	20.0 X 024.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Atwater Elementary	28	AM POLY 1"	20.0 X 025.0 X 01.0	\$3.00	\$504.00	\$2.00	\$3.07	\$515.76	\$3.07
Atwater Elementary	4	AM POLY 1"	24.0 X 024.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Atwater Elementary	31	MERV 13 HC PLEAT	16.0 X 020.0 X 02.0	\$7.27	\$1,352.22	\$2.00	\$10.51	\$1,954.86	\$10.51
Atwater Elementary	32	MERV 13 HC PLEAT	16.0 X 025.0 X 02.0	\$7.99	\$1,534.08	\$2.00	\$12.45	\$2,390.40	\$12.45
Atwater Elementary	15	MERV 13 HC PLEAT	20.0 X 020.0 X 02.0	\$8.04	\$723.60	\$2.00	\$12.00	\$1,080.00	\$12.00
Atwater Elementary	4	MERV 13 HC PLEAT	20.0 X 024.0 X 02.0	\$9.04	\$216.96	\$2.00	\$13.80	\$331.20	\$13.80
Atwater Elementary	28	MERV 13 HC PLEAT	20.0 X 025.0 X 02.0	\$8.96	\$1,505.28	\$2.00	\$13.55	\$2,276.40	\$13.55
Atwater Elementary	4	MERV 13 HC PLEAT	24.0 X 024.0 X 02.0	\$9.74	\$233.76	\$2.00	\$15.11	\$362.64	\$15.11
Atwater Elementary	7	WASH-OUT	WASH OUT FILTER	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Bay Haven	2	AM POLY 1"	09.4 X 028.6 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Bay Haven	2	AM POLY 1"	11.4 X 028.0 X 01.0	\$3.00	\$36.00	\$5.00	\$3.15	\$37.80	\$1.26
Bay Haven	6	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$108.00	\$5.00	\$3.15	\$113.40	\$1.90
Bay Haven	1	AM POLY 1"	17.0 X 021.5 X 01.0	\$3.00	\$18.00	\$4.00	\$3.15	\$18.90	\$1.45
Bay Haven	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$18.00	\$4.00	\$3.15	\$18.90	\$1.58
Bay Haven	6	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.38
Bay Haven	1	AM POLY 1"	20.2 X 021.5 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.72
Bay Haven	4	AM POLY 2"	11.6 X 037.1 X 02.0	\$8.00	\$192.00	\$8.00	\$3.15	\$75.60	\$2.15
Bay Haven	4	AM POLY 2"	11.6 X 039.1 X 02.0	\$8.00	\$192.00	\$8.00	\$3.15	\$75.60	\$2.27
Bay Haven	72	AM POLY 2"	12.0 X 024.0 X 02.0	\$4.00	\$1,728.00	\$4.00	\$3.15	\$1,360.80	\$1.44
Bay Haven	2	AM POLY 2"	14.4 X 025.0 X 02.0	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$1.80
Bay Haven	2	AM POLY 2"	15.6 X 020.0 X 02.0	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$1.56
Bay Haven	2	AM POLY 2"	15.6 X 023.2 X 02.0	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$1.81
Bay Haven	4	AM POLY 2"	16.0 X 020.0 X 02.0	\$5.00	\$120.00	\$5.00	\$3.15	\$75.60	\$1.60
Bay Haven	4	AM POLY 2"	16.0 X 021.0 X 02.0	\$5.00	\$120.00	\$5.00	\$3.15	\$75.60	\$1.68
Bay Haven	4	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.71
Bay Haven	4	AM POLY 2"	16.0 X 023.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.87
Bay Haven	18	AM POLY 2"	16.0 X 025.0 X 02.0	\$5.00	\$540.00	\$5.00	\$3.15	\$340.20	\$2.00
Bay Haven	1	AM POLY 2"	25.0 X 025.0 X 02.0	\$7.00	\$42.00	\$7.00	\$3.15	\$18.90	\$3.13
Bay Haven	1	AM POLY 2"	25.0 X 025.6 X 02.0	\$7.00	\$42.00	\$7.00	\$3.15	\$18.90	\$3.20
Bay Haven	4	MERV 8 SC PLEAT	16.0 X 025.0 X 04.0	\$10.00	\$240.00	\$10.00	\$4.21	\$101.04	\$2.21
Bay Haven	2	MERV 8 SC PLEAT	20.0 X 025.0 X 04.0	\$11.00	\$132.00	\$11.00	\$4.54	\$54.48	\$2.54
Bay Haven	1	AM POLY 1/2"	09.4 X 017.4 X 00.4	\$3.00	\$18.00	\$3.00	\$3.15	\$18.90	\$0.65
Bay Haven	1	WASH-OUT	09.0 X 012.0 X 00.2	\$3.00	\$18.00	\$7.00	\$3.15	\$18.90	\$7.09
Bay Haven	1	WASH-OUT	10.0 X 018.0 X 00.4	\$3.00	\$18.00	\$7.00	\$3.15	\$18.90	\$7.09
Bay Haven	1	WASH-OUT	10.0 X 041.0 X 00.4	\$5.00	\$30.00	\$7.00	\$3.15	\$18.90	\$15.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Bay Haven	2	AM POLY 1"	11.4 X 028.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Bay Haven	6	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Bay Haven	1	AM POLY 1"	17.0 X 021.5 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Bay Haven	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Bay Haven	6	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Bay Haven	1	AM POLY 1"	20.2 X 021.5 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Bay Haven	4	AM POLY 2"	11.6 X 037.1 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Bay Haven	4	AM POLY 2"	11.6 X 039.1 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Bay Haven	72	AM POLY 2"	12.0 X 024.0 X 02.0	\$3.00	\$1,296.00	\$2.00	\$3.07	\$1,326.24	\$3.07
Bay Haven	2	AM POLY 2"	14.4 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Bay Haven	2	AM POLY 2"	15.6 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Bay Haven	2	AM POLY 2"	15.6 X 023.2 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Bay Haven	4	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Bay Haven	4	AM POLY 2"	16.0 X 021.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Bay Haven	4	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Bay Haven	4	AM POLY 2"	16.0 X 023.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Bay Haven	18	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$324.00	\$2.00	\$3.07	\$331.56	\$3.07
Bay Haven	1	AM POLY 2"	25.0 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Bay Haven	1	AM POLY 2"	25.0 X 025.6 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Bay Haven	4	MERV 8 SC PLEAT	16.0 X 025.0 X 04.0	\$7.19	\$172.56	\$2.00	\$6.50	\$156.00	\$6.50
Bay Haven	2	MERV 8 SC PLEAT	20.0 X 025.0 X 04.0	\$7.37	\$88.44	\$2.00	\$6.50	\$78.00	\$6.50
Bay Haven	1	AM POLY 1/2"	09.4 X 017.4 X 00.4	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Bay Haven	1	WASH-OUT	09.0 X 012.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Bay Haven	1	WASH-OUT	10.0 X 018.0 X 00.4	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Bay Haven	1	WASH-OUT	10.0 X 041.0 X 00.4	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Bay Haven	4	WASH-OUT	12.0 X 012.0 X 00.2	\$5.00	\$120.00	\$7.00	\$3.15	\$75.60	\$7.09
Booker High	2	CHARCOAL POLY	20.0 X 020.0 X 01.0	\$8.00	\$96.00	\$8.00	\$6.14	\$73.68	\$4.14
Booker High	3	AM POLY 1"	08.6 X 028.4 X 01.0	\$3.00	\$54.00	\$3.00	\$3.15	\$56.70	\$0.97
Booker High	1	AM POLY 1"	08.6 X 044.4 X 01.0	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$1.51
Booker High	19	AM POLY 1"	09.2 X 080.2 X 01.0	\$18.00	\$2,052.00	\$18.00	\$3.15	\$359.10	\$2.92
Booker High	4	AM POLY 1"	09.4 X 024.0 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$0.89
Booker High	1	AM POLY 1"	09.4 X 032.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.19
Booker High	5	AM POLY 1"	10.0 X 025.0 X 01.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$0.99
Booker High	2	AM POLY 1"	10.0 X 037.0 X 01.0	\$7.00	\$84.00	\$7.00	\$3.15	\$37.80	\$1.46
Booker High	4	AM POLY 1"	10.0 X 061.0 X 01.0	\$12.00	\$288.00	\$12.00	\$3.15	\$75.60	\$2.41
Booker High	2	AM POLY 1"	10.0 X 073.0 X 01.0	\$20.00	\$240.00	\$20.00	\$3.15	\$37.80	\$2.89
Booker High	12	AM POLY 1"	12.2 X 019.0 X 01.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$0.92
Booker High	2	AM POLY 1"	14.2 X 066.0 X 01.0	\$12.00	\$144.00	\$12.00	\$3.15	\$37.80	\$3.71
Booker High	1	AM POLY 1"	14.4 X 025.0 X 01.0	\$12.00	\$72.00	\$12.00	\$3.15	\$18.90	\$1.43
Booker High	4	AM POLY 1"	15.0 X 030.5 X 01.0	\$12.00	\$288.00	\$12.00	\$3.15	\$75.60	\$1.81
Booker High	1	AM POLY 1"	15.6 X 054.0 X 01.0	\$12.00	\$72.00	\$12.00	\$3.15	\$18.90	\$3.33
Booker High	2	AM POLY 1"	15.6 X 066.0 X 01.0	\$12.00	\$144.00	\$12.00	\$3.15	\$37.80	\$4.08
Booker High	1	AM POLY 1"	16.0 X 016.0 X 01.0	\$3.00	\$18.00	\$3.00	\$3.15	\$18.90	\$1.01
Booker High	1	AM POLY 1"	16.0 X 017.0 X 01.0	\$3.00	\$18.00	\$3.00	\$3.15	\$18.90	\$1.08
Booker High	1	AM POLY 1"	16.0 X 020.0 X 01.0	\$3.00	\$18.00	\$3.00	\$3.15	\$18.90	\$1.27
Booker High	1	AM POLY 1"	16.0 X 020.2 X 01.0	\$3.00	\$18.00	\$3.00	\$3.15	\$18.90	\$1.28
Booker High	5	AM POLY 1"	16.0 X 025.0 X 01.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$1.58
Booker High	48	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$1,728.00	\$6.00	\$3.15	\$907.20	\$1.90
Booker High	9	AM POLY 1"	16.2 X 030.2 X 01.0	\$6.00	\$324.00	\$6.00	\$3.15	\$170.10	\$1.94
Booker High	2	AM POLY 1"	16.6 X 020.4 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.34

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Bay Haven	4	WASH-OUT	12.0 X 012.0 X 00.2	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Booker High	2	CHARCOAL POLY	20.0 X 020.0 X 01.0	\$5.55	\$66.60	\$2.00	\$10.30	\$123.60	\$10.30
Booker High	3	AM POLY 1"	08.6 X 028.4 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Booker High	1	AM POLY 1"	08.6 X 044.4 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker High	19	AM POLY 1"	09.2 X 080.2 X 01.0	\$3.00	\$342.00	\$2.00	\$3.07	\$349.98	\$3.07
Booker High	4	AM POLY 1"	09.4 X 024.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Booker High	1	AM POLY 1"	09.4 X 032.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker High	5	AM POLY 1"	10.0 X 025.0 X 01.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Booker High	2	AM POLY 1"	10.0 X 037.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker High	4	AM POLY 1"	10.0 X 061.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Booker High	2	AM POLY 1"	10.0 X 073.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker High	12	AM POLY 1"	12.2 X 019.0 X 01.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Booker High	2	AM POLY 1"	14.2 X 066.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker High	1	AM POLY 1"	14.4 X 025.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker High	4	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Booker High	1	AM POLY 1"	15.6 X 054.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker High	2	AM POLY 1"	15.6 X 066.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker High	1	AM POLY 1"	16.0 X 016.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker High	1	AM POLY 1"	16.0 X 017.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker High	1	AM POLY 1"	16.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker High	1	AM POLY 1"	16.0 X 020.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker High	5	AM POLY 1"	16.0 X 025.0 X 01.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Booker High	48	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$864.00	\$2.00	\$3.07	\$884.16	\$3.07
Booker High	9	AM POLY 1"	16.2 X 030.2 X 01.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Booker High	2	AM POLY 1"	16.6 X 020.4 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Booker High	1	AM POLY 1"	17.0 X 019.6 X 01.0	\$3.00	\$18.00	\$3.00	\$3.15	\$18.90	\$1.32
Booker High	1	AM POLY 1"	18.0 X 020.0 X 01.0	\$3.00	\$18.00	\$3.00	\$3.15	\$18.90	\$1.43
Booker High	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$4.00	\$24.00	\$4.00	\$3.15	\$18.90	\$1.58
Booker High	57	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$2,052.00	\$6.00	\$3.15	\$1,077.30	\$2.38
Booker High	10	AM POLY 1"	20.2 X 044.2 X 01.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$3.53
Booker High	2	AM POLY 2"	09.6 X 020.0 X 02.0	\$4.00	\$48.00	\$4.00	\$3.15	\$37.80	\$0.96
Booker High	2	AM POLY 2"	09.6 X 025.0 X 02.0	\$4.00	\$48.00	\$4.00	\$3.15	\$37.80	\$1.20
Booker High	1	AM POLY 2"	12.0 X 012.2 X 02.0	\$3.00	\$18.00	\$3.00	\$3.15	\$18.90	\$0.73
Booker High	7	AM POLY 2"	12.0 X 024.0 X 02.0	\$4.00	\$168.00	\$4.00	\$3.15	\$132.30	\$1.44
Booker High	1	AM POLY 2"	12.2 X 024.0 X 02.0	\$4.00	\$24.00	\$4.00	\$3.15	\$18.90	\$1.46
Booker High	8	AM POLY 2"	13.4 X 016.0 X 02.0	\$5.00	\$240.00	\$5.00	\$3.15	\$151.20	\$1.07
Booker High	4	AM POLY 2"	14.0 X 025.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.75
Booker High	3	AM POLY 2"	16.0 X 019.6 X 02.0	\$5.00	\$90.00	\$5.00	\$3.15	\$56.70	\$1.57
Booker High	30	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$1,080.00	\$6.00	\$3.15	\$567.00	\$1.60
Booker High	13	AM POLY 2"	16.0 X 020.2 X 02.0	\$6.00	\$468.00	\$6.00	\$3.15	\$245.70	\$1.62
Booker High	6	AM POLY 2"	16.0 X 020.4 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.63
Booker High	2	AM POLY 2"	16.0 X 021.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.73
Booker High	36	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$1,296.00	\$6.00	\$3.15	\$680.40	\$2.00
Booker High	1	AM POLY 2"	16.0 X 026.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.08
Booker High	4	AM POLY 2"	16.0 X 027.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.16
Booker High	2	AM POLY 2"	16.0 X 030.4 X 02.0	\$8.00	\$96.00	\$8.00	\$3.15	\$37.80	\$2.43
Booker High	2	AM POLY 2"	16.2 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.03
Booker High	4	AM POLY 2"	16.6 X 025.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.08
Booker High	13	AM POLY 2"	17.0 X 020.2 X 02.0	\$6.00	\$468.00	\$6.00	\$3.15	\$245.70	\$1.72
Booker High	3	AM POLY 2"	17.6 X 025.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.20

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Booker High	1	AM POLY 1"	17.0 X 019.6 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker High	1	AM POLY 1"	18.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker High	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker High	57	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$1,026.00	\$2.00	\$3.07	\$1,049.94	\$3.07
Booker High	10	AM POLY 1"	20.2 X 044.2 X 01.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Booker High	2	AM POLY 2"	09.6 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker High	2	AM POLY 2"	09.6 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker High	1	AM POLY 2"	12.0 X 012.2 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker High	7	AM POLY 2"	12.0 X 024.0 X 02.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Booker High	1	AM POLY 2"	12.2 X 024.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker High	8	AM POLY 2"	13.4 X 016.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Booker High	4	AM POLY 2"	14.0 X 025.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Booker High	3	AM POLY 2"	16.0 X 019.6 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Booker High	30	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$540.00	\$2.00	\$3.07	\$552.60	\$3.07
Booker High	13	AM POLY 2"	16.0 X 020.2 X 02.0	\$3.00	\$234.00	\$2.00	\$3.07	\$239.46	\$3.07
Booker High	6	AM POLY 2"	16.0 X 020.4 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Booker High	2	AM POLY 2"	16.0 X 021.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker High	36	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$648.00	\$2.00	\$3.07	\$663.12	\$3.07
Booker High	1	AM POLY 2"	16.0 X 026.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker High	4	AM POLY 2"	16.0 X 027.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Booker High	2	AM POLY 2"	16.0 X 030.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker High	2	AM POLY 2"	16.2 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker High	4	AM POLY 2"	16.6 X 025.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Booker High	13	AM POLY 2"	17.0 X 020.2 X 02.0	\$3.00	\$234.00	\$2.00	\$3.07	\$239.46	\$3.07
Booker High	3	AM POLY 2"	17.6 X 025.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Booker High	12	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$2.00
Booker High	2	AM POLY 2"	20.0 X 021.6 X 02.0	\$7.00	\$84.00	\$7.00	\$3.15	\$37.80	\$2.16
Booker High	2	AM POLY 2"	20.0 X 022.2 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.22
Booker High	10	AM POLY 2"	20.0 X 023.6 X 02.0	\$8.00	\$480.00	\$8.00	\$3.15	\$189.00	\$2.36
Booker High	72	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$2,592.00	\$6.00	\$3.15	\$1,360.80	\$2.50
Booker High	1	AM POLY 2"	20.0 X 026.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.60
Booker High	5	AM POLY 2"	20.0 X 027.6 X 02.0	\$7.00	\$210.00	\$7.00	\$3.15	\$94.50	\$2.76
Booker High	2	AM POLY 2"	20.4 X 023.6 X 02.0	\$7.00	\$84.00	\$7.00	\$3.15	\$37.80	\$2.41
Booker High	2	AM POLY 2"	23.0 X 025.0 X 02.0	\$8.00	\$96.00	\$8.00	\$3.15	\$37.80	\$2.88
Booker High	4	AM POLY 2"	24.0 X 024.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.88
Booker High	2	AM POLY 1/2"	09.0 X 020.0 X 00.2	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$0.71
Booker High	1	AM POLY 1/2"	12.0 X 021.4 X 00.4	\$3.00	\$18.00	\$3.00	\$3.15	\$18.90	\$1.02
Booker High	1	AM SLEVE	12.0 X 025.0	\$7.00	\$42.00	\$7.00	\$3.15	\$18.90	\$1.67
Booker High	12	WASH-OUT	09.0 X 012.0 X 00.4	\$3.00	\$216.00	\$1.00	\$3.15	\$226.80	\$7.09
Booker High	2	WASH-OUT	12.0 X 012.0 X 00.4	\$3.00	\$36.00	\$1.00	\$3.15	\$37.80	\$7.09
Booker High	1	WASH-OUT	16.0 X 020.0 X 00.4	\$3.00	\$18.00	\$1.00	\$3.15	\$18.90	\$13.07
Booker Middle	1	AM POLY 1"	14.2 X 015.2 X 01.0	\$4.00	\$24.00	\$4.00	\$3.15	\$18.90	\$0.85
Booker Middle	2	AM POLY 1"	20.0 X 020.0 X 01.0	\$4.00	\$48.00	\$4.00	\$3.15	\$37.80	\$1.58
Booker Middle	28	AM POLY 2"	12.4 X 016.2 X 02.0	\$5.00	\$840.00	\$5.00	\$3.15	\$529.20	\$1.00
Booker Middle	28	AM POLY 2"	14.0 X 025.0 X 02.0	\$5.00	\$840.00	\$5.00	\$3.15	\$529.20	\$1.75
Booker Middle	1	AM POLY 2"	16.0 X 018.4 X 02.0	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$1.47
Booker Middle	66	AM POLY 2"	16.0 X 020.0 X 02.0	\$5.00	\$1,980.00	\$5.00	\$3.15	\$1,247.40	\$1.60
Booker Middle	4	AM POLY 2"	16.0 X 023.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.84
Booker Middle	8	AM POLY 2"	16.0 X 024.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.92
Booker Middle	18	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$648.00	\$6.00	\$3.15	\$340.20	\$2.00

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Booker High	12	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Booker High	2	AM POLY 2"	20.0 X 021.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker High	2	AM POLY 2"	20.0 X 022.2 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker High	10	AM POLY 2"	20.0 X 023.6 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Booker High	72	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$1,296.00	\$2.00	\$3.07	\$1,326.24	\$3.07
Booker High	1	AM POLY 2"	20.0 X 026.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker High	5	AM POLY 2"	20.0 X 027.6 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Booker High	2	AM POLY 2"	20.4 X 023.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker High	2	AM POLY 2"	23.0 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker High	4	AM POLY 2"	24.0 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Booker High	2	AM POLY 1/2"	09.0 X 020.0 X 00.2	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker High	1	AM POLY 1/2"	12.0 X 021.4 X 00.4	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker High	1	AM SLEVE	12.0 X 025.0	\$3.75	\$22.50	\$2.00	\$4.35	\$26.10	\$4.35
Booker High	12	WASH-OUT	09.0 X 012.0 X 00.4	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Booker High	2	WASH-OUT	12.0 X 012.0 X 00.4	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker High	1	WASH-OUT	16.0 X 020.0 X 00.4	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker Middle	1	AM POLY 1"	14.2 X 015.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker Middle	2	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker Middle	28	AM POLY 2"	12.4 X 016.2 X 02.0	\$3.00	\$504.00	\$2.00	\$3.07	\$515.76	\$3.07
Booker Middle	28	AM POLY 2"	14.0 X 025.0 X 02.0	\$3.00	\$504.00	\$2.00	\$3.07	\$515.76	\$3.07
Booker Middle	1	AM POLY 2"	16.0 X 018.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker Middle	66	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$1,188.00	\$2.00	\$3.07	\$1,215.72	\$3.07
Booker Middle	4	AM POLY 2"	16.0 X 023.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Booker Middle	8	AM POLY 2"	16.0 X 024.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Booker Middle	18	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$324.00	\$2.00	\$3.07	\$331.56	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Booker Middle	12	AM POLY 2"	16.0 X 027.4 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$2.19
Booker Middle	1	AM POLY 2"	18.4 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.84
Booker Middle	23	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$828.00	\$6.00	\$3.15	\$434.70	\$2.00
Booker Middle	11	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$396.00	\$6.00	\$3.15	\$207.90	\$2.40
Booker Middle	22	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$792.00	\$6.00	\$3.15	\$415.80	\$2.50
Booker Middle	2	AM POLY 2"	20.0 X 027.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.74
Booker Middle	2	AM POLY 2"	21.0 X 021.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.21
Booker Middle	2	AM POLY 2"	21.4 X 042.0 X 02.0	\$8.00	\$96.00	\$8.00	\$3.15	\$37.80	\$4.49
Booker Middle	2	AM POLY 2"	22.4 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.80
Booker Middle	2	MERV 8 SC PLEAT	24.0 X 024.0 X 01.0	\$6.00	\$72.00	\$6.00	\$5.57	\$66.84	\$3.57
Booker Middle	2	CHARCOAL PLEAT	24.0 X 024.0 X 01.0	\$21.00	\$252.00	\$21.00	\$6.99	\$83.88	\$4.99
Booker Middle	2	AM SLEVE	14.2 X 020.2	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.41
Booker Middle	1	AM SLEVE	14.2 X 024.2	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.41
Booker Middle	2	WASH-OUT	12.0 X 013.0 X 00.2	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$7.09
Booker Middle	2	WASH-OUT	12.4 X 016.4 X 00.2	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$11.08
Brentwood Elementary	1	AM POLY 1"	16.0 X 025.0 X 01.0	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$1.58
Brentwood Elementary	3	AM POLY 2"	09.2 X 020.0 X 02.0	\$5.00	\$90.00	\$5.00	\$3.15	\$56.70	\$0.92
Brentwood Elementary	1	AM POLY 2"	09.2 X 020.5 X 02.0	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$0.94
Brentwood Elementary	28	AM POLY 2"	12.4 X 017.2 X 02.0	\$6.00	\$1,008.00	\$6.00	\$3.15	\$529.20	\$1.07
Brentwood Elementary	1	AM POLY 2"	13.6 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.70
Brentwood Elementary	28	AM POLY 2"	14.2 X 025.2 X 02.0	\$6.00	\$1,008.00	\$6.00	\$3.15	\$529.20	\$1.79
Brentwood Elementary	14	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$504.00	\$6.00	\$3.15	\$264.60	\$1.60
Brentwood Elementary	5	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$2.00
Brentwood Elementary	2	AM POLY 2"	16.0 X 025.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.05
Brentwood Elementary	4	AM POLY 2"	18.2 X 025.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.28

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Booker Middle	12	AM POLY 2"	16.0 X 027.4 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Booker Middle	1	AM POLY 2"	18.4 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Booker Middle	23	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$414.00	\$2.00	\$3.07	\$423.66	\$3.07
Booker Middle	11	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$198.00	\$2.00	\$3.07	\$202.62	\$3.07
Booker Middle	22	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$396.00	\$2.00	\$3.07	\$405.24	\$3.07
Booker Middle	2	AM POLY 2"	20.0 X 027.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker Middle	2	AM POLY 2"	21.0 X 021.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker Middle	2	AM POLY 2"	21.4 X 042.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker Middle	2	AM POLY 2"	22.4 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker Middle	2	MERV 8 SC PLEAT	24.0 X 024.0 X 01.0	\$5.49	\$65.88	\$2.00	\$5.00	\$60.00	\$5.00
Booker Middle	2	CHARCOAL PLEAT	24.0 X 024.0 X 01.0	\$13.75	\$165.00	\$2.00	\$13.15	\$157.80	\$13.15
Booker Middle	2	AM SLEVE	14.2 X 020.2	\$3.75	\$45.00	\$2.00	\$4.50	\$54.00	\$4.50
Booker Middle	1	AM SLEVE	14.2 X 024.2	\$3.75	\$22.50	\$2.00	\$5.00	\$30.00	\$5.00
Booker Middle	2	WASH-OUT	12.0 X 013.0 X 00.2	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Booker Middle	2	WASH-OUT	12.4 X 016.4 X 00.2	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Brentwood Elementary	1	AM POLY 1"	16.0 X 025.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Brentwood Elementary	3	AM POLY 2"	09.2 X 020.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Brentwood Elementary	1	AM POLY 2"	09.2 X 020.5 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Brentwood Elementary	28	AM POLY 2"	12.4 X 017.2 X 02.0	\$3.00	\$504.00	\$2.00	\$3.07	\$515.76	\$3.07
Brentwood Elementary	1	AM POLY 2"	13.6 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Brentwood Elementary	28	AM POLY 2"	14.2 X 025.2 X 02.0	\$3.00	\$504.00	\$2.00	\$3.07	\$515.76	\$3.07
Brentwood Elementary	14	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07
Brentwood Elementary	5	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Brentwood Elementary	2	AM POLY 2"	16.0 X 025.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Brentwood Elementary	4	AM POLY 2"	18.2 X 025.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Brentwood Elementary	37	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$1,332.00	\$6.00	\$3.15	\$699.30	\$2.00
Brentwood Elementary	1	AM POLY 2"	20.0 X 020.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.04
Brentwood Elementary	2	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.40
Brentwood Elementary	20	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$720.00	\$6.00	\$3.15	\$378.00	\$2.50
Brentwood Elementary	2	AM POLY 2"	20.0 X 025.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.56
Brentwood Elementary	4	AM POLY 2"	20.0 X 028.2 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.82
Brentwood Elementary	2	AM POLY 2"	20.5 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.56
Brentwood Elementary	4	MERV 8 SC PLEAT	16.0 X 025.0 X 04.0	\$11.00	\$264.00	\$11.00	\$7.33	\$175.92	\$5.33
Brentwood Elementary	12	MERV 8 SC PLEAT	20.0 X 025.0 X 04.0	\$11.00	\$792.00	\$11.00	\$8.24	\$593.28	\$6.24
Brentwood Elementary	2	AM POLY 1/2"	10.4 X 019.0 X 00.2	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$0.78
Brentwood Elementary	1	WASH-OUT	08.0 X 012.0 X 00.2	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$7.09
Brentwood Elementary	1	WASH-OUT	10.4 X 017.2 X 00.2	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$11.84
Brentwood Elementary	1	WASH-OUT	11.4 X 018.0 X 00.2	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$11.08
Brentwood Elementary	2	WASH-OUT	12.0 X 012.0 X 00.2	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$7.09
Brentwood Elementary	4	WASH-OUT	12.0 X 012.0 X 00.4	\$5.00	\$120.00	\$5.00	\$3.15	\$75.60	\$7.09
Brentwood Elementary	6	WASH-OUT	12.4 X 013.6 X 00.4	\$5.00	\$180.00	\$5.00	\$3.15	\$113.40	\$7.09
Brookside Middle	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.58
Brookside Middle	4	AM POLY 2"	12.2 X 020.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.22
Brookside Middle	12	AM POLY 2"	12.4 X 017.2 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$1.07
Brookside Middle	4	AM POLY 2"	13.6 X 025.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.70
Brookside Middle	4	AM POLY 2"	14.2 X 020.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.42
Brookside Middle	2	AM POLY 2"	14.2 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.78
Brookside Middle	12	AM POLY 2"	14.2 X 025.2 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$1.79
Brookside Middle	36	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$1,296.00	\$6.00	\$3.15	\$680.40	\$1.60
Brookside Middle	10	AM POLY 2"	16.0 X 021.2 X 02.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$1.70

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Brentwood Elementary	37	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$666.00	\$2.00	\$3.07	\$681.54	\$3.07
Brentwood Elementary	1	AM POLY 2"	20.0 X 020.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Brentwood Elementary	2	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Brentwood Elementary	20	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$360.00	\$2.00	\$3.07	\$368.40	\$3.07
Brentwood Elementary	2	AM POLY 2"	20.0 X 025.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Brentwood Elementary	4	AM POLY 2"	20.0 X 028.2 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Brentwood Elementary	2	AM POLY 2"	20.5 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Brentwood Elementary	4	MERV 8 SC PLEAT	16.0 X 025.0 X 04.0	\$7.19	\$172.56	\$2.00	\$6.50	\$156.00	\$6.50
Brentwood Elementary	12	MERV 8 SC PLEAT	20.0 X 025.0 X 04.0	\$7.37	\$530.64	\$2.00	\$6.50	\$468.00	\$6.50
Brentwood Elementary	2	AM POLY 1/2"	10.4 X 019.0 X 00.2	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Brentwood Elementary	1	WASH-OUT	08.0 X 012.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Brentwood Elementary	1	WASH-OUT	10.4 X 017.2 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Brentwood Elementary	1	WASH-OUT	11.4 X 018.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Brentwood Elementary	2	WASH-OUT	12.0 X 012.0 X 00.2	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Brentwood Elementary	4	WASH-OUT	12.0 X 012.0 X 00.4	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Brentwood Elementary	6	WASH-OUT	12.4 X 013.6 X 00.4	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Brookside Middle	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Brookside Middle	4	AM POLY 2"	12.2 X 020.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Brookside Middle	12	AM POLY 2"	12.4 X 017.2 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Brookside Middle	4	AM POLY 2"	13.6 X 025.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Brookside Middle	4	AM POLY 2"	14.2 X 020.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Brookside Middle	2	AM POLY 2"	14.2 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Brookside Middle	12	AM POLY 2"	14.2 X 025.2 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Brookside Middle	36	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$648.00	\$2.00	\$3.07	\$663.12	\$3.07
Brookside Middle	10	AM POLY 2"	16.0 X 021.2 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Brookside Middle	10	AM POLY 2"	16.0 X 021.6 X 02.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$1.73
Brookside Middle	8	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.00
Brookside Middle	3	AM POLY 2"	16.0 X 025.6 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.05
Brookside Middle	2	AM POLY 2"	16.0 X 027.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.21
Brookside Middle	4	AM POLY 2"	17.6 X 020.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.76
Brookside Middle	5	AM POLY 2"	17.6 X 025.0 X 02.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$2.20
Brookside Middle	2	AM POLY 2"	19.4 X 020.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.94
Brookside Middle	1	AM POLY 2"	19.4 X 025.6 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.48
Brookside Middle	36	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$1,296.00	\$6.00	\$3.15	\$680.40	\$2.00
Brookside Middle	18	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$648.00	\$6.00	\$3.15	\$340.20	\$2.50
Brookside Middle	6	AM POLY 2"	20.0 X 025.6 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.56
Brookside Middle	2	AM POLY 2"	20.0 X 027.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.76
Brookside Middle	6	AM POLY 2"	25.0 X 025.0 X 02.0	\$8.00	\$288.00	\$8.00	\$3.15	\$113.40	\$3.13
Brookside Middle	5	WASH-OUT	08.0 X 024.0 X 00.4	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$7.09
Brookside Middle	4	WASH-OUT	12.0 X 012.0 X 00.2	\$5.00	\$120.00	\$5.00	\$3.15	\$75.60	\$7.09
Brookside Middle	6	WASH-OUT	12.0 X 012.0 X 00.4	\$8.00	\$288.00	\$8.00	\$3.15	\$113.40	\$7.09
Cranberry Elementary	15	AM POLY 1"	16.2 X 030.2 X 01.0	\$5.00	\$450.00	\$5.00	\$3.15	\$283.50	\$1.94
Cranberry Elementary	15	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$540.00	\$6.00	\$3.15	\$283.50	\$2.38
Cranberry Elementary	4	AM POLY 2"	13.4 X 024.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.61
Cranberry Elementary	8	AM POLY 2"	14.0 X 020.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.40
Cranberry Elementary	12	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$1.60
Cranberry Elementary	10	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$1.71
Cranberry Elementary	4	AM POLY 2"	16.0 X 023.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.87
Cranberry Elementary	24	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$864.00	\$6.00	\$3.15	\$453.60	\$2.00
Cranberry Elementary	4	AM POLY 2"	16.0 X 025.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.03

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Brookside Middle	10	AM POLY 2"	16.0 X 021.6 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Brookside Middle	8	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Brookside Middle	3	AM POLY 2"	16.0 X 025.6 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Brookside Middle	2	AM POLY 2"	16.0 X 027.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Brookside Middle	4	AM POLY 2"	17.6 X 020.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Brookside Middle	5	AM POLY 2"	17.6 X 025.0 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Brookside Middle	2	AM POLY 2"	19.4 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Brookside Middle	1	AM POLY 2"	19.4 X 025.6 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Brookside Middle	36	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$648.00	\$2.00	\$3.07	\$663.12	\$3.07
Brookside Middle	18	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$324.00	\$2.00	\$3.07	\$331.56	\$3.07
Brookside Middle	6	AM POLY 2"	20.0 X 025.6 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Brookside Middle	2	AM POLY 2"	20.0 X 027.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Brookside Middle	6	AM POLY 2"	25.0 X 025.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Brookside Middle	5	WASH-OUT	08.0 X 024.0 X 00.4	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Brookside Middle	4	WASH-OUT	12.0 X 012.0 X 00.2	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Brookside Middle	6	WASH-OUT	12.0 X 012.0 X 00.4	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Cranberry Elementary	15	AM POLY 1"	16.2 X 030.2 X 01.0	\$3.00	\$270.00	\$2.00	\$3.07	\$276.30	\$3.07
Cranberry Elementary	15	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$270.00	\$2.00	\$3.07	\$276.30	\$3.07
Cranberry Elementary	4	AM POLY 2"	13.4 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Cranberry Elementary	8	AM POLY 2"	14.0 X 020.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Cranberry Elementary	12	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Cranberry Elementary	10	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Cranberry Elementary	4	AM POLY 2"	16.0 X 023.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Cranberry Elementary	24	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$432.00	\$2.00	\$3.07	\$442.08	\$3.07
Cranberry Elementary	4	AM POLY 2"	16.0 X 025.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Cranberry Elementary	2	AM POLY 2"	16.0 X 027.4 X 02.0	\$7.00	\$84.00	\$6.00	\$3.15	\$37.80	\$2.19
Cranberry Elementary	2	AM POLY 2"	17.4 X 020.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.74
Cranberry Elementary	18	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$648.00	\$6.00	\$3.15	\$340.20	\$2.00
Cranberry Elementary	4	AM POLY 2"	20.0 X 021.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.14
Cranberry Elementary	16	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$2.40
Cranberry Elementary	46	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$1,656.00	\$6.00	\$3.15	\$869.40	\$2.50
Cranberry Elementary	8	AM POLY 2"	20.0 X 025.4 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.54
Cranberry Elementary	5	WASH-OUT	11.0 X 028.0 X 00.2	\$6.00	\$180.00	\$15.00	\$3.15	\$94.50	\$13.07
Cranberry Elementary	1	WASH-OUT	11.0 X 038.0 X 00.2	\$6.00	\$36.00	\$15.00	\$3.15	\$18.90	\$15.07
Cranberry Elementary	2	WASH-OUT	12.0 X 012.0 X 00.2	\$6.00	\$72.00	\$15.00	\$3.15	\$37.80	\$7.09
Emma Booker Elementary	1	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.81
Emma Booker Elementary	1	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.90
Emma Booker Elementary	7	AM POLY 1"	16.2 X 030.2 X 01.0	\$6.00	\$252.00	\$8.00	\$3.15	\$132.30	\$1.94
Emma Booker Elementary	9	AM POLY 1"	20.0 X 030.0 X 01.0	\$8.00	\$432.00	\$8.00	\$3.15	\$170.10	\$2.38
Emma Booker Elementary	2	AM POLY 2"	07.4 X 020.0 X 02.0	\$7.00	\$84.00	\$7.00	\$3.15	\$37.80	\$0.74
Emma Booker Elementary	9	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$324.00	\$6.00	\$3.15	\$170.10	\$1.60
Emma Booker Elementary	1	AM POLY 2"	16.0 X 020.2 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.62
Emma Booker Elementary	2	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.71
Emma Booker Elementary	3	AM POLY 2"	16.0 X 021.6 X 02.0	\$8.00	\$144.00	\$8.00	\$3.15	\$56.70	\$1.73
Emma Booker Elementary	2	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.00
Emma Booker Elementary	24	AM POLY 2"	16.0 X 027.6 X 02.0	\$8.00	\$1,152.00	\$8.00	\$3.15	\$453.60	\$2.21
Emma Booker Elementary	1	AM POLY 2"	16.2 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.62
Emma Booker Elementary	9	AM POLY 2"	17.6 X 025.0 X 02.0	\$8.00	\$432.00	\$8.00	\$3.15	\$170.10	\$2.20
Emma Booker Elementary	1	AM POLY 2"	20.0 X 021.6 X 02.0	\$7.00	\$42.00	\$7.00	\$3.15	\$18.90	\$2.16
Emma Booker Elementary	2	AM POLY 2"	20.0 X 023.4 X 02.0	\$8.00	\$96.00	\$8.00	\$3.15	\$37.80	\$2.34

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Cranberry Elementary	2	AM POLY 2"	16.0 X 027.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Cranberry Elementary	2	AM POLY 2"	17.4 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Cranberry Elementary	18	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$324.00	\$2.00	\$3.07	\$331.56	\$3.07
Cranberry Elementary	4	AM POLY 2"	20.0 X 021.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Cranberry Elementary	16	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07
Cranberry Elementary	46	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$828.00	\$2.00	\$3.07	\$847.32	\$3.07
Cranberry Elementary	8	AM POLY 2"	20.0 X 025.4 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Cranberry Elementary	5	WASH-OUT	11.0 X 028.0 X 00.2	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Cranberry Elementary	1	WASH-OUT	11.0 X 038.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Cranberry Elementary	2	WASH-OUT	12.0 X 012.0 X 00.2	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Emma Booker Elementary	1	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Emma Booker Elementary	1	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Emma Booker Elementary	7	AM POLY 1"	16.2 X 030.2 X 01.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Emma Booker Elementary	9	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Emma Booker Elementary	2	AM POLY 2"	07.4 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Emma Booker Elementary	9	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Emma Booker Elementary	1	AM POLY 2"	16.0 X 020.2 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Emma Booker Elementary	2	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Emma Booker Elementary	3	AM POLY 2"	16.0 X 021.6 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Emma Booker Elementary	2	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Emma Booker Elementary	24	AM POLY 2"	16.0 X 027.6 X 02.0	\$3.00	\$432.00	\$2.00	\$3.07	\$442.08	\$3.07
Emma Booker Elementary	1	AM POLY 2"	16.2 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Emma Booker Elementary	9	AM POLY 2"	17.6 X 025.0 X 02.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Emma Booker Elementary	1	AM POLY 2"	20.0 X 021.6 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Emma Booker Elementary	2	AM POLY 2"	20.0 X 023.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Emma Booker Elementary	31	AM POLY 2"	20.0 X 025.0 X 02.0	\$7.00	\$1,302.00	\$7.00	\$3.15	\$585.90	\$2.50
Emma Booker Elementary	2	AM POLY 2"	20.0 X 027.6 X 02.0	\$8.00	\$96.00	\$8.00	\$3.15	\$37.80	\$2.76
Emma Booker Elementary	1	AM POLY 2"	25.0 X 025.0 X 02.0	\$8.00	\$48.00	\$8.00	\$3.15	\$18.90	\$3.13
Emma Booker Elementary	3	AM POLY 2"	25.0 X 025.2 X 02.0	\$8.00	\$144.00	\$8.00	\$3.15	\$56.70	\$3.15
Emma Booker Elementary	1	WASH-OUT	10.0 X 040.0 X 00.5	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$15.07
Emma Booker Elementary	2	WASH-OUT	10.0 X 040.0 X 02.0	\$5.00	\$60.00	\$10.00	\$3.15	\$37.80	\$15.07
Emma Booker Elementary	1	WASH-OUT	10.0 X 047.4 X 00.2	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$15.00
Englewood Elementary	1	AM POLY 1"	08.0 X 012.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.38
Englewood Elementary	1	AM POLY 1"	11.2 X 018.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.81
Englewood Elementary	4	AM POLY 1"	12.0 X 030.0 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.43
Englewood Elementary	3	AM POLY 1"	12.0 X 036.0 X 01.0	\$7.00	\$126.00	\$7.00	\$3.15	\$56.70	\$1.71
Englewood Elementary	1	AM POLY 1"	12.2 X 018.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.88
Englewood Elementary	10	AM POLY 1"	16.0 X 030.0 X 01.0	\$8.00	\$480.00	\$8.00	\$3.15	\$189.00	\$1.90
Englewood Elementary	3	AM POLY 1"	16.2 X 030.2 X 01.0	\$8.00	\$144.00	\$8.00	\$3.15	\$56.70	\$1.94
Englewood Elementary	3	AM POLY 1"	20.0 X 030.0 X 01.0	\$8.00	\$144.00	\$8.00	\$3.15	\$56.70	\$2.38
Englewood Elementary	8	AM POLY 2"	16.0 X 020.0 X 02.0	\$7.00	\$336.00	\$7.00	\$3.15	\$151.20	\$1.60
Englewood Elementary	1	AM POLY 2"	16.0 X 021.4 X 02.0	\$7.00	\$42.00	\$7.00	\$3.15	\$18.90	\$1.71
Englewood Elementary	4	AM POLY 2"	16.0 X 023.4 X 02.0	\$7.00	\$168.00	\$7.00	\$3.15	\$75.60	\$1.87
Englewood Elementary	10	AM POLY 2"	16.0 X 025.0 X 02.0	\$7.00	\$420.00	\$7.00	\$3.15	\$189.00	\$2.00
Englewood Elementary	4	AM POLY 2"	16.0 X 025.4 X 02.0	\$7.00	\$168.00	\$7.00	\$3.15	\$75.60	\$2.03
Englewood Elementary	2	AM POLY 2"	16.0 X 027.4 X 02.0	\$7.00	\$84.00	\$7.00	\$3.15	\$37.80	\$2.19
Englewood Elementary	5	AM POLY 2"	17.6 X 025.0 X 02.0	\$7.00	\$210.00	\$7.00	\$3.15	\$94.50	\$2.20
Englewood Elementary	6	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.00
Englewood Elementary	1	AM POLY 2"	20.0 X 021.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.10
Englewood Elementary	1	AM POLY 2"	20.0 X 021.2 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.12

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Emma Booker Elementary	31	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$558.00	\$2.00	\$3.07	\$571.02	\$3.07
Emma Booker Elementary	2	AM POLY 2"	20.0 X 027.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Emma Booker Elementary	1	AM POLY 2"	25.0 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Emma Booker Elementary	3	AM POLY 2"	25.0 X 025.2 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Emma Booker Elementary	1	WASH-OUT	10.0 X 040.0 X 00.5	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Emma Booker Elementary	2	WASH-OUT	10.0 X 040.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Emma Booker Elementary	1	WASH-OUT	10.0 X 047.4 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Englewood Elementary	1	AM POLY 1"	08.0 X 012.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Englewood Elementary	1	AM POLY 1"	11.2 X 018.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Englewood Elementary	4	AM POLY 1"	12.0 X 030.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Englewood Elementary	3	AM POLY 1"	12.0 X 036.0 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Englewood Elementary	1	AM POLY 1"	12.2 X 018.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Englewood Elementary	10	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Englewood Elementary	3	AM POLY 1"	16.2 X 030.2 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Englewood Elementary	3	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Englewood Elementary	8	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Englewood Elementary	1	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Englewood Elementary	4	AM POLY 2"	16.0 X 023.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Englewood Elementary	10	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Englewood Elementary	4	AM POLY 2"	16.0 X 025.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Englewood Elementary	2	AM POLY 2"	16.0 X 027.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Englewood Elementary	5	AM POLY 2"	17.6 X 025.0 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Englewood Elementary	6	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Englewood Elementary	1	AM POLY 2"	20.0 X 021.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Englewood Elementary	1	AM POLY 2"	20.0 X 021.2 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Englewood Elementary	1	AM POLY 2"	20.0 X 021.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.14
Englewood Elementary	4	AM POLY 2"	20.0 X 021.6 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.16
Englewood Elementary	17	AM POLY 2"	20.0 X 025.0 X 02.0	\$7.00	\$714.00	\$7.00	\$3.15	\$321.30	\$2.50
Englewood Elementary	2	AM POLY 2"	20.0 X 027.6 X 02.0	\$7.00	\$84.00	\$7.00	\$3.15	\$37.80	\$2.76
Englewood Elementary	1	AM POLY 2"	25.0 X 025.0 X 02.0	\$7.00	\$42.00	\$7.00	\$3.15	\$18.90	\$3.13
Englewood Elementary	6	WASH-OUT	12.0 X 012.0 X 00.2	\$5.00	\$180.00	\$10.00	\$3.15	\$113.40	\$7.09
Englewood Elementary	1	WASH-OUT	16.0 X 016.0 X 00.2	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$11.08
Englewood Elementary	1	WASH-OUT	20.0 X 020.0 X 01.0	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$15.07
Facilities Services	3	AM POLY 1"	16.0 X 025.0 X 01.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.58
Facilities Services	5	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$1.90
Facilities Services	1	AM POLY 1"	17.4 X 025.0 X 01.0	\$7.00	\$42.00	\$7.00	\$3.15	\$18.90	\$1.72
Facilities Services	7	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$1.58
Facilities Services	3	AM POLY 1"	22.0 X 022.0 X 01.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.92
Facilities Services	1	AM POLY 1/2"	09.0 X 020.4 X 00.2	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$0.73
Facilities Services	1	AM POLY 1/2"	10.0 X 018.0 X 00.2	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$0.71
Facilities Services	1	AM POLY 1/2"	12.0 X 016.0 X 00.2	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$0.76
Facilities Services	1	WASH-OUT	09.0 X 030.0 X 00.2	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$11.08
Facilities Services	2	WASH-OUT	10.0 X 018.0 X 00.2	\$5.00	\$60.00	\$10.00	\$3.15	\$37.80	\$7.09
Facilities Services	2	WASH-OUT	16.0 X 020.0 X 00.2	\$5.00	\$60.00	\$10.00	\$3.15	\$37.80	\$13.07
Fire & Science Academy	1	AM POLY 1"	14.4 X 022.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.25
Fire & Science Academy	2	AM POLY 1"	15.0 X 030.5 X 01.0	\$7.00	\$84.00	\$7.00	\$3.15	\$37.80	\$1.81
Fire & Science Academy	5	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$1.90
Fire & Science Academy	5	AM POLY 1"	20.0 X 030.0 X 01.0	\$7.00	\$210.00	\$7.00	\$3.15	\$94.50	\$2.38
Fire & Science Academy	1	WASH-OUT	08.0 X 014.0 X 00.4	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$7.09
Fire & Science Academy	2	WASH-OUT	10.0 X 018.0 X 00.4	\$5.00	\$60.00	\$10.00	\$3.15	\$37.80	\$9.08

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Englewood Elementary	1	AM POLY 2"	20.0 X 021.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Englewood Elementary	4	AM POLY 2"	20.0 X 021.6 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Englewood Elementary	17	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$306.00	\$2.00	\$3.07	\$313.14	\$3.07
Englewood Elementary	2	AM POLY 2"	20.0 X 027.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Englewood Elementary	1	AM POLY 2"	25.0 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Englewood Elementary	6	WASH-OUT	12.0 X 012.0 X 00.2	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Englewood Elementary	1	WASH-OUT	16.0 X 016.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Englewood Elementary	1	WASH-OUT	20.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Facilities Services	3	AM POLY 1"	16.0 X 025.0 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Facilities Services	5	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Facilities Services	1	AM POLY 1"	17.4 X 025.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Facilities Services	7	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Facilities Services	3	AM POLY 1"	22.0 X 022.0 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Facilities Services	1	AM POLY 1/2"	09.0 X 020.4 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Facilities Services	1	AM POLY 1/2"	10.0 X 018.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Facilities Services	1	AM POLY 1/2"	12.0 X 016.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Facilities Services	1	WASH-OUT	09.0 X 030.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Facilities Services	2	WASH-OUT	10.0 X 018.0 X 00.2	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Facilities Services	2	WASH-OUT	16.0 X 020.0 X 00.2	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Fire & Science Academy	1	AM POLY 1"	14.4 X 022.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Fire & Science Academy	2	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Fire & Science Academy	5	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Fire & Science Academy	5	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Fire & Science Academy	1	WASH-OUT	08.0 X 014.0 X 00.4	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Fire & Science Academy	2	WASH-OUT	10.0 X 018.0 X 00.4	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Florida Central Portable	1	AM POLY 1"	15.0 X 030.5 X 01.0	\$7.00	\$42.00	\$7.00	\$3.15	\$18.90	\$1.81
Fruitville Elementary	16	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$1.90
Fruitville Elementary	16	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$2.38
Fruitville Elementary	4	AM POLY 2"	10.4 X 024.0 X 02.0	\$7.00	\$168.00	\$7.00	\$3.15	\$75.60	\$1.25
Fruitville Elementary	12	AM POLY 2"	12.4 X 017.2 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$1.07
Fruitville Elementary	2	AM POLY 2"	13.2 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.65
Fruitville Elementary	12	AM POLY 2"	14.2 X 025.0 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$1.78
Fruitville Elementary	10	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$1.60
Fruitville Elementary	6	AM POLY 2"	16.0 X 021.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.68
Fruitville Elementary	2	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.71
Fruitville Elementary	4	AM POLY 2"	16.0 X 023.4 X 02.0	\$7.00	\$168.00	\$7.00	\$3.15	\$75.60	\$1.87
Fruitville Elementary	4	AM POLY 2"	16.0 X 024.0 X 02.0	\$7.00	\$168.00	\$7.00	\$3.15	\$75.60	\$1.92
Fruitville Elementary	8	AM POLY 2"	16.0 X 025.0 X 02.0	\$7.00	\$336.00	\$7.00	\$3.15	\$151.20	\$2.00
Fruitville Elementary	6	AM POLY 2"	16.0 X 027.4 X 02.0	\$9.00	\$324.00	\$9.00	\$3.15	\$113.40	\$2.19
Fruitville Elementary	2	AM POLY 2"	17.0 X 024.0 X 02.0	\$7.00	\$84.00	\$7.00	\$3.15	\$37.80	\$2.04
Fruitville Elementary	2	AM POLY 2"	17.4 X 020.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.74
Fruitville Elementary	6	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.00
Fruitville Elementary	2	AM POLY 2"	20.0 X 023.6 X 02.0	\$7.00	\$84.00	\$7.00	\$3.15	\$37.80	\$2.36
Fruitville Elementary	12	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$2.40
Fruitville Elementary	14	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$504.00	\$6.00	\$3.15	\$264.60	\$2.50
Fruitville Elementary	22	AM POLY 2"	24.0 X 024.0 X 02.0	\$8.00	\$1,056.00	\$8.00	\$3.15	\$415.80	\$2.88
Fruitville Elementary	4	AM POLY 1/2"	11.0 X 022.0 X 00.4	\$5.00	\$120.00	\$5.00	\$3.15	\$75.60	\$0.96
Fruitville Elementary	2	WASH-OUT	14.0 X 017.4 X 00.4	\$5.00	\$60.00	\$10.00	\$3.15	\$37.80	\$10.08
Garden Elementary	18	AM POLY 1"	16.0 X 030.0 X 01.0	\$7.00	\$756.00	\$7.00	\$3.15	\$340.20	\$1.90
Garden Elementary	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.58

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Florida Central Portable	1	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Fruitville Elementary	16	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07
Fruitville Elementary	16	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07
Fruitville Elementary	4	AM POLY 2"	10.4 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Fruitville Elementary	12	AM POLY 2"	12.4 X 017.2 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Fruitville Elementary	2	AM POLY 2"	13.2 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Fruitville Elementary	12	AM POLY 2"	14.2 X 025.0 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Fruitville Elementary	10	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Fruitville Elementary	6	AM POLY 2"	16.0 X 021.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Fruitville Elementary	2	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Fruitville Elementary	4	AM POLY 2"	16.0 X 023.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Fruitville Elementary	4	AM POLY 2"	16.0 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Fruitville Elementary	8	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Fruitville Elementary	6	AM POLY 2"	16.0 X 027.4 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Fruitville Elementary	2	AM POLY 2"	17.0 X 024.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Fruitville Elementary	2	AM POLY 2"	17.4 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Fruitville Elementary	6	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Fruitville Elementary	2	AM POLY 2"	20.0 X 023.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Fruitville Elementary	12	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Fruitville Elementary	14	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07
Fruitville Elementary	22	AM POLY 2"	24.0 X 024.0 X 02.0	\$3.00	\$396.00	\$2.00	\$3.07	\$405.24	\$3.07
Fruitville Elementary	4	AM POLY 1/2"	11.0 X 022.0 X 00.4	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Fruitville Elementary	2	WASH-OUT	14.0 X 017.4 X 00.4	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Garden Elementary	18	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$324.00	\$2.00	\$3.07	\$331.56	\$3.07
Garden Elementary	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Garden Elementary	14	AM POLY 1"	20.0 X 030.0 X 01.0	\$7.00	\$588.00	\$7.00	\$3.15	\$264.60	\$2.38
Garden Elementary	24	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$864.00	\$6.00	\$3.15	\$453.60	\$1.60
Garden Elementary	10	AM POLY 2"	16.0 X 021.2 X 02.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$1.70
Garden Elementary	4	AM POLY 2"	16.0 X 025.6 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.05
Garden Elementary	6	AM POLY 2"	17.2 X 020.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.72
Garden Elementary	2	AM POLY 2"	19.2 X 020.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.92
Garden Elementary	8	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.00
Garden Elementary	6	AM POLY 2"	20.0 X 021.6 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.16
Garden Elementary	2	AM POLY 2"	20.0 X 023.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.36
Garden Elementary	14	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$504.00	\$6.00	\$3.15	\$264.60	\$2.50
Garden Elementary	2	AM POLY 2"	20.0 X 027.6 X 02.0	\$8.00	\$96.00	\$8.00	\$3.15	\$37.80	\$2.76
Garden Elementary	2	AM POLY 2"	23.4 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.93
Garden Elementary	2	WASH-OUT	10.0 X 046.0 X 00.5	\$6.00	\$72.00	\$10.00	\$3.15	\$37.80	\$15.07
Glenallen Elementary	1	AM POLY 1"	12.0 X 024.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.14
Glenallen Elementary	2	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.81
Glenallen Elementary	3	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.90
Glenallen Elementary	3	AM POLY 1"	16.2 X 030.2 X 01.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.94
Glenallen Elementary	3	AM POLY 1"	20.0 X 030.0 X 01.0	\$7.00	\$126.00	\$7.00	\$3.15	\$56.70	\$2.38
Glenallen Elementary	1	AM POLY 1"	20.2 X 044.2 X 01.0	\$7.00	\$42.00	\$7.00	\$3.15	\$18.90	\$3.53
Glenallen Elementary	18	AM POLY 1"	21.6 X 021.6 X 01.0	\$6.00	\$648.00	\$6.00	\$3.15	\$340.20	\$1.85
Glenallen Elementary	1	AM POLY 2"	12.0 X 016.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.96
Glenallen Elementary	4	AM POLY 2"	13.0 X 020.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.30
Glenallen Elementary	1	AM POLY 2"	15.0 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.50
Glenallen Elementary	27	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$972.00	\$6.00	\$3.15	\$510.30	\$1.60
Glenallen Elementary	4	AM POLY 2"	16.0 X 021.2 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.70

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Garden Elementary	14	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07
Garden Elementary	24	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$432.00	\$2.00	\$3.07	\$442.08	\$3.07
Garden Elementary	10	AM POLY 2"	16.0 X 021.2 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Garden Elementary	4	AM POLY 2"	16.0 X 025.6 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Garden Elementary	6	AM POLY 2"	17.2 X 020.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Garden Elementary	2	AM POLY 2"	19.2 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Garden Elementary	8	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Garden Elementary	6	AM POLY 2"	20.0 X 021.6 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Garden Elementary	2	AM POLY 2"	20.0 X 023.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Garden Elementary	14	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07
Garden Elementary	2	AM POLY 2"	20.0 X 027.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Garden Elementary	2	AM POLY 2"	23.4 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Garden Elementary	2	WASH-OUT	10.0 X 046.0 X 00.5	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Glenallen Elementary	1	AM POLY 1"	12.0 X 024.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Glenallen Elementary	2	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Glenallen Elementary	3	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Glenallen Elementary	3	AM POLY 1"	16.2 X 030.2 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Glenallen Elementary	3	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Glenallen Elementary	1	AM POLY 1"	20.2 X 044.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Glenallen Elementary	18	AM POLY 1"	21.6 X 021.6 X 01.0	\$3.00	\$324.00	\$2.00	\$3.07	\$331.56	\$3.07
Glenallen Elementary	1	AM POLY 2"	12.0 X 016.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Glenallen Elementary	4	AM POLY 2"	13.0 X 020.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Glenallen Elementary	1	AM POLY 2"	15.0 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Glenallen Elementary	27	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$486.00	\$2.00	\$3.07	\$497.34	\$3.07
Glenallen Elementary	4	AM POLY 2"	16.0 X 021.2 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Glenallen Elementary	6	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.71
Glenallen Elementary	20	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$720.00	\$6.00	\$3.15	\$378.00	\$2.00
Glenallen Elementary	10	AM POLY 2"	16.0 X 025.4 X 02.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$2.03
Glenallen Elementary	12	AM POLY 2"	16.0 X 027.4 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$2.19
Glenallen Elementary	2	AM POLY 2"	16.0 X 040.6 X 02.0	\$7.00	\$84.00	\$7.00	\$3.15	\$37.80	\$3.25
Glenallen Elementary	1	AM POLY 2"	17.3 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.16
Glenallen Elementary	1	AM POLY 2"	18.2 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.28
Glenallen Elementary	1	AM POLY 2"	19.0 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.90
Glenallen Elementary	2	AM POLY 2"	19.4 X 020.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.94
Glenallen Elementary	32	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$1,152.00	\$6.00	\$3.15	\$604.80	\$2.00
Glenallen Elementary	7	AM POLY 2"	20.0 X 021.4 X 02.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$2.14
Glenallen Elementary	9	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$324.00	\$6.00	\$3.15	\$170.10	\$2.50
Glenallen Elementary	1	WASH-OUT	09.0 X 018.0 X 00.2	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$7.09
Glenallen Elementary	3	WASH-OUT	13.0 X 026.0 X 00.4	\$5.00	\$90.00	\$10.00	\$3.15	\$56.70	\$13.07
Gocio Elementary	12	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$1.81
Gocio Elementary	1	AM POLY 1"	15.6 X 066.0 X 01.0	\$7.00	\$42.00	\$7.00	\$3.15	\$18.90	\$4.08
Gocio Elementary	7	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$1.90
Gocio Elementary	6	AM POLY 1"	16.2 X 030.2 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.94
Gocio Elementary	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.58
Gocio Elementary	8	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.38
Gocio Elementary	1	AM POLY 1"	20.0 X 030.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.39
Gocio Elementary	2	AM POLY 2"	09.3 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.16
Gocio Elementary	12	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$1.60
Gocio Elementary	4	AM POLY 2"	16.0 X 021.6 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.73
Gocio Elementary	13	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$468.00	\$6.00	\$3.15	\$245.70	\$2.00

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Glenallen Elementary	6	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Glenallen Elementary	20	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$360.00	\$2.00	\$3.07	\$368.40	\$3.07
Glenallen Elementary	10	AM POLY 2"	16.0 X 025.4 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Glenallen Elementary	12	AM POLY 2"	16.0 X 027.4 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Glenallen Elementary	2	AM POLY 2"	16.0 X 040.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Glenallen Elementary	1	AM POLY 2"	17.3 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Glenallen Elementary	1	AM POLY 2"	18.2 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Glenallen Elementary	1	AM POLY 2"	19.0 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Glenallen Elementary	2	AM POLY 2"	19.4 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Glenallen Elementary	32	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$576.00	\$2.00	\$3.07	\$589.44	\$3.07
Glenallen Elementary	7	AM POLY 2"	20.0 X 021.4 X 02.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Glenallen Elementary	9	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Glenallen Elementary	1	WASH-OUT	09.0 X 018.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Glenallen Elementary	3	WASH-OUT	13.0 X 026.0 X 00.4	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Gocio Elementary	12	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Gocio Elementary	1	AM POLY 1"	15.6 X 066.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Gocio Elementary	7	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Gocio Elementary	6	AM POLY 1"	16.2 X 030.2 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Gocio Elementary	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Gocio Elementary	8	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Gocio Elementary	1	AM POLY 1"	20.0 X 030.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Gocio Elementary	2	AM POLY 2"	09.3 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Gocio Elementary	12	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Gocio Elementary	4	AM POLY 2"	16.0 X 021.6 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Gocio Elementary	13	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$234.00	\$2.00	\$3.07	\$239.46	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Gocio Elementary	2	AM POLY 2"	19.6 X 024.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.35
Gocio Elementary	1	AM POLY 2"	19.6 X 025.6 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.51
Gocio Elementary	16	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$2.00
Gocio Elementary	1	AM POLY 2"	20.0 X 021.2 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.12
Gocio Elementary	3	AM POLY 2"	20.0 X 021.6 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.16
Gocio Elementary	14	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$504.00	\$6.00	\$3.15	\$264.60	\$2.50
Gocio Elementary	6	AM POLY 2"	20.0 X 025.2 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.52
Gocio Elementary	2	AM POLY 2"	23.6 X 024.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.83
Gocio Elementary	1	AM POLY 2"	23.6 X 025.6 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$3.02
Gocio Elementary	6	AM POLY 2"	24.0 X 024.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.88
Gocio Elementary	1	WASH-OUT	12.0 X 016.0 X 00.4	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$7.09
Gocio Elementary	1	WASH-OUT	12.4 X 013.0 X 00.5	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$7.09
Gocio Elementary	2	WASH-OUT	14.0 X 014.0 X 00.4	\$5.00	\$60.00	\$10.00	\$3.15	\$37.80	\$7.09
Gocio Elementary	1	WASH-OUT	16.0 X 020.0 X 00.4	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$13.07
Gulf Gate Elementary	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.58
Gulf Gate Elementary	16	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$1.60
Gulf Gate Elementary	7	AM POLY 2"	16.0 X 025.6 X 02.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$2.05
Gulf Gate Elementary	2	AM POLY 2"	16.0 X 027.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.21
Gulf Gate Elementary	1	AM POLY 2"	16.0 X 028.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.24
Gulf Gate Elementary	7	AM POLY 2"	17.6 X 025.0 X 02.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$2.20
Gulf Gate Elementary	21	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$756.00	\$6.00	\$3.15	\$396.90	\$2.00
Gulf Gate Elementary	3	AM POLY 2"	20.0 X 021.2 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.12
Gulf Gate Elementary	6	AM POLY 2"	20.0 X 021.6 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.16
Gulf Gate Elementary	2	AM POLY 2"	20.0 X 023.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.36
Gulf Gate Elementary	28	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$1,008.00	\$6.00	\$3.15	\$529.20	\$2.50

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Gocio Elementary	2	AM POLY 2"	19.6 X 024.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Gocio Elementary	1	AM POLY 2"	19.6 X 025.6 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Gocio Elementary	16	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07
Gocio Elementary	1	AM POLY 2"	20.0 X 021.2 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Gocio Elementary	3	AM POLY 2"	20.0 X 021.6 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Gocio Elementary	14	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07
Gocio Elementary	6	AM POLY 2"	20.0 X 025.2 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Gocio Elementary	2	AM POLY 2"	23.6 X 024.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Gocio Elementary	1	AM POLY 2"	23.6 X 025.6 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Gocio Elementary	6	AM POLY 2"	24.0 X 024.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Gocio Elementary	1	WASH-OUT	12.0 X 016.0 X 00.4	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Gocio Elementary	1	WASH-OUT	12.4 X 013.0 X 00.5	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Gocio Elementary	2	WASH-OUT	14.0 X 014.0 X 00.4	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Gocio Elementary	1	WASH-OUT	16.0 X 020.0 X 00.4	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Gulf Gate Elementary	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Gulf Gate Elementary	16	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07
Gulf Gate Elementary	7	AM POLY 2"	16.0 X 025.6 X 02.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Gulf Gate Elementary	2	AM POLY 2"	16.0 X 027.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Gulf Gate Elementary	1	AM POLY 2"	16.0 X 028.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Gulf Gate Elementary	7	AM POLY 2"	17.6 X 025.0 X 02.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Gulf Gate Elementary	21	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$378.00	\$2.00	\$3.07	\$386.82	\$3.07
Gulf Gate Elementary	3	AM POLY 2"	20.0 X 021.2 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Gulf Gate Elementary	6	AM POLY 2"	20.0 X 021.6 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Gulf Gate Elementary	2	AM POLY 2"	20.0 X 023.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Gulf Gate Elementary	28	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$504.00	\$2.00	\$3.07	\$515.76	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Gulf Gate Elementary	7	AM POLY 2"	20.0 X 025.6 X 02.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$2.56
Gulf Gate Elementary	2	AM POLY 2"	20.0 X 027.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.76
Gulf Gate Elementary	1	AM POLY 2"	25.0 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$3.13
Gulf Gate Elementary	1	AM POLY 2"	25.0 X 025.2 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$3.15
Gulf Gate Elementary	4	WASH-OUT	09.0 X 025.0 X 00.2	\$5.00	\$120.00	\$5.00	\$3.15	\$75.60	\$10.08
Heron Creek Middle	5	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$1.81
Heron Creek Middle	4	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.90
Heron Creek Middle	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.58
Heron Creek Middle	4	AM POLY 2"	14.0 X 020.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.40
Heron Creek Middle	6	AM POLY 2"	16.0 X 016.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.28
Heron Creek Middle	2	AM POLY 2"	16.0 X 018.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.44
Heron Creek Middle	46	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$1,656.00	\$6.00	\$3.15	\$869.40	\$1.60
Heron Creek Middle	8	AM POLY 2"	16.0 X 021.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.68
Heron Creek Middle	17	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$612.00	\$6.00	\$3.15	\$321.30	\$1.71
Heron Creek Middle	2	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.00
Heron Creek Middle	2	AM POLY 2"	16.0 X 025.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.03
Heron Creek Middle	2	AM POLY 2"	16.0 X 027.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.19
Heron Creek Middle	2	AM POLY 2"	16.0 X 030.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.40
Heron Creek Middle	2	AM POLY 2"	16.0 X 030.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.45
Heron Creek Middle	6	AM POLY 2"	17.4 X 025.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.18
Heron Creek Middle	2	AM POLY 2"	17.5 X 020.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.75
Heron Creek Middle	11	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$396.00	\$6.00	\$3.15	\$207.90	\$2.00
Heron Creek Middle	1	AM POLY 2"	20.0 X 021.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.10
Heron Creek Middle	3	AM POLY 2"	20.0 X 021.4 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.14
Heron Creek Middle	2	AM POLY 2"	20.0 X 023.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.34

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Gulf Gate Elementary	7	AM POLY 2"	20.0 X 025.6 X 02.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Gulf Gate Elementary	2	AM POLY 2"	20.0 X 027.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Gulf Gate Elementary	1	AM POLY 2"	25.0 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Gulf Gate Elementary	1	AM POLY 2"	25.0 X 025.2 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Gulf Gate Elementary	4	WASH-OUT	09.0 X 025.0 X 00.2	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Heron Creek Middle	5	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Heron Creek Middle	4	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Heron Creek Middle	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Heron Creek Middle	4	AM POLY 2"	14.0 X 020.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Heron Creek Middle	6	AM POLY 2"	16.0 X 016.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Heron Creek Middle	2	AM POLY 2"	16.0 X 018.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Heron Creek Middle	46	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$828.00	\$2.00	\$3.07	\$847.32	\$3.07
Heron Creek Middle	8	AM POLY 2"	16.0 X 021.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Heron Creek Middle	17	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$306.00	\$2.00	\$3.07	\$313.14	\$3.07
Heron Creek Middle	2	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Heron Creek Middle	2	AM POLY 2"	16.0 X 025.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Heron Creek Middle	2	AM POLY 2"	16.0 X 027.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Heron Creek Middle	2	AM POLY 2"	16.0 X 030.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Heron Creek Middle	2	AM POLY 2"	16.0 X 030.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Heron Creek Middle	6	AM POLY 2"	17.4 X 025.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Heron Creek Middle	2	AM POLY 2"	17.5 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Heron Creek Middle	11	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$198.00	\$2.00	\$3.07	\$202.62	\$3.07
Heron Creek Middle	1	AM POLY 2"	20.0 X 021.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Heron Creek Middle	3	AM POLY 2"	20.0 X 021.4 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Heron Creek Middle	2	AM POLY 2"	20.0 X 023.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Heron Creek Middle	51	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$1,836.00	\$6.00	\$3.15	\$963.90	\$2.50
Heron Creek Middle	8	AM POLY 2"	20.0 X 025.4 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.54
Heron Creek Middle	2	AM POLY 2"	20.0 X 027.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.74
Heron Creek Middle	3	AM POLY 2"	25.0 X 025.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$3.13
Heron Creek Middle	1	WASH-OUT	11.0 X 028.0 X 00.2	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$13.07
Heron Creek Middle	14	WASH-OUT	12.0 X 012.0 X 00.2	\$5.00	\$420.00	\$10.00	\$3.15	\$264.60	\$7.09
Lamarque Elementary	17	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$612.00	\$6.00	\$3.15	\$321.30	\$1.90
Lamarque Elementary	16	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$2.38
Lamarque Elementary	8	AM POLY 2"	06.4 X 024.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$0.77
Lamarque Elementary	4	AM POLY 2"	07.0 X 024.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$0.84
Lamarque Elementary	8	AM POLY 2"	13.0 X 020.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.30
Lamarque Elementary	4	AM POLY 2"	13.0 X 024.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.56
Lamarque Elementary	4	AM POLY 2"	13.4 X 020.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.34
Lamarque Elementary	38	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$1,368.00	\$6.00	\$3.15	\$718.20	\$1.60
Lamarque Elementary	2	AM POLY 2"	16.0 X 021.2 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.70
Lamarque Elementary	4	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.71
Lamarque Elementary	8	AM POLY 2"	16.0 X 021.6 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.73
Lamarque Elementary	8	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.00
Lamarque Elementary	2	AM POLY 2"	16.0 X 025.2 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.02
Lamarque Elementary	2	AM POLY 2"	16.0 X 025.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.03
Lamarque Elementary	4	AM POLY 2"	16.0 X 025.5 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.04
Lamarque Elementary	1	AM POLY 2"	17.0 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.13
Lamarque Elementary	1	AM POLY 2"	17.2 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.15
Lamarque Elementary	1	AM POLY 2"	17.4 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.18
Lamarque Elementary	45	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$1,620.00	\$6.00	\$3.15	\$850.50	\$2.00

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Heron Creek Middle	51	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$918.00	\$2.00	\$3.07	\$939.42	\$3.07
Heron Creek Middle	8	AM POLY 2"	20.0 X 025.4 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Heron Creek Middle	2	AM POLY 2"	20.0 X 027.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Heron Creek Middle	3	AM POLY 2"	25.0 X 025.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Heron Creek Middle	1	WASH-OUT	11.0 X 028.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Heron Creek Middle	14	WASH-OUT	12.0 X 012.0 X 00.2	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07
Lamarque Elementary	17	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$306.00	\$2.00	\$3.07	\$313.14	\$3.07
Lamarque Elementary	16	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07
Lamarque Elementary	8	AM POLY 2"	06.4 X 024.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Lamarque Elementary	4	AM POLY 2"	07.0 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Lamarque Elementary	8	AM POLY 2"	13.0 X 020.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Lamarque Elementary	4	AM POLY 2"	13.0 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Lamarque Elementary	4	AM POLY 2"	13.4 X 020.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Lamarque Elementary	38	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$684.00	\$2.00	\$3.07	\$699.96	\$3.07
Lamarque Elementary	2	AM POLY 2"	16.0 X 021.2 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Lamarque Elementary	4	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Lamarque Elementary	8	AM POLY 2"	16.0 X 021.6 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Lamarque Elementary	8	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Lamarque Elementary	2	AM POLY 2"	16.0 X 025.2 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Lamarque Elementary	2	AM POLY 2"	16.0 X 025.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Lamarque Elementary	4	AM POLY 2"	16.0 X 025.5 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Lamarque Elementary	1	AM POLY 2"	17.0 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Lamarque Elementary	1	AM POLY 2"	17.2 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Lamarque Elementary	1	AM POLY 2"	17.4 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Lamarque Elementary	45	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$810.00	\$2.00	\$3.07	\$828.90	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Lamarque Elementary	1	AM POLY 2"	20.0 X 021.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.10
Lamarque Elementary	4	AM POLY 2"	20.0 X 021.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.14
Lamarque Elementary	76	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$2,736.00	\$6.00	\$3.15	\$1,436.40	\$2.40
Lamarque Elementary	6	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.50
Lamarque Elementary	1	AM POLY 2"	20.0 X 027.6 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.76
Lamarque Elementary	1	MERV 8 SC PLEAT	16.0 X 030.0 X 01.0	\$7.00	\$42.00	\$7.00	\$6.02	\$36.12	\$4.02
Lamarque Elementary	1	MERV 8 SC PLEAT	20.0 X 030.0 X 01.0	\$7.00	\$42.00	\$7.00	\$4.96	\$29.76	\$2.96
Lamarque Elementary	8	WASH-OUT	10.0 X 011.0 X 00.5	\$5.00	\$240.00	\$10.00	\$3.15	\$151.20	\$7.09
Lamarque Elementary	4	WASH-OUT	10.0 X 026.4 X 00.5	\$5.00	\$120.00	\$10.00	\$3.15	\$75.60	\$10.08
Lamarque Elementary	1	WASH-OUT	11.4 X 013.0 X 00.5	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$7.09
Lakeview Elementary	17	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$612.00	\$6.00	\$3.15	\$321.30	\$1.90
Lakeview Elementary	17	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$612.00	\$6.00	\$3.15	\$321.30	\$2.38
Lakeview Elementary	20	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$720.00	\$6.00	\$3.15	\$378.00	\$1.60
Lakeview Elementary	4	AM POLY 2"	16.0 X 021.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.68
Lakeview Elementary	2	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.71
Lakeview Elementary	13	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$468.00	\$6.00	\$3.15	\$245.70	\$2.00
Lakeview Elementary	22	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$792.00	\$6.00	\$3.15	\$415.80	\$2.00
Lakeview Elementary	10	AM POLY 2"	20.0 X 021.0 X 02.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$2.10
Lakeview Elementary	17	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$612.00	\$6.00	\$3.15	\$321.30	\$2.50
Lakeview Elementary	1	AM POLY 2"	25.0 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$3.13
Lakeview Elementary	1	AM POLY 1/2"	16.2 X 030.2 X 01.0	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$1.94
Lakeview Elementary	1	AM POLY 1/2"	20.0 X 030.0 X 01.0	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$2.38
Lakeview Elementary	1	WASH-OUT	10.0 X 014.0 X 00.4	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$7.09
Laurel Nokomis	2	AM POLY 1"	14.0 X 020.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.11
Laurel Nokomis	9	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$324.00	\$6.00	\$3.15	\$170.10	\$1.81

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Lamarque Elementary	1	AM POLY 2"	20.0 X 021.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Lamarque Elementary	4	AM POLY 2"	20.0 X 021.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Lamarque Elementary	76	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$1,368.00	\$2.00	\$3.07	\$1,399.92	\$3.07
Lamarque Elementary	6	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Lamarque Elementary	1	AM POLY 2"	20.0 X 027.6 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Lamarque Elementary	1	MERV 8 SC PLEAT	16.0 X 030.0 X 01.0	\$5.20	\$31.20	\$2.00	\$5.00	\$30.00	\$5.00
Lamarque Elementary	1	MERV 8 SC PLEAT	20.0 X 030.0 X 01.0	\$5.31	\$31.86	\$2.00	\$5.00	\$30.00	\$5.00
Lamarque Elementary	8	WASH-OUT	10.0 X 011.0 X 00.5	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Lamarque Elementary	4	WASH-OUT	10.0 X 026.4 X 00.5	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Lamarque Elementary	1	WASH-OUT	11.4 X 013.0 X 00.5	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Lakeview Elementary	17	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$306.00	\$2.00	\$3.07	\$313.14	\$3.07
Lakeview Elementary	17	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$306.00	\$2.00	\$3.07	\$313.14	\$3.07
Lakeview Elementary	20	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$360.00	\$2.00	\$3.07	\$368.40	\$3.07
Lakeview Elementary	4	AM POLY 2"	16.0 X 021.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Lakeview Elementary	2	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Lakeview Elementary	13	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$234.00	\$2.00	\$3.07	\$239.46	\$3.07
Lakeview Elementary	22	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$396.00	\$2.00	\$3.07	\$405.24	\$3.07
Lakeview Elementary	10	AM POLY 2"	20.0 X 021.0 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Lakeview Elementary	17	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$306.00	\$2.00	\$3.07	\$313.14	\$3.07
Lakeview Elementary	1	AM POLY 2"	25.0 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Lakeview Elementary	1	AM POLY 1/2"	16.2 X 030.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Lakeview Elementary	1	AM POLY 1/2"	20.0 X 030.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Lakeview Elementary	1	WASH-OUT	10.0 X 014.0 X 00.4	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Laurel Nokomis	2	AM POLY 1"	14.0 X 020.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Laurel Nokomis	9	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Laurel Nokomis	14	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$504.00	\$6.00	\$3.15	\$264.60	\$1.90
Laurel Nokomis	2	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.58
Laurel Nokomis	5	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$2.38
Laurel Nokomis	2	AM POLY 1"	20.2 X 020.2 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.62
Laurel Nokomis	18	AM POLY 1"	21.6 X 021.6 X 01.0	\$6.00	\$648.00	\$6.00	\$3.15	\$340.20	\$1.85
Laurel Nokomis	6	AM POLY 2"	12.0 X 017.6 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.06
Laurel Nokomis	27	AM POLY 2"	12.0 X 024.0 X 02.0	\$6.00	\$972.00	\$6.00	\$3.15	\$510.30	\$1.44
Laurel Nokomis	3	AM POLY 2"	12.0 X 025.6 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.54
Laurel Nokomis	1	AM POLY 2"	15.4 X 036.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.77
Laurel Nokomis	1	AM POLY 2"	16.0 X 016.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.31
Laurel Nokomis	1	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.60
Laurel Nokomis	2	AM POLY 2"	16.6 X 024.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.99
Laurel Nokomis	6	AM POLY 2"	17.6 X 024.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.11
Laurel Nokomis	1	AM POLY 2"	17.6 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.20
Laurel Nokomis	3	AM POLY 2"	19.6 X 024.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.35
Laurel Nokomis	19	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$684.00	\$6.00	\$3.15	\$359.10	\$2.40
Laurel Nokomis	2	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.50
Laurel Nokomis	2	AM POLY 2"	21.2 X 024.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.54
Laurel Nokomis	6	AM POLY 2"	23.6 X 024.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.83
Laurel Nokomis	1	AM POLY 2"	23.6 X 025.6 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$3.02
Laurel Nokomis	49	AM POLY 2"	24.0 X 024.0 X 02.0	\$6.00	\$1,764.00	\$6.00	\$3.15	\$926.10	\$2.88
Laurel Nokomis	10	AM POLY 2"	24.0 X 025.6 X 02.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$3.07
Laurel Nokomis	1	AM SLEVE	20.0 X 020.0	\$7.00	\$42.00	\$7.00	\$3.15	\$18.90	\$1.92
Laurel Nokomis	1	WASH-OUT	10.0 X 014.4 X 00.2	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$7.09
McIntosh Middle	1	AM POLY 1"	14.0 X 025.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.39

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Laurel Nokomis	14	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07
Laurel Nokomis	2	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Laurel Nokomis	5	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Laurel Nokomis	2	AM POLY 1"	20.2 X 020.2 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Laurel Nokomis	18	AM POLY 1"	21.6 X 021.6 X 01.0	\$3.00	\$324.00	\$2.00	\$3.07	\$331.56	\$3.07
Laurel Nokomis	6	AM POLY 2"	12.0 X 017.6 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Laurel Nokomis	27	AM POLY 2"	12.0 X 024.0 X 02.0	\$3.00	\$486.00	\$2.00	\$3.07	\$497.34	\$3.07
Laurel Nokomis	3	AM POLY 2"	12.0 X 025.6 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Laurel Nokomis	1	AM POLY 2"	15.4 X 036.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Laurel Nokomis	1	AM POLY 2"	16.0 X 016.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Laurel Nokomis	1	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Laurel Nokomis	2	AM POLY 2"	16.6 X 024.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Laurel Nokomis	6	AM POLY 2"	17.6 X 024.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Laurel Nokomis	1	AM POLY 2"	17.6 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Laurel Nokomis	3	AM POLY 2"	19.6 X 024.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Laurel Nokomis	19	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$342.00	\$2.00	\$3.07	\$349.98	\$3.07
Laurel Nokomis	2	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Laurel Nokomis	2	AM POLY 2"	21.2 X 024.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Laurel Nokomis	6	AM POLY 2"	23.6 X 024.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Laurel Nokomis	1	AM POLY 2"	23.6 X 025.6 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Laurel Nokomis	49	AM POLY 2"	24.0 X 024.0 X 02.0	\$3.00	\$882.00	\$2.00	\$3.07	\$902.58	\$3.07
Laurel Nokomis	10	AM POLY 2"	24.0 X 025.6 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Laurel Nokomis	1	AM SLEVE	20.0 X 020.0	\$3.75	\$22.50	\$2.00	\$4.47	\$26.82	\$4.47
Laurel Nokomis	1	WASH-OUT	10.0 X 014.4 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
McIntosh Middle	1	AM POLY 1"	14.0 X 025.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
McIntosh Middle	7	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$1.81
McIntosh Middle	3	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.90
McIntosh Middle	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.58
McIntosh Middle	18	AM POLY 1"	21.6 X 021.6 X 01.0	\$6.00	\$648.00	\$6.00	\$3.15	\$340.20	\$1.85
McIntosh Middle	4	AM POLY 2"	13.4 X 024.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.61
McIntosh Middle	2	AM POLY 2"	13.4 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.68
McIntosh Middle	16	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$1.60
McIntosh Middle	10	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$1.71
McIntosh Middle	4	AM POLY 2"	16.0 X 023.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.87
McIntosh Middle	8	AM POLY 2"	16.0 X 024.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.92
McIntosh Middle	12	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$2.00
McIntosh Middle	2	AM POLY 2"	16.2 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.03
McIntosh Middle	2	AM POLY 2"	17.0 X 024.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.04
McIntosh Middle	4	AM POLY 2"	17.4 X 025.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.18
McIntosh Middle	1	AM POLY 2"	18.2 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.28
McIntosh Middle	1	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.00
McIntosh Middle	6	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.00
McIntosh Middle	6	AM POLY 2"	20.0 X 021.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.10
McIntosh Middle	2	AM POLY 2"	20.0 X 021.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.14
McIntosh Middle	4	AM POLY 2"	20.0 X 023.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.34
McIntosh Middle	40	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$1,440.00	\$6.00	\$3.15	\$756.00	\$2.40
McIntosh Middle	39	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$1,404.00	\$6.00	\$3.15	\$737.10	\$2.50
McIntosh Middle	2	AM POLY 2"	20.0 X 027.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.74
McIntosh Middle	6	AM POLY 2"	24.0 X 024.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.88
McIntosh Middle	3	AM POLY 2"	25.0 X 025.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$3.13

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
McIntosh Middle	7	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
McIntosh Middle	3	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
McIntosh Middle	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
McIntosh Middle	18	AM POLY 1"	21.6 X 021.6 X 01.0	\$3.00	\$324.00	\$2.00	\$3.07	\$331.56	\$3.07
McIntosh Middle	4	AM POLY 2"	13.4 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
McIntosh Middle	2	AM POLY 2"	13.4 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
McIntosh Middle	16	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07
McIntosh Middle	10	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
McIntosh Middle	4	AM POLY 2"	16.0 X 023.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
McIntosh Middle	8	AM POLY 2"	16.0 X 024.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
McIntosh Middle	12	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
McIntosh Middle	2	AM POLY 2"	16.2 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
McIntosh Middle	2	AM POLY 2"	17.0 X 024.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
McIntosh Middle	4	AM POLY 2"	17.4 X 025.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
McIntosh Middle	1	AM POLY 2"	18.2 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
McIntosh Middle	1	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
McIntosh Middle	6	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
McIntosh Middle	6	AM POLY 2"	20.0 X 021.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
McIntosh Middle	2	AM POLY 2"	20.0 X 021.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
McIntosh Middle	4	AM POLY 2"	20.0 X 023.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
McIntosh Middle	40	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$720.00	\$2.00	\$3.07	\$736.80	\$3.07
McIntosh Middle	39	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$702.00	\$2.00	\$3.07	\$718.38	\$3.07
McIntosh Middle	2	AM POLY 2"	20.0 X 027.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
McIntosh Middle	6	AM POLY 2"	24.0 X 024.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
McIntosh Middle	3	AM POLY 2"	25.0 X 025.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
North Port High	1	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.81
North Port High	2	AM POLY 1"	16.0 X 025.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.58
North Port High	5	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$1.90
North Port High	1	AM POLY 1"	17.0 X 025.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.68
North Port High	1	AM POLY 1"	19.0 X 020.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.50
North Port High	4	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.58
North Port High	5	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$2.38
North Port High	2	AM POLY 2"	08.2 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.03
North Port High	8	AM POLY 2"	13.4 X 024.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.61
North Port High	8	AM POLY 2"	14.0 X 020.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.40
North Port High	4	AM POLY 2"	14.5 X 025.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.81
North Port High	2	AM POLY 2"	14.6 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.83
North Port High	6	AM POLY 2"	15.0 X 020.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.50
North Port High	2	AM POLY 2"	15.0 X 021.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.61
North Port High	8	AM POLY 2"	15.6 X 020.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.56
North Port High	12	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$1.60
North Port High	10	AM POLY 2"	16.0 X 021.6 X 02.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$1.73
North Port High	20	AM POLY 2"	16.0 X 023.6 X 02.0	\$6.00	\$720.00	\$6.00	\$3.15	\$378.00	\$1.89
North Port High	48	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$1,728.00	\$6.00	\$3.15	\$907.20	\$2.00
North Port High	4	AM POLY 2"	16.2 X 025.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.03
North Port High	6	AM POLY 2"	17.2 X 020.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.72
North Port High	8	AM POLY 2"	17.4 X 020.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.74
North Port High	6	AM POLY 2"	17.6 X 025.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.20
North Port High	16	AM POLY 2"	18.0 X 024.0 X 02.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$2.16
North Port High	4	AM POLY 2"	19.1 X 025.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.39

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
North Port High	1	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
North Port High	2	AM POLY 1"	16.0 X 025.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
North Port High	5	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
North Port High	1	AM POLY 1"	17.0 X 025.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
North Port High	1	AM POLY 1"	19.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
North Port High	4	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
North Port High	5	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
North Port High	2	AM POLY 2"	08.2 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
North Port High	8	AM POLY 2"	13.4 X 024.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
North Port High	8	AM POLY 2"	14.0 X 020.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
North Port High	4	AM POLY 2"	14.5 X 025.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
North Port High	2	AM POLY 2"	14.6 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
North Port High	6	AM POLY 2"	15.0 X 020.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
North Port High	2	AM POLY 2"	15.0 X 021.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
North Port High	8	AM POLY 2"	15.6 X 020.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
North Port High	12	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
North Port High	10	AM POLY 2"	16.0 X 021.6 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
North Port High	20	AM POLY 2"	16.0 X 023.6 X 02.0	\$3.00	\$360.00	\$2.00	\$3.07	\$368.40	\$3.07
North Port High	48	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$864.00	\$2.00	\$3.07	\$884.16	\$3.07
North Port High	4	AM POLY 2"	16.2 X 025.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
North Port High	6	AM POLY 2"	17.2 X 020.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
North Port High	8	AM POLY 2"	17.4 X 020.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
North Port High	6	AM POLY 2"	17.6 X 025.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
North Port High	16	AM POLY 2"	18.0 X 024.0 X 02.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07
North Port High	4	AM POLY 2"	19.1 X 025.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
North Port High	59	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$2,124.00	\$6.00	\$3.15	\$1,115.10	\$2.00
North Port High	1	AM POLY 2"	20.0 X 021.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.10
North Port High	4	AM POLY 2"	20.0 X 021.2 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.12
North Port High	2	AM POLY 2"	20.0 X 021.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.16
North Port High	2	AM POLY 2"	20.0 X 023.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.36
North Port High	32	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$1,152.00	\$6.00	\$3.15	\$604.80	\$2.40
North Port High	166	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$5,976.00	\$6.00	\$3.15	\$3,137.40	\$2.50
North Port High	4	AM POLY 2"	20.0 X 025.2 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.52
North Port High	24	AM POLY 2"	20.0 X 025.6 X 02.0	\$6.00	\$864.00	\$6.00	\$3.15	\$453.60	\$2.56
North Port High	1	AM POLY 2"	20.0 X 027.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.74
North Port High	1	AM POLY 2"	20.0 X 027.6 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.76
North Port High	7	AM POLY 2"	20.2 X 025.0 X 02.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$2.53
North Port High	4	AM POLY 2"	20.6 X 024.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.47
North Port High	7	AM POLY 2"	25.0 X 025.0 X 02.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$3.13
North Port High	8	AM POLY 1/2"	11.0 X 017.0 X 00.2	\$5.00	\$240.00	\$5.00	\$3.15	\$151.20	\$0.74
North Port High	2	WASH-OUT	08.0 X 020.0 X 00.4	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$7.09
North Port High	1	WASH-OUT	08.0 X 024.0 X 00.2	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$7.09
North Port High	14	WASH-OUT	12.0 X 012.0 X 00.2	\$5.00	\$420.00	\$5.00	\$3.15	\$264.60	\$7.09
North Port High	4	WASH-OUT	13.0 X 015.0 X 00.4	\$5.00	\$120.00	\$5.00	\$3.15	\$75.60	\$7.09
Oak Park	2	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.81
Oak Park	7	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$1.90
Oak Park	4	AM POLY 1"	16.2 X 030.2 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.94
Oak Park	6	AM POLY 1"	20.0 X 025.0 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.98
Oak Park	7	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$2.38
Oak Park	5	AM POLY 2"	09.4 X 020.0 X 02.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$0.94

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
North Port High	59	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$1,062.00	\$2.00	\$3.07	\$1,086.78	\$3.07
North Port High	1	AM POLY 2"	20.0 X 021.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
North Port High	4	AM POLY 2"	20.0 X 021.2 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
North Port High	2	AM POLY 2"	20.0 X 021.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
North Port High	2	AM POLY 2"	20.0 X 023.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
North Port High	32	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$576.00	\$2.00	\$3.07	\$589.44	\$3.07
North Port High	166	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$2,988.00	\$2.00	\$3.07	\$3,057.72	\$3.07
North Port High	4	AM POLY 2"	20.0 X 025.2 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
North Port High	24	AM POLY 2"	20.0 X 025.6 X 02.0	\$3.00	\$432.00	\$2.00	\$3.07	\$442.08	\$3.07
North Port High	1	AM POLY 2"	20.0 X 027.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
North Port High	1	AM POLY 2"	20.0 X 027.6 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
North Port High	7	AM POLY 2"	20.2 X 025.0 X 02.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
North Port High	4	AM POLY 2"	20.6 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
North Port High	7	AM POLY 2"	25.0 X 025.0 X 02.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
North Port High	8	AM POLY 1/2"	11.0 X 017.0 X 00.2	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
North Port High	2	WASH-OUT	08.0 X 020.0 X 00.4	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
North Port High	1	WASH-OUT	08.0 X 024.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
North Port High	14	WASH-OUT	12.0 X 012.0 X 00.2	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07
North Port High	4	WASH-OUT	13.0 X 015.0 X 00.4	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Oak Park	2	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Oak Park	7	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Oak Park	4	AM POLY 1"	16.2 X 030.2 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Oak Park	6	AM POLY 1"	20.0 X 025.0 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Oak Park	7	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Oak Park	5	AM POLY 2"	09.4 X 020.0 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Oak Park	1	AM POLY 2"	12.0 X 016.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.96
Oak Park	2	AM POLY 2"	12.0 X 024.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.44
Oak Park	2	AM POLY 2"	12.4 X 016.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$0.99
Oak Park	1	AM POLY 2"	14.4 X 023.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.66
Oak Park	4	AM POLY 2"	15.4 X 020.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.54
Oak Park	39	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$1,404.00	\$6.00	\$3.15	\$737.10	\$1.60
Oak Park	1	AM POLY 2"	16.0 X 020.6 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.65
Oak Park	2	AM POLY 2"	16.0 X 021.1 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.69
Oak Park	8	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.71
Oak Park	8	AM POLY 2"	16.0 X 023.6 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.89
Oak Park	2	AM POLY 2"	16.0 X 025.3 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.02
Oak Park	4	AM POLY 2"	16.0 X 025.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.03
Oak Park	2	AM POLY 2"	16.0 X 026.7 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.14
Oak Park	6	AM POLY 2"	16.0 X 027.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.16
Oak Park	2	AM POLY 2"	16.0 X 038.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$3.07
Oak Park	1	AM POLY 2"	16.2 X 033.6 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.72
Oak Park	1	AM POLY 2"	17.0 X 023.5 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.00
Oak Park	3	AM POLY 2"	17.0 X 023.6 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.01
Oak Park	1	AM POLY 2"	17.2 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.15
Oak Park	1	AM POLY 2"	17.4 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.18
Oak Park	4	AM POLY 2"	18.0 X 024.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.16
Oak Park	2	AM POLY 2"	19.4 X 020.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.94
Oak Park	2	AM POLY 2"	19.6 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.45
Oak Park	6	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.00
Oak Park	1	AM POLY 2"	20.0 X 020.2 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.02

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Oak Park	1	AM POLY 2"	12.0 X 016.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Oak Park	2	AM POLY 2"	12.0 X 024.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Oak Park	2	AM POLY 2"	12.4 X 016.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Oak Park	1	AM POLY 2"	14.4 X 023.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Oak Park	4	AM POLY 2"	15.4 X 020.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Oak Park	39	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$702.00	\$2.00	\$3.07	\$718.38	\$3.07
Oak Park	1	AM POLY 2"	16.0 X 020.6 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Oak Park	2	AM POLY 2"	16.0 X 021.1 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Oak Park	8	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Oak Park	8	AM POLY 2"	16.0 X 023.6 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Oak Park	2	AM POLY 2"	16.0 X 025.3 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Oak Park	4	AM POLY 2"	16.0 X 025.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Oak Park	2	AM POLY 2"	16.0 X 026.7 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Oak Park	6	AM POLY 2"	16.0 X 027.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Oak Park	2	AM POLY 2"	16.0 X 038.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Oak Park	1	AM POLY 2"	16.2 X 033.6 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Oak Park	1	AM POLY 2"	17.0 X 023.5 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Oak Park	3	AM POLY 2"	17.0 X 023.6 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Oak Park	1	AM POLY 2"	17.2 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Oak Park	1	AM POLY 2"	17.4 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Oak Park	4	AM POLY 2"	18.0 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Oak Park	2	AM POLY 2"	19.4 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Oak Park	2	AM POLY 2"	19.6 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Oak Park	6	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Oak Park	1	AM POLY 2"	20.0 X 020.2 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Oak Park	1	AM POLY 2"	20.0 X 023.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.34
Oak Park	4	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.40
Oak Park	9	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$324.00	\$6.00	\$3.15	\$170.10	\$2.50
Oak Park	3	AM POLY 2"	20.0 X 027.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.70
Oak Park	2	AM POLY 2"	20.0 X 027.2 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.72
Oak Park	1	AM POLY 2"	22.0 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.75
Oak Park	4	AM POLY 2"	24.0 X 024.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.88
Oak Park	2	AM POLY 2"	24.0 X 027.2 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$3.26
Oak Park	3	AM POLY 2"	25.0 X 025.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$3.13
Oak Park	1	WASH-OUT	10.0 X 016.0 X 00.4	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$7.09
Oak Park South	8	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.90
Oak Park South	8	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.38
Oak Park South	4	AM POLY 2"	20.0 X 027.6 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.76
Oak Park South	2	AM POLY 2"	21.4 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.68
Oak Park South	2	WASH-OUT	12.0 X 012.0 X 00.2	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$7.09
Phillippi Shores Elementary	2	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.58
Phillippi Shores Elementary	26	AM POLY 2"	16.0 X 020.0 X 02.0	\$5.00	\$780.00	\$5.00	\$3.15	\$491.40	\$1.60
Phillippi Shores Elementary	2	AM POLY 2"	16.0 X 021.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.68
Phillippi Shores Elementary	4	AM POLY 2"	16.0 X 021.3 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.70
Phillippi Shores Elementary	12	AM POLY 2"	16.0 X 023.3 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$1.86
Phillippi Shores Elementary	8	AM POLY 2"	16.0 X 023.4 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.87
Phillippi Shores Elementary	48	AM POLY 2"	16.0 X 025.0 X 02.0	\$5.00	\$1,440.00	\$5.00	\$3.15	\$907.20	\$2.00
Phillippi Shores Elementary	12	AM POLY 2"	16.0 X 025.4 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$2.03
Phillippi Shores Elementary	12	AM POLY 2"	16.0 X 027.4 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$2.19
Phillippi Shores Elementary	6	AM POLY 2"	20.0 X 020.0 X 02.0	\$5.00	\$180.00	\$5.00	\$3.15	\$113.40	\$2.00

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Oak Park	1	AM POLY 2"	20.0 X 023.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Oak Park	4	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Oak Park	9	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Oak Park	3	AM POLY 2"	20.0 X 027.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Oak Park	2	AM POLY 2"	20.0 X 027.2 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Oak Park	1	AM POLY 2"	22.0 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Oak Park	4	AM POLY 2"	24.0 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Oak Park	2	AM POLY 2"	24.0 X 027.2 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Oak Park	3	AM POLY 2"	25.0 X 025.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Oak Park	1	WASH-OUT	10.0 X 016.0 X 00.4	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Oak Park South	8	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Oak Park South	8	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Oak Park South	4	AM POLY 2"	20.0 X 027.6 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Oak Park South	2	AM POLY 2"	21.4 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Oak Park South	2	WASH-OUT	12.0 X 012.0 X 00.2	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Phillippi Shores Elementary	2	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Phillippi Shores Elementary	26	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$468.00	\$2.00	\$3.07	\$478.92	\$3.07
Phillippi Shores Elementary	2	AM POLY 2"	16.0 X 021.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Phillippi Shores Elementary	4	AM POLY 2"	16.0 X 021.3 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Phillippi Shores Elementary	12	AM POLY 2"	16.0 X 023.3 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Phillippi Shores Elementary	8	AM POLY 2"	16.0 X 023.4 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Phillippi Shores Elementary	48	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$864.00	\$2.00	\$3.07	\$884.16	\$3.07
Phillippi Shores Elementary	12	AM POLY 2"	16.0 X 025.4 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Phillippi Shores Elementary	12	AM POLY 2"	16.0 X 027.4 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Phillippi Shores Elementary	6	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Phillippi Shores Elementary	2	AM POLY 2"	20.0 X 021.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.14
Phillippi Shores Elementary	10	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$2.50
Phillippi Shores Elementary	4	AM POLY 2"	20.0 X 025.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.54
Phillippi Shores Elementary	1	AM POLY 2"	20.0 X 027.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.70
Phillippi Shores Elementary	1	AM POLY 2"	20.0 X 027.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.74
Phillippi Shores Elementary	5	WASH-OUT	10.0 X 028.0 X 00.4	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$10.08
Phillippi Shores Elementary	2	WASH-OUT	10.0 X 042.0 X 00.4	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$15.07
Phoenix Academy	4	AM POLY 1"	20.0 X 025.0 X 01.0	\$5.00	\$120.00	\$5.00	\$3.15	\$75.60	\$1.98
Phoenix Academy	16	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$2.38
Pine View	12	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$1.81
Pine View	3	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.90
Pine View	22	AM POLY 1"	16.2 X 030.2 X 01.0	\$6.00	\$792.00	\$6.00	\$3.15	\$415.80	\$1.94
Pine View	25	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$900.00	\$6.00	\$3.15	\$472.50	\$2.38
Pine View	1	AM POLY 1"	20.2 X 020.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.62
Pine View	1	AM POLY 2"	08.0 X 016.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.64
Pine View	3	AM POLY 2"	09.0 X 016.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$0.72
Pine View	1	AM POLY 2"	09.4 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.94
Pine View	2	AM POLY 2"	10.0 X 016.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$0.80
Pine View	3	AM POLY 2"	10.0 X 020.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.00
Pine View	1	AM POLY 2"	10.4 X 016.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.83
Pine View	28	AM POLY 2"	12.4 X 017.2 X 02.0	\$6.00	\$1,008.00	\$6.00	\$3.15	\$529.20	\$1.07
Pine View	28	AM POLY 2"	14.2 X 025.0 X 02.0	\$6.00	\$1,008.00	\$6.00	\$3.15	\$529.20	\$1.78
Pine View	2	AM POLY 2"	14.6 X 020.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.46
Pine View	1	AM POLY 2"	15.6 X 027.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.11
Pine View	8	AM POLY 2"	16.0 X 017.6 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.41

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Phillippi Shores Elementary	2	AM POLY 2"	20.0 X 021.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Phillippi Shores Elementary	10	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Phillippi Shores Elementary	4	AM POLY 2"	20.0 X 025.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Phillippi Shores Elementary	1	AM POLY 2"	20.0 X 027.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Phillippi Shores Elementary	1	AM POLY 2"	20.0 X 027.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Phillippi Shores Elementary	5	WASH-OUT	10.0 X 028.0 X 00.4	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Phillippi Shores Elementary	2	WASH-OUT	10.0 X 042.0 X 00.4	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Phoenix Academy	4	AM POLY 1"	20.0 X 025.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Phoenix Academy	16	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07
Pine View	12	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Pine View	3	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Pine View	22	AM POLY 1"	16.2 X 030.2 X 01.0	\$3.00	\$396.00	\$2.00	\$3.07	\$405.24	\$3.07
Pine View	25	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$450.00	\$2.00	\$3.07	\$460.50	\$3.07
Pine View	1	AM POLY 1"	20.2 X 020.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Pine View	1	AM POLY 2"	08.0 X 016.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Pine View	3	AM POLY 2"	09.0 X 016.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Pine View	1	AM POLY 2"	09.4 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Pine View	2	AM POLY 2"	10.0 X 016.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Pine View	3	AM POLY 2"	10.0 X 020.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Pine View	1	AM POLY 2"	10.4 X 016.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Pine View	28	AM POLY 2"	12.4 X 017.2 X 02.0	\$3.00	\$504.00	\$2.00	\$3.07	\$515.76	\$3.07
Pine View	28	AM POLY 2"	14.2 X 025.0 X 02.0	\$3.00	\$504.00	\$2.00	\$3.07	\$515.76	\$3.07
Pine View	2	AM POLY 2"	14.6 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Pine View	1	AM POLY 2"	15.6 X 027.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Pine View	8	AM POLY 2"	16.0 X 017.6 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Pine View	20	AM POLY 2"	16.0 X 018.2 X 02.0	\$6.00	\$720.00	\$6.00	\$3.15	\$378.00	\$1.46
Pine View	21	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$756.00	\$6.00	\$3.15	\$396.90	\$1.60
Pine View	16	AM POLY 2"	16.0 X 023.2 X 02.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$1.86
Pine View	2	AM POLY 2"	16.0 X 023.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.89
Pine View	16	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$2.00
Pine View	5	AM POLY 2"	16.0 X 027.0 X 02.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$2.16
Pine View	12	AM POLY 2"	16.0 X 036.0 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$2.88
Pine View	2	AM POLY 2"	16.2 X 023.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.86
Pine View	2	AM POLY 2"	16.2 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.03
Pine View	33	AM POLY 2"	19.2 X 020.0 X 02.0	\$6.00	\$1,188.00	\$6.00	\$3.15	\$623.70	\$1.92
Pine View	6	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.00
Pine View	2	AM POLY 2"	20.0 X 023.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.36
Pine View	8	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.40
Pine View	22	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$792.00	\$6.00	\$3.15	\$415.80	\$2.50
Pine View	2	AM POLY 2"	20.0 X 026.2 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.62
Pine View	14	AM POLY 2"	20.0 X 038.0 X 02.0	\$6.00	\$504.00	\$6.00	\$3.15	\$264.60	\$3.80
Pine View	1	AM SLEVE	10.4 X 022.0	\$6.00	\$36.00	\$7.00	\$3.15	\$18.90	\$1.41
Pine View	1	AM SLEVE	11.0 X 022.4	\$6.00	\$36.00	\$7.00	\$3.15	\$18.90	\$1.41
Pine View	1	AM SLEVE	14.2 X 021.2	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.67
Pine View	2	WASH-OUT	12.0 X 012.0 X 00.2	\$5.00	\$60.00	\$10.00	\$3.15	\$37.80	\$7.09
Riverview High	1	AM POLY 1"	10.0 X 061.6 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.44
Riverview High	2	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.90
Riverview High	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.58
Riverview High	12	AM POLY 1"	21.6 X 021.6 X 01.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$1.85
Riverview High	4	AM POLY 2"	10.2 X 020.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.02

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Pine View	20	AM POLY 2"	16.0 X 018.2 X 02.0	\$3.00	\$360.00	\$2.00	\$3.07	\$368.40	\$3.07
Pine View	21	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$378.00	\$2.00	\$3.07	\$386.82	\$3.07
Pine View	16	AM POLY 2"	16.0 X 023.2 X 02.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07
Pine View	2	AM POLY 2"	16.0 X 023.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Pine View	16	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07
Pine View	5	AM POLY 2"	16.0 X 027.0 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Pine View	12	AM POLY 2"	16.0 X 036.0 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Pine View	2	AM POLY 2"	16.2 X 023.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Pine View	2	AM POLY 2"	16.2 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Pine View	33	AM POLY 2"	19.2 X 020.0 X 02.0	\$3.00	\$594.00	\$2.00	\$3.07	\$607.86	\$3.07
Pine View	6	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Pine View	2	AM POLY 2"	20.0 X 023.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Pine View	8	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Pine View	22	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$396.00	\$2.00	\$3.07	\$405.24	\$3.07
Pine View	2	AM POLY 2"	20.0 X 026.2 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Pine View	14	AM POLY 2"	20.0 X 038.0 X 02.0	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07
Pine View	1	AM SLEVE	10.4 X 022.0	\$3.75	\$22.50	\$2.00	\$4.07	\$24.42	\$4.07
Pine View	1	AM SLEVE	11.0 X 022.4	\$3.75	\$22.50	\$2.00	\$4.07	\$24.42	\$4.07
Pine View	1	AM SLEVE	14.2 X 021.2	\$3.75	\$22.50	\$2.00	\$4.00	\$24.00	\$4.00
Pine View	2	WASH-OUT	12.0 X 012.0 X 00.2	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Riverview High	1	AM POLY 1"	10.0 X 061.6 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Riverview High	2	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Riverview High	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Riverview High	12	AM POLY 1"	21.6 X 021.6 X 01.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Riverview High	4	AM POLY 2"	10.2 X 020.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Riverview High	1	AM POLY 2"	12.0 X 024.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.44
Riverview High	14	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$504.00	\$6.00	\$3.15	\$264.60	\$1.60
Riverview High	22	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$792.00	\$6.00	\$3.15	\$415.80	\$1.60
Riverview High	1	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.71
Riverview High	1	AM POLY 2"	16.0 X 021.6 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.73
Riverview High	20	AM POLY 2"	16.0 X 024.0 X 02.0	\$6.00	\$720.00	\$6.00	\$3.15	\$378.00	\$1.92
Riverview High	28	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$1,008.00	\$6.00	\$3.15	\$529.20	\$2.00
Riverview High	6	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.00
Riverview High	146	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$5,256.00	\$6.00	\$3.15	\$2,759.40	\$2.00
Riverview High	1	AM POLY 2"	20.0 X 021.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.14
Riverview High	3	AM POLY 2"	20.0 X 021.6 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.16
Riverview High	6	AM POLY 2"	20.0 X 023.6 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.36
Riverview High	88	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$3,168.00	\$6.00	\$3.15	\$1,663.20	\$2.40
Riverview High	54	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$1,944.00	\$6.00	\$3.15	\$1,020.60	\$2.50
Riverview High	46	AM POLY 2"	24.0 X 024.0 X 02.0	\$6.00	\$1,656.00	\$6.00	\$3.15	\$869.40	\$2.88
Riverview High	2	AM POLY 2"	25.0 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$3.13
Riverview High	9	WASH-OUT	WASH OUT FILTER	\$6.00	\$324.00	\$6.00			
SCTI-Venice	2	AM POLY 1"	14.0 X 028.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.55
SCTI-Venice	6	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.81
SCTI-Venice	7	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$1.19
SCTI-Venice	2	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.38
SCTI-Venice	1	WASH-OUT	10.0 X 016.0 X 00.2	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$7.09
SCTI-Sarasota	1	AM POLY 1"	09.0 X 024.6 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.88
SCTI-Sarasota	6	AM POLY 1"	09.2 X 021.2 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$0.77
SCTI-Sarasota	2	AM POLY 1"	09.2 X 024.4 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$0.89

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Riverview High	1	AM POLY 2"	12.0 X 024.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Riverview High	14	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07
Riverview High	22	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$396.00	\$2.00	\$3.07	\$405.24	\$3.07
Riverview High	1	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Riverview High	1	AM POLY 2"	16.0 X 021.6 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Riverview High	20	AM POLY 2"	16.0 X 024.0 X 02.0	\$3.00	\$360.00	\$2.00	\$3.07	\$368.40	\$3.07
Riverview High	28	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$504.00	\$2.00	\$3.07	\$515.76	\$3.07
Riverview High	6	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Riverview High	146	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$2,628.00	\$2.00	\$3.07	\$2,689.32	\$3.07
Riverview High	1	AM POLY 2"	20.0 X 021.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Riverview High	3	AM POLY 2"	20.0 X 021.6 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Riverview High	6	AM POLY 2"	20.0 X 023.6 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Riverview High	88	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$1,584.00	\$2.00	\$3.07	\$1,620.96	\$3.07
Riverview High	54	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$972.00	\$2.00	\$3.07	\$994.68	\$3.07
Riverview High	46	AM POLY 2"	24.0 X 024.0 X 02.0	\$3.00	\$828.00	\$2.00	\$3.07	\$847.32	\$3.07
Riverview High	2	AM POLY 2"	25.0 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Riverview High	9	WASH-OUT	WASH OUT FILTER	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
SCTI-Venice	2	AM POLY 1"	14.0 X 028.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Venice	6	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
SCTI-Venice	7	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
SCTI-Venice	2	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Venice	1	WASH-OUT	10.0 X 016.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	1	AM POLY 1"	09.0 X 024.6 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	6	AM POLY 1"	09.2 X 021.2 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
SCTI-Sarasota	2	AM POLY 1"	09.2 X 024.4 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
SCTI-Sarasota	1	AM POLY 1"	09.2 X 027.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.99
SCTI-Sarasota	1	AM POLY 1"	09.2 X 031.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.13
SCTI-Sarasota	2	AM POLY 1"	09.2 X 031.2 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.14
SCTI-Sarasota	1	AM POLY 1"	09.2 X 042.5 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.55
SCTI-Sarasota	2	AM POLY 1"	09.2 X 043.6 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.59
SCTI-Sarasota	4	AM POLY 1"	09.2 X 046.2 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.68
SCTI-Sarasota	6	AM POLY 1"	09.2 X 068.2 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.48
SCTI-Sarasota	6	AM POLY 1"	09.2 X 080.2 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.92
SCTI-Sarasota	6	AM POLY 1"	09.3 X 030.4 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.12
SCTI-Sarasota	2	AM POLY 1"	09.4 X 021.6 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$0.80
SCTI-Sarasota	2	AM POLY 1"	09.4 X 024.6 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$0.92
SCTI-Sarasota	2	AM POLY 1"	09.4 X 032.6 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.21
SCTI-Sarasota	1	AM POLY 1"	09.4 X 034.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.27
SCTI-Sarasota	1	AM POLY 1"	09.7 X 035.7 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.37
SCTI-Sarasota	16	AM POLY 1"	10.4 X 037.0 X 01.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$1.52
SCTI-Sarasota	2	AM POLY 1"	10.4 X 049.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.02
SCTI-Sarasota	5	AM POLY 1"	10.4 X 061.0 X 01.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$2.51
SCTI-Sarasota	1	AM POLY 1"	10.4 X 073.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$3.01
SCTI-Sarasota	3	AM POLY 1"	11.4 X 046.0 X 01.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.08
SCTI-Sarasota	10	AM POLY 1"	11.4 X 066.0 X 01.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$2.98
SCTI-Sarasota	3	AM POLY 1"	11.4 X 066.0 X 01.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.98
SCTI-Sarasota	5	AM POLY 1"	11.4 X 086.0 X 01.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$3.88
SCTI-Sarasota	2	AM POLY 1"	12.0 X 020.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$0.95
SCTI-Sarasota	4	AM POLY 1"	14.4 X 033.0 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.88
SCTI-Sarasota	8	AM POLY 1"	14.4 X 044.0 X 01.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.51

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
SCTI-Sarasota	1	AM POLY 1"	09.2 X 027.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	1	AM POLY 1"	09.2 X 031.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	2	AM POLY 1"	09.2 X 031.2 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	1	AM POLY 1"	09.2 X 042.5 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	2	AM POLY 1"	09.2 X 043.6 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	4	AM POLY 1"	09.2 X 046.2 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
SCTI-Sarasota	6	AM POLY 1"	09.2 X 068.2 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
SCTI-Sarasota	6	AM POLY 1"	09.2 X 080.2 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
SCTI-Sarasota	6	AM POLY 1"	09.3 X 030.4 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
SCTI-Sarasota	2	AM POLY 1"	09.4 X 021.6 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	2	AM POLY 1"	09.4 X 024.6 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	2	AM POLY 1"	09.4 X 032.6 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	1	AM POLY 1"	09.4 X 034.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	1	AM POLY 1"	09.7 X 035.7 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	16	AM POLY 1"	10.4 X 037.0 X 01.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07
SCTI-Sarasota	2	AM POLY 1"	10.4 X 049.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	5	AM POLY 1"	10.4 X 061.0 X 01.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
SCTI-Sarasota	1	AM POLY 1"	10.4 X 073.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	3	AM POLY 1"	11.4 X 046.0 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
SCTI-Sarasota	10	AM POLY 1"	11.4 X 066.0 X 01.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
SCTI-Sarasota	3	AM POLY 1"	11.4 X 066.0 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
SCTI-Sarasota	5	AM POLY 1"	11.4 X 086.0 X 01.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
SCTI-Sarasota	2	AM POLY 1"	12.0 X 020.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	4	AM POLY 1"	14.4 X 033.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
SCTI-Sarasota	8	AM POLY 1"	14.4 X 044.0 X 01.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
SCTI-Sarasota	4	AM POLY 1"	14.4 X 055.0 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$3.14
SCTI-Sarasota	33	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$1,188.00	\$6.00	\$3.15	\$623.70	\$1.81
SCTI-Sarasota	1	AM POLY 1"	15.6 X 078.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$4.82
SCTI-Sarasota	6	AM POLY 1"	16.0 X 025.0 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.58
SCTI-Sarasota	15	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$540.00	\$6.00	\$3.15	\$283.50	\$1.90
SCTI-Sarasota	2	AM POLY 1"	16.2 X 066.4 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$4.26
SCTI-Sarasota	1	AM POLY 1"	17.0 X 025.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.68
SCTI-Sarasota	1	AM POLY 1"	18.2 X 036.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.61
SCTI-Sarasota	2	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.58
SCTI-Sarasota	2	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.38
SCTI-Sarasota	4	AM POLY 1"	22.0 X 022.0 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.92
SCTI-Sarasota	8	AM POLY 2"	10.4 X 024.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.25
SCTI-Sarasota	1	AM POLY 2"	10.6 X 016.2 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.86
SCTI-Sarasota	1	AM POLY 2"	10.6 X 020.2 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.07
SCTI-Sarasota	1	AM POLY 2"	12.0 X 012.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.72
SCTI-Sarasota	1	AM POLY 2"	12.0 X 016.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.96
SCTI-Sarasota	6	AM POLY 2"	15.0 X 020.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.50
SCTI-Sarasota	2	AM POLY 2"	15.0 X 021.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.62
SCTI-Sarasota	42	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$1,512.00	\$6.00	\$3.15	\$793.80	\$1.60
SCTI-Sarasota	10	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$1.71
SCTI-Sarasota	20	AM POLY 2"	16.0 X 023.4 X 02.0	\$6.00	\$720.00	\$6.00	\$3.15	\$378.00	\$1.87
SCTI-Sarasota	50	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$1,800.00	\$6.00	\$3.15	\$945.00	\$2.00
SCTI-Sarasota	8	AM POLY 2"	16.0 X 025.4 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.03
SCTI-Sarasota	8	AM POLY 2"	16.0 X 027.4 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.19
SCTI-Sarasota	3	AM POLY 2"	16.2 X 018.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.46

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
SCTI-Sarasota	4	AM POLY 1"	14.4 X 055.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
SCTI-Sarasota	33	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$594.00	\$2.00	\$3.07	\$607.86	\$3.07
SCTI-Sarasota	1	AM POLY 1"	15.6 X 078.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	6	AM POLY 1"	16.0 X 025.0 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
SCTI-Sarasota	15	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$270.00	\$2.00	\$3.07	\$276.30	\$3.07
SCTI-Sarasota	2	AM POLY 1"	16.2 X 066.4 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	1	AM POLY 1"	17.0 X 025.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	1	AM POLY 1"	18.2 X 036.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	2	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	2	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	4	AM POLY 1"	22.0 X 022.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
SCTI-Sarasota	8	AM POLY 2"	10.4 X 024.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
SCTI-Sarasota	1	AM POLY 2"	10.6 X 016.2 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	1	AM POLY 2"	10.6 X 020.2 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	1	AM POLY 2"	12.0 X 012.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	1	AM POLY 2"	12.0 X 016.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	6	AM POLY 2"	15.0 X 020.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
SCTI-Sarasota	2	AM POLY 2"	15.0 X 021.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	42	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$756.00	\$2.00	\$3.07	\$773.64	\$3.07
SCTI-Sarasota	10	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
SCTI-Sarasota	20	AM POLY 2"	16.0 X 023.4 X 02.0	\$3.00	\$360.00	\$2.00	\$3.07	\$368.40	\$3.07
SCTI-Sarasota	50	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$900.00	\$2.00	\$3.07	\$921.00	\$3.07
SCTI-Sarasota	8	AM POLY 2"	16.0 X 025.4 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
SCTI-Sarasota	8	AM POLY 2"	16.0 X 027.4 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
SCTI-Sarasota	3	AM POLY 2"	16.2 X 018.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
SCTI-Sarasota	6	AM POLY 2"	17.4 X 020.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.74
SCTI-Sarasota	3	AM POLY 2"	18.0 X 020.2 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.82
SCTI-Sarasota	1	AM POLY 2"	19.4 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.43
SCTI-Sarasota	24	AM POLY 2"	20.0 X 020.0 X 02.0	\$5.00	\$720.00	\$5.00	\$3.15	\$453.60	\$2.00
SCTI-Sarasota	2	AM POLY 2"	20.0 X 021.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.14
SCTI-Sarasota	17	AM POLY 2"	20.0 X 024.0 X 02.0	\$5.00	\$510.00	\$5.00	\$3.15	\$321.30	\$2.40
SCTI-Sarasota	48	AM POLY 2"	20.0 X 025.0 X 02.0	\$5.00	\$1,440.00	\$5.00	\$3.15	\$907.20	\$2.50
SCTI-Sarasota	2	AM POLY 2"	20.0 X 027.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.74
SCTI-Sarasota	1	AM POLY 2"	20.0 X 044.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$4.40
SCTI-Sarasota	4	AM POLY 2"	21.0 X 024.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.52
SCTI-Sarasota	44	AM POLY 2"	24.0 X 024.0 X 02.0	\$5.00	\$1,320.00	\$5.00	\$3.15	\$831.60	\$2.88
SCTI-Sarasota	1	AM POLY 1/2"	09.0 X 018.0 X 00.2	\$3.00	\$18.00	\$3.00	\$3.15	\$18.90	\$0.64
SCTI-Sarasota	1	AM POLY 1/2"	11.0 X 018.0 X 00.4	\$3.00	\$18.00	\$3.00	\$3.15	\$18.90	\$0.78
SCTI-Sarasota	1	AM POLY 1/2"	11.0 X 019.0 X 00.2	\$3.00	\$18.00	\$3.00	\$3.15	\$18.90	\$0.83
SCTI-Sarasota	1	AM SLEVE	09.2 X 033.0	\$7.00	\$42.00	\$7.00	\$3.15	\$18.90	\$1.67
SCTI-Sarasota	2	AM SLEVE	09.2 X 045.0	\$8.00	\$96.00	\$8.00	\$3.15	\$37.80	\$1.67
SCTI-Sarasota	1	AM SLEVE	20.4 X 022.6	\$11.00	\$66.00	\$11.00	\$3.15	\$18.90	\$1.92
SCTI-Sarasota	2	WASH-OUT	10.0 X 016.0 X 00.5	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$7.09
SCTI-Sarasota	1	WASH-OUT	10.0 X 017.0 X 00.2	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$7.09
SCTI-Sarasota	2	WASH-OUT	12.0 X 014.0 X 00.2	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$7.09
SCTI-Sarasota	2	WASH-OUT	12.0 X 014.0 X 00.4	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$7.09
SCTI-Sarasota	2	WASH-OUT	12.0 X 016.4 X 00.2	\$5.00	\$60.00	\$8.00	\$3.15	\$37.80	\$7.09
SCTI-Sarasota	1	WASH-OUT	12.0 X 018.0 X 00.5	\$5.00	\$30.00	\$8.00	\$3.15	\$18.90	\$10.08
SCTI-Sarasota	12	WASH-OUT	12.0 X 030.0 X 00.4	\$5.00	\$360.00	\$10.00	\$3.15	\$226.80	\$13.07
Sarasota High	14	AM POLY 1"	10.0 X 073.0 X 01.0	\$8.00	\$672.00	\$8.00	\$3.15	\$264.60	\$2.89

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
SCTI-Sarasota	6	AM POLY 2"	17.4 X 020.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
SCTI-Sarasota	3	AM POLY 2"	18.0 X 020.2 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
SCTI-Sarasota	1	AM POLY 2"	19.4 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	24	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$432.00	\$2.00	\$3.07	\$442.08	\$3.07
SCTI-Sarasota	2	AM POLY 2"	20.0 X 021.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	17	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$306.00	\$2.00	\$3.07	\$313.14	\$3.07
SCTI-Sarasota	48	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$864.00	\$2.00	\$3.07	\$884.16	\$3.07
SCTI-Sarasota	2	AM POLY 2"	20.0 X 027.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	1	AM POLY 2"	20.0 X 044.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	4	AM POLY 2"	21.0 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
SCTI-Sarasota	44	AM POLY 2"	24.0 X 024.0 X 02.0	\$3.00	\$792.00	\$2.00	\$3.07	\$810.48	\$3.07
SCTI-Sarasota	1	AM POLY 1/2"	09.0 X 018.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	1	AM POLY 1/2"	11.0 X 018.0 X 00.4	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	1	AM POLY 1/2"	11.0 X 019.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	1	AM SLEVE	09.2 X 033.0	\$3.75	\$22.50	\$2.00	\$5.10	\$30.60	\$5.10
SCTI-Sarasota	2	AM SLEVE	09.2 X 045.0	\$3.75	\$45.00	\$2.00	\$6.23	\$74.76	\$6.23
SCTI-Sarasota	1	AM SLEVE	20.4 X 022.6	\$3.75	\$22.50	\$2.00	\$4.80	\$28.80	\$4.80
SCTI-Sarasota	2	WASH-OUT	10.0 X 016.0 X 00.5	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	1	WASH-OUT	10.0 X 017.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	2	WASH-OUT	12.0 X 014.0 X 00.2	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	2	WASH-OUT	12.0 X 014.0 X 00.4	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	2	WASH-OUT	12.0 X 016.4 X 00.2	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
SCTI-Sarasota	1	WASH-OUT	12.0 X 018.0 X 00.5	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
SCTI-Sarasota	12	WASH-OUT	12.0 X 030.0 X 00.4	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Sarasota High	14	AM POLY 1"	10.0 X 073.0 X 01.0	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Sarasota High	2	AM POLY 1"	10.2 X 023.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$0.93
Sarasota High	2	AM POLY 1"	10.2 X 025.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.01
Sarasota High	1	AM POLY 1"	10.2 X 063.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.55
Sarasota High	4	AM POLY 1"	10.4 X 037.0 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.52
Sarasota High	3	AM POLY 1"	10.4 X 073.0 X 01.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$3.01
Sarasota High	1	AM POLY 1"	11.4 X 046.6 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.10
Sarasota High	1	AM POLY 1"	11.6 X 021.6 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.99
Sarasota High	4	AM POLY 1"	12.2 X 012.2 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$0.59
Sarasota High	2	AM POLY 1"	12.2 X 024.2 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.17
Sarasota High	2	AM POLY 1"	14.0 X 025.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.39
Sarasota High	14	AM POLY 1"	15.0 X 030.2 X 01.0	\$6.00	\$504.00	\$6.00	\$3.15	\$264.60	\$1.79
Sarasota High	7	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$1.81
Sarasota High	1	AM POLY 1"	15.6 X 066.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$4.08
Sarasota High	3	AM POLY 1"	15.6 X 078.0 X 01.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$4.82
Sarasota High	1	AM POLY 1"	16.0 X 020.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.28
Sarasota High	4	AM POLY 1"	16.0 X 025.0 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.58
Sarasota High	11	AM POLY 1"	16.0 X 025.0 X 01.0	\$6.00	\$396.00	\$6.00	\$3.15	\$207.90	\$1.58
Sarasota High	10	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$1.90
Sarasota High	2	AM POLY 1"	16.2 X 028.3 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.81
Sarasota High	1	AM POLY 1"	16.6 X 025.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.64
Sarasota High	1	AM POLY 1"	16.6 X 030.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.97
Sarasota High	2	AM POLY 1"	17.4 X 025.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.72
Sarasota High	1	AM POLY 1"	20.0 X 022.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.74
Sarasota High	2	AM POLY 1"	20.0 X 022.2 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.76
Sarasota High	5	AM POLY 1"	20.0 X 025.0 X 01.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$1.98

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Sarasota High	2	AM POLY 1"	10.2 X 023.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	2	AM POLY 1"	10.2 X 025.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	1	AM POLY 1"	10.2 X 063.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	4	AM POLY 1"	10.4 X 037.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Sarasota High	3	AM POLY 1"	10.4 X 073.0 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Sarasota High	1	AM POLY 1"	11.4 X 046.6 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	1	AM POLY 1"	11.6 X 021.6 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	4	AM POLY 1"	12.2 X 012.2 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Sarasota High	2	AM POLY 1"	12.2 X 024.2 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	2	AM POLY 1"	14.0 X 025.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	14	AM POLY 1"	15.0 X 030.2 X 01.0	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07
Sarasota High	7	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Sarasota High	1	AM POLY 1"	15.6 X 066.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	3	AM POLY 1"	15.6 X 078.0 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Sarasota High	1	AM POLY 1"	16.0 X 020.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	4	AM POLY 1"	16.0 X 025.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Sarasota High	11	AM POLY 1"	16.0 X 025.0 X 01.0	\$3.00	\$198.00	\$2.00	\$3.07	\$202.62	\$3.07
Sarasota High	10	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Sarasota High	2	AM POLY 1"	16.2 X 028.3 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	1	AM POLY 1"	16.6 X 025.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	1	AM POLY 1"	16.6 X 030.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	2	AM POLY 1"	17.4 X 025.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	1	AM POLY 1"	20.0 X 022.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	2	AM POLY 1"	20.0 X 022.2 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	5	AM POLY 1"	20.0 X 025.0 X 01.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Sarasota High	10	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$2.35
Sarasota High	4	AM POLY 1"	21.6 X 021.6 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.85
Sarasota High	3	AM POLY 1"	21.6 X 032.5 X 01.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.78
Sarasota High	1	AM POLY 1"	23.6 X 035.6 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$3.33
Sarasota High	1	AM POLY 2"	04.6 X 016.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.37
Sarasota High	10	AM POLY 2"	09.2 X 024.0 X 02.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$1.10
Sarasota High	4	AM POLY 2"	09.4 X 016.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$0.75
Sarasota High	1	AM POLY 2"	10.2 X 016.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.82
Sarasota High	2	AM POLY 2"	11.6 X 020.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.16
Sarasota High	2	AM POLY 2"	12.0 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.50
Sarasota High	1	AM POLY 2"	13.5 X 019.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.31
Sarasota High	5	AM POLY 2"	13.5 X 020.0 X 02.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$1.35
Sarasota High	2	AM POLY 2"	13.5 X 024.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.62
Sarasota High	6	AM POLY 2"	13.6 X 016.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.09
Sarasota High	1	AM POLY 2"	13.6 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.36
Sarasota High	3	AM POLY 2"	14.0 X 024.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.68
Sarasota High	1	AM POLY 2"	14.2 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.42
Sarasota High	1	AM POLY 2"	14.2 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.78
Sarasota High	4	AM POLY 2"	15.6 X 020.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.56
Sarasota High	4	AM POLY 2"	16.0 X 016.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.28
Sarasota High	2	AM POLY 2"	16.0 X 018.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.47
Sarasota High	31	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$1,116.00	\$6.00	\$3.15	\$585.90	\$1.60
Sarasota High	6	AM POLY 2"	16.0 X 021.2 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.70
Sarasota High	7	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$1.71
Sarasota High	7	AM POLY 2"	16.0 X 023.0 X 02.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$1.84

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Sarasota High	10	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Sarasota High	4	AM POLY 1"	21.6 X 021.6 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Sarasota High	3	AM POLY 1"	21.6 X 032.5 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Sarasota High	1	AM POLY 1"	23.6 X 035.6 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	1	AM POLY 2"	04.6 X 016.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	10	AM POLY 2"	09.2 X 024.0 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Sarasota High	4	AM POLY 2"	09.4 X 016.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Sarasota High	1	AM POLY 2"	10.2 X 016.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	2	AM POLY 2"	11.6 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	2	AM POLY 2"	12.0 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	1	AM POLY 2"	13.5 X 019.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	5	AM POLY 2"	13.5 X 020.0 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Sarasota High	2	AM POLY 2"	13.5 X 024.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	6	AM POLY 2"	13.6 X 016.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Sarasota High	1	AM POLY 2"	13.6 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	3	AM POLY 2"	14.0 X 024.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Sarasota High	1	AM POLY 2"	14.2 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	1	AM POLY 2"	14.2 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	4	AM POLY 2"	15.6 X 020.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Sarasota High	4	AM POLY 2"	16.0 X 016.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Sarasota High	2	AM POLY 2"	16.0 X 018.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	31	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$558.00	\$2.00	\$3.07	\$571.02	\$3.07
Sarasota High	6	AM POLY 2"	16.0 X 021.2 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Sarasota High	7	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Sarasota High	7	AM POLY 2"	16.0 X 023.0 X 02.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Sarasota High	3	AM POLY 2"	16.0 X 023.2 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.86
Sarasota High	2	AM POLY 2"	16.0 X 024.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.92
Sarasota High	32	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$1,152.00	\$6.00	\$3.15	\$604.80	\$2.00
Sarasota High	2	AM POLY 2"	16.0 X 025.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.03
Sarasota High	2	AM POLY 2"	16.0 X 027.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.21
Sarasota High	4	AM POLY 2"	16.0 X 030.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.40
Sarasota High	2	AM POLY 2"	16.0 X 036.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.91
Sarasota High	1	AM POLY 2"	16.1 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.01
Sarasota High	1	AM POLY 2"	16.1 X 026.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.13
Sarasota High	2	AM POLY 2"	16.4 X 024.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.97
Sarasota High	2	AM POLY 2"	17.4 X 020.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.74
Sarasota High	2	AM POLY 2"	18.0 X 020.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.80
Sarasota High	2	AM POLY 2"	18.6 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.33
Sarasota High	4	AM POLY 2"	19.4 X 025.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.43
Sarasota High	49	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$1,764.00	\$6.00	\$3.15	\$926.10	\$2.00
Sarasota High	2	AM POLY 2"	20.0 X 021.2 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.12
Sarasota High	2	AM POLY 2"	20.0 X 021.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.16
Sarasota High	1	AM POLY 2"	20.0 X 023.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.30
Sarasota High	65	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$2,340.00	\$6.00	\$3.15	\$1,228.50	\$2.40
Sarasota High	31	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$1,116.00	\$6.00	\$3.15	\$585.90	\$2.50
Sarasota High	1	AM POLY 2"	20.0 X 025.3 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.53
Sarasota High	1	AM POLY 2"	20.0 X 037.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$3.74
Sarasota High	9	AM POLY 2"	20.2 X 025.0 X 02.0	\$6.00	\$324.00	\$6.00	\$3.15	\$170.10	\$2.53
Sarasota High	8	AM POLY 2"	24.0 X 024.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.88
Sarasota High	1	AM POLY 2"	24.0 X 025.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$3.05

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Sarasota High	3	AM POLY 2"	16.0 X 023.2 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Sarasota High	2	AM POLY 2"	16.0 X 024.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	32	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$576.00	\$2.00	\$3.07	\$589.44	\$3.07
Sarasota High	2	AM POLY 2"	16.0 X 025.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	2	AM POLY 2"	16.0 X 027.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	4	AM POLY 2"	16.0 X 030.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Sarasota High	2	AM POLY 2"	16.0 X 036.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	1	AM POLY 2"	16.1 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	1	AM POLY 2"	16.1 X 026.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	2	AM POLY 2"	16.4 X 024.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	2	AM POLY 2"	17.4 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	2	AM POLY 2"	18.0 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	2	AM POLY 2"	18.6 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	4	AM POLY 2"	19.4 X 025.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Sarasota High	49	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$882.00	\$2.00	\$3.07	\$902.58	\$3.07
Sarasota High	2	AM POLY 2"	20.0 X 021.2 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	2	AM POLY 2"	20.0 X 021.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota High	1	AM POLY 2"	20.0 X 023.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	65	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$1,170.00	\$2.00	\$3.07	\$1,197.30	\$3.07
Sarasota High	31	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$558.00	\$2.00	\$3.07	\$571.02	\$3.07
Sarasota High	1	AM POLY 2"	20.0 X 025.3 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	1	AM POLY 2"	20.0 X 037.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	9	AM POLY 2"	20.2 X 025.0 X 02.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Sarasota High	8	AM POLY 2"	24.0 X 024.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Sarasota High	1	AM POLY 2"	24.0 X 025.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Sarasota High	1	AM POLY 1/2"	11.0 X 017.4 X 00.2	\$3.00	\$18.00	\$3.00	\$3.15	\$18.90	\$0.76
Sarasota High	2	AM SLEVE	10.4 X 073.0	\$12.00	\$144.00	\$12.00	\$3.15	\$37.80	\$2.94
Sarasota High	4	WASH-OUT	11.0 X 011.0 X 00.2	\$5.00	\$120.00	\$5.00	\$3.15	\$75.60	\$7.09
Sarasota High	4	WASH-OUT	12.0 X 020.0 X 00.2	\$5.00	\$120.00	\$5.00	\$3.15	\$75.60	\$10.08
Sarasota Middle	1	AM POLY 1"	14.2 X 015.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.84
Sarasota Middle	2	AM POLY 1"	14.2 X 020.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.12
Sarasota Middle	1	AM POLY 1"	14.2 X 024.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.35
Sarasota Middle	6	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.81
Sarasota Middle	2	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.90
Sarasota Middle	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.58
Sarasota Middle	2	AM POLY 2"	14.0 X 020.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.40
Sarasota Middle	1	AM POLY 2"	14.0 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.75
Sarasota Middle	1	AM POLY 2"	14.4 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.80
Sarasota Middle	1	AM POLY 2"	15.0 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.50
Sarasota Middle	2	AM POLY 2"	16.0 X 017.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.36
Sarasota Middle	7	AM POLY 2"	16.0 X 018.0 X 02.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$1.44
Sarasota Middle	44	AM POLY 2"	16.0 X 020.0 X 02.0	\$5.00	\$1,320.00	\$5.00	\$3.15	\$831.60	\$1.60
Sarasota Middle	1	AM POLY 2"	16.0 X 020.2 X 02.0	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$1.62
Sarasota Middle	4	AM POLY 2"	16.0 X 023.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.84
Sarasota Middle	30	AM POLY 2"	16.0 X 024.0 X 02.0	\$5.00	\$900.00	\$5.00	\$3.15	\$567.00	\$1.92
Sarasota Middle	4	AM POLY 2"	16.0 X 025.0 X 02.0	\$5.00	\$120.00	\$5.00	\$3.15	\$75.60	\$2.00
Sarasota Middle	10	AM POLY 2"	16.0 X 027.4 X 02.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$2.19
Sarasota Middle	4	AM POLY 2"	16.0 X 028.7 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.30
Sarasota Middle	6	AM POLY 2"	18.0 X 020.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.80
Sarasota Middle	1	AM POLY 2"	18.4 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.84

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Sarasota High	1	AM POLY 1/2"	11.0 X 017.4 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota High	2	AM SLEVE	10.4 X 073.0	\$3.75	\$45.00	\$2.00	\$8.85	\$106.20	\$8.85
Sarasota High	4	WASH-OUT	11.0 X 011.0 X 00.2	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Sarasota High	4	WASH-OUT	12.0 X 020.0 X 00.2	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Sarasota Middle	1	AM POLY 1"	14.2 X 015.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota Middle	2	AM POLY 1"	14.2 X 020.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota Middle	1	AM POLY 1"	14.2 X 024.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota Middle	6	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Sarasota Middle	2	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota Middle	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota Middle	2	AM POLY 2"	14.0 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota Middle	1	AM POLY 2"	14.0 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota Middle	1	AM POLY 2"	14.4 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota Middle	1	AM POLY 2"	15.0 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota Middle	2	AM POLY 2"	16.0 X 017.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota Middle	7	AM POLY 2"	16.0 X 018.0 X 02.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Sarasota Middle	44	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$792.00	\$2.00	\$3.07	\$810.48	\$3.07
Sarasota Middle	1	AM POLY 2"	16.0 X 020.2 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota Middle	4	AM POLY 2"	16.0 X 023.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Sarasota Middle	30	AM POLY 2"	16.0 X 024.0 X 02.0	\$3.00	\$540.00	\$2.00	\$3.07	\$552.60	\$3.07
Sarasota Middle	4	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Sarasota Middle	10	AM POLY 2"	16.0 X 027.4 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Sarasota Middle	4	AM POLY 2"	16.0 X 028.7 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Sarasota Middle	6	AM POLY 2"	18.0 X 020.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Sarasota Middle	1	AM POLY 2"	18.4 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Sarasota Middle	6	AM POLY 2"	20.0 X 020.0 X 02.0	\$5.00	\$180.00	\$5.00	\$3.15	\$113.40	\$2.00
Sarasota Middle	24	AM POLY 2"	20.0 X 024.0 X 02.0	\$5.00	\$720.00	\$5.00	\$3.15	\$453.60	\$2.40
Sarasota Middle	18	AM POLY 2"	20.0 X 025.0 X 02.0	\$5.00	\$540.00	\$5.00	\$3.15	\$340.20	\$2.50
Sarasota Middle	2	AM POLY 2"	20.0 X 027.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.74
Sarasota Middle	1	AM POLY 2"	20.0 X 030.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$3.04
Sarasota Middle	2	MERV 8 SC PLEAT	24.0 X 024.0 X 01.0	\$6.00	\$72.00	\$6.00	\$5.57	\$66.84	\$3.57
Sarasota Middle	2	MERV 8 SC PLEAT	22.0 X 022.0 X 02.0	\$11.00	\$132.00	\$11.00	\$8.46	\$101.52	\$6.46
Sarasota Middle	2	CHARCOAL PLEAT	24.0 X 024.0 X 01.0	\$19.00	\$228.00	\$19.00	\$6.99	\$83.88	\$4.99
Sarasota Middle	4	WASH-OUT	10.0 X 012.0 X 00.4	\$5.00	\$120.00	\$10.00	\$3.15	\$75.60	\$7.09
Sheriff Driver Training Portable	1	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.38
Southside Elementary	29	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$1,044.00	\$6.00	\$3.15	\$548.10	\$1.60
Southside Elementary	4	AM POLY 2"	16.0 X 020.6 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.65
Southside Elementary	4	AM POLY 2"	16.0 X 021.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.68
Southside Elementary	2	AM POLY 2"	16.0 X 021.2 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.70
Southside Elementary	6	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.00
Southside Elementary	5	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$2.00
Southside Elementary	2	AM POLY 2"	20.0 X 021.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.14
Southside Elementary	14	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$504.00	\$6.00	\$3.15	\$264.60	\$2.50
Southside Elementary	61	MERV 8 SC PLEAT	12.0 X 024.0 X 02.0	\$6.00	\$2,196.00	\$6.00	\$4.04	\$1,478.64	\$2.04
Southside Elementary	4	MERV 8 SC PLEAT	16.0 X 020.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.93	\$94.32	\$1.93
Southside Elementary	4	MERV 8 SC PLEAT	20.0 X 020.0 X 02.0	\$7.00	\$168.00	\$7.00	\$4.21	\$101.04	\$2.21
Suncoast Polytechnical High	2	AM POLY 2"	12.0 X 024.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.44
Suncoast Polytechnical High	16	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$1.60
Suncoast Polytechnical High	3	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.00
Suncoast Polytechnical High	9	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$324.00	\$6.00	\$3.15	\$170.10	\$2.00

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Sarasota Middle	6	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Sarasota Middle	24	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$432.00	\$2.00	\$3.07	\$442.08	\$3.07
Sarasota Middle	18	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$324.00	\$2.00	\$3.07	\$331.56	\$3.07
Sarasota Middle	2	AM POLY 2"	20.0 X 027.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Sarasota Middle	1	AM POLY 2"	20.0 X 030.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Sarasota Middle	2	MERV 8 SC PLEAT	24.0 X 024.0 X 01.0	\$5.49	\$65.88	\$2.00	\$5.00	\$60.00	\$5.00
Sarasota Middle	2	MERV 8 SC PLEAT	22.0 X 022.0 X 02.0	\$7.08	\$84.96	\$2.00	\$5.00	\$60.00	\$5.00
Sarasota Middle	2	CHARCOAL PLEAT	24.0 X 024.0 X 01.0	\$13.75	\$165.00	\$2.00	\$13.15	\$157.80	\$13.15
Sarasota Middle	4	WASH-OUT	10.0 X 012.0 X 00.4	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Sheriff Driver Training Portable	1	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Southside Elementary	29	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$522.00	\$2.00	\$3.07	\$534.18	\$3.07
Southside Elementary	4	AM POLY 2"	16.0 X 020.6 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Southside Elementary	4	AM POLY 2"	16.0 X 021.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Southside Elementary	2	AM POLY 2"	16.0 X 021.2 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Southside Elementary	6	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Southside Elementary	5	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Southside Elementary	2	AM POLY 2"	20.0 X 021.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Southside Elementary	14	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07
Southside Elementary	61	MERV 8 SC PLEAT	12.0 X 024.0 X 02.0	\$4.75	\$1,738.50	\$2.00	\$5.00	\$1,830.00	\$5.00
Southside Elementary	4	MERV 8 SC PLEAT	16.0 X 020.0 X 02.0	\$4.94	\$118.56	\$2.00	\$5.00	\$120.00	\$5.00
Southside Elementary	4	MERV 8 SC PLEAT	20.0 X 020.0 X 02.0	\$5.24	\$125.76	\$2.00	\$5.00	\$120.00	\$5.00
Suncoast Polytechnical High	2	AM POLY 2"	12.0 X 024.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Suncoast Polytechnical High	16	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07
Suncoast Polytechnical High	3	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Suncoast Polytechnical High	9	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Suncoast Polytechnical High	21	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$756.00	\$6.00	\$3.15	\$396.90	\$2.40
Suncoast Polytechnical High	5	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$2.50
Suncoast Polytechnical High	9	AM POLY 2"	24.0 X 024.0 X 02.0	\$6.00	\$324.00	\$6.00	\$3.15	\$170.10	\$2.88
Tatum Ridge Elementary	9	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$324.00	\$6.00	\$3.15	\$170.10	\$1.90
Tatum Ridge Elementary	1	AM POLY 1"	16.2 X 030.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.94
Tatum Ridge Elementary	10	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$2.38
Tatum Ridge Elementary	8	AM POLY 2"	10.2 X 024.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.22
Tatum Ridge Elementary	4	AM POLY 2"	10.4 X 024.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.25
Tatum Ridge Elementary	1	AM POLY 2"	13.4 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.68
Tatum Ridge Elementary	20	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$720.00	\$6.00	\$3.15	\$378.00	\$1.60
Tatum Ridge Elementary	8	AM POLY 2"	16.0 X 021.2 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.70
Tatum Ridge Elementary	6	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.71
Tatum Ridge Elementary	18	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$648.00	\$6.00	\$3.15	\$340.20	\$2.00
Tatum Ridge Elementary	4	AM POLY 2"	16.0 X 025.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.03
Tatum Ridge Elementary	1	AM POLY 2"	17.4 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.18
Tatum Ridge Elementary	5	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$2.00
Tatum Ridge Elementary	1	AM POLY 2"	20.0 X 021.2 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.12
Tatum Ridge Elementary	2	AM POLY 2"	20.0 X 021.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.14
Tatum Ridge Elementary	3	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.50
Tatum Ridge Elementary	1	AM POLY 2"	20.0 X 027.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.74
Tatum Ridge Elementary	8	AM POLY 2"	21.0 X 024.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.52
Tatum Ridge Elementary	72	AM POLY 2"	24.0 X 024.0 X 02.0	\$6.00	\$2,592.00	\$6.00	\$3.15	\$1,360.80	\$2.88
Tatum Ridge Elementary	1	AM POLY 2"	25.0 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$3.13
Tatum Ridge Elementary	4	WASH-OUT	11.0 X 028.0 X 00.4	\$5.00	\$120.00	\$15.00	\$3.15	\$75.60	\$13.07
Tatum Ridge Elementary	2	WASH-OUT	11.0 X 037.0 X 00.4	\$5.00	\$60.00	\$10.00	\$3.15	\$37.80	\$15.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Suncoast Polytechnical High	21	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$378.00	\$2.00	\$3.07	\$386.82	\$3.07
Suncoast Polytechnical High	5	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Suncoast Polytechnical High	9	AM POLY 2"	24.0 X 024.0 X 02.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Tatum Ridge Elementary	9	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Tatum Ridge Elementary	1	AM POLY 1"	16.2 X 030.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Tatum Ridge Elementary	10	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Tatum Ridge Elementary	8	AM POLY 2"	10.2 X 024.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Tatum Ridge Elementary	4	AM POLY 2"	10.4 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Tatum Ridge Elementary	1	AM POLY 2"	13.4 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Tatum Ridge Elementary	20	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$360.00	\$2.00	\$3.07	\$368.40	\$3.07
Tatum Ridge Elementary	8	AM POLY 2"	16.0 X 021.2 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Tatum Ridge Elementary	6	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Tatum Ridge Elementary	18	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$324.00	\$2.00	\$3.07	\$331.56	\$3.07
Tatum Ridge Elementary	4	AM POLY 2"	16.0 X 025.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Tatum Ridge Elementary	1	AM POLY 2"	17.4 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Tatum Ridge Elementary	5	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Tatum Ridge Elementary	1	AM POLY 2"	20.0 X 021.2 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Tatum Ridge Elementary	2	AM POLY 2"	20.0 X 021.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Tatum Ridge Elementary	3	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Tatum Ridge Elementary	1	AM POLY 2"	20.0 X 027.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Tatum Ridge Elementary	8	AM POLY 2"	21.0 X 024.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Tatum Ridge Elementary	72	AM POLY 2"	24.0 X 024.0 X 02.0	\$3.00	\$1,296.00	\$2.00	\$3.07	\$1,326.24	\$3.07
Tatum Ridge Elementary	1	AM POLY 2"	25.0 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Tatum Ridge Elementary	4	WASH-OUT	11.0 X 028.0 X 00.4	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Tatum Ridge Elementary	2	WASH-OUT	11.0 X 037.0 X 00.4	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Tatum Ridge Elementary	2	WASH-OUT	13.0 X 013.0 X 00.4	\$5.00	\$60.00	\$10.00	\$3.15	\$37.80	\$7.09
Taylor Ranch Elementary	4	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.90
Taylor Ranch Elementary	10	AM POLY 1"	16.2 X 030.2 X 01.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$1.94
Taylor Ranch Elementary	11	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$396.00	\$6.00	\$3.15	\$207.90	\$2.38
Taylor Ranch Elementary	18	AM POLY 1"	21.6 X 021.6 X 01.0	\$6.00	\$648.00	\$6.00	\$3.15	\$340.20	\$1.85
Taylor Ranch Elementary	2	AM POLY 1"	22.0 X 022.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.92
Taylor Ranch Elementary	2	AM POLY 1"	24.0 X 024.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.28
Taylor Ranch Elementary	7	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$1.60
Taylor Ranch Elementary	2	AM POLY 2"	16.0 X 020.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.65
Taylor Ranch Elementary	2	AM POLY 2"	16.0 X 025.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.03
Taylor Ranch Elementary	6	AM POLY 2"	16.0 X 026.4 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.11
Taylor Ranch Elementary	14	AM POLY 2"	16.0 X 027.4 X 02.0	\$6.00	\$504.00	\$6.00	\$3.15	\$264.60	\$2.19
Taylor Ranch Elementary	3	AM POLY 2"	17.2 X 025.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.15
Taylor Ranch Elementary	5	AM POLY 2"	17.4 X 025.0 X 02.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$2.18
Taylor Ranch Elementary	1	AM POLY 2"	18.0 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.25
Taylor Ranch Elementary	1	AM POLY 2"	18.2 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.28
Taylor Ranch Elementary	4	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.00
Taylor Ranch Elementary	1	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.00
Taylor Ranch Elementary	2	AM POLY 2"	20.0 X 022.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.24
Taylor Ranch Elementary	2	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.50
Taylor Ranch Elementary	24	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$864.00	\$6.00	\$3.15	\$453.60	\$2.50
Taylor Ranch Elementary	2	AM POLY 2"	20.0 X 027.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.74
Taylor Ranch Elementary	1	AM POLY 2"	24.0 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$3.00
Taylor Ranch Elementary	1	AM POLY 2"	24.6 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$3.08
Taylor Ranch Elementary	2	AM POLY 2"	25.0 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$3.13

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Tatum Ridge Elementary	2	WASH-OUT	13.0 X 013.0 X 00.4	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Taylor Ranch Elementary	4	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Taylor Ranch Elementary	10	AM POLY 1"	16.2 X 030.2 X 01.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Taylor Ranch Elementary	11	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$198.00	\$2.00	\$3.07	\$202.62	\$3.07
Taylor Ranch Elementary	18	AM POLY 1"	21.6 X 021.6 X 01.0	\$3.00	\$324.00	\$2.00	\$3.07	\$331.56	\$3.07
Taylor Ranch Elementary	2	AM POLY 1"	22.0 X 022.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Taylor Ranch Elementary	2	AM POLY 1"	24.0 X 024.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Taylor Ranch Elementary	7	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Taylor Ranch Elementary	2	AM POLY 2"	16.0 X 020.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Taylor Ranch Elementary	2	AM POLY 2"	16.0 X 025.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Taylor Ranch Elementary	6	AM POLY 2"	16.0 X 026.4 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Taylor Ranch Elementary	14	AM POLY 2"	16.0 X 027.4 X 02.0	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07
Taylor Ranch Elementary	3	AM POLY 2"	17.2 X 025.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Taylor Ranch Elementary	5	AM POLY 2"	17.4 X 025.0 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Taylor Ranch Elementary	1	AM POLY 2"	18.0 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Taylor Ranch Elementary	1	AM POLY 2"	18.2 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Taylor Ranch Elementary	4	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Taylor Ranch Elementary	1	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Taylor Ranch Elementary	2	AM POLY 2"	20.0 X 022.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Taylor Ranch Elementary	2	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Taylor Ranch Elementary	24	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$432.00	\$2.00	\$3.07	\$442.08	\$3.07
Taylor Ranch Elementary	2	AM POLY 2"	20.0 X 027.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Taylor Ranch Elementary	1	AM POLY 2"	24.0 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Taylor Ranch Elementary	1	AM POLY 2"	24.6 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Taylor Ranch Elementary	2	AM POLY 2"	25.0 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Taylor Ranch Elementary	1	WASH-OUT	09.0 X 017.0 X 00.2	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$7.09
Taylor Ranch Elementary	7	WASH-OUT	12.0 X 012.0 X 00.2	\$5.00	\$210.00	\$5.00	\$3.15	\$132.30	\$7.09
The Landings	4	AM POLY 1"	06.2 X 012.2 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$0.30
The Landings	1	AM POLY 1"	07.4 X 026.3 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.77
The Landings	2	AM POLY 1"	08.0 X 026.3 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$0.83
The Landings	2	AM POLY 1"	10.2 X 020.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$0.81
The Landings	16	AM POLY 1"	11.0 X 016.0 X 01.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$0.70
The Landings	2	AM POLY 1"	11.1 X 020.2 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$0.89
The Landings	2	AM POLY 1"	11.1 X 020.6 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$0.91
The Landings	1	AM POLY 1"	11.6 X 017.6 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.81
The Landings	1	AM POLY 1"	12.2 X 012.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$0.59
The Landings	2	AM POLY 1"	15.5 X 026.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.60
The Landings	6	AM POLY 1"	16.0 X 025.0 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.58
The Landings	18	AM POLY 1"	16.0 X 025.0 X 01.0	\$6.00	\$648.00	\$6.00	\$3.15	\$340.20	\$1.58
The Landings	4	AM POLY 1"	16.0 X 026.0 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.65
The Landings	1	AM POLY 1"	16.2 X 016.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.04
The Landings	1	AM POLY 1"	16.2 X 022.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.42
The Landings	1	AM POLY 1"	16.6 X 021.6 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.42
The Landings	1	AM POLY 1"	17.0 X 025.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.68
The Landings	1	AM POLY 1"	17.4 X 021.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.45
The Landings	1	AM POLY 1"	17.4 X 025.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.72
The Landings	1	AM POLY 1"	17.6 X 017.6 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.23
The Landings	6	AM POLY 1"	18.2 X 019.0 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.37
The Landings	1	AM POLY 1"	19.6 X 021.6 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.68
The Landings	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.58

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Taylor Ranch Elementary	1	WASH-OUT	09.0 X 017.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Taylor Ranch Elementary	7	WASH-OUT	12.0 X 012.0 X 00.2	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
The Landings	4	AM POLY 1"	06.2 X 012.2 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
The Landings	1	AM POLY 1"	07.4 X 026.3 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	2	AM POLY 1"	08.0 X 026.3 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
The Landings	2	AM POLY 1"	10.2 X 020.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
The Landings	16	AM POLY 1"	11.0 X 016.0 X 01.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07
The Landings	2	AM POLY 1"	11.1 X 020.2 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
The Landings	2	AM POLY 1"	11.1 X 020.6 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
The Landings	1	AM POLY 1"	11.6 X 017.6 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	1	AM POLY 1"	12.2 X 012.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	2	AM POLY 1"	15.5 X 026.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
The Landings	6	AM POLY 1"	16.0 X 025.0 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
The Landings	18	AM POLY 1"	16.0 X 025.0 X 01.0	\$3.00	\$324.00	\$2.00	\$3.07	\$331.56	\$3.07
The Landings	4	AM POLY 1"	16.0 X 026.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
The Landings	1	AM POLY 1"	16.2 X 016.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	1	AM POLY 1"	16.2 X 022.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	1	AM POLY 1"	16.6 X 021.6 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	1	AM POLY 1"	17.0 X 025.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	1	AM POLY 1"	17.4 X 021.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	1	AM POLY 1"	17.4 X 025.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	1	AM POLY 1"	17.6 X 017.6 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	6	AM POLY 1"	18.2 X 019.0 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
The Landings	1	AM POLY 1"	19.6 X 021.6 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
The Landings	19	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$684.00	\$6.00	\$3.15	\$359.10	\$1.58
The Landings	3	AM POLY 1"	20.0 X 022.0 X 01.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.74
The Landings	2	AM POLY 1"	20.0 X 022.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.74
The Landings	4	AM POLY 1"	20.0 X 025.0 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.98
The Landings	1	AM POLY 1"	20.2 X 020.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.62
The Landings	1	AM POLY 1"	20.4 X 021.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.71
The Landings	2	AM POLY 1"	21.6 X 021.6 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.85
The Landings	7	AM POLY 1"	22.2 X 022.2 X 01.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$1.95
The Landings	1	AM POLY 1"	22.2 X 023.6 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.07
The Landings	1	AM POLY 1"	22.2 X 026.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.30
The Landings	1	AM POLY 2"	14.4 X 024.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.73
The Landings	12	AM POLY 2"	15.0 X 020.0 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$1.50
The Landings	2	AM POLY 2"	15.0 X 021.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.61
The Landings	2	AM POLY 2"	15.0 X 022.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.65
The Landings	1	AM POLY 2"	15.7 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.57
The Landings	1	AM POLY 2"	15.7 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.96
The Landings	3	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.00
The Landings	1	AM POLY 2"	17.2 X 022.6 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.94
The Landings	1	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.00
The Landings	3	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.00
The Landings	3	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.40
The Landings	3	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.50
The Landings	1	AM POLY 2"	23.6 X 024.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.88
The Landings	1	AM SLEVE	19.6 X 022.0	\$9.00	\$54.00	\$9.00	\$3.15	\$18.90	\$1.92
The Landings	1	AM SLEVE	19.6 X 026.0	\$10.00	\$60.00	\$10.00	\$3.15	\$18.90	\$2.16

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
The Landings	19	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$342.00	\$2.00	\$3.07	\$349.98	\$3.07
The Landings	3	AM POLY 1"	20.0 X 022.0 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
The Landings	2	AM POLY 1"	20.0 X 022.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
The Landings	4	AM POLY 1"	20.0 X 025.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
The Landings	1	AM POLY 1"	20.2 X 020.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	1	AM POLY 1"	20.4 X 021.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	2	AM POLY 1"	21.6 X 021.6 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
The Landings	7	AM POLY 1"	22.2 X 022.2 X 01.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
The Landings	1	AM POLY 1"	22.2 X 023.6 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	1	AM POLY 1"	22.2 X 026.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	1	AM POLY 2"	14.4 X 024.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	12	AM POLY 2"	15.0 X 020.0 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
The Landings	2	AM POLY 2"	15.0 X 021.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
The Landings	2	AM POLY 2"	15.0 X 022.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
The Landings	1	AM POLY 2"	15.7 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	1	AM POLY 2"	15.7 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	3	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
The Landings	1	AM POLY 2"	17.2 X 022.6 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	1	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	3	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
The Landings	3	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
The Landings	3	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
The Landings	1	AM POLY 2"	23.6 X 024.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
The Landings	1	AM SLEVE	19.6 X 022.0	\$3.75	\$22.50	\$2.00	\$4.73	\$28.38	\$4.73
The Landings	1	AM SLEVE	19.6 X 026.0	\$3.75	\$22.50	\$2.00	\$5.22	\$31.32	\$5.22

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
The Landings	1	AM SLEVE	20.0 X 020.0	\$9.00	\$54.00	\$9.00	\$3.15	\$18.90	\$1.92
The Landings	2	WASH-OUT	12.0 X 012.0 X 00.4	\$5.00	\$60.00	\$10.00	\$3.15	\$37.80	\$7.09
The Landings	1	WASH-OUT	17.4 X 019.4 X 01.0	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$13.07
Toledo Blade Elementary	6	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.90
Toledo Blade Elementary	2	AM POLY 1"	16.0 X 030.6 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.94
Toledo Blade Elementary	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.58
Toledo Blade Elementary	1	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.38
Toledo Blade Elementary	30	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$1,080.00	\$6.00	\$3.15	\$567.00	\$1.60
Toledo Blade Elementary	4	AM POLY 2"	16.0 X 021.6 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.73
Toledo Blade Elementary	9	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$324.00	\$6.00	\$3.15	\$170.10	\$2.00
Toledo Blade Elementary	16	AM POLY 2"	16.0 X 027.4 X 02.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$2.19
Toledo Blade Elementary	6	AM POLY 2"	17.4 X 025.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.18
Toledo Blade Elementary	3	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.00
Toledo Blade Elementary	5	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$2.00
Toledo Blade Elementary	3	AM POLY 2"	20.0 X 021.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.10
Toledo Blade Elementary	1	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.50
Toledo Blade Elementary	21	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$756.00	\$6.00	\$3.15	\$396.90	\$2.50
Toledo Blade Elementary	4	AM POLY 2"	20.0 X 027.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.74
Toledo Blade Elementary	1	AM POLY 2"	20.2 X 027.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.77
Toledo Blade Elementary	3	AM POLY 2"	25.0 X 025.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$3.13
Toledo Blade Elementary	1	AM POLY 2"	25.0 X 025.2 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$3.15
Toledo Blade Elementary	14	WASH-OUT	12.0 X 012.0 X 00.2	\$5.00	\$420.00	\$10.00	\$3.15	\$264.60	\$7.09
Transportation/Purchasing	3	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.81
Transportation/Purchasing	3	AM POLY 1"	16.0 X 025.0 X 01.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.58
Transportation/Purchasing	2	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.90

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
The Landings	1	AM SLEVE	20.0 X 020.0	\$3.75	\$22.50	\$2.00	\$4.47	\$26.82	\$4.47
The Landings	2	WASH-OUT	12.0 X 012.0 X 00.4	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
The Landings	1	WASH-OUT	17.4 X 019.4 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Toledo Blade Elementary	6	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Toledo Blade Elementary	2	AM POLY 1"	16.0 X 030.6 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Toledo Blade Elementary	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Toledo Blade Elementary	1	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Toledo Blade Elementary	30	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$540.00	\$2.00	\$3.07	\$552.60	\$3.07
Toledo Blade Elementary	4	AM POLY 2"	16.0 X 021.6 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Toledo Blade Elementary	9	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Toledo Blade Elementary	16	AM POLY 2"	16.0 X 027.4 X 02.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07
Toledo Blade Elementary	6	AM POLY 2"	17.4 X 025.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Toledo Blade Elementary	3	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Toledo Blade Elementary	5	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Toledo Blade Elementary	3	AM POLY 2"	20.0 X 021.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Toledo Blade Elementary	1	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Toledo Blade Elementary	21	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$378.00	\$2.00	\$3.07	\$386.82	\$3.07
Toledo Blade Elementary	4	AM POLY 2"	20.0 X 027.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Toledo Blade Elementary	1	AM POLY 2"	20.2 X 027.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Toledo Blade Elementary	3	AM POLY 2"	25.0 X 025.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Toledo Blade Elementary	1	AM POLY 2"	25.0 X 025.2 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Toledo Blade Elementary	14	WASH-OUT	12.0 X 012.0 X 00.2	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07
Transportation/Purchasing	3	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Transportation/Purchasing	3	AM POLY 1"	16.0 X 025.0 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Transportation/Purchasing	2	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Transportation/Purchasing	1	AM POLY 1"	18.0 X 020.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.43
Transportation/Purchasing	1	AM POLY 1"	18.6 X 020.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.47
Transportation/Purchasing	2	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.58
Transportation/Purchasing	7	AM POLY 1"	20.0 X 025.0 X 01.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$1.98
Transportation/Purchasing	1	AM POLY 1"	20.2 X 020.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.62
Transportation/Purchasing	1	AM POLY 1"	20.2 X 030.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.41
Transportation/Purchasing	2	AM POLY 1"	22.2 X 023.4 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.06
Transportation/Purchasing	4	AM POLY 1"	22.2 X 025.0 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.20
Transportation/Purchasing	6	AM POLY 2"	15.0 X 020.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.50
Transportation/Purchasing	2	AM POLY 2"	15.0 X 021.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.61
Transportation/Purchasing	4	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.00
Transportation/Purchasing	4	AM POLY 2"	16.2 X 025.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.03
Transportation/Purchasing	2	AM POLY 2"	18.4 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.30
Transportation/Purchasing	2	AM POLY 2"	20.0 X 021.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.16
Transportation/Purchasing	24	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$864.00	\$6.00	\$3.15	\$453.60	\$25.00
Transportation/Purchasing	1	AM POLY 2"	20.0 X 027.6 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.76
Transportation/Purchasing	2	MERV 8 SC PLEAT	16.0 X 020.0 X 02.0	\$7.00	\$84.00	\$7.00	\$3.93	\$47.16	\$1.93
Transportation/Purchasing	1	AM POLY 1/2"	08.4 X 014.0 X 00.2	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$0.47
Transportation/Purchasing	1	AM POLY 1/2"	09.0 X 017.4 X 00.2	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$0.62
Transportation/Purchasing	2	AM POLY 1/2"	09.0 X 039.4 X 00.2	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$1.40
Transportation/Purchasing	1	AM POLY 1/2"	11.6 X 017.4 X 00.2	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$0.80
Transportation/Purchasing	1	WASH-OUT	10.0 X 046.0 X 00.2	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	
Triad North (New Location)	2	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.81
Triad North (New Location)	4	AM POLY 2"	15.4 X 016.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.23
Triad North (New Location)	8	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.60

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Transportation/Purchasing	1	AM POLY 1"	18.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Transportation/Purchasing	1	AM POLY 1"	18.6 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Transportation/Purchasing	2	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Transportation/Purchasing	7	AM POLY 1"	20.0 X 025.0 X 01.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Transportation/Purchasing	1	AM POLY 1"	20.2 X 020.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Transportation/Purchasing	1	AM POLY 1"	20.2 X 030.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Transportation/Purchasing	2	AM POLY 1"	22.2 X 023.4 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Transportation/Purchasing	4	AM POLY 1"	22.2 X 025.0 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Transportation/Purchasing	6	AM POLY 2"	15.0 X 020.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Transportation/Purchasing	2	AM POLY 2"	15.0 X 021.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Transportation/Purchasing	4	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Transportation/Purchasing	4	AM POLY 2"	16.2 X 025.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Transportation/Purchasing	2	AM POLY 2"	18.4 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Transportation/Purchasing	2	AM POLY 2"	20.0 X 021.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Transportation/Purchasing	24	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$432.00	\$2.00	\$3.07	\$442.08	\$3.07
Transportation/Purchasing	1	AM POLY 2"	20.0 X 027.6 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Transportation/Purchasing	2	MERV 8 SC PLEAT	16.0 X 020.0 X 02.0	\$4.94	\$59.28	\$2.00	\$5.00	\$60.00	\$5.00
Transportation/Purchasing	1	AM POLY 1/2"	08.4 X 014.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Transportation/Purchasing	1	AM POLY 1/2"	09.0 X 017.4 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Transportation/Purchasing	2	AM POLY 1/2"	09.0 X 039.4 X 00.2	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Transportation/Purchasing	1	AM POLY 1/2"	11.6 X 017.4 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Transportation/Purchasing	1	WASH-OUT	10.0 X 046.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Triad North (New Location)	2	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Triad North (New Location)	4	AM POLY 2"	15.4 X 016.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Triad North (New Location)	8	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Triad North (New Location)	4	AM POLY 2"	16.0 X 021.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.68
Triad North (New Location)	2	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.71
Triad North (New Location)	8	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.00
Triad North (New Location)	1	AM POLY 2"	20.0 X 027.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.74
Triad North (New Location)	2	AM POLY 2"	20.0 X 048.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$4.80
Triad North (New Location)	1	WASH-OUT	24.0 X 024.0 X 01.0	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$17.05
Tuttle Elementary	3	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.81
Tuttle Elementary	1	AM POLY 1"	16.0 X 028.1 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.78
Tuttle Elementary	13	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$468.00	\$6.00	\$3.15	\$245.70	\$1.90
Tuttle Elementary	13	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$468.00	\$6.00	\$3.15	\$245.70	\$2.38
Tuttle Elementary	20	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$720.00	\$6.00	\$3.15	\$378.00	\$1.60
Tuttle Elementary	6	AM POLY 2"	16.0 X 021.6 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.73
Tuttle Elementary	4	AM POLY 2"	16.0 X 022.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.76
Tuttle Elementary	4	AM POLY 2"	16.2 X 025.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.03
Tuttle Elementary	2	AM POLY 2"	16.4 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.05
Tuttle Elementary	2	AM POLY 2"	17.6 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.20
Tuttle Elementary	2	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.00
Tuttle Elementary	1	AM POLY 2"	20.0 X 021.2 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.12
Tuttle Elementary	1	AM POLY 2"	20.0 X 021.4 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.14
Tuttle Elementary	2	AM POLY 2"	20.0 X 021.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.16
Tuttle Elementary	2	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.40
Tuttle Elementary	32	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$1,152.00	\$6.00	\$3.15	\$604.80	\$2.50
Tuttle Elementary	2	AM POLY 2"	20.0 X 027.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.76
Tuttle Elementary	2	AM POLY 2"	25.0 X 025.2 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$3.15
Tuttle Elementary	10	WASH-OUT	12.0 X 013.0 X 00.2	\$5.00	\$300.00	\$10.00	\$3.15	\$189.00	\$7.09

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Triad North (New Location)	4	AM POLY 2"	16.0 X 021.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Triad North (New Location)	2	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Triad North (New Location)	8	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Triad North (New Location)	1	AM POLY 2"	20.0 X 027.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Triad North (New Location)	2	AM POLY 2"	20.0 X 048.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Triad North (New Location)	1	WASH-OUT	24.0 X 024.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Tuttle Elementary	3	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Tuttle Elementary	1	AM POLY 1"	16.0 X 028.1 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Tuttle Elementary	13	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$234.00	\$2.00	\$3.07	\$239.46	\$3.07
Tuttle Elementary	13	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$234.00	\$2.00	\$3.07	\$239.46	\$3.07
Tuttle Elementary	20	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$360.00	\$2.00	\$3.07	\$368.40	\$3.07
Tuttle Elementary	6	AM POLY 2"	16.0 X 021.6 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Tuttle Elementary	4	AM POLY 2"	16.0 X 022.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Tuttle Elementary	4	AM POLY 2"	16.2 X 025.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Tuttle Elementary	2	AM POLY 2"	16.4 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Tuttle Elementary	2	AM POLY 2"	17.6 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Tuttle Elementary	2	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Tuttle Elementary	1	AM POLY 2"	20.0 X 021.2 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Tuttle Elementary	1	AM POLY 2"	20.0 X 021.4 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Tuttle Elementary	2	AM POLY 2"	20.0 X 021.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Tuttle Elementary	2	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Tuttle Elementary	32	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$576.00	\$2.00	\$3.07	\$589.44	\$3.07
Tuttle Elementary	2	AM POLY 2"	20.0 X 027.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Tuttle Elementary	2	AM POLY 2"	25.0 X 025.2 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Tuttle Elementary	10	WASH-OUT	12.0 X 013.0 X 00.2	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Venice Elementary	4	AM POLY 2"	12.2 X 020.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.22
Venice Elementary	2	AM POLY 2"	13.4 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.68
Venice Elementary	32	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$1,152.00	\$6.00	\$3.15	\$604.80	\$1.60
Venice Elementary	8	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.71
Venice Elementary	7	AM POLY 2"	16.0 X 025.4 X 02.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$2.03
Venice Elementary	6	AM POLY 2"	17.0 X 025.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$2.13
Venice Elementary	2	AM POLY 2"	17.4 X 020.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.74
Venice Elementary	30	AM POLY 2"	18.0 X 025.0 X 02.0	\$6.00	\$1,080.00	\$6.00	\$3.15	\$567.00	\$2.25
Venice Elementary	5	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$2.00
Venice Elementary	1	AM POLY 2"	20.0 X 021.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.10
Venice Elementary	2	AM POLY 2"	20.0 X 023.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.34
Venice Elementary	8	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.40
Venice Elementary	12	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$2.50
Venice Elementary	2	AM POLY 2"	20.0 X 027.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.74
Venice Elementary	5	WASH-OUT	11.0 X 027.0 X 00.2	\$5.00	\$150.00	\$10.00	\$3.15	\$94.50	\$21.05
Venice Elementary	1	WASH-OUT	11.0 X 038.0 X 00.2	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$15.07
Venice High	6	AM POLY 1"	06.2 X 019.4 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$0.48
Venice High	5	AM POLY 1"	10.0 X 025.0 X 01.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$0.99
Venice High	6	AM POLY 1"	10.4 X 019.4 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$0.80
Venice High	2	AM POLY 1"	11.2 X 027.6 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.22
Venice High	6	AM POLY 1"	12.0 X 020.0 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$0.95
Venice High	2	AM POLY 1"	13.0 X 020.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.03
Venice High	1	AM POLY 1"	14.0 X 025.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.39
Venice High	10	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$1.81
Venice High	2	AM POLY 1"	16.0 X 020.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.27

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Venice Elementary	4	AM POLY 2"	12.2 X 020.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Venice Elementary	2	AM POLY 2"	13.4 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice Elementary	32	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$576.00	\$2.00	\$3.07	\$589.44	\$3.07
Venice Elementary	8	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Venice Elementary	7	AM POLY 2"	16.0 X 025.4 X 02.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Venice Elementary	6	AM POLY 2"	17.0 X 025.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Venice Elementary	2	AM POLY 2"	17.4 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice Elementary	30	AM POLY 2"	18.0 X 025.0 X 02.0	\$3.00	\$540.00	\$2.00	\$3.07	\$552.60	\$3.07
Venice Elementary	5	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Venice Elementary	1	AM POLY 2"	20.0 X 021.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice Elementary	2	AM POLY 2"	20.0 X 023.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice Elementary	8	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Venice Elementary	12	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Venice Elementary	2	AM POLY 2"	20.0 X 027.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice Elementary	5	WASH-OUT	11.0 X 027.0 X 00.2	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Venice Elementary	1	WASH-OUT	11.0 X 038.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice High	6	AM POLY 1"	06.2 X 019.4 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Venice High	5	AM POLY 1"	10.0 X 025.0 X 01.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Venice High	6	AM POLY 1"	10.4 X 019.4 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Venice High	2	AM POLY 1"	11.2 X 027.6 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice High	6	AM POLY 1"	12.0 X 020.0 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Venice High	2	AM POLY 1"	13.0 X 020.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice High	1	AM POLY 1"	14.0 X 025.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice High	10	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Venice High	2	AM POLY 1"	16.0 X 020.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Venice High	1	AM POLY 1"	16.0 X 020.4 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.29
Venice High	14	AM POLY 1"	16.0 X 025.0 X 01.0	\$6.00	\$504.00	\$6.00	\$3.15	\$264.60	\$1.58
Venice High	9	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$324.00	\$6.00	\$3.15	\$170.10	\$1.90
Venice High	1	AM POLY 1"	17.0 X 025.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.68
Venice High	10	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$1.58
Venice High	4	AM POLY 1"	20.0 X 020.4 X 01.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.62
Venice High	1	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.38
Venice High	6	AM POLY 1"	21.6 X 021.6 X 01.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$1.85
Venice High	1	AM POLY 1"	21.6 X 024.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.07
Venice High	1	AM POLY 1"	22.4 X 024.4 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.16
Venice High	1	AM POLY 1"	36.2 X 036.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$5.19
Venice High	6	AM POLY 2"	10.0 X 016.0 X 02.0	\$6.00	\$216.00	\$6.00	\$3.15	\$113.40	\$0.80
Venice High	2	AM POLY 2"	11.4 X 016.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$0.91
Venice High	2	AM POLY 2"	12.0 X 014.1 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$0.85
Venice High	3	AM POLY 2"	13.6 X 025.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.70
Venice High	4	AM POLY 2"	15.4 X 016.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.23
Venice High	4	AM POLY 2"	15.6 X 020.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.56
Venice High	1	AM POLY 2"	15.6 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00			
Venice High	1	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.60
Venice High	109	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$3,924.00	\$6.00	\$3.15	\$2,060.10	\$1.60
Venice High	1	AM POLY 2"	16.0 X 020.2 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.62
Venice High	8	AM POLY 2"	16.0 X 020.2 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$1.62
Venice High	13	AM POLY 2"	16.0 X 020.4 X 02.0	\$6.00	\$468.00	\$6.00	\$3.15	\$245.70	\$1.63
Venice High	7	AM POLY 2"	16.0 X 021.0 X 02.0	\$6.00	\$252.00	\$6.00	\$3.15	\$132.30	\$1.68
Venice High	5	AM POLY 2"	16.0 X 021.2 X 02.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$1.70

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Venice High	1	AM POLY 1"	16.0 X 020.4 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice High	14	AM POLY 1"	16.0 X 025.0 X 01.0	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07
Venice High	9	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Venice High	1	AM POLY 1"	17.0 X 025.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice High	10	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Venice High	4	AM POLY 1"	20.0 X 020.4 X 01.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Venice High	1	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice High	6	AM POLY 1"	21.6 X 021.6 X 01.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Venice High	1	AM POLY 1"	21.6 X 024.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice High	1	AM POLY 1"	22.4 X 024.4 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice High	1	AM POLY 1"	36.2 X 036.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice High	6	AM POLY 2"	10.0 X 016.0 X 02.0	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07
Venice High	2	AM POLY 2"	11.4 X 016.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice High	2	AM POLY 2"	12.0 X 014.1 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice High	3	AM POLY 2"	13.6 X 025.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Venice High	4	AM POLY 2"	15.4 X 016.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Venice High	4	AM POLY 2"	15.6 X 020.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Venice High	1	AM POLY 2"	15.6 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice High	1	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice High	109	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$1,962.00	\$2.00	\$3.07	\$2,007.78	\$3.07
Venice High	1	AM POLY 2"	16.0 X 020.2 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice High	8	AM POLY 2"	16.0 X 020.2 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Venice High	13	AM POLY 2"	16.0 X 020.4 X 02.0	\$3.00	\$234.00	\$2.00	\$3.07	\$239.46	\$3.07
Venice High	7	AM POLY 2"	16.0 X 021.0 X 02.0	\$3.00	\$126.00	\$2.00	\$3.07	\$128.94	\$3.07
Venice High	5	AM POLY 2"	16.0 X 021.2 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Venice High	3	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$1.71
Venice High	12	AM POLY 2"	16.0 X 021.6 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$1.73
Venice High	66	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$2,376.00	\$6.00	\$3.15	\$1,247.40	\$2.00
Venice High	2	AM POLY 2"	16.0 X 026.2 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.10
Venice High	2	AM POLY 2"	16.0 X 027.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.21
Venice High	3	AM POLY 2"	16.0 X 028.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.24
Venice High	2	AM POLY 2"	16.2 X 020.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.62
Venice High	4	AM POLY 2"	17.6 X 020.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.76
Venice High	2	AM POLY 2"	17.6 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.20
Venice High	57	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$2,052.00	\$6.00	\$3.15	\$1,077.30	\$2.00
Venice High	21	AM POLY 2"	20.0 X 020.4 X 02.0	\$6.00	\$756.00	\$6.00	\$3.15	\$396.90	\$2.04
Venice High	2	AM POLY 2"	20.0 X 021.2 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.12
Venice High	10	AM POLY 2"	20.0 X 021.6 X 02.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$2.16
Venice High	2	AM POLY 2"	20.0 X 022.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.20
Venice High	4	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.40
Venice High	2	AM POLY 2"	20.0 X 024.2 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.42
Venice High	27	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$972.00	\$6.00	\$3.15	\$510.30	\$2.50
Venice High	2	AM POLY 2"	20.0 X 025.2 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.52
Venice High	9	AM POLY 2"	20.0 X 027.6 X 02.0	\$6.00	\$324.00	\$6.00	\$3.15	\$170.10	\$2.76
Venice High	5	AM POLY 2"	20.0 X 032.0 X 02.0	\$6.00	\$180.00	\$6.00	\$3.15	\$94.50	\$3.20
Venice High	4	AM POLY 2"	20.2 X 020.2 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.04
Venice High	8	AM POLY 2"	20.2 X 025.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.53
Venice High	8	AM POLY 2"	20.2 X 029.7 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$3.00
Venice High	1	AM POLY 2"	20.4 X 040.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$4.08
Venice High	1	AM POLY 2"	22.0 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$2.75

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Venice High	3	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Venice High	12	AM POLY 2"	16.0 X 021.6 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Venice High	66	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$1,188.00	\$2.00	\$3.07	\$1,215.72	\$3.07
Venice High	2	AM POLY 2"	16.0 X 026.2 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice High	2	AM POLY 2"	16.0 X 027.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice High	3	AM POLY 2"	16.0 X 028.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Venice High	2	AM POLY 2"	16.2 X 020.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice High	4	AM POLY 2"	17.6 X 020.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Venice High	2	AM POLY 2"	17.6 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice High	57	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$1,026.00	\$2.00	\$3.07	\$1,049.94	\$3.07
Venice High	21	AM POLY 2"	20.0 X 020.4 X 02.0	\$3.00	\$378.00	\$2.00	\$3.07	\$386.82	\$3.07
Venice High	2	AM POLY 2"	20.0 X 021.2 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice High	10	AM POLY 2"	20.0 X 021.6 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Venice High	2	AM POLY 2"	20.0 X 022.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice High	4	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Venice High	2	AM POLY 2"	20.0 X 024.2 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice High	27	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$486.00	\$2.00	\$3.07	\$497.34	\$3.07
Venice High	2	AM POLY 2"	20.0 X 025.2 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice High	9	AM POLY 2"	20.0 X 027.6 X 02.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Venice High	5	AM POLY 2"	20.0 X 032.0 X 02.0	\$3.00	\$90.00	\$2.00	\$3.07	\$92.10	\$3.07
Venice High	4	AM POLY 2"	20.2 X 020.2 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Venice High	8	AM POLY 2"	20.2 X 025.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Venice High	8	AM POLY 2"	20.2 X 029.7 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Venice High	1	AM POLY 2"	20.4 X 040.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice High	1	AM POLY 2"	22.0 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Venice High	1	AM POLY 2"	25.0 X 025.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$3.13
Venice High	4	AM SLEVE	16.0 X 040.0	\$10.00	\$240.00	\$12.00	\$3.15	\$75.60	\$2.42
Venice High	1	WASH-OUT	08.0 X 014.0 X 00.2	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$7.09
Venice High	1	WASH-OUT	08.2 X 016.0 X 00.5	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$7.09
Venice High	1	WASH-OUT	10.0 X 017.0 X 00.2	\$5.00	\$30.00	\$10.00	\$3.15	\$18.90	\$7.09
Venice Middle	1	AM POLY 1"	15.0 X 030.5 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.81
Venice Middle	2	AM POLY 1"	16.0 X 025.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.58
Venice Middle	12	AM POLY 1"	16.0 X 030.0 X 01.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$1.90
Venice Middle	1	AM POLY 1"	17.0 X 025.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.68
Venice Middle	2	AM POLY 1"	20.0 X 020.0 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.58
Venice Middle	9	AM POLY 1"	20.0 X 030.0 X 01.0	\$6.00	\$324.00	\$6.00	\$3.15	\$170.10	\$2.38
Venice Middle	1	AM POLY 1"	20.2 X 020.2 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.62
Venice Middle	2	AM POLY 1"	21.2 X 022.7 X 01.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.90
Venice Middle	1	AM POLY 1"	21.6 X 046.0 X 01.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$3.93
Venice Middle	4	AM POLY 2"	11.0 X 025.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.38
Venice Middle	2	AM POLY 2"	12.0 X 024.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$1.44
Venice Middle	4	AM POLY 2"	14.1 X 020.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.41
Venice Middle	1	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$36.00	\$6.00	\$3.15	\$18.90	\$1.60
Venice Middle	8	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$288.00	\$6.00	\$3.15	\$151.20	\$2.00
Venice Middle	2	AM POLY 2"	18.6 X 030.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.85
Venice Middle	2	AM POLY 2"	20.0 X 022.6 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.26
Venice Middle	4	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.40
Venice Middle	20	AM POLY 2"	20.0 X 024.0 X 02.0	\$6.00	\$720.00	\$6.00	\$3.15	\$378.00	\$2.40
Venice Middle	3	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$108.00	\$6.00	\$3.15	\$56.70	\$2.50
Venice Middle	16	AM POLY 2"	20.0 X 027.6 X 02.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$2.76

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Venice High	1	AM POLY 2"	25.0 X 025.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice High	4	AM SLEVE	16.0 X 040.0	\$3.75	\$90.00	\$2.00	\$6.77	\$162.48	\$6.77
Venice High	1	WASH-OUT	08.0 X 014.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice High	1	WASH-OUT	08.2 X 016.0 X 00.5	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice High	1	WASH-OUT	10.0 X 017.0 X 00.2	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice Middle	1	AM POLY 1"	15.0 X 030.5 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice Middle	2	AM POLY 1"	16.0 X 025.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice Middle	12	AM POLY 1"	16.0 X 030.0 X 01.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Venice Middle	1	AM POLY 1"	17.0 X 025.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice Middle	2	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice Middle	9	AM POLY 1"	20.0 X 030.0 X 01.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Venice Middle	1	AM POLY 1"	20.2 X 020.2 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice Middle	2	AM POLY 1"	21.2 X 022.7 X 01.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice Middle	1	AM POLY 1"	21.6 X 046.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice Middle	4	AM POLY 2"	11.0 X 025.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Venice Middle	2	AM POLY 2"	12.0 X 024.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice Middle	4	AM POLY 2"	14.1 X 020.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Venice Middle	1	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice Middle	8	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Venice Middle	2	AM POLY 2"	18.6 X 030.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice Middle	2	AM POLY 2"	20.0 X 022.6 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice Middle	4	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Venice Middle	20	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$360.00	\$2.00	\$3.07	\$368.40	\$3.07
Venice Middle	3	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$54.00	\$2.00	\$3.07	\$55.26	\$3.07
Venice Middle	16	AM POLY 2"	20.0 X 027.6 X 02.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Venice Middle	16	AM POLY 2"	20.0 X 027.6 X 02.0	\$6.00	\$576.00	\$6.00	\$3.15	\$302.40	\$2.76
Venice Middle	2	AM POLY 2"	20.0 X 030.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$3.00
Venice Middle	12	AM POLY 2"	21.4 X 025.0 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$2.68
Venice Middle	22	AM POLY 2"	24.0 X 024.0 X 02.0	\$6.00	\$792.00	\$6.00	\$3.15	\$415.80	\$2.88
Venice Middle	2	MERV 8 SC PLEAT	20.0 X 024.0 X 02.0	\$6.00	\$72.00	\$6.00	\$4.64	\$55.68	\$2.64
Venice Middle	1	AM POLY 1/2"	09.0 X 039.4 X 00.5	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$1.40
Venice Middle	2	WASH-OUT	16.2 X 019.4 X 00.5	\$5.00	\$60.00	\$10.00	\$3.15	\$37.80	\$13.07
Wilkinson Elementary	4	AM POLY 2"	13.5 X 020.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.35
Wilkinson Elementary	14	AM POLY 2"	16.0 X 020.0 X 02.0	\$6.00	\$504.00	\$6.00	\$3.15	\$264.60	\$1.60
Wilkinson Elementary	10	AM POLY 2"	16.0 X 021.0 X 02.0	\$6.00	\$360.00	\$6.00	\$3.15	\$189.00	\$1.68
Wilkinson Elementary	4	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.71
Wilkinson Elementary	20	AM POLY 2"	16.0 X 023.4 X 02.0	\$6.00	\$720.00	\$6.00	\$3.15	\$378.00	\$1.87
Wilkinson Elementary	56	AM POLY 2"	16.0 X 025.0 X 02.0	\$6.00	\$2,016.00	\$6.00	\$3.15	\$1,058.40	\$2.00
Wilkinson Elementary	4	AM POLY 2"	16.0 X 025.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.03
Wilkinson Elementary	4	AM POLY 2"	16.0 X 027.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.19
Wilkinson Elementary	4	AM POLY 2"	16.0 X 040.5 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$3.24
Wilkinson Elementary	12	AM POLY 2"	20.0 X 020.0 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$2.00
Wilkinson Elementary	2	AM POLY 2"	20.0 X 021.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.14
Wilkinson Elementary	20	AM POLY 2"	20.0 X 025.0 X 02.0	\$6.00	\$720.00	\$6.00	\$3.15	\$378.00	\$2.50
Wilkinson Elementary	2	AM POLY 2"	20.0 X 027.4 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.74
Wilkinson Elementary	4	AM POLY 2"	21.0 X 024.0 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$2.52
Wilkinson Elementary	12	AM POLY 2"	24.0 X 024.0 X 02.0	\$6.00	\$432.00	\$6.00	\$3.15	\$226.80	\$2.88
Wilkinson Elementary	2	WASH-OUT	11.0 X 030.0 X 00.4	\$6.00	\$72.00	\$10.00	\$3.15	\$37.80	\$13.07
Wilkinson Elementary	8	WASH-OUT	12.0 X 012.0 X 00.4	\$6.00	\$288.00	\$10.00	\$3.15	\$151.20	\$7.09
Wilkinson Elementary	6	WASH-OUT	12.4 X 013.0 X 00.5	\$6.00	\$216.00	\$10.00	\$3.15	\$113.40	\$7.09

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Venice Middle	16	AM POLY 2"	20.0 X 027.6 X 02.0	\$3.00	\$288.00	\$2.00	\$3.07	\$294.72	\$3.07
Venice Middle	2	AM POLY 2"	20.0 X 030.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Venice Middle	12	AM POLY 2"	21.4 X 025.0 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Venice Middle	22	AM POLY 2"	24.0 X 024.0 X 02.0	\$3.00	\$396.00	\$2.00	\$3.07	\$405.24	\$3.07
Venice Middle	2	MERV 8 SC PLEAT	20.0 X 024.0 X 02.0	\$5.38	\$64.56	\$2.00	\$5.00	\$60.00	\$5.00
Venice Middle	1	AM POLY 1/2"	09.0 X 039.4 X 00.5	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Venice Middle	2	WASH-OUT	16.2 X 019.4 X 00.5	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Wilkinson Elementary	4	AM POLY 2"	13.5 X 020.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Wilkinson Elementary	14	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$252.00	\$2.00	\$3.07	\$257.88	\$3.07
Wilkinson Elementary	10	AM POLY 2"	16.0 X 021.0 X 02.0	\$3.00	\$180.00	\$2.00	\$3.07	\$184.20	\$3.07
Wilkinson Elementary	4	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Wilkinson Elementary	20	AM POLY 2"	16.0 X 023.4 X 02.0	\$3.00	\$360.00	\$2.00	\$3.07	\$368.40	\$3.07
Wilkinson Elementary	56	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$1,008.00	\$2.00	\$3.07	\$1,031.52	\$3.07
Wilkinson Elementary	4	AM POLY 2"	16.0 X 025.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Wilkinson Elementary	4	AM POLY 2"	16.0 X 027.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Wilkinson Elementary	4	AM POLY 2"	16.0 X 040.5 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Wilkinson Elementary	12	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Wilkinson Elementary	2	AM POLY 2"	20.0 X 021.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Wilkinson Elementary	20	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$360.00	\$2.00	\$3.07	\$368.40	\$3.07
Wilkinson Elementary	2	AM POLY 2"	20.0 X 027.4 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Wilkinson Elementary	4	AM POLY 2"	21.0 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Wilkinson Elementary	12	AM POLY 2"	24.0 X 024.0 X 02.0	\$3.00	\$216.00	\$2.00	\$3.07	\$221.04	\$3.07
Wilkinson Elementary	2	WASH-OUT	11.0 X 030.0 X 00.4	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Wilkinson Elementary	8	WASH-OUT	12.0 X 012.0 X 00.4	\$3.00	\$144.00	\$2.00	\$3.07	\$147.36	\$3.07
Wilkinson Elementary	6	WASH-OUT	12.4 X 013.0 X 00.5	\$3.00	\$108.00	\$2.00	\$3.07	\$110.52	\$3.07

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Air Mechanical and Service Corporation			Con-Air Industries		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Woodland Middle	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$1.58
Woodland Middle	59	AM POLY 2"	16.0 X 020.0 X 02.0	\$5.00	\$1,770.00	\$5.00	\$3.15	\$1,115.10	\$1.60
Woodland Middle	4	AM POLY 2"	16.0 X 021.4 X 02.0	\$6.00	\$144.00	\$6.00	\$3.15	\$75.60	\$1.71
Woodland Middle	4	AM POLY 2"	16.0 X 024.0 X 02.0	\$5.00	\$120.00	\$5.00	\$3.15	\$75.60	\$1.92
Woodland Middle	28	AM POLY 2"	16.0 X 025.0 X 02.0	\$5.00	\$840.00	\$5.00	\$3.15	\$529.20	\$2.00
Woodland Middle	2	AM POLY 2"	17.4 X 025.0 X 02.0	\$6.00	\$72.00	\$6.00	\$3.15	\$37.80	\$2.16
Woodland Middle	9	AM POLY 2"	20.0 X 020.0 X 02.0	\$5.00	\$270.00	\$5.00	\$3.15	\$170.10	\$2.00
Woodland Middle	22	AM POLY 2"	20.0 X 024.0 X 02.0	\$5.00	\$660.00	\$5.00	\$3.15	\$415.80	\$2.40
Woodland Middle	24	AM POLY 2"	20.0 X 025.0 X 02.0	\$5.00	\$720.00	\$5.00	\$3.15	\$453.60	\$25.00
Woodland Middle	1	AM POLY 2"	24.0 X 024.0 X 02.0	\$5.00	\$30.00	\$5.00	\$3.15	\$18.90	\$2.88
Woodland Middle	2	AM POLY 2"	24.0 X 025.0 X 02.0	\$5.00	\$60.00	\$5.00	\$3.15	\$37.80	\$3.00
Woodland Middle	4	AM POLY 2"	25.0 X 025.0 X 02.0	\$5.00	\$120.00	\$5.00	\$3.15	\$75.60	\$3.13
Woodland Middle	9	WASH-OUT	10.0 X 020.0 X 01.0	\$5.00	\$270.00	\$10.00	\$3.15	\$170.10	\$10.08
TOTAL					\$326,682.00			\$176,932.74	

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.				Kleen Air Research			Pure Air (Lott Enterprise)		
A	B	C	D	E	F	OPTION	E	F	OPTION
Facility Name	Qty	Filter Description	Filter Size	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)	Price per filter change including filter	Total for six filter changes (including filter) per year (Qty. x each x 6 changes)	Price per filter Material Only (delivered to each location)
Woodland Middle	1	AM POLY 1"	20.0 X 020.0 X 01.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Woodland Middle	59	AM POLY 2"	16.0 X 020.0 X 02.0	\$3.00	\$1,062.00	\$2.00	\$3.07	\$1,086.78	\$3.07
Woodland Middle	4	AM POLY 2"	16.0 X 021.4 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Woodland Middle	4	AM POLY 2"	16.0 X 024.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Woodland Middle	28	AM POLY 2"	16.0 X 025.0 X 02.0	\$3.00	\$504.00	\$2.00	\$3.07	\$515.76	\$3.07
Woodland Middle	2	AM POLY 2"	17.4 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Woodland Middle	9	AM POLY 2"	20.0 X 020.0 X 02.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
Woodland Middle	22	AM POLY 2"	20.0 X 024.0 X 02.0	\$3.00	\$396.00	\$2.00	\$3.07	\$405.24	\$3.07
Woodland Middle	24	AM POLY 2"	20.0 X 025.0 X 02.0	\$3.00	\$432.00	\$2.00	\$3.07	\$442.08	\$3.07
Woodland Middle	1	AM POLY 2"	24.0 X 024.0 X 02.0	\$3.00	\$18.00	\$2.00	\$3.07	\$18.42	\$3.07
Woodland Middle	2	AM POLY 2"	24.0 X 025.0 X 02.0	\$3.00	\$36.00	\$2.00	\$3.07	\$36.84	\$3.07
Woodland Middle	4	AM POLY 2"	25.0 X 025.0 X 02.0	\$3.00	\$72.00	\$2.00	\$3.07	\$73.68	\$3.07
Woodland Middle	9	WASH-OUT	10.0 X 020.0 X 01.0	\$3.00	\$162.00	\$2.00	\$3.07	\$165.78	\$3.07
TOTAL					\$168,615.00			\$175,353.06	

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.	Air Mechanical and Service Corporation	Con-Air Industries
SERVICE TELEPHONE. Single, local telephone number for the SBSC personnel to call to contact the Contractor's supervisory personnel during standard working hours. Must be manned on a continuous basis during normal working hours.	941-475-3715	800-327-5733 407-298-5733
RECYCLABLE FILTER MATERIAL. Details of the recyclability of the filter material if recyclable filter material is bid.		
	Extension corrected	Extension corrected
Contact	Blaine Byers	Charles Adkinson
Address	2700 Avenue of the Americas Englewood, FL 34224	4157 Seaboard Road Orlando, FL 32808
Phone	941-475-3715	407-298-5733
Fax	941-475-3725	407-297-4356
Federal I.D.	592158902	592032848
Email	bbyers@amsco-ac.com	cadkinson@conairindustries.com

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

HVAC Filter Replacement Service - Bid #12-0130

Opened June 29, 2011 - 2:00 p.m.

<p>Pricing for HVAC filter replacement service six (6) times per year for all locations to include (1) provision of all filter media, frames (if required) and (2) all required labor, supervision, materials, equipment, travel, fuel, overhead, profit, proper disposal of all materials, and vehicles for those facilities specified within.</p>	<p>Kleen Air Research</p>	<p>Pure Air (Lott Enterprise)</p>
<p>SERVICE TELEPHONE. Single, local telephone number for the SBSC personnel to call to contact the Contractor's supervisory personnel during standard working hours. Must be manned on a continuous basis during normal working hours.</p>	<p>888-767-5122</p>	<p>727-528-1700</p>
<p>RECYCLABLE FILTER MATERIAL. Details of the recyclability of the filter material if recyclable filter material is bid.</p>	<p>Due to the bacterial and fungal growth that is eliminated by our product, it is unable to be recycled.</p>	
		<p>Extension corrected</p>
<p>Contact</p>	<p>Dewayne Brock</p>	<p>Fred Lopacki</p>
<p>Address</p>	<p>4510 Helton Drive</p>	<p>204 Eastman Street</p>
	<p>Florence, AL 35630</p>	<p>Greenwood, MS 38930</p>
<p>Phone</p>	<p>256-767-5122</p>	<p>662-466-0469 / 727-528-1700</p>
<p>Fax</p>	<p>256-767-5188</p>	<p>662-453-8199 / 727-528-1474</p>
<p>Federal I.D.</p>	<p>630803993</p>	<p>640655737</p>
<p>Email</p>	<p>dbrock@filterpro.com</p>	<p>f.lopacki@pureairco.com</p>
	<p>Recorded by: Peggy Long Witnessed by: Joyce Haney JoAnn Joyce</p>	