

MATERIALS MANAGEMENT DEPARTMENT

101 OLD VENICE ROAD

OSPREY, FLORIDA 34229

TELEPHONE (941) 486-2183

FAX (941) 486-2188

MEMORANDUM

- TO: Members of the School Board Lori White, Superintendent Mitsi Corcoran, Chief Financial Officer
- FROM: Pat Black, CPPB, Director of Materials Management

TITLE: APPROVAL TO AWARD BID #0537 FOR BUS BRAKE REPAIR PARTS

Bids to provide 'Bus Brake Repair Parts' were received from nine vendors on May 26, 2010. The bids of Fleet Acquisitions, LLC, dba Fleet Products, Fleet Pride, Sun State International and TPH Acquisition, LLLP, dba The Parts House were the best low bids meeting the advertised specifications. Reasons for not selecting the apparent low bids are included with the bid tabulation. This bid is for a period of one year with the option for renew for two additional one-year periods. The funds for these purchases are contained in the operating budget allocated to the Transportation Services Department.

Requested by: Ellery Girard "Failure to file a protest within the time prescribed in Section 120.57(3), Florida Statutes, or failure to post the protest bond or other security required by law within the time allowed for filing a bond shall constitute a waiver of proceedings under Chapter 120. Florida Statutes."

Posting Date: 07-27-10

Fiscal Impact:

Not to exceed \$115,000.00

Funding:

Operating

<u>Recommended Motion</u>: That the bids of Fleet Acquisitions, LLC, dba Fleet Products, Fleet Pride, Sun State International and TPH Acquisition, LLLP, dba The Parts House, to provide 'Bus Brake Repair Parts' in an amount not to exceed \$115,000.00, be approved for award and purchase.

Tabulation for Bus Brake Repair Parts - Bid #0537

| Scho rema | rake linings will be riveted on Sarasota ool District brake shoes, OEM factory anufacturered brake shoes, or new e shoes. | Fleet Acquisitio | ns, LLC dba | a Fleet Pro | oducts | | Fleet Prid | e | - |
|--------------|--|--|--------------------|---------------|---------------------|--|--------------------|---------------|---------------------|
| Item # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** |
| MER | RITOR 312 or approved alternate. | | | | | | | | |
| | New Front Shoe Kit, includes 2 Shoes and Hadware Kit (Freightliner) - SUB8824HD | KSMA4702QP | \$143.74 | 66% | \$48.87 | KSMA3124702QP | \$143.64 | 64% | \$51.71 |
| 2. | New Rear Shoe Kit, includes 2 Shoes and Hardware Kit - SUB8000HD | KSMA4707QP | \$204.06 | 66% | \$69.38 | KSMA3124707QP | \$204.06 | 64% | \$73.46 |
| 3. | Remanufactured Front Shoe Kit - includes 2 Shoes and Hardware Kit - KIT8824HD | XK3124702QP | \$133.60 | 66% | \$45.42 | XK3124702QP | \$133.60 | 64% | \$48.10 |
| 4. | Remanufactured Rear Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8000HD | XK3124707QP | \$144.14 | 66% | \$49.01 | XK3124707QP | \$144.14 | 64% | \$51.89 |
| 5. | Balance of line item discount for Meritor 312 or approved alternate. | | MERITOF 669 | | | | 64 | % | |
| MER | ITOR or approved alternate. | | | | | | | | |
| 6. | Tapered Roller Hardware Kit - 8847HDA KIT | KIT8847HDA | \$70.49 | 56% | \$31.02 | | \$70.49 | 55% | \$31.72 |
| 7. | Tapered Roller Only - 8847HD | KIT8847HD | \$29.07 | 56% | \$12.79 | | \$29.07 | 55% | \$13.08 |
| | Balance of line item discount for Meritor or approved alternate. | | MERI 569 | | | | 55 | % | |
| BEN | DIX or approved alternate. | | | | | | | | |
| 9. | Drier - 107794X - AD9 | BENDIX 107794X | \$52.55 | 57% | \$22.60 | | \$52.55 | 53% | \$24.70 |
| 10. | Foot Pedal Valve - BW286171 E-6 | BENDIX 286171 | \$87.79 | 57% | \$37.75 | 286171N | \$161.09 | 53% | \$75.71 |
| 11. | Governor - 18530 | AS SPEC | \$33.68 | 57% | \$14.48 | | \$33.68 | 53% | \$15.83 |
| 12. | Park Brake Valve - 800142 PP1 | BENDIX 800142 | \$187.42 | 57% | \$80.59 | | \$187.42 | 53% | \$88.09 |

Tabulation for Bus Brake Repair Parts - Bid #0537

| | | | | | | | e, _e.e.e.e.e | |
|---|---|--|--|--|--|--|--|---|
| ake linings will be riveted on Sarasota ol District brake shoes, OEM factory nufacturered brake shoes, or new e shoes. | Florida I | Detroit Diese | I-Allison | | Ga | ry Yeomans I | Ford | |
| Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** |
| ITOR 312 or approved alternate. | | | | | | | | |
| New Front Shoe Kit, includes 2 Shoes and Hadware Kit (Freightliner) - SUB8824HD | TDA KSR6094702QP | \$116.93 | | \$116.93 | KSR6094702QP | \$105.96 | 17% | \$87.95 |
| New Rear Shoe Kit, includes 2 Shoes and Hardware Kit - SUB8000HD | TDA KSR6104702QP | \$138.15 | | \$138.15 | KSR6104702QP | \$133.56 | 17% | \$110.85 |
| Remanufactured Front Shoe Kit - includes 2 Shoes and Hardware Kit - KIT8824HD | TDA XK2124707QP | \$52.88 | | \$52.88 | XK3124702QP | \$95.84 | 17% | \$79.55 |
| Remanufactured Rear Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8000HD | TDA SMG14702QP | \$30.66 | | \$30.66 | XK3124707QP | \$73.89 | 17% | \$61.33 |
| Balance of line item discount for Meritor 312 or approved alternate. | | | | | | 179 | % | |
| ITOR or approved alternate. | | | | | | | | |
| Tapered Roller Hardware Kit - 8847HDA KIT | | | | | AS SPEC | \$36.71 | 17% | \$30.47 |
| Tapered Roller Only - 8847HD | | | | | AS SPEC | \$15.13 | 17% | \$12.56 |
| Balance of line item discount for Meritor or approved alternate. | | | | | | 179 | % | |
| DIX or approved alternate. | | | | | | | | |
| Drier - 107794X - AD9 | BW R107794 | \$27.96 | | \$27.96 | BX 107794X | \$27.40 | 17% | \$22.74 |
| Foot Pedal Valve - BW286171 E-6 | BW 286171 | \$68.70 | | \$68.70 | BX 286171N | \$88.41 | 17% | \$73.38 |
| Governor - 18530 | | | | | BSJ 18530 | \$38.81 | 17% | \$32.21 |
| Park Brake Valve - 800142 PP1 | BW 800142 | \$98.74 | | \$98.74 | BX 800142 | \$102.87 | 17% | \$85.38 |
| | ol District brake shoes, OEM factory nufacturered brake shoes, or new e shoes. Item and Description ITOR 312 or approved alternate. New Front Shoe Kit, includes 2 Shoes and Hadware Kit (Freightliner) - SUB8824HD New Rear Shoe Kit, includes 2 Shoes and Hardware Kit - SUB8000HD Remanufactured Front Shoe Kit - includes 2 Shoes and Hardware Kit - KIT8824HD Remanufactured Rear Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8824HD Remanufactured Rear Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8000HD Balance of line item discount for Meritor 312 or approved alternate. ITOR or approved alternate. ITOR or approved alternate. ITOR or approved alternate. Dalance of line item discount for Meritor or approved alternate. DIX or approved alternate. DIX or approved alternate. Drier - 107794X - AD9 Foot Pedal Valve - BW286171 E-6 Governor - 18530 | ol District brake shoes, OEM factory nufacturered brake shoes, or new e shoes.Florida IItem and DescriptionCircle Mfr & Part # or indicate alternate Mfr and Part #ITOR 312 or approved alternate.New Front Shoe Kit, includes 2 Shoes and Hadware Kit (Freightliner) - SUB8824HDNew Rear Shoe Kit, includes 2 Shoes and Hardware Kit - SUB8000HDTDA KSR6104702QPNew Rear Shoe Kit, includes 2 Shoes and Hardware Kit - SUB8000HDTDA KSR6104702QPRemanufactured Front Shoe Kit - includes 2 Shoes and Hardware Kit - KIT8824HDTDA XK2124707QPRemanufactured Rear Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8000HDTDA SMG14702QPBalance of line item discount for Meritor 312 or approved alternate.TDA SMG14702QPITOR or approved alternate.TDA SMG14702QPBalance of line item discount for Meritor 312 or approved alternate.TDA SMG14702QPITOR or approved alternate.TDA SMG14702QPITOR or approved alternate.TDA SMG14702QPBalance of line item discount for Meritor or approved alternate.Email Balance of line item discount for Meritor or approved alternate.DIX or approved alternate.Direr - 107794X - AD9BW R107794Foot Pedal Valve - BW286171 E-6BW 286171Governor - 18530Email Balance of line item discount for Meritor - 18530Email Balance of line item discount for Meritor - 18530 | ol District brake shoes, OEM factory nufacturered brake shoes, or new e shoes. Florida Detroit Diese Item and Description Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price ITOR 312 or approved alternate. New Front Shoe Kit, includes 2 Shoes and Hadware Kit (Freightliner) - SUB8824HD TDA KSR6094702QP \$116.93 New Rear Shoe Kit, includes 2 Shoes and Hardware Kit - SUB8000HD TDA KSR6104702QP \$118.15 Remanufactured Front Shoe Kit - includes 2 Shoes and Hardware Kit - KIT8824HD TDA XK2124707QP \$52.88 Remanufactured Rear Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8000HD TDA SMG14702QP \$30.66 Balance of line item discount for Meritor 312 or approved alternate. TDA SMG14702QP \$30.66 Balance of line item discount for Meritor 312 or approved alternate. TDA SMG14702QP \$30.66 Tapered Roller Hardware Kit - 8847HDA KIT Image: Comparison of the tem discount for Meritor or approved alternate. Image: Comparison of the tem discount for Meritor or approved alternate. Image: Comparison of tem discount for Meritor or approved alternate. Image: Comparison of tem discount for Meritor or approved alternate. Image: Comparison of tem discount for Meritor or approved alternate. Image: Comparison of tem discount for Meritor or approved alternate. Image: Comparison of tem discount for Merit | Plorida Detroit Diesel-Allison Florida Detroit Diesel-Allison Item and Description Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price % Discount ITOR 312 or approved alternate. Mr and Part # Wholesale Price % New Front Shoe Kit, includes 2 Shoes and Hadware Kit (Freightliner) - SUB8824HD TDA KSR6094702QP \$116.93 New Rear Shoe Kit, includes 2 Shoes and Hardware Kit - SUB8000HD TDA KSR6104702QP \$138.15 Remanufactured Front Shoe Kit - includes 2 Shoes and Hardware Kit - KIT8824HD TDA XK2124707QP \$52.88 Remanufactured Rear Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8000HD TDA SMG14702QP \$30.66 Balance of line item discount for Meritor 312 or approved alternate. TDA SMG14702QP \$30.66 TAP ered Roller Hardware Kit - 8847HDA KIT Image: State St | Florida Detroit Diesel-AllisonFlorida Detroit Diesel-AllisonItem and DescriptionCircle Mfr & Part # or indicate alternate Mfr and Part #Wholesale Price% DiscountDistrict Price***ITOR 312 or approved alternate. </td <td>Item and Description Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price % District Price** Circle Mfr & Part # or indicate alternate Mfr and Part # TOR 312 or approved alternate. Image: Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price % District Price** Circle Mfr & Part # or indicate alternate Mfr and Part # New Front Shoe Kit, includes 2 Shoes and Hadware Kit (Freightliner) - SUB8824HD TDA KSR6094702QP \$116.93 \$1</td> <td>IDENTICE brake shoes, OEM factory nufacturered brake shoes, or new shoes. Florida Detroit Diesel-Allison Gary Yeomans Item and Description Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price % Discount District Price** Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate S105.96 Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate S105.96 Circle Mfr & Part # or indicate alternate S105.96 Circle Mfr & Part # Circle Mfr & Staft S105.96 Circle Mfr & Staft S105.96 Circle Mfr & Staft S105.96 Circle Mfr & Staft S105.96 Staft S105.96 Circle Mfr & Staft S105.96 Staft S105.96 Circle Mfr & S</br></br></br></br></br></td> <td>IDIGENTIGE Trades shoes, OEM factory nudacturered brake shoes, OEM factory nudacturered brake shoes, OEM factory nudacturered brake shoes, or new is shoes. Florida Detroit Diesel-Allison Garry Yeomans Furtheresties Item and Description Circle Mfr & Part # or indicate alternate Mr and Part # Wholesale Price % District Price** Circle Mfr & Part # or indicate alternate Mr and Part # Wholesale Price % District Mfr and Part # Wholesale Shoes indicate alternate % Molesale Price % District Mfr and Part # Wholesale Shoes indicate alternate % Indic</td> | Item and Description Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price % District Price** Circle Mfr & Part # or indicate alternate Mfr and Part # TOR 312 or approved alternate. Image: Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price % District Price** Circle Mfr & Part # or indicate alternate Mfr and Part # New Front Shoe Kit, includes 2 Shoes and Hadware Kit (Freightliner) - SUB8824HD TDA KSR6094702QP \$116.93 \$1 | IDENTICE brake shoes, OEM factory nufacturered brake shoes, or new shoes. Florida Detroit Diesel-Allison Gary Yeomans Item and Description Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price % Discount District Price** Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate | IDIGENTIGE Trades shoes, OEM factory nudacturered brake shoes, OEM factory nudacturered brake shoes, OEM factory nudacturered brake shoes, or new is shoes. Florida Detroit Diesel-Allison Garry Yeomans Furtheresties Item and Description Circle Mfr & Part # or indicate alternate Mr and Part # Wholesale Price % District Price** Circle Mfr & Part # or indicate alternate Mr and Part # Wholesale Price % District Mfr and Part # Wholesale Shoes indicate alternate % Molesale Price % District Mfr and Part # Wholesale Shoes indicate alternate % Indic |

Tabulation for Bus Brake Repair Parts - Bid #0537

| Scho rema | Take linings will be riveted on Sarasota tool District brake shoes, OEM factory unufacturered brake shoes, or new to shoes. | NA | \PA Auto Par | ts | | | Neopart, LLC | | |
|--------------|--|--|--------------------|---------------|---------------------|--|--------------------|---------------|---------------------|
| Item # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** |
| MER | ITOR 312 or approved alternate. | | | | | | | | |
| 1. | New Front Shoe Kit, includes 2 Shoes and Hadware Kit (Freightliner) - SUB8824HD | 059U83-6N | \$58.15 | 16% | \$48.85 | MERITOR | \$233.79 | 61% | \$91.18 |
| 2. | | | | | | | | | |
| I | New Rear Shoe Kit, includes 2 Shoes and Hardware Kit - SUB8000HD | 046U93-6N | \$67.99 | 13% | \$59.15 | | | | |
| 3. | Remanufactured Front Shoe Kit - includes 2 Shoes and Hardware Kit - KIT8824HD | GR4702QG | \$52.99 | 3% | \$51.40 | | | | |
| 4. | Remanufactured Rear Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8000HD | GN4707QG | \$41.41 | 9% | \$37.68 | | | | |
| 5. | Balance of line item discount for Meritor 312 or approved alternate. | | 109 | % | | | 619 | 6 | |
| MER | ITOR or approved alternate. | | | | | | | | |
| 6. | Tapered Roller Hardware Kit - 8847HDA KIT | KIT8847HD | \$15.95 | 0% | \$15.95 | | \$70.50 | | |
| 7. | Tapered Roller Only - 8847HD | | | | | | \$25.86 | | |
| 8. | Balance of line item discount for Meritor or approved alternate. | | | | | | 619 | 6 | |
| BEN | DIX or approved alternate. | | | | | | | | |
| 9. | Drier - 107794X - AD9 | 107794X | \$33.08 | 6% | \$31.10 | | | | |
| 10. | Foot Pedal Valve - BW286171 E-6 | 286171RX | \$54.98 | 13% | \$47.83 | | \$161.09 | 54% | \$74.10 |
| 11. | Governor - 18530 | H284358 | \$12.92 | 21% | \$10.21 | | | | |
| 12. | Park Brake Valve - 800142 PP1 | 107794X | \$33.08 | 6% | \$31.10 | | \$187.42 | 54% | \$86.21 |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA Tabulation for Bus Brake Repair Parts - Bid #0537

| Scho rema | ake linings will be riveted on Sarasota ol District brake shoes, OEM factory nufacturered brake shoes, or new e shoes. | Ροι | wer Brake, LL | .C | | Sun S | tate Interna | itional | |
|--------------|---|--|--------------------|---------------|---------------------|--|---------------------|---------------|---------------------|
| ltem # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price* | % Discount | District Price** |
| MER | ITOR 312 or approved alternate. | | | | | | | | |
| 1. | New Front Shoe Kit, includes 2 Shoes and Hadware Kit (Freightliner) - SUB8824HD | | | | | KSMA3124702QP | \$55.72 | 10% | \$50.15 |
| 2. | New Rear Shoe Kit, includes 2 Shoes and Hardware Kit - SUB8000HD | | | | | KSMA3124707QP | \$79.10 | 10% | \$71.19 |
| 3. | Remanufactured Front Shoe Kit - includes 2 Shoes and Hardware Kit - KIT8824HD | 4702QP MARATHON KUT | \$61.90 | 13.5% | \$53.54 | XK3124702QP | \$51.79 | 10% | \$46.61 |
| 4. | Remanufactured Rear Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8000HD | 4707QP MARATHON KUT | \$68.36 | 13.5% | \$59.13 | XK3124707QP | \$55.86 | 10% | \$50.27 |
| 5. | Balance of line item discount for Meritor 312 or approved alternate. | | 13.5 | % | | | 10% | 6 | |
| MER | ITOR or approved alternate. | | | | | | | | |
| 6. | Tapered Roller Hardware Kit - 8847HDA KIT | EUCLID KIT8847HDA | \$56.40 | 37.5% | \$35.25 | KIT8847HD | \$14.09 | 0% | \$14.09 |
| 7. | Tapered Roller Only - 8847HD | EUCLID KIT8847HD | \$23.26 | 37.5% | \$14.54 | 2297T7222 | \$1.86 | 0% | \$1.86 |
| 8. | Balance of line item discount for Meritor or approved alternate. | | 37.5 | % | | | 0% | 0 | |
| BEN | DIX or approved alternate. | | | | | | | | |
| 9. | Drier - 107794X - AD9 | | | | | BX107794X | \$24.66 | 0% | \$24.66 |
| 10. | Foot Pedal Valve - BW286171 E-6 | | | | | SMR286171N | \$38.10 | 0% | \$38.10 |
| 11. | Governor - 18530 | | | | | SMR275491N | \$9.42 | 0% | \$9.42 |
| 12. | Park Brake Valve - 800142 PP1 | | | | | BX800142 | \$92.59 | 0% | \$92.59 |

Tabulation for Bus Brake Repair Parts - Bid #0537

| Scho rema | rake linings will be riveted on Sarasota ool District brake shoes, OEM factory anufacturered brake shoes, or new e shoes. | TPH Acquisitio | TPH Acquisition, LLLP dba The Parts House | | | | | | |
|--------------|--|--|---|------------|---------------------|--|--|--|--|
| ltem # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price* | % Discount | District Price** | | | | |
| MER | NTOR 312 or approved alternate. | | | | | | | | |
| 1. | New Front Shoe Kit, includes 2 Shoes and Hadware Kit (Freightliner) - SUB8824HD | KSMA3124702QP | \$143.74 | 65% | \$50.31 | | | | |
| 2. | New Rear Shoe Kit, includes 2 Shoes and Hardware Kit - SUB8000HD | KSMA3124707QP | \$204.06 | 65% | \$71.42 | | | | |
| 3. | Remanufactured Front Shoe Kit - includes 2 Shoes and Hardware Kit - KIT8824HD | XK3124702QP | \$133.60 | 65% | \$46.76 | | | | |
| 4. | Remanufactured Rear Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8000HD | XK3124707QP | \$144.14 | 65% | \$50.45 | | | | |
| 5. | Balance of line item discount for Meritor 312 or approved alternate. | | 58 | % | | | | | |
| MER | ITOR or approved alternate. | | | | | | | | |
| 6. | Tapered Roller Hardware Kit - 8847HDA KIT | KIT 8847HDA | \$70.49 | 58% | \$29.61 | | | | |
| 7. | Tapered Roller Only - 8847HD | KIT 8847HD | \$29.07 | 58% | \$12.21 | | | | |
| 8. | Balance of line item discount for Meritor or approved alternate. | | 58 | % | | | | | |
| BEN | DIX or approved alternate. | | | | | | | | |
| 9. | Drier - 107794X - AD9 | 107794X | \$52.55 | 60% | \$21.02 | | | | |
| 10. | Foot Pedal Valve - BW286171 E-6 | OR286171X | \$87.79 | 58% | \$36.87 | | | | |
| 11. | Governor - 18530 | OR275491X | \$29.11 | 58% | \$12.23 | | | | |
| 12. | Park Brake Valve - 800142 PP1 | 800142 | \$187.42 | 55% | \$84.34 | | | | |
| | | | | | | | | | |

Tabulation for Bus Brake Repair Parts - Bid #0537

| | ion for Bao Brake Ropan Farto | | | | | | 1 7 | 20, 2010 a | I |
|---------------------------|---|--|--------------------|---------------|---------------------|--|--------------------|---------------|---------------------|
| School Distric | igs will be riveted on Sarasota ct brake shoes, OEM factory rered brake shoes, or new | Fleet Acquisition | ns, LLC dba | a Fleet Pr | oducts | | Fleet Prid | e | |
| Item # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** |
| BENDIX or ap | pproved alternate (continued). | | | | | | | | |
| 13. Park Bra | ake Valve - 801315 C2 PP1 | BENDIX 801315 | \$262.16 | 57% | \$112.73 | | \$262.16 | 53% | \$123.22 |
| 14. Purge V | /alve Kit - 5005037 - AD9 | BENDIX 5005037 | \$58.64 | 57% | \$25.22 | | \$58.64 | 53% | \$27.56 |
| 15. Quick R | elease Valve - 800063 | AS SPEC | \$22.53 | 57% | \$9.69 | | \$22.53 | 53% | \$10.59 |
| 16. Quick R | elease Valve - 800064 | AS SPEC | \$22.53 | 57% | \$9.69 | | \$22.53 | 53% | \$10.59 |
| 17. Valve - 0 | QRN-2 | BENDIX 800219 | \$59.17 | | \$25.44 | 800063 | \$22.53 | 53% | \$10.59 |
| | e of line item discount for or approved alternate. | | BEN 579 | | | | 539 | 53% | |
| GUNITE or W approved alte | VEBB where indicated or errate. | | | | | | | | |
| | rum (Freightliner) - 3800X or 65548B Webb | GUNITE 3800X | \$353.04 | 67% | \$116.50 | 65548B | \$354.30 | 67% | \$116.92 |
| | rum (International Harvester Gunite 3721 or Webb 61528B | GUNITE 3721AX | \$350.89 | 67% | \$115.79 | 61528B | \$373.40 | 67% | \$123.22 |
| 21. Grooved 66884B | d Drum (Freightliner) - Webb | GUNITE 3576X | \$369.74 | 67% | \$122.01 | 66884B | \$412.67 | 67% | \$136.18 |
| | rum (International Harvester 3647 Gunite or 66353F Webb | GUNITE 3757 | \$403.37 | 67% | \$133.11 | 66353F | \$461.97 | 67% | \$152.45 |
| 23. Rear Dr Webb | rum (Freightliner) - 66843B | WEBB 66843B | \$454.77 | 65% | \$159.17 | 66843B | \$454.77 | 67% | \$150.07 |
| | (5) | MERITOR 03123207002 | \$212.83 | 56% | \$93.65 | 66864B | \$359.90 | 67% | \$118.77 |
| | e of line item discount for Webb, or approved alternate. | | GUN 679 | | | | 679 | % | |

Tabulation for Bus Brake Repair Parts - Bid #0537

| | | | | | | , | -, | |
|--|--|--|---|---|---|---|---|---|
| ol District brake shoes, OEM factory nufacturered brake shoes, or new | Florida I | Detroit Diesel | -Allison | | Ga | ry Yeomans I | Ford | |
| Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** |
| DIX or approved alternate (continued). | | | | | | | | |
| Park Brake Valve - 801315 C2 PP1 | BW 801315 | \$137.14 | | \$137.14 | BX 801315 | \$143.90 | 17% | \$119.44 |
| Purge Valve Kit - 5005037 - AD9 | BW 5005037 | \$30.65 | | \$30.65 | BX 5005037 | \$32.18 | 17% | \$26.71 |
| Quick Release Valve - 800063 | BW 800063 | \$11.87 | | \$11.87 | BX 800063 | \$12.36 | 17% | \$10.26 |
| Quick Release Valve - 800064 | BW 800064 | \$11.87 | | \$11.87 | BX 800064 | \$12.36 | 17% | \$10.26 |
| Valve - QRN-2 | BW 065067 | \$24.32 | | \$24.32 | BX 800219 | \$32.47 | 17% | \$26.95 |
| Balance of line item discount for Bendix or approved alternate. | | | | | | \$32.47 17% 17% | | |
| | | | | | | | | |
| Front Drum (Freightliner) - 3800X Gunite or 65548B Webb | GUN 3800XBULK | \$93.68 | | \$93.68 | AS SPEC WEBB | \$135.10 | 17% | \$112.13 |
| Front Drum (International Harvester Corp.) - Gunite 3721 or Webb 61528B | GUN 3721AXBULK | \$92.58 | | \$92.58 | AS SPEC WEBB | \$141.68 | 17% | \$117.59 |
| Grooved Drum (Freightliner) - 66884B Webb | WWD 66884B | \$170.13 | | \$170.13 | AS SPEC | \$156.56 | 17% | \$129.94 |
| Rear Drum (International Harvester Corp.) - 3647 Gunite or 66353F Webb | GUN 3757BULK | \$124.90 | | \$124.90 | ZBR 3647 | \$153.78 | 17% | \$127.64 |
| Rear Drum (Freightliner) - 66843B Webb | WWD 66843B | \$202.44 | | \$202.44 | WWP 66843B | \$175.98 | 17% | \$146.06 |
| Rear Drum (Freightliner) - 3600AX Gunite or 66864B Webb | GUN 3600AXBULK | \$79.38 | | \$79.38 | ZBR 3600AX | \$116.42 | 17% | \$96.63 |
| Balance of line item discount for Gunite, Webb, or approved alternate. | | | | | | 17% | 6 | |
| | DIX or approved alternate (continued). Park Brake Valve - 801315 C2 PP1 Purge Valve Kit - 5005037 - AD9 Quick Release Valve - 800063 Quick Release Valve - 800064 Valve - QRN-2 Balance of line item discount for Bendix or approved alternate. ITE or WEBB where indicated or oved alternate. Front Drum (Freightliner) - 3800X Gunite or 65548B Webb Front Drum (International Harvester Corp.) - Gunite 3721 or Webb 61528B Grooved Drum (Freightliner) - 66884B Webb Rear Drum (International Harvester Corp.) - 3647 Gunite or 66353F Webb Rear Drum (Freightliner) - 66843B Webb Rear Drum (Freightliner) - 3600AX Gunite or 66864B Webb Balance of line item discount for | Not District brake shoes, OEM factory nufacturered brake shoes, or new e shoes.Florida IItem and DescriptionCircle Mfr & Part # or indicate alternate Mfr and Part #DIX or approved alternate (continued).Park Brake Valve - 801315 C2 PP1Purge Valve Kit - 5005037 - AD9BW 801315Purge Valve Kit - 5005037 - AD9BW 800063Quick Release Valve - 800063BW 800064Valve - QRN-2BW 065067Balance of line item discount for Bendix or approved alternate.BW 065067ITE or WEBB where indicated or oved alternate.GUN 3800XBULKFront Drum (Freightliner) - 3800X Gunite or 65548B WebbGUN 3721AXBULKGrooved Drum (Freightliner) - 66884B WebbGUN 3757BULKRear Drum (International Harvester Corp.) - 3647 Gunite or 66353F WebbGUN 3757BULKRear Drum (Freightliner) - 66843B WebbWWD 66843BRear Drum (Freightliner) - 3600AX Gunite or 66864B WebbGUN 3600AXBULK | Not District brake shoes, OEM factory mufacturered brake shoes, or new a shoes.Florida Detroit DieselItem and DescriptionCircle Mfr & Part # or indicate alternate Mfr and Part #Wholesale PriceDIX or approved alternate (continued).Park Brake Valve - 801315 C2 PP1BW 801315\$137.14Purge Valve Kit - 5005037 - AD9BW 5005037\$30.65Quick Release Valve - 800063BW 800063\$11.87Quick Release Valve - 800064BW 800064\$11.87Quick Release Valve - 800064BW 065067\$24.32Balance of line item discount for Bendix or approved alternate.BW 065067\$24.32TE or WEBB where indicated or oved alternate.GUN 3800XBULK\$93.68Front Drum (Freightliner) - 3800X Gunite or 65548B WebbGUN 3721AXBULK\$92.58Grooved Drum (Freightliner) - 66884B WebbWWD 66884B\$170.13Rear Drum (International Harvester Corp.) - 3647 Gunite or 66353F WebbGUN 3757BULK\$124.90Rear Drum (Freightliner) - 66843B Webb\$202.44Rear Drum (Freightliner) - 3600AX Gunite or 66864B WebbGUN 3757BULK\$124.90 | Plorida District brake shoes, OEM factory unfacturered brake shoes, or new e shoes. Florida Detroit Diesel-Allison Item and Description Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price % Discount DIX or approved alternate (continued). Park Brake Valve - 801315 C2 PP1 BW 801315 \$1137.14 Image: Content of | Florida Detroit Diesel-AllisonFlorida Detroit Diesel-AllisonItem and DescriptionCircle Mfr & Part # or indicate alternate Mfr and Part #Wholesale Price% DiscourtDistrict Price***DIX or approved alternate (continued). </td <td>Priorida Detroit Diesel-Allison Ga Item and Description Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price % District Price*** Circle Mfr & Part # or indicate alternate Mfr and Part # District Price*** Circle Mfr & Part # or indicate alternate Mfr and Part # DX or approved alternate (continued). Image: Circle Mfr & Part # or indicate alternate Mholesale Price % District Price*** Circle Mfr & Part # or indicate alternate Park Brake Valve - 801315 C2 PP1 BW 801315 \$137.14 S137.14 S137.14 BX 8001315 Quick Release Valve - 80063 BW 80063 \$11.87 S11.87 BX 800063 Quick Release Valve - 80064 BW 800064 \$11.87 S11.87 BX 800064 Quick Release Valve - 80064 BW 065067 \$24.32 \$24.32 BX 800219 Balance of line item discount for Bendix or approved alternate. Image: Circle Mfr & Part # or indicate alternate S11.87 S11.87 BX 800219 Front Drum (Freightliner) - 3800X GUN 3800XBULK \$93.68 \$93.68 AS SPEC WEBB Front Drum (International Harvester Corp.) - Gunite 3721 or Webb 61528B GUN 3721AXBULK \$92.58 \$170.13 AS SPEC Rear Drum (Int</br></br></br></br></br></td> <td>Florida Detroit Diesel-Allison Gary Yeomans I shoes. Item and Description Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price % Discount District Price* Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate Sti 43.90 Quick Release Valve - 8005037 - AD9 BW 8005037 \$30.65 Sti 11.87 BX 800063 \$11.87 BX 800063 \$12.36 Quick Release Valve - 800563 BW 800567 \$24.32 Sti 8.80064 \$12.36 \$17.97 TE or WEBB where indicated or oved alternate. BW 065067 \$24.32 \$24.32 BX 800064 \$11.87 \$18.000 <t< td=""><td>Initial brack shoes, OEM factory as hoes. Florida Detroit Diesel-Allison Gary Yeomans Jest Service Stress Item and Description Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Mfr and Part # % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # % No No</td></t<></td> | Priorida Detroit Diesel-Allison Ga Item and Description Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price % District Price*** Circle Mfr & Part # or indicate alternate Mfr and Part # District Price*** Circle Mfr & Part # or indicate alternate Mfr and Part # DX or approved alternate (continued). Image: Circle Mfr & Part # or indicate alternate Mholesale | Florida Detroit Diesel-Allison Gary Yeomans I shoes. Item and Description Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price % Discount District Price* Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price Circle Mfr & Part # or indicate alternate Mfr and Part # Circle Mfr & Part # or indicate alternate Sti 43.90 Quick Release Valve - 8005037 - AD9 BW 8005037 \$30.65 Sti 11.87 BX 800063 \$11.87 BX 800063 \$12.36 Quick Release Valve - 800563 BW 800567 \$24.32 Sti 8.80064 \$12.36 \$17.97 TE or WEBB where indicated or oved alternate. BW 065067 \$24.32 \$24.32 BX 800064 \$11.87 \$18.000 <t< td=""><td>Initial brack shoes, OEM factory as hoes. Florida Detroit Diesel-Allison Gary Yeomans Jest Service Stress Item and Description Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Mfr and Part # % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # % No No</td></t<> | Initial brack shoes, OEM factory as hoes. Florida Detroit Diesel-Allison Gary Yeomans Jest Service Stress Item and Description Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Price Circle Mfr & Part # or indicate alternate Mfr and Part # Wholesale Mfr and Part # % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # % District Discourt Circle Mfr & Part # or indicate alternate Mfr and Part # % No No |

Tabulation for Bus Brake Repair Parts - Bid #0537

| | | | | | | | , | | | |
|--------------|--|--|--------------------|---------------|---------------------|--|--------------------|---------------|---------------------|--|
| Scho rema | rake linings will be riveted on Sarasota ool District brake shoes, OEM factory anufacturered brake shoes, or new e shoes. | NA | APA Auto Par | ts | | | Neopart, LLC | | | |
| Item # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | |
| BEN | DIX or approved alternate (continued). | | | | | | | | | |
| 13. | Park Brake Valve - 801315 C2 PP1 | BEN 801315 | \$160.39 | 13% | \$139.54 | | \$262.16 | 54% | \$120.59 | |
| 14. | Purge Valve Kit - 5005037 - AD9 | 5005037K | \$40.99 | 3% | \$39.76 | | \$58.64 | 54% | \$26.97 | |
| 15. | Quick Release Valve - 800063 | KN32011 | \$10.99 | 5% | \$10.44 | | \$22.53 | 54% | \$10.36 | |
| 16. | Quick Release Valve - 800064 | KN32005 | \$10.99 | 5% | \$10.44 | | \$22.53 | 54% | \$10.36 | |
| 17. | Valve - QRN-2 | | | | | | | | | |
| 18. | Balance of line item discount for Bendix or approved alternate. | | 109 | % | | | 54% | | | |
| | ITE or WEBB where indicated or oved alternate. | | | | | | | | | |
| 19. | Front Drum (Freightliner) - 3800X Gunite or 65548B Webb | AS SPEC GUNITE | \$157.69 | 13% | \$137.19 | WEBB | \$354.30 | 48% | \$184.24 | |
| 20. | Front Drum (International Harvester Corp.) - Gunite 3721 or Webb 61528B | AS SPEC WEBB | \$179.99 | 13% | \$156.59 | | \$373.40 | 48% | \$194.17 | |
| 21. | Grooved Drum (Freightliner) - 66884B Webb | AS SPEC | \$165.69 | 13% | \$144.15 | | \$412.67 | 48% | \$214.59 | |
| 22. | Rear Drum (International Harvester Corp.) - 3647 Gunite or 66353F Webb | AS SPEC WEBB | \$222.69 | 13% | \$193.74 | | \$461.97 | 48% | \$240.22 | |
| 23. | Rear Drum (Freightliner) - 66843B Webb | AS SPEC | \$219.39 | 13% | \$190.87 | | \$454.77 | 48% | \$236.48 | |
| 24. | Rear Drum (Freightliner) - 3600AX Gunite or 66864B Webb | AS SPEC GUNITE | \$112.62 | 14% | \$96.85 | | \$359.90 | 48% | \$187.15 | |
| 25. | Balance of line item discount for Gunite, Webb, or approved alternate. | | 139 | % | | | 489 | 48% | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA Tabulation for Bus Brake Repair Parts - Bid #0537

| | | | | | | peried may 2 | -, | |
|---|--|--------------------|---------------|---------------------|--|-------------------------|---------------|---------------------|
| All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufacturered brake shoes, or new brake shoes. | | wer Brake, LL | _C | | Sun S | Sun State International | | |
| Item # Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price* | % Discount | District Price** |
| BENDIX or approved alternate (continued). | | | | | | | | |
| 13. Park Brake Valve - 801315 C2 PP1 | | | | | BX800315 | \$129.51 | 0% | \$129.51 |
| 14. Purge Valve Kit - 5005037 - AD9 | | | | | BX5005037 | \$28.96 | 0% | \$28.96 |
| 15. Quick Release Valve - 800063 | | | | | BX800063 | \$11.13 | 0% | \$11.13 |
| 16. Quick Release Valve - 800064 | | | | | BX800064 | \$11.13 | 0% | \$11.13 |
| 17. Valve - QRN-2 | | | | | BX800064 | \$11.13 | 0% | \$11.13 |
| 18. Balance of line item discount for Bendix or approved alternate. | | | 1 | | | 0% | | |
| GUNITE or WEBB where indicated or approved alternate. | | | | | | | | |
| 19. Front Drum (Freightliner) - 3800X Gunite or 65548B Webb | AS SPEC WEBB* | \$272.91 | 24.15% | \$207.00 | ZBR3800X | \$115.70 | 10% | \$104.13 |
| 20. Front Drum (International Harvester Corp.) - Gunite 3721 or Webb 61528B | OTR1501* | \$235.73 | 25.6% | \$175.38 | ZBR3721AX | \$115.00 | 10% | \$103.50 |
| 21. Grooved Drum (Freightliner) - 66884B Webb | AS SPEC WEBB* | \$268.25 | 24.32% | \$203.01 | WWP66884B | \$142.30 | 10% | \$128.07 |
| 22. Rear Drum (International Harvester Corp.) - 3647 Gunite or 66353F Webb | AS SPEC WEBB* | \$285.39 | 23.76% | \$217.58 | ZBR3647X | \$134.59 | 10% | \$121.13 |
| 23. Rear Drum (Freightliner) - 66843B Webb | OTR1601* | \$250.09 | 39.28% | \$151.85 | W66843B | \$156.82 | 5% | \$148.98 |
| 24. Rear Drum (Freightliner) - 3600AX Gunite or 66864B Webb | OTR1601* | \$250.09 | 39.28% | \$151.85 | ZBR3600AX | \$94.22 | 21% | \$74.43 |
| 25. Balance of line item discount for Gunite, Webb, or approved alternate. | | 29.91 | 1% | | | \$94.22 21% 5% | | |

Tabulation for Bus Brake Repair Parts - Bid #0537

| Scho rema | rake linings will be riveted on Sarasota ool District brake shoes, OEM factory anufacturered brake shoes, or new e shoes. | TPH Acquisitio | n, LLLP dba | The Parts H | ouse |
|--------------|--|--|---------------------|-------------|---------------------|
| ltem # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price* | % Discount | District Price** |
| BEN | DIX or approved alternate (continued). | | | | |
| 13. | Park Brake Valve - 801315 C2 PP1 | 801315 | \$262.16 | 55% | \$117.97 |
| 14. | Purge Valve Kit - 5005037 - AD9 | 5005037 | \$58.64 | 55% | \$26.39 |
| 15. | Quick Release Valve - 800063 | AS SPEC | \$22.53 | 55% | \$10.14 |
| 16. | Quick Release Valve - 800064 | AS SPEC | \$22.53 | 55% | \$10.14 |
| 17. | Valve - QRN-2 | 800063 | \$22.53 | 55% | \$10.14 |
| 18. | Balance of line item discount for Bendix or approved alternate. | | 55 | % | |
| | ITE or WEBB where indicated or oved alternate. | | | | |
| 19. | Front Drum (Freightliner) - 3800X Gunite or 65548B Webb | AS SPEC GUNITE | \$353.04 | 67% | \$116.50 |
| 20. | Front Drum (International Harvester Corp.) - Gunite 3721 or Webb 61528B | GUNITE 3721AX | \$350.89 | 67% | \$115.79 |
| 21. | Grooved Drum (Freightliner) - 66884B Webb | AS SPEC | \$412.67 | 72% | \$115.55 |
| 22. | Rear Drum (International Harvester Corp.) - 3647 Gunite or 66353F Webb | AS SPEC WEBB | \$461.97 | 67% | \$152.45 |
| 23. | Rear Drum (Freightliner) - 66843B Webb | AS SPEC | \$454.77 | 67% | \$150.07 |
| 24. | Rear Drum (Freightliner) - 3600AX Gunite or 66864B Webb | AS SPEC GUNITE | \$279.86 | 69% | \$86.76 |
| 25. | Balance of line item discount for Gunite, Webb, or approved alternate. | | WEBE GUNIT | | |

Tabulation for Bus Brake Repair Parts - Bid #0537

| | | | | | | | | 20, 2010 a | |
|--------------|--|--|--------------------|---------------|---------------------|--|--------------------|---------------|---------------------|
| Scho rema | rake linings will be riveted on Sarasota ool District brake shoes, OEM factory anufacturered brake shoes, or new e shoes. | Fleet Acquisitior | ns, LLC dba | a Fleet Pro | oducts | | Fleet Pride | e | |
| ltem # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** |
| MON | NROE or approved alternate. | | | | | | | | |
| 26. | Front Shocks (International Harvester Corp.) - 66923 | AS SPEC | \$77.91 | 67% | \$25.71 | | \$79.16 | 63% | \$29.29 |
| 27. | Front Shocks (Freightliner) - 85006 | EUCLID 85006 | \$80.56 | 48% | \$41.89 | | \$89.89 | 63% | \$33.26 |
| 28. | Front C2 Shocks - 65140 | AS SPEC | \$128.51 | 67% | \$42.41 | | \$130.60 | 63% | \$48.32 |
| 29. | Rear Shocks (International Harvester Corp.) - 66924 | AS SPEC | \$79.63 | 67% | \$26.28 | | \$80.92 | 63% | \$29.94 |
| 30. | Rear Shocks (Freightliner) - 65409 | AS SPEC | \$135.90 | 67% | \$44.85 | | \$135.90 | 63% | \$50.28 |
| 31. | Rear Shocks (Freightliner) - 85013 | EUCLID 85013 | \$88.31 | 48% | \$45.92 | 66894 | \$88.03 | 63% | \$32.57 |
| 32. | Rear C2 Shocks - 65490 | AS SPEC | \$162.00 | 67% | \$53.46 | | \$164.60 | 63% | \$60.90 |
| 33. | Balance of line item discount for Monroe or approved alternate. | | MONE 679 | | | | 63 ⁴ | % | |
| MIDI | LAND or approved alternate. | | | | | | | | |
| 34. | Check Valve - KN23000 | AS SPEC | \$42.50 | 57% | \$18.28 | | \$42.50 | 54% | \$19.55 |
| 35. | Clevis Brake Chamber - KN36470 | AS SPEC | \$4.95 | 57% | \$2.13 | | \$7.05 | 54% | \$3.24 |
| 36. | Dash Valve - KN20033 | AS SPEC | \$54.82 | 57% | \$23.57 | | \$54.82 | 54% | \$25.22 |
| 37. | Park Brake Valve (International Harvester Corp.) - RKN20031 PP1 | MIDLAND KN20031 | \$54.82 | 57% | \$23.57 | | \$54.82 | 54% | \$25.22 |
| 38. | Balance of line item discount for Midland or approved alternate. | | MIDL 579 | | | | 54% | | |

Tabulation for Bus Brake Repair Parts - Bid #0537

| | 1 | | | | | 1 | | , | I |
|--------------|--|--|--------------------|---------------|---------------------|--|--------------------|---------------|---------------------|
| Scho rema | rake linings will be riveted on Sarasota ool District brake shoes, OEM factory anufacturered brake shoes, or new e shoes. | Florida I | Detroit Diesel | -Allison | | Ga | Gary Yeomans Ford | | |
| ltem # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** |
| MON | IROE or approved alternate. | | | | | | | | |
| 26. | Front Shocks (International Harvester Corp.) - 66923 | MAE 66923 | \$30.70 | | \$30.70 | AMS 66923 | \$39.40 | 24% | \$29.94 |
| 27. | Front Shocks (Freightliner) - 85006 | TDA 85006 | \$41.94 | | \$41.94 | AMS 6898 | \$50.23 | 43% | \$28.63 |
| 28. | Front C2 Shocks - 65140 | MAE 65140 | \$47.25 | | \$47.25 | AMS 65140 | \$60.53 | 24% | \$46.00 |
| 29. | Rear Shocks (International Harvester Corp.) - 66924 | MAE 66924 | \$33.77 | | \$33.77 | AMS 66924 | \$40.28 | 25% | \$30.21 |
| 30. | Rear Shocks (Freightliner) - 65409 | MAE 65409 | \$68.98 | | \$68.98 | AMS 65409 | \$62.99 | 25% | \$47.24 |
| 31. | Rear Shocks (Freightliner) - 85013 | TDA 85013 | \$45.98 | | \$45.98 | AMS 85013 | \$55.06 | 17% | \$45.70 |
| 32. | Rear C2 Shocks - 65490 | MAE 65490 | \$68.71 | | \$68.71 | AMS 65490 | \$76.30 | 23% | \$58.75 |
| 33. | Balance of line item discount for Monroe or approved alternate. | | | | | | 25% | 6 | |
| MIDI | AND or approved alternate. | | | | | | | | |
| 34. | Check Valve - KN23000 | | | | | BENDIX BX800372 | \$19.41 | 16% | \$16.30 |
| 35. | Clevis Brake Chamber - KN36470 | HDX KN36470 | | | | MID ZZCF2 | \$4.12 | 20% | \$3.30 |
| 36. | Dash Valve - KN20033 | | | | | MERITOR RKN20033 | \$34.27 | 22% | \$26.73 |
| 37. | Park Brake Valve (International Harvester Corp.) - RKN20031 PP1 | TDA RKN 20031 | \$28.15 | | \$28.15 | MERITOR RKN20031 | \$34.27 | 22% | \$26.73 |
| 38. | Balance of line item discount for Midland or approved alternate. | | | | | 20% | | | |

Tabulation for Bus Brake Repair Parts - Bid #0537

| | • | | | | | | | , | |
|--------------|--|--|--------------------|---------------|---------------------|--|--------------------|---------------|---------------------|
| Scho rema | rake linings will be riveted on Sarasota ool District brake shoes, OEM factory unufacturered brake shoes, or new e shoes. | NA | NPA Auto Par | Neopart, LLC | | | | | |
| ltem # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** |
| MON | IROE or approved alternate. | | | | | | | | |
| 26. | Front Shocks (International Harvester Corp.) - 66923 | AS SPEC | \$41.74 | 20% | \$33.39 | | \$79.16 | 52% | \$38.00 |
| 27. | Front Shocks (Freightliner) - 85006 | 66898 | \$45.94 | 20% | \$36.75 | | | | |
| 28. | Front C2 Shocks - 65140 | AS SPEC | \$68.95 | 20% | \$55.16 | | \$130.60 | 52% | \$62.69 |
| 29. | Rear Shocks (International Harvester Corp.) - 66924 | AS SPEC | \$42.66 | 20% | \$34.13 | | \$80.92 | | |
| 30. | Rear Shocks (Freightliner) - 65409 | AS SPEC | \$71.73 | 20% | \$57.38 | | \$135.90 | | |
| 31. | Rear Shocks (Freightliner) - 85013 | 66894 | \$46.44 | 20% | \$37.15 | | | | |
| 32. | Rear C2 Shocks - 65490 | AS SPEC | \$86.52 | 20% | \$69.22 | | | | |
| 33. | Balance of line item discount for Monroe or approved alternate. | | 209 | % | | | | | |
| MIDL | AND or approved alternate. | | | | | | | | |
| 34. | Check Valve - KN23000 | AS SPEC | \$21.39 | 4% | \$20.53 | | \$46.72 | 62% | \$17.75 |
| 35. | Clevis Brake Chamber - KN36470 | CF2 | \$3.69 | 7% | \$3.43 | | | | |
| | Dash Valve - KN20033 | AS SPEC | \$27.39 | 3% | \$26.57 | | \$60.91 | 62% | \$23.15 |
| 37. | Park Brake Valve (International Harvester Corp.) - RKN20031 PP1 | KN20031 | \$37.39 | 29% | \$26.55 | | \$60.91 | 62% | \$23.15 |
| 38. | Balance of line item discount for Midland or approved alternate. | | 104 | % | | | | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA Tabulation for Bus Brake Repair Parts - Bid #0537

| | | | | | | - | ponoa may 2 | -, | 1 |
|--------------|--|--|--------------------|-------------------------|---------------------|--|---------------------|---------------|---------------------|
| Scho rema | rake linings will be riveted on Sarasota ool District brake shoes, OEM factory anufacturered brake shoes, or new e shoes. | Po | wer Brake, Ll | Sun State International | | | | | |
| Item # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price* | % Discount | District Price** |
| MON | IROE or approved alternate. | | | | | | | | |
| 26. | Front Shocks (International Harvester Corp.) - 66923 | | | | | AMS66923 | \$33.92 | 5% | \$32.22 |
| 27. | Front Shocks (Freightliner) - 85006 | | | | | AMS66884 | \$39.38 | 5% | \$37.41 |
| 28. | Front C2 Shocks - 65140 | | | | | AMS65140 | \$49.18 | 5% | \$46.72 |
| 29. | Rear Shocks (International Harvester Corp.) - 66924 | | | | | AMS66924 | \$34.68 | 5% | \$32.95 |
| 30. | Rear Shocks (Freightliner) - 65409 | | | | | AMS65409 | \$51.18 | 5% | \$48.62 |
| 31. | Rear Shocks (Freightliner) - 85013 | | | | | AMS66894 | \$37.72 | 5% | \$35.83 |
| 32. | Rear C2 Shocks - 65490 | | | | | AMS65490 | \$61.99 | 5% | \$58.89 |
| 33. | Balance of line item discount for Monroe or approved alternate. | | | | | | 5% | / 0 | |
| MIDI | AND or approved alternate. | | | | | | | | |
| 34. | Check Valve - KN23000 | | | | | RKN23000 | \$22.43 | 5% | \$21.31 |
| 35. | Clevis Brake Chamber - KN36470 | | | | | ZZCF2 | \$3.57 | 5% | \$3.39 |
| 36. | Dash Valve - KN20033 | | | | | RKN20033 | \$29.24 | 5% | \$27.78 |
| 37. | Park Brake Valve (International Harvester Corp.) - RKN20031 PP1 | | | | | RKN20031 | \$29.24 | 5% | \$27.78 |
| 38. | Balance of line item discount for Midland or approved alternate. | | | | | | 5% | , 0 | |

Tabulation for Bus Brake Repair Parts - Bid #0537

| Scho rema | rake linings will be riveted on Sarasota ool District brake shoes, OEM factory anufacturered brake shoes, or new e shoes. | TPH Acquisitio | on, LLLP dba | The Parts He | ouse |
|--------------|--|--|---------------------|--------------|---------------------|
| ltem # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price* | % Discount | District Price** |
| MON | IROE or approved alternate. | GABRIEL | | | |
| 26. | Front Shocks (International Harvester Corp.) - 66923 | 83456 | \$58.03 | 48% | \$30.18 |
| 27. | Front Shocks (Freightliner) - 85006 | 85006 | \$80.56 | 48% | \$41.89 |
| 28. | Front C2 Shocks - 65140 | 85918 | \$86.20 | 48% | \$44.82 |
| 29. | Rear Shocks (International Harvester Corp.) - 66924 | 83317 | \$57.96 | 48% | \$30.14 |
| 30. | Rear Shocks (Freightliner) - 65409 | 85003 | \$83.45 | 48% | \$43.39 |
| 31. | Rear Shocks (Freightliner) - 85013 | 85013 | \$88.31 | 48% | \$45.92 |
| 32. | Rear C2 Shocks - 65490 | 85724 | \$100.92 | 48% | \$52.48 |
| 33. | Balance of line item discount for Monroe or approved alternate. | | GABRI | EL 48% | |
| MIDI | _AND or approved alternate. | | | | |
| 34. | Check Valve - KN23000 | AS SPEC | \$42.50 | 56% | \$18.70 |
| 35. | Clevis Brake Chamber - KN36470 | REPLACED BY CF2 | \$7.05 | 56% | \$3.10 |
| 36. | Dash Valve - KN20033 | AS SPEC | \$54.82 | 56% | \$24.12 |
| 37. | Park Brake Valve (International Harvester Corp.) - RKN20031 PP1 | KN20031 | \$54.82 | 56% | \$24.12 |
| 38. | Balance of line item discount for Midland or approved alternate. | | HALDEX/MI | DLAND 56% | |

Tabulation for Bus Brake Repair Parts - Bid #0537

| Scho | rake linings will be riveted on Sarasota ool District brake shoes, OEM factory | Fleet Acquisition | ns, LLC dba | a Fleet Pro | oducts | Fleet Pride | | | | |
|-----------|---|--|--------------------|---------------|---------------------|--|--------------------|---------------|---------------------|--|
| | anufacturered brake shoes, or new e shoes. | | | | | | | | | |
| Item # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | |
| | IONAL or CHICAGO RAWHIDE where ated, or approved alternate. | | | | | | | | | |
| 39. | Front Seal - 35066 Chicago Rawhide | AS SPEC | \$66.01 | 62% | \$25.08 | 370001A | \$28.64 | 20% | \$22.91 | |
| 40. | Front Seal (International Harvester Corp. and Freightliner) - 370001A National | AS SPEC | \$63.58 | 67% | \$20.98 | | \$28.64 | 20% | \$22.91 | |
| | Rear Seal (International Harvester Corp.) - 370023A National | AS SPEC | \$81.23 | 67% | \$26.81 | | \$36.59 | 20% | \$29.27 | |
| 42. | Rear Seal (Freightliner) - 370003A National or 47697 Chicago Rawhide | AS SPEC NATIONAL | \$80.74 | 67% | \$26.64 | | \$36.37 | 20% | \$29.10 | |
| 43. | Balance of line item discount for National, Chicago Rawhide, or approved alternate. | | NATIC 679 | | | | 20% | | | |
| FED | ERAL or approved alternate. | | | | | | | | | |
| 44. | Bearings (Freightliner) - 572 | TIMKEN 572 | \$51.26 | 76% | \$12.30 | | \$23.05 | 60% | \$9.22 | |
| 45. | Bearings (Freightliner) - 580 | TIMKEN 580 | \$82.23 | 76% | \$19.74 | | \$36.93 | 60% | \$14.77 | |
| 46. | Bearings (Freightliner) - 592-A | TIMKEN 592A | \$62.60 | 76% | \$15.02 | | \$28.36 | 60% | \$11.34 | |
| 47. | Bearings (Freightliner) - 594-A | TIMKEN 594A | \$95.93 | 76% | \$23.02 | | \$43.00 | 60% | \$17.20 | |
| 48. | Bearings (International Harvester Corp.) - 39520 | TIMKEN 39520 | \$34.05 | 76% | \$8.17 | | \$14.89 | 60% | \$5.96 | |
| 49. | Bearings (International Harvester Corp.) - 39590 | TIMKEN 39590 | \$57.25 | 76% | \$13.74 | | \$25.11 | 60% | \$10.04 | |
| 50. | Bearings (International Harvester Corp.) - 47620 | TIMKEN 47620 | \$58.52 | 76% | \$14.04 | | \$26.38 | 60% | \$10.55 | |
| 51. | Bearings (International Harvester Corp.) - 47686 | TIMKEN 47686 | \$91.11 | 76% | \$21.87 | | \$40.63 | 60% | \$16.25 | |
| 52. | Balance of line item discount for Federal or approved alternate. | | TIMK 769 | | | | 60 | % | | |

Tabulation for Bus Brake Repair Parts - Bid #0537

| | • | | | | | | | | |
|--------------|--|--|--------------------|---------------|---------------------|--|--------------------|---------------|---------------------|
| Scho rema | rake linings will be riveted on Sarasota ool District brake shoes, OEM factory anufacturered brake shoes, or new e shoes. | | Detroit Diese | l-Allison | | Ga | ry Yeomans I | Ford | |
| Item # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** |
| | IONAL or CHICAGO RAWHIDE where cated, or approved alternate. | _ | | | | | | | |
| - | Front Seal - 35066 Chicago Rawhide | AS SPEC | \$25.72 | | \$25.72 | AS SPEC | \$29.36 | 22% | \$22.90 |
| 40. | Front Seal (International Harvester Corp. and Freightliner) - 370001A National | AS SPEC | \$21.26 | | \$21.26 | AS SPEC | \$24.14 | 19% | \$19.55 |
| | Rear Seal (International Harvester Corp.) - 370023A National | AS SPEC | \$26.12 | | \$26.12 | AS SPEC | \$30.22 | 21% | \$23.87 |
| 42. | Rear Seal (Freightliner) - 370003A National or 47697 Chicago Rawhide | AS SPEC NATIONAL | \$26.96 | | \$26.96 | AS SPEC NATIONAL | \$30.14 | 17% | \$25.02 |
| 43. | Balance of line item discount for National, Chicago Rawhide, or approved alternate. | | | | | | 20% | 6 | |
| FED | ERAL or approved alternate. | | | | | | | | |
| 44. | Bearings (Freightliner) - 572 | SBN 572TRB | \$12.75 | | \$12.75 | C/R SKFBR572 | \$18.91 | 12% | \$16.64 |
| 45. | Bearings (Freightliner) - 580 | SBN 580TRB | \$20.61 | | \$20.61 | C/R SKFBR580 | \$30.44 | 12% | \$26.79 |
| 46. | Bearings (Freightliner) - 592-A | SBN 592ATRB | \$15.71 | | \$15.71 | C/R SKFBR592A | \$22.90 | 13% | \$19.92 |
| 47. | Bearings (Freightliner) - 594-A | SBN 594ATRB | \$24.35 | | \$24.35 | C/R SKFBR594A | \$34.98 | 13% | \$30.43 |
| 48. | Bearings (International Harvester Corp.) - 39520 | SBN 39520TRB | \$9.33 | | \$9.33 | C/R FP39520 | \$12.01 | 14% | \$10.33 |
| 49. | Bearings (International Harvester Corp.) - 39590 | TDA 39590 | \$25.16 | | \$25.16 | C/R FP39590 | \$20.19 | 12% | \$17.77 |
| 50. | Bearings (International Harvester Corp.) - 47620 | SBN 47620TRB | \$16.19 | | \$16.19 | C/R SKFBR47620 | \$22.02 | 12% | \$19.38 |
| | Bearings (International Harvester Corp.) - 47686 | TDA 47686 | \$38.00 | | \$38.00 | C/R SKFBR47686 | \$34.91 | 13% | \$30.37 |
| 52. | Balance of line item discount for Federal or approved alternate. | | | | | | 13% | 6 | |

Tabulation for Bus Brake Repair Parts - Bid #0537

| | • | | | | | | , | , | |
|--------------|--|--|--------------------|---------------|---------------------|--|--------------------|---------------|---------------------|
| Scho rema | rake linings will be riveted on Sarasota ool District brake shoes, OEM factory anufacturered brake shoes, or new e shoes. | NA | NPA Auto Par | ts | | | Neopart, LLC | ; | |
| ltem # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** |
| | IONAL or CHICAGO RAWHIDE where | | | | | | | 1 1 | |
| | ated, or approved alternate. | | | | | | No | List Availa | ble |
| 39. | Front Seal - 35066 Chicago Rawhide | AS SPEC | \$31.72 | 5% | \$30.13 | | | | |
| 40. | Front Seal (International Harvester Corp. and Freightliner) - 370001A National | AS SPEC | \$24.99 | 0% | \$24.99 | | | | |
| 41. | Rear Seal (International Harvester Corp.) - 370023A National | AS SPEC | \$29.99 | 0% | \$29.99 | | | | |
| 42. | Rear Seal (Freightliner) - 370003A National or 47697 Chicago Rawhide | AS SPEC NATIONAL | \$31.99 | 0% | \$31.99 | | | | |
| 43. | Balance of line item discount for National, Chicago Rawhide, or approved alternate. | | 5% | /o | | | | | |
| FED | ERAL or approved alternate. | | | | | | No | List Availa | ble |
| 44. | Bearings (Freightliner) - 572 | TIMKEN 572 | \$17.39 | 5% | \$16.52 | | | | |
| 45. | Bearings (Freightliner) - 580 | AS SPEC | \$27.99 | 5% | \$26.59 | | | | |
| 46. | Bearings (Freightliner) - 592-A | AS SPEC | \$21.69 | 6% | \$20.39 | | | | |
| 47. | Bearings (Freightliner) - 594-A | AS SPEC | \$32.39 | 5% | \$30.77 | | | | |
| 48. | Bearings (International Harvester Corp.) - 39520 | AS SPEC | \$11.99 | 7% | \$11.15 | | | | |
| 49. | Bearings (International Harvester Corp.) - 39590 | AS SPEC | \$19.69 | 5% | \$18.71 | | | | |
| 50. | Bearings (International Harvester Corp.) - 47620 | AS SPEC | \$20.69 | 5% | \$19.66 | | | | |
| 51. | Bearings (International Harvester Corp.) - 47686 | AS SPEC | \$32.39 | 5% | \$30.77 | | | | |
| 52. | Balance of line item discount for Federal or approved alternate. | | 5% | 6 | | | | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA Tabulation for Bus Brake Repair Parts - Bid #0537

| Scho rema | ake linings will be riveted on Sarasota ol District brake shoes, OEM factory nufacturered brake shoes, or new e shoes. | Po | wer Brake, Ll | | Sun State International | | | | |
|--------------|---|--|--------------------|---------------|-------------------------|--|---------------------|---------------|---------------------|
| Item # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price* | % Discount | District Price** |
| | ONAL or CHICAGO RAWHIDE where | | | | | | | | |
| | ated, or approved alternate. | | | | | | | | |
| 39. | Front Seal - 35066 Chicago Rawhide | | | | | AS SPEC | \$27.53 | 10% | \$24.78 |
| | Front Seal (International Harvester Corp. and Freightliner) - 370001A National | | | | | V370001A | \$23.26 | 5% | \$22.10 |
| | Rear Seal (International Harvester Corp.) - 370023A National | | | | | V370023A | \$28.64 | 5% | \$27.21 |
| | Rear Seal (Freightliner) - 370003A National or 47697 Chicago Rawhide | | | | | V370003A | \$29.55 | 5% | \$28.07 |
| | Balance of line item discount for National, Chicago Rawhide, or approved alternate. | | | | | | 5% | 6 | |
| FEDE | ERAL or approved alternate. | | | | | | | | |
| 44. | Bearings (Freightliner) - 572 | | | | | FP572 | \$16.27 | 5% | \$15.46 |
| 45. | Bearings (Freightliner) - 580 | | | | | FP580 | \$23.19 | 5% | \$22.03 |
| 46. | Bearings (Freightliner) - 592-A | | | | | FP592A | \$22.33 | 5% | \$21.21 |
| 47. | Bearings (Freightliner) - 594-A | | | | | FP594A | \$29.52 | 5% | \$28.04 |
| | Bearings (International Harvester Corp.) - 39520 | | | | | FP39520 | \$12.00 | 5% | \$11.40 |
| | Bearings (International Harvester Corp.) - 39590 | | | | | FP39590 | \$19.52 | 5% | \$18.54 |
| | Bearings (International Harvester Corp.) - 47620 | | | | | FP47620 | \$21.00 | 5% | \$19.95 |
| | Bearings (International Harvester Corp.) - 47686 | | | | | FP47686 | \$33.51 | 5% | \$31.83 |
| 52. | Balance of line item discount for Federal or approved alternate. | | | | | | 5% | ́о | |

Tabulation for Bus Brake Repair Parts - Bid #0537

| Scho rema | rake linings will be riveted on Sarasota ool District brake shoes, OEM factory anufacturered brake shoes, or new e shoes. | TPH Acquisitic | on, LLLP dba | The Parts Ho | ouse |
|--------------|--|--|---------------------|--------------|---------------------|
| ltem # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price* | % Discount | District Price** |
| | IONAL or CHICAGO RAWHIDE where | | | | |
| | ated, or approved alternate. | NATIONAL 370001A | *Jobber Price | 23% | ¢22.05 |
| | Front Seal - 35066 Chicago Rawhide | NATIONAL 370001A | \$28.64 | 23% | \$22.05 |
| 40. | Front Seal (International Harvester Corp. and Freightliner) - 370001A National | AS SPEC | \$28.64 | 23% | \$22.05 |
| | Rear Seal (International Harvester Corp.) - 370023A National | AS SPEC | \$36.59 | 23% | \$28.17 |
| | Rear Seal (Freightliner) - 370003A National or 47697 Chicago Rawhide | AS SPEC NATIONAL | \$36.37 | 23% | \$28.00 |
| 43. | Balance of line item discount for National, Chicago Rawhide, or approved alternate. | | NATIONA | | |
| FED | ERAL or approved alternate. | TIMKEN | *Jobber Price | | |
| 44. | Bearings (Freightliner) - 572 | 572 | \$23.09 | 38% | \$14.32 |
| 45. | Bearings (Freightliner) - 580 | 580 | \$37.04 | 38% | \$22.96 |
| 46. | Bearings (Freightliner) - 592-A | 592A | \$28.20 | 38% | \$17.48 |
| 47. | Bearings (Freightliner) - 594-A | 594A | \$43.21 | 38% | \$26.79 |
| 48. | Bearings (International Harvester Corp.) - 39520 | 39520 | \$15.34 | 38% | \$9.51 |
| 49. | Bearings (International Harvester Corp.) - 39590 | 39590 | \$25.79 | 38% | \$15.99 |
| 50. | Bearings (International Harvester Corp.) - 47620 | 47620 | \$26.36 | 38% | \$16.34 |
| | Bearings (International Harvester Corp.) - 47686 | 47686 | \$41.04 | 38% | \$25.44 |
| 52. | Balance of line item discount for Federal or approved alternate. | | TIMKEN Less | | |

Tabulation for Bus Brake Repair Parts - Bid #0537

| Tabalation for Bae Braite Repair r | | | | | | oponioù may | 20, 2010 a | 0.00 piiii | | |
|---|--|--------------------|---------------|---------------------|--|--------------------|---------------|---------------------|--|--|
| All brake linings will be riveted on Saras School District brake shoes, OEM factor remanufacturered brake shoes, or new brake shoes. | | ns, LLC dba | Fleet Pride | | | | | | | |
| Item # Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | | |
| STEMCO or CHICAGO RAWHIDE whe indicated or approved alternate. | e | | | | | | | | | |
| 53. Front Gasket (Freightliner) - 45386 Chicago Rawhide | 9 AS SPEC | \$2.69 | 62% | \$1.02 | 330-3024 | \$2.49 | 50% | \$1.25 | | |
| 54. Front Hub, Oiler (International Harvester Corp.) - 343-4009 Stem | | \$32.63 | 53% | \$15.34 | | \$32.61 | 50% | \$16.31 | | |
| 55. Front Hub, Oiler (Freightliner) - 343 4024 Stemco | AS SPEC | \$55.93 | 53% | \$26.29 | | \$55.92 | 50% | \$27.96 | | |
| 56. Front Hub, Oiler (Freightliner) - 16 Chicago Rawhide | AS SPEC | \$44.15 | 62% | \$16.78 | | \$50.73 | 50% | \$25.37 | | |
| 57. Front Hub Gasket (Freightliner) - 330-3024 Stemco | AS SPEC | \$2.50 | 53% | \$1.18 | | \$2.49 | 50% | \$1.25 | | |
| 58. Hub Cap, Oiler - 359-5990 Stemco 450434 Chicago Rawhide | or AS SPEC STEMCO | \$5.10 | 53% | \$2.40 | | \$5.09 | 50% | \$2.55 | | |
| 59. Hub Gasket, Large, Oiler - 330-300 Stemco | AS SPEC | \$2.45 | 53% | \$1.15 | | \$2.44 | 50% | \$1.22 | | |
| 60. Balance of line item discount for Stemco, Chicago Rawhide, or approved alternate. | | STEMCO 53% | | | | | % | | | |
| | ** Ext | ension corre | ctions | | ** Ex | tension corre | ections | | | |
| Contact | Anth | nony V. Zur | nmo | | | Andrew Be | ell | | | |
| Address | 6510 Go | olden Grov | es Lane | | | Vhitfield Pa | • | | | |
| Address | Tar | mpa, FL 33 | 610 | | Sar | asota, FL 3 | 34243 | | | |
| Phone | | 13-621-173 | | | - | 941-758-82 | | | | |
| Fax | | 13-626-201 | | | 9 | 941-752-36 | | | | |
| Federal I.D. # | | 621868964 | | | | | 630681070 | | | |
| E-mail | 2711000 | Ofleetprodu | ictsfl.com | | andy be | ell2@fleetp | ride.com | | | |

Tabulation for Bus Brake Repair Parts - Bid #0537

| · · · · · · · · · · · · · · · · · · · | | | | | | · · · · · · · · · · · · · · · · · · | -, | |
|---|--|--------------------------|---------------|---------------------|--|-------------------------------------|---------------|---------------------|
| All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufacturered brake shoes, or new brake shoes. | | Detroit Diesel | -Allison | Gary Yeomans Ford | | | | |
| Item # Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** |
| STEMCO or CHICAGO RAWHIDE where indicated or approved alternate. 53. Front Gasket (Freightliner) - 453869 | _ | | | | | | | |
| Chicago Rawhide | AS SPEC | \$1.18 | | \$1.18 | AS SPEC | \$1.20 | 19% | \$0.97 |
| 54. Front Hub, Oiler (International Harvester Corp.) - 343-4009 Stemco | AS SPEC | \$16.18 | | \$16.18 | ZCP 3434009 | \$18.41 | 20% | \$14.73 |
| 55. Front Hub, Oiler (Freightliner) - 343- 4024 Stemco | AS SPEC | \$27.75 | | \$27.75 | ZCP 3434024 | \$31.23 | 20% | \$24.98 |
| 56. Front Hub, Oiler (Freightliner) - 1612 Chicago Rawhide | AS SPEC | \$16.59 | | \$16.59 | AS SPEC | \$19.63 | 19% | \$15.90 |
| 57. Front Hub Gasket (Freightliner) - 330-3024 Stemco | AS SPEC | \$1.48 | | \$1.48 | ZCP 3303024 | \$1.39 | 20% | \$1.11 |
| 58. Hub Cap, Oiler - 359-5990 Stemco or 450434 Chicago Rawhide | AS SPEC STEMCO | \$2.68 | | \$2.68 | AS SPEC CHICAGO RAWHIDE | \$1.71 | 18% | \$1.40 |
| 59. Hub Gasket, Large, Oiler - 330-3009 Stemco | AS SPEC | \$1.29 | | \$1.29 | ZCP 3303009 | \$1.36 | 20% | \$1.09 |
| 60. Balance of line item discount for Stemco, Chicago Rawhide, or approved alternate. | | | | | | 20% | % | |
| | ** Ext | ension correc | ctions | | ** Ex | tension corre | ctions | |
| Contact | F | hil Singletary | / | | | Ray Grubbs | | |
| Address | | I1 Adamo Dri | | | 1420 Nor | th Tomoka Fa | arms Road | |
| Address | Та | mpa, FL 336 ⁻ | 19 | | Dayto | na Beach, FL | 32124 | |
| Phone | 8 | 313-621-5651 | | | | 800-231-617 | 2 | |
| Fax | 8 | 313-620-1172 | 2 | | 386-274-6744 | | | |
| Federal I.D. # | | | | | | 592164165 | | |
| | | | .com | | | garyyeoman | | |

Tabulation for Bus Brake Repair Parts - Bid #0537

| Scho rema | rake linings will be riveted on Sarasota ool District brake shoes, OEM factory anufacturered brake shoes, or new e shoes. | NA | Neopart, LLC | | | | | | | |
|--------------|--|--|--------------------|---------------|-----------------------|--|--------------------------|---------------|---------------------|--|
| ltem # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | |
| | MCO or CHICAGO RAWHIDE where | | | | | | | | | |
| | ated or approved alternate. | - | | | | | | | | |
| 53. | Front Gasket (Freightliner) - 453869 Chicago Rawhide | AS SPEC | \$1.29 | 5% | \$1.23 | | | | | |
| 54. | Front Hub, Oiler (International Harvester Corp.) - 343-4009 Stemco | AS SPEC | \$19.69 | 5% | \$18.71 | | | | | |
| 55. | Front Hub, Oiler (Freightliner) - 343- 4024 Stemco | AS SPEC | \$33.69 | | \$32.01 | | | | | |
| 56. | Front Hub, Oiler (Freightliner) - 1612 Chicago Rawhide | AS SPEC | \$21.21 | 5% | \$20.15 | | | | | |
| 57. | Front Hub Gasket (Freightliner) - 330-3024 Stemco | AS SPEC | \$1.69 | 15% | \$1.44 | | | | | |
| 58. | Hub Cap, Oiler - 359-5990 Stemco or 450434 Chicago Rawhide | AS SPEC CHICAGO RAWHIDE | \$1.84 | 5% | \$1.75 | | | | | |
| | Hub Gasket, Large, Oiler - 330-3009 Stemco | AS SPEC | \$1.69 | 17% | \$1.40 | | | | | |
| 60. | Balance of line item discount for Stemco, Chicago Rawhide, or approved alternate. | 5% | | | | | | | | |
| | | ** Ext | ension correc | tions | | ** Ex | tension corre | ctions | | |
| Cont | act | Jol | hn F. Chianes | se | | | P. Gendall | | | |
| Addr | ess | 1955 | Upper Beech | wood | | 505 ⁻ | 1 Horseshoe | Drive | | |
| Addr | ess | Sar | asota, FL 342 | 231 | | Hone | y Brook, PA | 19344 | | |
| Phor | ne | g | 941-924-1241 | | | | 610-518-757 | 5 | | |
| Fax | | g | 941-922-5041 | | | | 610-518-755 [,] | 1 | | |
| Fede | eral I.D. # | | 580254510 | | | | 260654890 | | | |
| E-ma | ail | john ch | nianese@gen | pt.com | marketing@neopart.com | | | | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA Tabulation for Bus Brake Repair Parts - Bid #0537

| | Tabulation for Bus Brake Repair Parts | - Bid #0537 | | | | • | pened May 2 | 6, 2010 at | 3:00 p.m. | |
|--------------|---|--|---------------------------------|---------------|---------------------|--|--------------------------------|----------------|---------------------|--|
| Scho rema | ake linings will be riveted on Sarasota ol District brake shoes, OEM factory nufacturered brake shoes, or new e shoes. | Po | wer Brake, Ll | LC | | Sun State International | | | | |
| Item # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price | % Discount | District Price** | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price* | % Discount | District Price** | |
| | MCO or CHICAGO RAWHIDE where | | | | | | | | | |
| | ated or approved alternate. Front Gasket (Freightliner) - 453869 Chicago Rawhide | | | | | AS SPEC | \$1.13 | 10% | \$1.02 | |
| | Front Hub, Oiler (International Harvester Corp.) - 343-4009 Stemco | | | | | ZCP3434009 | \$16.04 | 0% | \$16.04 | |
| 55. | Front Hub, Oiler (Freightliner) - 343- 4024 Stemco | | | | | ZCP3434024 | \$27.20 | 0% | \$27.20 | |
| 56. | Front Hub, Oiler (Freightliner) - 1612 Chicago Rawhide | | | | | AS SPEC | | | \$16.56 | |
| 57. | Front Hub Gasket (Freightliner) - 330-3024 Stemco | | | | | ZCP3303024 | \$1.21 | 0% | \$1.21 | |
| 58. | Hub Cap, Oiler - 359-5990 Stemco or 450434 Chicago Rawhide | | | | | ZCP3595990 | \$2.45 | 0% | \$2.45 | |
| 59. | Hub Gasket, Large, Oiler - 330-3009 Stemco | | | | | ZCP3593009 | \$1.19 | 0% | \$1.19 | |
| 60. | Balance of line item discount for Stemco, Chicago Rawhide, or approved alternate. | | | | | | 0% | , D | | |
| | | | ension corrected d carry a 4 ye | | / | | tension corre onal Fleet Pr | | | |
| Cont | act | TI | homas D. Co | x | | Paul Dearth | | | | |
| Addr | ess | 4351 E | 3 34th Street | North | | 8247 15th Street East | | | | |
| Addr | | St. Pet | tersburg, FL | 33714 | | | asota, FL 34 | | | |
| Phor | le | 7 | 27-526-1333 | 3 | | | 41-355-768 | | | |
| Fax | | 7 | 27-526-1306 | 6 | | | 41-351-910 | | | |
| | ral I.D. # | | 223934354 | | | | 593750718 | | | |
| E-ma | ail | | | | | paul@r | <u>mail.sunsti</u> | <u>ntl.com</u> | | |
| | | | | | | | | | | |

Tabulation for Bus Brake Repair Parts - Bid #0537

| | rabalation for Bao Braito repair raito | | | | | oponou may 20, 2010 |
|----------------|--|--|---------------------|------------|-------------------------------|------------------------------|
| Scho rema | rake linings will be riveted on Sarasota ool District brake shoes, OEM factory anufacturered brake shoes, or new e shoes. | TPH Acquisition, LLLP dba The Parts House | | | | |
| Item # | Item and Description | Circle Mfr & Part # or indicate alternate Mfr and Part # | Wholesale Price* | % Discount | District Price** | |
| | MCO or CHICAGO RAWHIDE where | | | | | |
| | ated or approved alternate. | | | | | |
| 53. | Front Gasket (Freightliner) - 453869 Chicago Rawhide | | | | | |
| 54. | Front Hub, Oiler (International Harvester Corp.) - 343-4009 Stemco | | | | | _ |
| 55. | Front Hub, Oiler (Freightliner) - 343- 4024 Stemco | | | | | |
| 56. | Front Hub, Oiler (Freightliner) - 1612 Chicago Rawhide | | | | | |
| 57. | Front Hub Gasket (Freightliner) - 330-3024 Stemco | | | | | |
| 58. | Hub Cap, Oiler - 359-5990 Stemco or 450434 Chicago Rawhide | | | | | |
| 59. | Hub Gasket, Large, Oiler - 330-3009 Stemco | | | | | _ |
| 60. | Balance of line item discount for Stemco, Chicago Rawhide, or approved alternate. | | | | | |
| | | ** Extension corrections List Price | | | | |
| Contact | | Richard Kilpatrick | | | | _ |
| Address | | 4083 Sawyer Court | | | | |
| Address | | Sarasota, FL 34233 | | | | |
| Phone | | 941-924-2394 | | | | |
| Fax | | 941-924-8621 | | | | Recorded by: Peggy Long |
| Federal I.D. # | | 611436406 | | | | |
| E-mail | | rkilpatrick@thepartshouse.com | | | Witnessed by: Carol A. Lichon | |
| | | | | | | No bid from Tampa Spring Co. |
| | | | | | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA JUSTIFICATION

| Item # | Bidder | Reason For Not Awarding To Other Than Low Bidder | | | |
|----------|---|--|--|--|--|
| 1 2 | NAPA Auto Parts | Unable to evaluate discount as only net pricing (Customer List) was submitted with bid. | | | |
| 4 | Florida Detroit Diesel-Allison | Price sheets were not submitted as required in bid specifications. | | | |
| | NAPA Auto Parts | Unable to evaluate discount as only net pricing (Customer List) was submitted with bid. | | | |
| | NAPA Auto Parts | Unable to evaluate discount as only net pricing (Customer List) was submitted with bid. | | | |
| 6 | Neopart, LLC | Price sheets were not submitted as required in bid specifications. | | | |
| | Sun State International | Pricing incorrect for parts required. | | | |
| 7 | Neopart, LLC | Price sheets were not submitted as required in bid specifications. | | | |
| , | Sun State International | Pricing incorrect for parts required. | | | |
| 8 | Neopart, LLC | Price sheets were not submitted as required in bid specifications. | | | |
| 12 | NAPA Auto Parts | Unable to evaluate discount as only net pricing (Customer List) was submitted with bid. | | | |
| 19 20 | Florida Detroit Diesel-Allison | Price sheets were not submitted as required in bid specifications. | | | |
| 23 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. | | | |
| | Fleet Acquisitions, LLC dba Fleet Products Fleet Pride | Vendors were not awarded any item in the category. | | | |
| 25 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. | | | |
| 20 | NAPA Auto Parts | Unable to evaluate discount as only net pricing (Customer List) was submitted with bid. | | | |
| | Neopart, LLC | Price sheets were not submitted as required in bid specifications. | | | |
| | Power Brake, LLC | Price sheets were not submitted as required in bid specifications. | | | |
| | Fleet Acquisitions, LLC dba Fleet Products | Price sheets were not submitted as required in bid specifications. | | | |
| 26 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. | | | |
| | Fleet Pride | Price sheets were not submitted as required in bid specifications. Could not access price sheets on disc as document was a 'shortcut' to price sheets. | | | |
| 27 | Fleet Pride | Price sheets were not submitted as required in bid specifications. Could not access price sheets on disc as document was a 'shortcut' to price sheets. | | | |
| 21 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. | | | |
| | NAPA Auto Parts | Unable to evaluate discount as only net pricing (Customer List) was submitted with bid. | | | |
| 28 | Fleet Acquisitions, LLC dba Fleet Products | Price sheets were not submitted as required in bid specifications. | | | |
| | Fleet Acquisitions, LLC dba Fleet Products | Price sheets were not submitted as required in bid specifications. | | | |
| 29 | Fleet Pride | Price sheets were not submitted as required in bid specifications. Could not access price sheets on disc as document was a 'shortcut' to price sheets. | | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA JUSTIFICATION

| | | 303111641101 | | | |
|----------|--|--|--|--|--|
| 31 | Fleet Pride | Price sheets were not submitted as required in bid specifications. Could not access price sheets on disc as document was a 'shortcut' to price sheets. | | | |
| | Fleet Acquisitions, LLC dba Fleet Products | Price sheets were not submitted as required in bid specifications. Vendor was not awarded any item in the category. | | | |
| 33 | Fleet Pride Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. | | | |
| | NAPA Auto Parts | Unable to evaluate discount as only net pricing (Customer List) was submitted with bid. | | | |
| 34 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. | | | |
| 34 | Neopart, LLC | Price sheets were not submitted as required in bid specifications. | | | |
| 36 37 | Neopart, LLC | Price sheets were not submitted as required in bid specifications. | | | |
| 40 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. | | | |
| | Florida Detroit Diesel-Allison | | | | |
| 41 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. | | | |
| | Neopart, LLC | 1 | | | |
| 42 | Gary Yeomans Ford Neopart, LLC | Price sheets were not submitted as required in bid specifications. | | | |
| 52 | Fleet Acquisitions, LLC dba Fleet Products | Price sheets were not submitted as required in bid specifications. Vendor was not awarded any item in the category. | | | |
| | Fleet Acquisitions, LLC dba Fleet Products | Price sheets were not submitted as required in bid specifications. Tie bid awarded to Sun State International per tie bid specifications. | | | |
| 53 | Neopart, LLC | Price sheets were not submitted as required in bid specifications. Unable to evaluate discount as only net pricing was indicated. | | | |
| | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. | | | |
| 54 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. | | | |
| 55 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. | | | |
| | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. | | | |
| 56 | Neopart, LLC | Price sheets were not submitted as required in bid specifications. Unable to evaluate discount as only net pricing was indicated. | | | |
| 57 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. | | | |
| | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. | | | |
| 58 | NAPA Auto Parts | Unable to evaluate discount as only net pricing (Customer List) was submitted with bid. | | | |
| 00 | Neopart, LLC | Price sheets were not submitted as required in bid specifications. Unable to evaluate discount as only net pricing was indicated. | | | |
| 59 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. | | | |
| | · · · | | | | |