



THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

MATERIALS MANAGEMENT DEPARTMENT

101 OLD VENICE ROAD

OSPREY, FLORIDA 34229

TELEPHONE (941) 486-2183 • FAX (941) 486-2188

MEMORANDUM

**TO: Members of the School Board
Dr. Gary Norris, Superintendent
Ms. Mitsi Corcoran, Chief Financial Officer**

FROM: Pat Black, CPPB, Director of Materials Management

TITLE: APPROVAL TO AWARD BID #8099 FOR GYMNASIUM INSPECTION AND REPAIRS

Bids to provide 'Gymnasium Inspection and Repairs' were received from eight vendors on April 22, 2008. The bid of Southeastern Surfaces and Equipment was the best overall low bid utilizing a sealed scenario. This bid is for a period of one year with the option to renew for two additional one year periods. The funds for these purchases are contained in the capital budget allocated to the Facilities Services Department.

Requested by:
Jody Dumas

"Failure to file a protest within the time prescribed in Section 120.57(3), Florida Statutes, or failure to post the protest bond or other security required by law within the time allowed for filing a bond shall constitute a waiver of proceedings under Chapter 120, Florida Statutes."

Posting Date: 5-13-08

Fiscal Impact:

Not to exceed
\$300,000.00

Funding:

1180 Capital

Recommended Motion: That the bid of Southeastern Surfaces and Equipment, to provide 'Gymnasium Inspection and Repairs' in an amount not to exceed \$300,000.00, be approved for award and purchase.

(over)

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Bid Tabulation: Gymnasium Inspection and Repairs - Bid #8099

Bid Opening: April 22, 2008 - 2:00 p.m.

			Charron Sports Services, Inc.	Gymdoors Florida, LLC	Hufcor Florida Group
Item	Description	Unit	Unit Price	Unit Price	Unit Price
A	INSPECTION SERVICES:				
1.	High Schools	Each	\$250.00	* \$24.00	\$900.00
2.	Middle Schools	Each	\$125.00	* \$24.00	\$900.00
B	BLEACHER REFURBISHMENT:				
3.	Refurbishment of one 16' section x 10 row bleachers as detailed in specifications	Each	\$90.00	\$325.00	\$440.00
C	UNIT PRICES FOR BLEACHER REPAIRS/REFURBISHMENTS:				
4.	Replace broken wheels or axles	Each	\$20.00	\$19.00	\$5.00
5.	Replace first row locking assemblies	Each	\$55.00	\$44.00	\$15.00
6.	Replace brake pads	Each	\$15.00	\$17.00	\$2.00
7.	Replace wheels	Each	\$20.00	\$19.00	\$80.00
8.	Replace first row lock release	Each	\$45.00	\$44.00	\$20.00
9.	Replace row locks	Each	\$25.00	\$20.00	\$10.00
10.	Straighten uprights	Each	\$70.00	\$40.00	\$55.00
11.	Adjust cantaliefvers	Each	\$18.00	\$20.00	\$12.00
12.	Weld stress fractures	Each	\$22.00	\$19.00	\$9.00
13.	Weld seat baffles	Each	\$22.00	\$19.00	\$9.00
14.	Weld seat brackets	Each	\$22.00	\$19.00	\$10.00
15.	Repair cracked boards	Each	\$24.00	\$19.00	\$15.00
16.	replace lower guide	Each	\$25.00	\$65.00	\$6.00
17.	Supply and install self storing rails	Each	\$146.00	\$125.00	\$145.00
18.	Supply and install motor operation system	Each	\$1,800.00	\$1,800.00	\$1,800.00
19.	Furnish and install floor anchors	Each	\$9.00	\$5.00	\$2.00
20.	Furnish and install wall toggle bolts	Each	\$19.00	\$15.00	\$2.00
21.	Furnish and install wall anchor brackets	Each	\$21.00	\$19.00	\$5.00
22.	Furnish and install replacement boards	Each	\$170.00	\$8.80/LF	\$128.00
23.	Furnish and install plywood deck (2' x 8')	Each	\$40.00	\$40.00	\$20.00
24.	Stain and apply water based finish to seat boards	Each	\$95.00	\$40.00	\$35.00
25.	Move and re-anchor 16' x 10-row bank in gymnasium	Each	\$250.00	\$525.00	\$375.00
D	BASKETBALL BACKSTOP REFURBISHMENT:				
26.	Service one basketball backstop as detailed in general specifications excluding unit price items listed below	Each	\$110.00	\$49.00	\$80.00
E	UNIT PRICES FOR BACKSTOP REPAIRS/REFURBISHMENTS:				
27.	Weld stress fractures	Each	\$70.00	\$65.00	\$25.00
28.	Replace pulley	Each	\$45.00	\$45.00	\$40.00
29.	Replace cable	Each	\$125.00	\$120.00	\$75.00
30.	Furnish and install manual winch	Each	\$560.00	\$505.00	\$450.00
31.	Furnish and install electric winch	Each	\$1,470.00	\$1,400.00	\$1,125.00
32.	Furnish and install safety strap	Each	\$475.00	\$470.00	\$460.00

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Bid Tabulation: Gymnasium Inspection and Repairs - Bid #8099

Bid Opening: April 22, 2008 - 2:00 p.m.

			Lyle Bleachers Inc.
Item	Description	Unit	Unit Price
A	INSPECTION SERVICES:		
1.	High Schools	Each	\$98.00
2.	Middle Schools	Each	\$98.00
B	BLEACHER REFURBISHMENT:		
3.	Refurbishment of one 16' section x 10 row bleachers as detailed in specifications	Each	\$475.00
C	UNIT PRICES FOR BLEACHER REPAIRS/REFURBISHMENTS:		
4.	Replace broken wheels or axles	Each	\$0.50
5.	Replace first row locking assemblies	Each	\$5.00
6.	Replace brake pads	Each	\$0.10
7.	Replace wheels	Each	\$0.50
8.	Replace first row lock release	Each	\$10.00
9.	Replace row locks	Each	\$41.99
10.	Straighten uprights	Each	\$55.00
11.	Adjust cantaliefvers	Each	\$42.47
12.	Weld stress fractures	Each	\$10.00
13.	Weld seat baffles	Each	\$10.00
14.	Weld seat brackets	Each	\$10.00
15.	Repair cracked boards	Each	\$15.00
16.	replace lower guide	Each	\$6.00
17.	Supply and install self storing rails	Each	\$248.00
18.	Supply and install motor operation system	Each	\$1,900.00
19.	Furnish and install floor anchors	Each	\$2.00
20.	Furnish and install wall toggle bolts	Each	\$2.00
21.	Furnish and install wall anchor brackets	Each	\$5.00
22.	Furnish and install replacement boards	Each	* \$7.00/LF
23.	Furnish and install plywood deck (2' x 8')	Each	\$20.00
24.	Stain and apply water based finish to seat boards	Each	* \$1.00/LF
25.	Move and re-anchor 16' x 10-row bank in gymnasium	Each	\$200.00
D	BASKETBALL BACKSTOP REFURBISHMENT:		
26.	Service one basketball backstop as detailed in general specifications excluding unit price items listed below	Each	\$121.00
E	UNIT PRICES FOR BACKSTOP REPAIRS/REFURBISHMENTS:		
27.	Weld stress fractures	Each	\$10.00
28.	Replace pulley	Each	\$25.00
29.	Replace cable	Each	\$119.00
30.	Furnish and install manual winch	Each	\$400.00
31.	Furnish and install electric winch	Each	\$1,155.00
32.	Furnish and install safety strap	Each	\$632.50

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Bid Tabulation: Gymnasium Inspection and Repairs - Bid #8099

Bid Opening: April 22, 2008 - 2:00 p.m.

Item	Description	Unit	Riptide Unlimited, Inc. Unit Price	Robbins Sport Floors Florida, LLC Unit Price	Seating Constructors USA Unit Price	Southeastern Surfaces & Equipment Unit Price
A	INSPECTION SERVICES:					
1.	High Schools	Each			\$210.00	\$0.00
2.	Middle Schools	Each			\$110.00	\$0.00
B	BLEACHER REFURBISHMENT:					
3.	Refurbishment of one 16' section x 10 row bleachers as detailed in specifications	Each			\$695.00	\$450.00
C	UNIT PRICES FOR BLEACHER REPAIRS/REFURBISHMENTS:					
4.	Replace broken wheels or axles	Each			\$22.00	\$5.00
5.	Replace first row locking assemblies	Each			\$22.00	\$15.00
6.	Replace brake pads	Each			\$18.00	\$2.50
7.	Replace wheels	Each			\$22.00	\$5.00
8.	Replace first row lock release	Each			\$80.00	\$15.00
9.	Replace row locks	Each			\$20.00	\$10.00
10.	Straighten uprights	Each			\$50.00	\$55.00
11.	Adjust cantaliefers	Each			\$25.00	\$10.00
12.	Weld stress fractures	Each			\$75.00	\$10.00
13.	Weld seat baffles	Each			\$18.00	\$10.00
14.	Weld seat brackets	Each			\$19.00	\$10.00
15.	Repair cracked boards	Each			\$20.00	\$15.00
16.	replace lower guide	Each			\$70.00	\$5.00
17.	Supply and install self storing rails	Each			\$190.00	\$140.00
18.	Supply and install motor operation system	Each			\$1,900.00	\$1,600.00
19.	Furnish and install floor anchors	Each			\$8.00	\$2.00
20.	Furnish and install wall toggle bolts	Each			\$19.00	\$2.00
21.	Furnish and install wall anchor brackets	Each			\$21.00	\$2.00
22.	Furnish and install replacement boards	Each			\$9.00/ft	* \$8.00/LF
23.	Furnish and install plywood deck (2' x 8')	Each			\$40.00	\$20.00
24.	Stain and apply water based finish to seat boards	Each			\$6.00/ft	* \$305.00
25.	Move and re-anchor 16' x 10-row bank in gymnasium	Each			\$600.00	\$400.00
D	BASKETBALL BACKSTOP REFURBISHMENT:					
26.	Service one basketball backstop as detailed in general specifications excluding unit price items listed below	Each			\$210.00	\$125.00
E	UNIT PRICES FOR BACKSTOP REPAIRS/REFURBISHMENTS:					
27.	Weld stress fractures	Each			\$80.00	\$25.00
28.	Replace pulley	Each			\$42.50	\$40.00
29.	Replace cable	Each			\$125.00	\$65.00
30.	Furnish and install manual winch	Each			\$600.00	\$450.00
31.	Furnish and install electric winch	Each			\$1,500.00	\$1,100.00
32.	Furnish and install safety strap	Each			\$500.00	\$450.00

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Bid Tabulation: Gymnasium Inspection and Repairs - Bid #8099

Bid Opening: April 22, 2008 - 2:00 p.m.

			Charron Sports Services, Inc.	Gymdoors Florida, LLC	Hufcor Florida Group
Item	Description	Unit	Unit Price	Unit Price	Unit Price
E	UNIT PRICES FOR BACKSTOP REPAIRS/REFURBISHMENTS (CONTINUED):				
33.	Furnish and install volleyball floor coverplate (8")	Each	\$170.00	\$250.00	\$125.00
34.	Furnish and install volleyball floor coverplate (5")	Each	\$145.00	\$220.00	\$125.00
35.	Furnish and install 2' x 6' wall pad	Each	\$52.00	\$75.00	\$70.00
36.	Furnish and install limit winch assembly	Each	\$90.00	\$200.00	\$75.00
37.	Furnish and install breakaway goal	Each	\$155.00	\$150.00	\$149.00
38.	Furnish and install manual height adjusters	Each	\$500.00	\$1,195.00	\$650.00
39.	Furnish and install electric height adjusters	Each	\$1,400.00	\$1,500.00	\$1,600.00
40.	Furnish and install fan fiberglass backboard	Each	\$550.00	\$815.00	\$450.00
41.	Furnish and install fan aluminum backboard	Each	\$480.00	\$578.00	\$350.00
42.	Furnish and install rectangular glass backboard	Each	\$800.00	\$1,016.00	\$760.00
43.	Furnish and install rectangular fiberglass board	Each	\$800.00	\$1,010.00	\$565.00
44.	Furnish and install glue on edge padding	Each	\$155.00	\$100.00	\$85.00
45.	Furnish and install bolt on edge padding	Each	\$250.00	\$195.00	\$195.00
46.	Furnish and install key switches	Each	\$230.00	\$50.00	\$25.00
47.	Replacement pipe	Lin. Ft.	\$9.00	\$20.00	\$5.00
48.	Raise or lower goals	Each	\$50.00	\$45.00	\$50.00
F	OPERABLE WALL REFURBISHMENT:				
49.	Refurbishment of one 16' section x 10' high operable partition as detailed in specifications	Each	\$100.00	\$95.00	\$48.00
G	UNIT PRICES FOR OPERABLE WALL REPAIRS/REFURBISHMENTS:				See notes
50.	Replace broken trolley	Each	\$360.00	\$150.00	* \$33.00
51.	Replace sweep material	Lin. Ft.	\$9.00	\$5.00	* \$2.00
52.	Replace soffit trim	Lin. Ft.	\$16.00	\$10.00	* \$4.00
53.	Replace steel track	Lin. Ft.	\$50.00	\$60.00	* \$22.00
54.	Replace aluminum track	Lin. Ft.	\$70.00	\$70.00	* \$13.00
55.	Replace automatic 2" bottom seals	Each	\$180.00	\$100.00	* \$79.00
56.	Replace manual 2" bottom seals	Each	\$180.00	\$100.00	* \$56.00
57.	Provide 15 oz. vinyl for recover, material only	Lin. Yd.	\$16.00	\$20.00	* \$12.00
58.	Provide ribbed carpet for recover, material only	Lin. Yd.	\$26.00	\$22.00	* \$12.00
59.	Replace astragal (10' height)	Each	\$170.00	\$100.00	* \$50.00
60.	Replace bulb seal (10' height)	Each	\$160.00	\$100.00	* \$25.00
61.	Replace bottom seal end caps	Each	\$26.00	\$15.00	* \$4.00
62.	Replace expander mechanism	Each	\$300.00	\$200.00	* \$125.00
63.	Provide replacement operating handle	Each	\$250.00	\$75.00	* \$30.00
64.	Replace horizontal trim (4' width)	Each	\$36.00	\$30.00	* \$18.00

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Bid Tabulation: Gymnasium Inspection and Repairs - Bid #8099

Bid Opening: April 22, 2008 - 2:00 p.m.

			Lyle Bleachers Inc.
Item	Description	Unit	Unit Price
E	UNIT PRICES FOR BACKSTOP REPAIRS/REFURBISHMENTS (CONTINUED):		
33.	Furnish and install volleyball floor coverplate (8")	Each	\$80.00
34.	Furnish and install volleyball floor coverplate (5")	Each	\$80.00
35.	Furnish and install 2' x 6' wall pad	Each	\$70.00
36.	Furnish and install limit winch assembly	Each	\$40.00
37.	Furnish and install breakaway goal	Each	\$265.00
38.	Furnish and install manual height adjusters	Each	\$589.00
39.	Furnish and install electric height adjusters	Each	\$689.00
40.	Furnish and install fan fiberglass backboard	Each	\$501.00
41.	Furnish and install fan aluminum backboard	Each	\$495.00
42.	Furnish and install rectangular glass backboard	Each	\$895.00
43.	Furnish and install rectangular fiberglass board	Each	\$765.00
44.	Furnish and install glue on edge padding	Each	\$160.00
45.	Furnish and install bolt on edge padding	Each	\$205.00
46.	Furnish and install key switches	Each	\$181.50
47.	Replacement pipe	Lin. Ft.	\$5.00
48.	Raise or lower goals	Each	\$100.00
F	OPERABLE WALL REFURBISHMENT:		
49.	Refurbishment of one 16' section x 10' high operable partition as detailed in specifications	Each	
G	UNIT PRICES FOR OPERABLE WALL REPAIRS/REFURBISHMENTS:		
50.	Replace broken trolley	Each	
51.	Replace sweep material	Lin. Ft.	
52.	Replace soffit trim	Lin. Ft.	
53.	Replace steel track	Lin. Ft.	
54.	Replace aluminum track	Lin. Ft.	
55.	Replace automatic 2" bottom seals	Each	
56.	Replace manual 2" bottom seals	Each	
57.	Provide 15 oz. vinyl for recover, material only	Lin. Yd.	
58.	Provide ribbed carpet for recover, material only	Lin. Yd.	
59.	Replace astragal (10' height)	Each	
60.	Replace bulb seal (10' height)	Each	
61.	Replace bottom seal end caps	Each	
62.	Replace expander mechanism	Each	
63.	Provide replacement operating handle	Each	
64.	Replace horizontal trim (4' width)	Each	

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Bid Tabulation: Gymnasium Inspection and Repairs - Bid #8099

Bid Opening: April 22, 2008 - 2:00 p.m.

Item	Description	Unit	Riptide Unlimited, Inc. Unit Price	Robbins Sport Floors Florida, LLC Unit Price	Seating Constructors USA Unit Price	Southeastern Surfaces & Equipment Unit Price
E	UNIT PRICES FOR BACKSTOP REPAIRS/REFURBISHMENTS (CONTINUED):					
33.	Furnish and install volleyball floor coverplate (8")	Each			\$45.00	\$200.00
34.	Furnish and install volleyball floor coverplate (5")	Each			\$110.00	\$200.00
35.	Furnish and install 2' x 6' wall pad	Each			\$80.00	\$95.00
36.	Furnish and install limit winch assembly	Each			\$340.00	\$75.00
37.	Furnish and install breakaway goal	Each			\$260.00	\$235.00
38.	Furnish and install manual height adjusters	Each			\$1,145.00	\$675.00
39.	Furnish and install electric height adjusters	Each			\$2,140.00	\$1,075.00
40.	Furnish and install fan fiberglass backboard	Each			\$903.00	\$460.00
41.	Furnish and install fan aluminum backboard	Each			\$878.00	\$450.00
42.	Furnish and install rectangular glass backboard	Each			\$1,254.00	\$895.00
43.	Furnish and install rectangular fiberglass board	Each			\$1,070.00	\$650.00
44.	Furnish and install glue on edge padding	Each			\$90.00	\$75.00
45.	Furnish and install bolt on edge padding	Each			\$90.00	\$200.00
46.	Furnish and install key switches	Each			\$120.00	\$85.00
47.	Replacement pipe	Lin. Ft.			\$12.50	\$3.00
48.	Raise or lower goals	Each			\$80.00	\$90.00
F	OPERABLE WALL REFURBISHMENT:					
49.	Refurbishment of one 16' section x 10' high operable partition as detailed in specifications	Each				\$100.00
G	UNIT PRICES FOR OPERABLE WALL REPAIRS/REFURBISHMENTS:					
50.	Replace broken trolley	Each				\$60.00
51.	Replace sweep material	Lin. Ft.				\$5.00
52.	Replace soffit trim	Lin. Ft.				\$10.00
53.	Replace steel track	Lin. Ft.				\$45.00
54.	Replace aluminum track	Lin. Ft.				\$65.00
55.	Replace automatic 2" bottom seals	Each				\$60.00
56.	Replace manual 2" bottom seals	Each				\$100.00
57.	Provide 15 oz. vinyl for recover, material only	Lin. Yd.				\$14.95
58.	Provide ribbed carpet for recover, material only	Lin. Yd.				\$25.50
59.	Replace astragal (10' height)	Each				\$20.00
60.	Replace bulb seal (10' height)	Each				\$25.00
61.	Replace bottom seal end caps	Each				\$4.00
62.	Replace expander mechanism	Each				\$395.00
63.	Provide replacement operating handle	Each				\$15.00
64.	Replace horizontal trim (4' width)	Each				\$15.00

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Bid Tabulation: Gymnasium Inspection and Repairs - Bid #8099

Bid Opening: April 22, 2008 - 2:00 p.m.

			Charron Sports Services, Inc.	Gymdoors Florida, LLC	Hufcor Florida Group
Item	Description	Unit	Unit Price	Unit Price	Unit Price
H	WOOD FLOOR MAINTENANCE:				
65.	Screen and recoat gymnasium floors with <i>oil modified</i> finish per specifications	Sq. Ft.			\$0.293
66.	Screen and recoat stage floors with <i>oil modified</i> finish per specifications	Sq. Ft.			\$0.38
67.	Screen and recoat gymnasium floors with <i>water based</i> finish per specifications	Sq. Ft.			\$0.40
68.	Screen and recoat stage floors with <i>water based</i> finish per specifications	Sq. Ft.			\$0.48
69.	Drum sand gymnasium floors with <i>oil modified</i> finish per specifications	Sq. Ft.			\$1.21
70.	Drum sand stage floors with <i>oil modified</i> finish per specifications	Sq. Ft.			\$1.65
71.	Drum sand gymnasium floors with <i>water based</i> finish per specifications	Sq. Ft.			\$1.43
72.	Drum sand stage floors with <i>water based</i> finish per specifications	Sq. Ft.			\$1.85
73.	Repair damaged wood per specifications	Sq. Ft.			\$13.20
74.	Logos:				
a.	up to and including 6' single color logo	Each			\$650.00
b.	up to and including 6' two color logo	Each			\$750.00
c.	up to and including 6' three color logo	Each			\$865.00
d.	up to and including 6' four color logo	Each			\$970.00
e.	over 6' - 12' single color logo	Each			\$1,080.00
f.	over 6' - 12' two color logo	Each			\$1,200.00
g.	over 6' - 12' three color logo	Each			\$1,300.00
h.	over 6' - 12' four color logo	Each			\$1,400.00
I	SYNTHETIC FLOOR MAINTENANCE:				
75.	Clean synthetic vinyl and rubber gymnasium floors per technical specifications with auto scrubber	Sq. Ft.			\$0.13
76.	Apply two coats of Vision Mat coating to vinyl gymnasium floors per technical specifications	Sq. Ft.			\$0.17
77.	Apply two coats of Vision Mat coating to rubber gymnasium floors per technical specifications	Sq. Ft.			\$0.17
78.	Re-weld heat welds per technical specifications	Lin. Ft.			\$2.20
79.	Repair Mondo floors per technical specifications	Sq. Ft.			\$13.20
80.	Repair Taraflex floors per technical specifications	Sq. Ft.			\$11.00
81.	Provide and install Isolsport Moisture membrane per technical specifications	Sq. Ft.			\$1.90

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Bid Tabulation: Gymnasium Inspection and Repairs - Bid #8099

Bid Opening: April 22, 2008 - 2:00 p.m.

			Lyle Bleachers Inc.
Item	Description	Unit	Unit Price
H	WOOD FLOOR MAINTENANCE:		
65.	Screen and recoat gymnasium floors with <i>oil modified</i> finish per specifications	Sq. Ft.	
66.	Screen and recoat stage floors with <i>oil modified</i> finish per specifications	Sq. Ft.	
67.	Screen and recoat gymnasium floors with <i>water based</i> finish per specifications	Sq. Ft.	
68.	Screen and recoat stage floors with <i>water based</i> finish per specifications	Sq. Ft.	
69.	Drum sand gymnasium floors with <i>oil modified</i> finish per specifications	Sq. Ft.	
70.	Drum sand stage floors with <i>oil modified</i> finish per specifications	Sq. Ft.	
71.	Drum sand gymnasium floors with <i>water based</i> finish per specifications	Sq. Ft.	
72.	Drum sand stage floors with <i>water based</i> finish per specifications	Sq. Ft.	
73.	Repair damaged wood per specifications	Sq. Ft.	
74.	Logos:		
a.	up to and including 6' single color logo	Each	
b.	up to and including 6' two color logo	Each	
c.	up to and including 6' three color logo	Each	
d.	up to and including 6' four color logo	Each	
e.	over 6' - 12' single color logo	Each	
f.	over 6' - 12' two color logo	Each	
g.	over 6' - 12' three color logo	Each	
h.	over 6' - 12' four color logo	Each	
I	SYNTHETIC FLOOR MAINTENANCE:		
75.	Clean synthetic vinyl and rubber gymnasium floors per technical specifications with auto scrubber	Sq. Ft.	
76.	Apply two coats of Vision Mat coating to vinyl gymnasium floors per technical specifications	Sq. Ft.	
77.	Apply two coats of Vision Mat coating to rubber gymnasium floors per technical specifications	Sq. Ft.	
78.	Re-weld heat welds per technical specifications	Lin. Ft.	
79.	Repair Mondo floors per technical specifications	Sq. Ft.	
80.	Repair Taraflex floors per technical specifications	Sq. Ft.	
81.	Provide and install Isolsport Moisture membrane per technical specifications	Sq. Ft.	

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Bid Tabulation: Gymnasium Inspection and Repairs - Bid #8099

Bid Opening: April 22, 2008 - 2:00 p.m.

Item	Description	Unit	Riptide Unlimited, Inc. Unit Price	Robbins Sport Floors Florida, LLC Unit Price	Seating Constructors USA Unit Price	Southeastern Surfaces & Equipment Unit Price
H	WOOD FLOOR MAINTENANCE:					
65.	Screen and recoat gymnasium floors with <i>oil modified</i> finish per specifications	Sq. Ft.	\$0.30	\$0.28		\$0.25
66.	Screen and recoat stage floors with <i>oil modified</i> finish per specifications	Sq. Ft.	\$0.30	\$0.85		\$0.65
67.	Screen and recoat gymnasium floors with <i>water based</i> finish per specifications	Sq. Ft.	\$0.45	\$0.44		\$0.70
68.	Screen and recoat stage floors with <i>water based</i> finish per specifications	Sq. Ft.	\$0.45	\$1.00		\$0.95
69.	Drum sand gymnasium floors with <i>oil modified</i> finish per specifications	Sq. Ft.	\$1.05	\$1.25		\$1.00
70.	Drum sand stage floors with <i>oil modified</i> finish per specifications	Sq. Ft.	\$1.25	\$2.45		\$1.50
71.	Drum sand gymnasium floors with <i>water based</i> finish per specifications	Sq. Ft.	\$1.25	\$1.60		\$1.40
72.	Drum sand stage floors with <i>water based</i> finish per specifications	Sq. Ft.	\$1.55	\$2.75		\$1.75
73.	Repair damaged wood per specifications	Sq. Ft.	\$10.00	\$15.00 >50/SF \$35.00 < 50/SF		\$10.00
74.	Logos:					
a.	up to and including 6' single color logo	Each	\$500.00	\$450.00		\$200.00
b.	up to and including 6' two color logo	Each	\$750.00	\$600.00		\$400.00
c.	up to and including 6' three color logo	Each	\$1,000.00	\$750.00		\$500.00
d.	up to and including 6' four color logo	Each	\$1,500.00	\$900.00		\$600.00
e.	over 6' - 12' single color logo	Each	\$750.00	\$750.00		\$500.00
f.	over 6' - 12' two color logo	Each	\$1,000.00	\$900.00		\$750.00
g.	over 6' - 12' three color logo	Each	\$1,500.00	\$1,050.00		\$1,000.00
h.	over 6' - 12' four color logo	Each	\$2,000.00	\$1,200.00		\$1,500.00
I	SYNTHETIC FLOOR MAINTENANCE:					
75.	Clean synthetic vinyl and rubber gymnasium floors per technical specifications with auto scrubber	Sq. Ft.				\$0.25
76.	Apply two coats of Vision Mat coating to vinyl gymnasium floors per technical specifications	Sq. Ft.				
77.	Apply two coats of Vision Mat coating to rubber gymnasium floors per technical specifications	Sq. Ft.				\$0.45
78.	Re-weld heat welds per technical specifications	Lin. Ft.				\$1.00
79.	Repair Mondo floors per technical specifications	Sq. Ft.				\$8.95
80.	Repair Taraflex floors per technical specifications	Sq. Ft.				\$6.95
81.	Provide and install Isolsport Moisture membrane per technical specifications	Sq. Ft.				\$1.35

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Bid Tabulation: Gymnasium Inspection and Repairs - Bid #8099

Bid Opening: April 22, 2008 - 2:00 p.m.

			Charron Sports Services, Inc.	Gymdoors Florida, LLC	Hufcor Florida Group
Item	Description	Unit	Unit Price	Unit Price	Unit Price
I	SYNTHETIC FLOOR MAINTENANCE (CONTINUED):				
82.	Remove and dispose of existing Mondo or Taraflex sports flooring per technical specifications	Sq. Ft.			\$1.10
83.	Provide and install vented cove base per technical specifications	Lin. Ft.			\$9.35
84.	Provide and install reduce strip at door ways	Lin. Ft.			\$2.75
J	LABOR RATE FOR ALL ITEMS NOT DETAILED IN BID:				
85.	Standard working hours (Monday through Friday 8:00 A.M. - 5:00	Hour		\$58.00	\$44.50
86.	Non-standard working hours (Monday through Friday prior to 8:00 A.M. and after 5:00 P.M., and Saturday and Sunday); hourly rate.	Hour		\$58.00	\$57.00
K	MARK-UP FOR MATERIALS NOT DETAILED IN BID:				
87.	Materials to be billed at net cost. Include a percentage allowed for overhead and profit, plus sales tax. No mark-up of sales tax allowed. (Indicate this percentage in the space to the right).	% Mark-Up		9.00%	14.00%
Notes:				* A1. & A2.: Bleacher, backstops and operable walls only. C22. Lin. Ft.	*G50. Hufcor #38, G51. Hufcor Brown TopSweep, G52. Modernfold, G53. Hufcor #11, G54. Hufcor #38, G55. Modernfold, G56. Hufcor, G59. Hufcor 631, G60. Hufcor, G61. Modernfold 2", G62. Hufcor, G63. Hufcor, G64. Hufcor
Contact Name:			Maury Purcell	Clement Baburam	Jeremy Deshotels
Address:			8533 Liberty Hwy.	522 S. Hunt Club Blvd., #403	11527 Pyramid Dr., #101
			Liberty, SC 29657	Apopka, FL 32703	Odessa, FL 33556
Phone:			800-745-0465	407-574-7366	727-376-1909
Fax:			864-261-8542	407-574-7367	727-376-1948
Federal ID#:			57-0927059	02-0744547	59-3098424
E-Mail Address:			css@charronbleachers.com	gymdoorsfl@aol.com	jdeshotels@hufcorfl.com

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Bid Tabulation: Gymnasium Inspection and Repairs - Bid #8099

Bid Opening: April 22, 2008 - 2:00 p.m.

			Lyle Bleachers Inc.
Item	Description	Unit	Unit Price
I	SYNTHETIC FLOOR MAINTENANCE (CONTINUED):		
82.	Remove and dispose of existing Mondo or Taraflex sports flooring per technical specifications	Sq. Ft.	
83.	Provide and install vented cove base per technical specifications	Lin. Ft.	
84.	Provide and install reduce strip at door ways	Lin. Ft.	
J	LABOR RATE FOR ALL ITEMS NOT DETAILED IN BID:		
85.	Standard working hours (Monday through Friday 8:00 A.M. - 5:00	Hour	\$38.50
86.	Non-standard working hours (Monday through Friday prior to 8:00 A.M. and after 5:00 P.M., and Saturday and Sunday); hourly rate.	Hour	\$48.50
K	MARK-UP FOR MATERIALS NOT DETAILED IN BID:		
87.	Materials to be billed at net cost. Include a percentage allowed for overhead and profit, plus sales tax. No mark-up of sales tax allowed. (Indicate this percentage in the space to the right).	% Mark-Up	10.00%
Notes:			C22: Lin. Ft. C24: Lin. Ft.
Contact Name:			David Lyle
Address:			5817 Lynn Rd.
			Tampa, FL 33624
Phone:			813-968-3629
Fax:			813-962-7592
Federal ID#:			59-3436311
E-Mail Address:			davetpa1@aol.com

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Bid Tabulation: Gymnasium Inspection and Repairs - Bid #8099

Bid Opening: April 22, 2008 - 2:00 p.m.

			Riptide Unlimited, Inc.	Robbins Sport Floors Florida, LLC	Seating Constructors USA	Southeastern Surfaces & Equipment
Item	Description	Unit	Unit Price	Unit Price	Unit Price	Unit Price
I	SYNTHETIC FLOOR MAINTENANCE (CONTINUED):					
82.	Remove and dispose of existing Mondo or Taraflex sports flooring per technical specifications	Sq. Ft.				\$0.75
83.	Provide and install vented cove base per technical specifications	Lin. Ft.				\$7.25
84.	Provide and install reduce strip at door ways	Lin. Ft.				\$5.00
J	LABOR RATE FOR ALL ITEMS NOT DETAILED IN BID:					
85.	Standard working hours (Monday through Friday 8:00 A.M. - 5:00	Hour	\$20.00	\$18.00	\$60.00	\$45.00
86.	Non-standard working hours (Monday through Friday prior to 8:00 A.M. and after 5:00 P.M., and Saturday and Sunday); hourly rate.	Hour	\$25.00	\$27.00	\$75.00	\$65.00
K	MARK-UP FOR MATERIALS NOT DETAILED IN BID:					
87.	Materials to be billed at net cost. Include a percentage allowed for overhead and profit, plus sales tax. No mark-up of sales tax allowed. (Indicate this percentage in the space to the right).	% Mark-Up	10.00%	12.00%	20.00%	12.00%
Notes:				73. \$15.00/Sq. Ft. > 50 Sq. Ft. 73. \$35.00/Sq. Ft. < 50 Sq. Ft.	C22. & C24.: Ft.	C22: Lin. Ft. C24: bleacher section, 16' long x 10 rows high
Contact Name:			Jason Duke	Chris Newton	Phil Vanderhider	Tracie A. Ward
Address:			P.O. Box 531	6540 E. Rogers Cir.	2347 Circuit Wy.	569 Canal St.
			New Smyrna Beach, FL 32170	Boca Raton, FL 33487	Brooksville, FL 34604	New Smyrna Beach, FL 32168
Phone:			954-306-6471	561-997-7759	727-539-1017	386-428-8875
Fax:			954-306-6472	561-997-7590	352-799-0308	386-428-8767
Federal ID#:			59-3476737	01-0562005	59-3731310	59-3265072
E-Mail Address:			jasonduke1313@yahoo.com	cnewton@robbinsfloor.com	sales@seatingUSA.com	tward@sseteam.com
			Recorded by:	Michelle F. Miller		
			Witnessed by:	Joyce Haney		