

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

MATERIALS MANAGEMENT DEPARTMENT

101 OLD VENICE ROAD

OSPREY, FLORIDA 34229

TELEPHONE (941) 486-2183

FAX (941) 486-2188

MEMORANDUM

TO: Members of the School Board

Lori White, Superintendent

Mitsi Corcoran, Chief Financial Officer

FROM: Pat Black, CPPB, Director of Materials Management

TITLE: APPROVAL TO AWARD BID #12-0160 FOR SIMPLEX-GRINNELL OEM

FIRE ALARM PARTS

Bids to provide 'Simplex-Grinnell OEM Fire Alarm Parts' were received from two vendors on January 31, 2012. The bid of SimplexGrinnell was the best low bid meeting the advertised specifications. This bid is for a period of one year with the option to renew for two additional one-year periods. The funds for these purchases are contained in the transfer from capital budget allocated to the Facilities Services Department.

Requested by:

Jody Dumas

"Failure to file a protest within the time prescribed in Section 120.57(3), Florida Statutes, or failure to post the protest bond or other security required by law within the time allowed for filing a bond shall constitute a waiver of proceedings under Chapter 120. Florida Statutes."

Posting Date: 02-14-12

Not to exceed \$60,000

Recommended Motion: That the bid of SimplexGrinnell to 'provide Simplex-Grinnell OEM Fire Alarm Parts' in an amount not to exceed \$60,000, be approved for award and purchase.

Opened January 31, 2012 at 3:00 p.m.

SIMPLE	K-GRINNELL	REPLACEMENT PARTS	International Systems of America, LLC	SimplexGrinnell
Item #	Part #	Description		
Simplex 4	4020 FACP			
1	565-325	Master Controller	\$1,723.27	\$1,882.24
				Remanufactured only #8565-325
2	636-341	Power Supply, UPS Switching	\$1,636.14	\$1,787.06
				Remanufactured only #8636-341
3	565-256	Power Supply Interface	\$1,255.69	\$1,371.53
				Remanufactured only #8565-256
4	566-759	Standard Slave Card	\$1,148.45	\$1,243.38
5	565-211	8-Point I/O	\$1,409.02	\$1,539.00
				Remanufactured only #8565-211
6	566-750	MAPNET Transceiver	\$1,285.66	\$1,446.63
7	565-627	CCDACT, Communicator	\$490.08	\$562.05
8	566-826	Network Interface Card, Modular	\$660.18	\$779.82
9	566-376	Fiber Optic Media Board	\$636.87	\$641.79
10	565-430	RS-232 Interface Module	\$733.64	\$826.22
				Remanufactured only #8565-430
Simplex 4	4100+ FACP			
11	565-333	Master Controller	\$1,535.84	\$1,617.20
				Remanufactured only #8565-333
12	565-274	Master Motherboard	\$333.25	\$385.98
13	566-736	MAPNET II Transceiver	\$520.52	\$517.52
14	562-974	MAPNET II Motherboard / Power Supply	\$333.36	\$321.79
15	562-795	Master Display Board	\$810.29	\$893.63
16	562-731	Monitor Card, 8-Zone	\$1,038.08	\$1,093.05
17	562-760	Relay Card, 4 x 2A	\$358.73	\$363.27
18	562-951	Relay Card, 4 x 10A	\$946.95	\$1,093.05
19	565-045	Relay Card, 8 x 3A	\$701.69	\$363.27
20	565-453	Signal Card, 6-Circuit	\$472.36	\$1,096.84
21	565-415	Dual RS-232 Card	\$769.17	\$772.77
	223 113		Ψ. σσ	Remanufactured only #8565-415
22	562-799	Motherboard, w/Suppression	\$333.49	\$386.29
23	740-802	Universal Power Supply	\$2,914.46	\$3,068.85
	7 10 002	Chirologic ever eapply	Ψ2,011.10	Remanufactured only #8740-802

Opened January 31, 2012 at 3:00 p.m.

SIMPLE	X-GRINNELL	REPLACEMENT PARTS	International Systems of America, LLC	SimplexGrinnell
Item #	Part #	Description	,	•
	4100+ FACP	· · · · · · · · · · · · · · · · · · ·		
24	740-886	Expansion Power Supply, 8A	\$664.69	\$801.44
25	562-894	Audio Controller Board	\$1,583.67	\$1,834.33
	302 00 .		V 1,000101	Remanufactured only #8562-894
26	636-064	Amplifier, 70v, 100w	\$1,260.90	\$1,460.46
27	562-905	Amplifier, 25w	\$840.33	\$824.95
28	562-917	Amplifier Power Supply, 25w	\$640.40	\$630.38
Simplex	4100U / 4100	ES		
29	566-145	4100U Master Controller	not correct part #	\$712.54
30	566-719	4100ES Master Controller	not correct part #	\$1,882.13
31	742-590	CPU Motherboard	\$641.80	\$463.64
				Remanufactured only #742-516
32	742-590	Master Operator Interface	\$641.80	\$723.18
33	742-342	System Power Supply PCA	\$907.09	\$1,049.05
34	566-075	Expansion Power Supply	\$403.56	\$466.74
35	566-323	Power Supply	\$825.80	\$985.35
36	566-848	4100ES Front Panel Ethernet	\$36.35	\$40.39
37	566-787	Event and Point DACT	\$336.19	\$412.60
38	4100-6014	Network Interface Card	\$1,925.06	\$2,131.30
39	565-413	Media Card, Wired	\$197.33	\$179.74
40	566-376	Media Card, Fiber Optic	\$636.87	\$636.24
41	4100-3101	IDNet Module, 250 Point Capacity	\$5,345.17	\$5,738.07
42	4100-3104	IDNet Module, 127 Point Capacity	\$3,562.25	\$1,738.21
43	4100-3105	IDNet Module, 64 Point Capacity	\$1,781.72	\$869.39
44	4100-3204	Relay Module, 4 DPDT w/feedback x 2A	\$489.21	\$541.61
45	4100-3206	Relay Module, 8 SPDT x 2A	\$668.75	\$791.90
46	565-226	Zone Module, Class B	\$584.26	\$609.91
47	566-218	Audio Controller, Analog	\$615.33	* \$1,790.15
				Actual part # 4100-1210
48	742-437	Amplifier 70v 50w	not correct part #	* \$1,360.49
				Actual part # 4100-1313

THE SCHOOL BOARD OF SARASOTA, FLORIDA

Tabulation for Simplex-Grinnell OEM Fire Alarm Parts - Bid #12-0160

Opened January 31, 2012 at 3:00 p.m.

SIMPLEX-GRINNELL REPLACEMENT PARTS		International Systems of America, LLC	SimplexGrinnell	
Item #	Part #	Description		
Simplex	4100U / 4100	ES - Continued		
49	743-439	Amplifier, 70v 100w	not correct part #	* \$2,076.58
				Actual part # 4100-1315
50	4100-0620	Transponder Interface Module	\$513.67	\$573.18
51	562-789	Graphic I/O Module, 24-point	\$1,140.36	* \$930.81
				Actual part # 4100-1290
52	4100-1266	Expansion Signal Card	\$1,096.20	\$709.29
53	4100-5115	Expansion NAC Module	\$635.12	\$714.69
Periphe	ral Devices			
54	4009-9401	True Alert Addressable Controller	\$911.28	\$768.33
55	4009-9201	NAC Extender Panel	\$132.08	\$430.24
56	4099-9001	Manual Station, Single-action		* \$57.82
57	4099-9003	Manual Station, Double-action	\$154.87	\$67.81
58	2099-9754	Manual Station, Single-action	\$52.83	\$22.03
59	2099-9756	Manual Station, Double-action	\$73.24	\$33.62
60	4098-9714	Addressable Photoelectric Smoke Detector Head	\$101.69	\$33.11
61	4098-9733	Addressable Heat Detector	\$55.47	\$22.07
62	4098-9792	Addressable Sensor Base	\$130.76	\$42.58
63	4098-9791	Addressable Sensor Base, w/Relay Module	\$272.06	\$39.37
64	4098-9601	Photoelectric Smoke Detector	\$109.61	\$42.13
65	4098-9682	Detector Base, 4-Wire	\$77.93	\$50.44
66	4098-9788	Detector Base, 2-Wire	\$28.09	\$7.24
67	4098-9756	Air Duct Sensor Housing w/Relay, 4-Wire	\$536.20	\$206.07
68	4098-9755	Air Duct Sensor, 2-Wire	\$495.25	\$165.80
69	4098-9686	Duct Detector, 4-Wire	\$343.40	\$140.48
70	4098-9685	Duct Detector, 2-Wire	\$336.77	\$137.79
71	2098-9806	Remote Test Station	\$92.46	\$29.73
72	4090-9001	Supervised Individual Addressable Module Assembly	\$141.33	\$42.61
73	4090-9051	Addressable Individual Addressable Module, Encapsulated	\$167.72	\$66.76
74	4090-9002	Relay Individual Addressable Module	\$285.26	\$113.53
75	4906-9127	Horn/Strobe, Red Multi-Candela	\$141.60	\$42.88

THE SCHOOL BOARD OF SARASOTA, FLORIDA

Tabulation for Simplex-Grinnell OEM Fire Alarm Parts - Bid #12-0160

Opened January 31, 2012 at 3:00 p.m.

SIMPLEX	GRINNELL	REPLACEMENT PARTS	International Systems of America, LLC	SimplexGrinnell
Item #	Part #	Description	<u>·</u>	,
	al Devices - C			
76		Strobe, Red Multi-Candela	\$122.67	\$31.53
77	4906-9227	Addressable Horn/Strobe, Red Multi-Candela	\$159.68	\$40.80
78	4906-9201	Addressable Strobe, Red Multi-Candela	\$98.24	\$30.00
79		Electronic Horn/Strobe, Red, Multi-Candela WP	\$98.17	\$44.67
80	4905-9828	Back box, Red, WP AV/VO 1.5"	\$29.70	\$13.51
81	4905-9914	SmartSync Cube	\$71.44	\$32.51
82	4905-9938	SmartSync Control Module	\$64.54	\$48.09
83	Balance of L	ine - Percentage discount off Simplex-Grinnell parts not listed above	12%	30%
		TOTAL		* Removed items for equalization/evaluation of bids.
Contact			Mark Shoemaker	James Hampton
Address			1812 Cargo Court	4701 Oak Fair Boulevard
			Louisville, KY 40299	Tampa, FL 33610
Phone			502-499-9485	813-626-5482
Fax			502-499-8511	813-313-1610
Federal I.	D.		273279774	582608861
Email			gobrien@isa-net.com	<u>ihampton</u> @simplexgrinnell.com

Witnessed by: Joyce E. Haney

Recorded by: Peggy Long