



THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

MATERIALS MANAGEMENT DEPARTMENT

101 OLD VENICE ROAD

OSPREY, FLORIDA 34229

TELEPHONE (941) 486-2183 • FAX (941) 486-2188

MEMORANDUM

**TO: Members of the School Board
Lori White, Superintendent
Mitsi Corcoran, Chief Financial Officer**

FROM: Pat Black, CPPB, Director of Materials Management

TITLE: APPROVAL TO AWARD BID #12-0155 FOR BUS BRAKE REPAIR PARTS

Bids to provide 'Bus Brake Repair Parts' were received from seven vendors on September 28, 2011. The bids of Fleet Acquisitions, LLC, dba Fleet Products, Fleet Pride, Napa Auto Parts and The Parts House were the best low bids meeting the advertised specifications. Reasons for not selecting the apparent low bid are included with the bid tabulation. This bid is for a period of one year with the option to renew for two additional one-year periods. The funds for these purchases are contained in the operating budget allocated to the Transportation Services Department.

Requested by:
Ellery Girard

"Failure to file a protest within the time prescribed in Section 120.57(3), Florida Statutes, or failure to post the protest bond or other security required by law within the time allowed for filing a bond shall constitute a waiver of proceedings under Chapter 120, Florida Statutes."

Posting Date: 11-9-11

Fiscal Impact:

Not to exceed
\$115,000.00

Funding:

Operating

Recommended Motion: That the bids of Fleet Acquisitions, LLC, dba Fleet Products, Fleet Pride, Napa Auto Parts and the Parts House to provide 'Bus Brake Repair Parts' in an amount not to exceed \$115,000.00, be approved for award and purchase.

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for Bus Brake Repair Parts - Bid #12-0155

Opened September 28, 2011 at 2:00 p.m.

| All brake linings to be riveted on SBSC brake shoes, OEM factory remanufactured brake shoes, or new brake shoes. | | Fleet Acquisitions dba Fleet Products | | | | Fleet Pride | | | |
|--|--|---------------------------------------|-----------------|------------|----------------|------------------------|-----------------|------------|----------------|
| Item # | Item and Description | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price |
| MERITOR 312 or approved alternate. | | | | | | | | | |
| 1. | New Front Shoe Kit, includes 2 Shoes and Hardware Kit (Freightliner) - SUB8824HD | as spec | | 66% | \$48.99 | KSMA3124702QP | \$144.09 | 65% | \$50.43 |
| 2. | New Rear Shoe Kit, includes 2 Shoes and Hardware Kit - SUB8000HD | as spec | | 66% | \$90.01 | KSMA3124707QP | \$204.56 | 64% | \$73.64 |
| 3. | Remanufactured Front Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8824HD | as spec | | 66% | \$45.54 | XK3124702QP | \$133.93 | 60% | \$53.57 |
| 4. | Remanufactured Rear Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8000HD | as spec | | 66% | \$49.00 | XK3124707QP | \$144.49 | 60% | \$57.80 |
| 5. | Balance of line item discount for Meritor 312 or approved alternate. | | | 66% | | | | | |
| MERITOR or approved alternate. | | | | | | | | | |
| 6. | Tapered Roller Hardware Kit - 8847HDA KIT | as spec | | 56% | \$31.64 | | \$71.92 | 60% | \$28.77 |
| 7. | Tapered Roller Only - 8847HD | as spec | | 56% | \$12.80 | | \$29.07 | 60% | \$11.63 |
| 8. | Slack Adjuster Replacement Pawl for front and rear slack adjustment assemblies - AY PAWL ASA | as spec | | 56% | \$40.04 | | \$21.38 | 60% | \$8.55 |
| 9. | Balance of line item discount for Meritor or approved alternate. | | | 56% | | | | 60% | |
| BENDIX or approved alternate. | | | | | | | | | |
| 10. | Drier - 107794X - AD9 | as spec | | 57% | \$23.28 | | \$54.13 | 64% | \$19.49 |
| 11. | Foot Pedal Valve - BW286171 E-6 | as spec | | 57% | \$37.75 | OR286171X | \$87.79 | 58% | \$36.87 |
| 12. | Governor - 18530 | as spec | | 57% | \$14.48 | OR275491X | \$29.11 | 60% | \$11.64 |
| 13. | Park Brake Valve - 800142 PP1 | as spec | | 57% | \$84.62 | | \$196.79 | 57% | \$84.62 |
| 14. | Park Brake Valve - 801315 C2 PP1 | as spec | | 57% | \$118.37 | | \$275.27 | 57% | \$118.37 |
| 15. | Purge Valve Kit - 5005037 - AD9 | as spec | | 57% | \$25.97 | | \$60.39 | 58% | \$25.36 |
| 16. | Quick Release Valve - 800063 | as spec | | 57% | \$9.98 | | \$23.21 | 57% | \$9.98 |
| 17. | Quick Release Valve - 800064 | | | 57% | \$9.98 | | \$23.21 | 57% | \$9.98 |
| 18. | Valve - QRN-2 | | | 57% | \$18.64 | | \$23.21 | 57% | \$9.98 |
| 19. | Balance of line item discount for Bendix or approved alternate. | | | 57% | | | | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for Bus Brake Repair Parts - Bid #12-0155

Opened September 28, 2011 at 2:00 p.m.

| All brake linings to be riveted on SBSC brake shoes, OEM factory remanufactured brake shoes, or new brake shoes. | | Gary Yeomans Ford | | | | Napa Auto Parts | | | |
|--|--|------------------------|-----------------|------------|----------------|------------------------|-----------------|------------|----------------|
| Item # | Item and Description | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price |
| MERITOR 312 or approved alternate. | | | | | | | | | |
| 1. | New Front Shoe Kit, includes 2 Shoes and Hardware Kit (Freightliner) - SUB8824HD | KSMA3124702QP | \$147.45 | 61% | \$57.51 | Haldex HV761308EJ | \$73.72 | 28% | \$53.08 |
| 2. | New Rear Shoe Kit, includes 2 Shoes and Hardware Kit - SUB8000HD | KSMA3124707QP | \$204.92 | 61% | \$79.92 | Haldex HV884515QN | \$33.62 | 27% | \$24.54 |
| 3. | Remanufactured Front Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8824HD | XK3124702QP | \$134.13 | 61% | \$52.31 | Haldex HV761308EG | \$46.77 | 27% | \$34.14 |
| 4. | Remanufactured Rear Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8000HD | XK3124707QP | \$144.77 | 61% | \$56.46 | Haldex HV884707QG | \$61.37 | 28% | \$44.19 |
| 5. | Balance of line item discount for Meritor 312 or approved alternate. | | | 61% | | | | 28% | |
| MERITOR or approved alternate. | | | | | | | | | |
| 6. | Tapered Roller Hardware Kit - 8847HDA KIT | | \$71.92 | 64% | \$25.89 | BHK059 | \$11.57 | 28% | \$8.33 |
| 7. | Tapered Roller Only - 8847HD | | \$31.09 | 58% | \$13.06 | | | | |
| 8. | Slack Adjuster Replacement Pawl for front and rear slack adjustment assemblies - AY PAWL ASA | No Pt. # | | | | CS52358 | \$118.65 | 28% | \$85.43 |
| 9. | Balance of line item discount for Meritor or approved alternate. | | | 61% | | | | 28% | |
| BENDIX or approved alternate. | | | | | | | | | |
| 10. | Drier - 107794X - AD9 | BX107794X | \$50.87 | 60% | \$20.35 | R955205 | \$584.61 | 28% | \$420.92 |
| 11. | Foot Pedal Valve - BW286171 E-6 | BX286171N | \$173.66 | 59% | \$71.20 | KN22150 | \$150.00 | 28% | \$108.00 |
| 12. | Governor - 18530 | B8J18530 | \$74.98 | 60% | \$29.99 | KN18530X | \$21.56 | 27% | \$15.74 |
| 13. | Park Brake Valve - 800142 PP1 | BX800142 | \$208.47 | 60% | \$83.39 | KN20021 | \$36.99 | 27% | \$27.00 |
| 14. | Park Brake Valve - 801315 C2 PP1 | BX801315 | \$275.27 | 57% | \$118.37 | BEN801315 | \$231.37 | 28% | \$166.59 |
| 15. | Purge Valve Kit - 5005037 - AD9 | BX5005037 | \$63.97 | 59% | \$26.23 | 5005037K | \$38.75 | 27% | \$28.29 |
| 16. | Quick Release Valve - 800063 | BX800063 | \$24.59 | 59% | \$10.08 | KN32011 | \$14.95 | 26% | \$11.06 |
| 17. | Quick Release Valve - 800064 | BX800064 | \$23.89 | 58% | \$10.03 | KN32005 | \$14.95 | 26% | \$11.06 |
| 18. | Valve - QRN-2 | BX800219 | \$65.20 | 57% | \$28.04 | KN32011 | \$14.95 | 26% | \$11.06 |
| 19. | Balance of line item discount for Bendix or approved alternate. | | | 60% | | | | 28% | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for Bus Brake Repair Parts - Bid #12-0155

Opened September 28, 2011 at 2:00 p.m.

| All brake linings to be riveted on SBSC brake shoes, OEM factory remanufactured brake shoes, or new brake shoes. | | The Parts House | | | | Power Brake, LLC | | | |
|--|--|--------------------------------------|-----------------|------------|-----------------|------------------------|-----------------|------------|----------------|
| Item # | Item and Description | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price |
| MERITOR 312 or approved alternate. | | | | | | | | | |
| 1. | New Front Shoe Kit, includes 2 Shoes and Hardware Kit (Freightliner) - SUB8824HD | KSMA3124702QP | \$144.09 | 67% | \$47.55 | HS Marathon HS4702 | \$103.32 | 50% | \$51.66 |
| 2. | New Rear Shoe Kit, includes 2 Shoes and Hardware Kit - SUB8000HD | KSMA3124707QP | \$204.56 | 67% | \$67.50 | HS Marathon HS4707 | \$112.44 | 50% | \$56.22 |
| 3. | Remanufactured Front Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8824HD | XK3124702QP | \$133.93 | 67% | \$44.20 | FLOE Marathon FL4702 | \$95.44 | 50% | \$47.72 |
| 4. | Remanufactured Rear Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8000HD | XK3124707QP | \$144.49 | 67% | \$47.68 | FLOE Marathon FL4707 | \$106.34 | 50% | \$53.17 |
| 5. | Balance of line item discount for Meritor 312 or approved alternate. | Meritor Shoe Kits | | 67% | | | | | |
| MERITOR or approved alternate. | | | | | | | | | |
| 6. | Tapered Roller Hardware Kit - 8847HDA KIT | as spec | \$71.92 | 58% | \$30.21 | | | | |
| 7. | Tapered Roller Only - 8847HD | KIT 8847HD | \$29.07 | 58% | \$12.21 | | | | |
| 8. | Slack Adjuster Replacement Pawl for front and rear slack adjustment assemblies - AY PAWL ASA | Meritor R801700 | \$21.38 | 58% | \$8.98 | | | | |
| 9. | Balance of line item discount for Meritor or approved alternate. | Meritor Hardware & Slacks | | 58% | | | | | |
| BENDIX or approved alternate. | | | | | | | | | |
| 10. | Drier - 107794X - AD9 | as spec | \$54.13 | 59% | \$22.19 | | | | |
| 11. | Foot Pedal Valve - BW286171 E-6 | OR286171X | \$87.79 | 59% | \$35.99 | | | | |
| 12. | Governor - 18530 | OR275491X | \$29.11 | 59% | \$11.94 | | | | |
| 13. | Park Brake Valve - 800142 PP1 | 800142 | \$196.79 | 59% | \$80.68 | | | | |
| 14. | Park Brake Valve - 801315 C2 PP1 | 801315 | \$275.27 | 59% | \$112.86 | | | | |
| 15. | Purge Valve Kit - 5005037 - AD9 | 5005037 | \$60.39 | 59% | \$24.76 | | | | |
| 16. | Quick Release Valve - 800063 | as spec | \$23.21 | 59% | \$9.52 | | | | |
| 17. | Quick Release Valve - 800064 | as spec | \$23.21 | 59% | \$9.52 | | | | |
| 18. | Valve - QRN-2 | 800063 | \$23.21 | 59% | \$9.52 | | | | |
| 19. | Balance of line item discount for Bendix or approved alternate. | Bendix Air Brake | | 59% | | | | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for Bus Brake Repair Parts - Bid #12-0155

Opened September 28, 2011 at 2:00 p.m.

| All brake linings to be riveted on SBSC brake shoes, OEM factory remanufactured brake shoes, or new brake shoes. | | Tampa Truck Center | | | |
|--|--|------------------------|-----------------|------------|----------------|
| Item # | Item and Description | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price |
| MERITOR 312 or approved alternate. | | | | | |
| 1. | New Front Shoe Kit, includes 2 Shoes and Hardware Kit (Freightliner) - SUB8824HD | KMSA3124702QP | \$64.40 | 10% | \$57.96 |
| 2. | New Rear Shoe Kit, includes 2 Shoes and Hardware Kit - SUB8000HD | KMSA3124707QP | \$91.50 | 10% | \$82.35 |
| 3. | Remanufactured Front Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8824HD | TDA/XK3124702QP | \$55.00 | 10% | \$49.50 |
| 4. | Remanufactured Rear Shoe Kit, includes 2 Shoes and Hardware Kit - KIT8000HD | TDA/XK3124707QP | \$53.10 | 10% | \$47.79 |
| 5. | Balance of line item discount for Meritor 312 or approved alternate. | | | | |
| MERITOR or approved alternate. | | | | | |
| 6. | Tapered Roller Hardware Kit - 8847HDA KIT | | \$34.16 | 5% | \$32.45 |
| 7. | Tapered Roller Only - 8847HD | | \$13.82 | 5% | \$13.13 |
| 8. | Slack Adjuster Replacement Pawl for front and rear slack adjustment assemblies - AY PAWL ASA | | \$9.99 | 0% | \$9.99 |
| 9. | Balance of line item discount for Meritor or approved alternate. | | | | |
| BENDIX or approved alternate. | | | | | |
| 10. | Drier - 107794X - AD9 | AD9 New | \$27.06 | 10% | \$24.35 |
| 11. | Foot Pedal Valve - BW286171 E-6 | | \$84.80 | 10% | \$76.32 |
| 12. | Governor - 18530 | 275707 | \$32.49 | 0% | \$32.49 |
| 13. | Park Brake Valve - 800142 PP1 | | \$104.74 | 10% | \$94.27 |
| 14. | Park Brake Valve - 801315 C2 PP1 | | \$147.52 | 10% | \$132.77 |
| 15. | Purge Valve Kit - 5005037 - AD9 | | \$32.37 | 10% | \$29.13 |
| 16. | Quick Release Valve - 800063 | | \$12.46 | 10% | \$11.21 |
| 17. | Quick Release Valve - 800064 | | \$12.46 | 10% | \$11.21 |
| 18. | Valve - QRN-2 | same as above | | | |
| 19. | Balance of line item discount for Bendix or approved alternate. | | | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for Bus Brake Repair Parts - Bid #12-0155

Opened September 28, 2011 at 2:00 p.m.

| All brake linings to be riveted on SBSC brake shoes, OEM factory remanufactured brake shoes, or new brake shoes. | | Fleet Acquisitions dba Fleet Products | | | | Fleet Pride | | | |
|--|---|---------------------------------------|-----------------|--------------------|-----------------|------------------------|-----------------|------------|----------------|
| Item # | Item and Description | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price |
| GUNITE or WEBB where indicated or approved alternate. | | | | | | | | | |
| 20. | Front Drum (Freightliner) - 3800X Gunite or 65548B Webb | as spec Gunite | | 67% | \$124.47 | | \$435.30 | 68% | \$139.30 |
| 21. | Front Drum (International Harvester Corp.) - Gunite 3721 or Webb 61528B | Gunite 3721 AX | | 67% | \$123.71 | | \$453.67 | 68% | \$145.17 |
| 22. | Grooved Drum (Freightliner) - 66884B Webb | Gunite 3576X | | 67% | \$135.95 | | \$467.27 | 68% | \$149.53 |
| 23. | Rear Drum (International Harvester Corp.) - 3647 Gunite or 66353F Webb | Gunite 3757 | | 67% | \$148.80 | | \$524.70 | 68% | \$167.90 |
| 24. | Rear Drum (Freightliner) - 66843B Webb | as spec Webb | | 65% | \$214.87 | | \$542.30 | 65% | \$189.81 |
| 25. | Rear Drum (Freightliner) - 3600AX Gunite or 66864B Webb | Gunite 3600AX | | 67% | \$102.88 | | \$408.47 | 74% | \$106.20 |
| 26. | Balance of line item discount for Gunite, Webb, or approved alternate. | Gunite Webb | | 67% 65% | | | | | |
| MONROE or approved alternate. | | | | | | | | | |
| 27. | Front Shocks (International Harvester Corp.) - 66923 | as spec | | 67% | \$26.65 | | \$80.75 | 70% | \$24.23 |
| 28. | Front Shocks (Freightliner) - 85006 | Monroe 66884 | | 67% | \$30.93 | 66884 | \$93.72 | 70% | \$28.12 |
| 29. | Front C2 Shocks - 65140 | as spec | | 67% | \$43.96 | | \$133.20 | 70% | \$39.96 |
| 30. | Rear Shocks (International Harvester Corp.) - 66924 | as spec | | 67% | \$27.23 | | \$82.53 | 70% | \$24.76 |
| 31. | Rear Shocks (Freightliner) - 65409 | as spec | | 67% | \$45.75 | | \$138.63 | 70% | \$41.59 |
| 32. | Rear Shocks (Freightliner) - 85013 | Euclid E85013 | | 48% | \$47.07 | 66894 | \$89.78 | 70% | \$26.93 |
| 33. | Rear C2 Shocks - 65490 | as spec | | 67% | \$43.46 | | \$131.70 | 70% | \$39.51 |
| 34. | Balance of line item discount for Monroe or approved alternate. | Monroe Euclid | | 67% 48% | | | | 70% | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for Bus Brake Repair Parts - Bid #12-0155

Opened September 28, 2011 at 2:00 p.m.

| All brake linings to be riveted on SBSC brake shoes, OEM factory remanufactured brake shoes, or new brake shoes. | | Gary Yeomans Ford | | | | Napa Auto Parts | | | |
|--|---|------------------------|-----------------|------------|----------------|------------------------|-----------------|------------|----------------|
| Item # | Item and Description | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price |
| GUNITE or WEBB where indicated or approved alternate. | | | | | | | | | |
| 20. | Front Drum (Freightliner) - 3800X Gunite or 65548B Webb | ZBR3800X | \$399.72 | 67% | \$131.91 | 65545B | \$313.63 | 28% | \$225.81 |
| 21. | Front Drum (International Harvester Corp.) - Gunite 3721 or Webb 61528B | ZBR3721AX | \$397.29 | 67% | \$131.11 | 61527B | \$304.11 | 28% | \$218.96 |
| 22. | Grooved Drum (Freightliner) - 66884B Webb | | \$475.46 | 66% | \$161.66 | X60794 | \$159.64 | 14% | \$137.29 |
| 23. | Rear Drum (International Harvester Corp.) - 3647 Gunite or 66353F Webb | ZBR3647 | \$462.57 | 67% | \$152.65 | 66353B | \$371.95 | 28% | \$267.80 |
| 24. | Rear Drum (Freightliner) - 66843B Webb | WWP66843B | \$552.10 | 64% | \$198.76 | as spec | \$379.61 | 28% | \$273.32 |
| 25. | Rear Drum (Freightliner) - 3600AX Gunite or 66864B Webb | ZBR3600AX | \$330.29 | 68% | \$105.69 | 66864B | \$194.24 | 28% | \$139.85 |
| 26. | Balance of line item discount for Gunite, Webb, or approved alternate. | | | 66% | | | | 28% | |
| MONROE or approved alternate. | | | | | | | | | |
| 27. | Front Shocks (International Harvester Corp.) - 66923 | | \$81.80 | 64% | \$29.45 | as spec | \$80.83 | 47% | \$42.84 |
| 28. | Front Shocks (Freightliner) - 85006 | AMS6898 | \$100.93 | 69% | \$31.29 | 66898 | \$87.05 | 47% | \$46.14 |
| 29. | Front C2 Shocks - 65140 | | \$131.09 | 67% | \$43.26 | as spec | \$133.33 | 47% | \$70.66 |
| 30. | Rear Shocks (International Harvester Corp.) - 66924 | | \$85.20 | 66% | \$28.97 | as spec | \$82.63 | 47% | \$43.79 |
| 31. | Rear Shocks (Freightliner) - 65409 | | \$143.12 | 67% | \$47.23 | as spec | \$138.75 | 47% | \$73.54 |
| 32. | Rear Shocks (Freightliner) - 85013 | AMS66894 | \$89.23 | 66% | \$30.34 | 66894 | \$89.86 | 47% | \$47.63 |
| 33. | Rear C2 Shocks - 65490 | | \$165.23 | 67% | \$54.53 | as spec | \$131.81 | 47% | \$69.86 |
| 34. | Balance of line item discount for Monroe or approved alternate. | | | 66% | | | | 47% | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for Bus Brake Repair Parts - Bid #12-0155

Opened September 28, 2011 at 2:00 p.m.

| All brake linings to be riveted on SBSC brake shoes, OEM factory remanufactured brake shoes, or new brake shoes. | | The Parts House | | | | Power Brake, LLC | | | |
|--|---|---|-----------------|------------|-----------------|------------------------|-----------------|------------|----------------|
| Item # | Item and Description | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price |
| GUNITE or WEBB where indicated or approved alternate. | | | | | | | | | |
| 20. | Front Drum (Freightliner) - 3800X Gunite or 65548B Webb | as spec Gunite | \$399.72 | 68% | \$127.91 | Power Brake 65548B | \$255.00 | 50% | \$127.50 |
| 21. | Front Drum (International Harvester Corp.) - Gunite 3721 or Webb 61528B | Gunite 3721AX | \$397.29 | 68% | \$127.13 | Power Brake 61528B | \$230.00 | 50% | \$115.00 |
| 22. | Grooved Drum (Freightliner) - 66884B Webb | Webb 66884B-20 B-20 = pallet qty | \$397.00 | 68% | \$127.04 | Power Brake 66884B | \$220.00 | 50% | \$110.00 |
| 23. | Rear Drum (International Harvester Corp.) - 3647 Gunite or 66353F Webb | Gunite 3757X* Aftermarket | \$478.57 | 68% | \$153.14 | Power Brake 66353F | \$243.00 | 50% | \$121.50 |
| 24. | Rear Drum (Freightliner) - 66843B Webb | as spec | \$542.30 | 68% | \$173.54 | as spec | \$341.50 | 50% | \$170.75 |
| 25. | Rear Drum (Freightliner) - 3600AX Gunite or 66864B Webb | as spec Gunite | \$330.29 | 68% | \$105.69 | Power Brake 66864B | \$160.00 | 50% | \$80.00 |
| 26. | Balance of line item discount for Gunite, Webb, or approved alternate. | Gunite & Webb | | 68% | | | | | |
| MONROE or approved alternate. | | | | | | | | | |
| 27. | Front Shocks (International Harvester Corp.) - 66923 | Meritor/Euclid/ Gabriel 83456 | \$59.19 | 49% | \$30.19 | | | | |
| 28. | Front Shocks (Freightliner) - 85006 | Meritor/Euclid/ Gabriel 85006 | \$82.57 | 49% | \$42.11 | | | | |
| 29. | Front C2 Shocks - 65140 | Meritor/Euclid/ Gabriel 85918 | \$88.36 | 49% | \$45.06 | | | | |
| 30. | Rear Shocks (International Harvester Corp.) - 66924 | Meritor/Euclid/ Gabriel 83317 | \$62.87 | 49% | \$32.06 | | | | |
| 31. | Rear Shocks (Freightliner) - 65409 | Meritor/Euclid/ Gabriel 85003 | \$85.54 | 49% | \$43.63 | | | | |
| 32. | Rear Shocks (Freightliner) - 85013 | Meritor/Euclid/ Gabriel 85013 | \$90.52 | 49% | \$46.17 | | | | |
| 33. | Rear C2 Shocks - 65490 | Meritor/Euclid/ Gabriel 85724 | \$103.44 | 49% | \$52.75 | | | | |
| 34. | Balance of line item discount for Monroe or approved alternate. | Gabriel products distributed by Euclid and Meritor | | 49% | | | | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for Bus Brake Repair Parts - Bid #12-0155

Opened September 28, 2011 at 2:00 p.m.

| All brake linings to be riveted on SBSC brake shoes, OEM factory remanufactured brake shoes, or new brake shoes. | | Tampa Truck Center | | | |
|--|---|------------------------|-----------------|------------|----------------|
| Item # | Item and Description | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price |
| GUNITE or WEBB where indicated or approved alternate. | | | | | |
| 20. | Front Drum (Freightliner) - 3800X Gunite or 65548B Webb | as spec Gunite | \$151.61 | 12% | \$133.42 |
| 21. | Front Drum (International Harvester Corp.) - Gunite 3721 or Webb 61528B | as spec Gunite | \$150.77 | 5% | \$143.23 |
| 22. | Grooved Drum (Freightliner) - 66884B Webb | | \$205.02 | 5% | \$194.77 |
| 23. | Rear Drum (International Harvester Corp.) - 3647 Gunite or 66353F Webb | as spec Gunite | \$262.48 | 10% | \$236.23 |
| 24. | Rear Drum (Freightliner) - 66843B Webb | | \$258.38 | 10% | \$232.54 |
| 25. | Rear Drum (Freightliner) - 3600AX Gunite or 66864B Webb | as spec Gunite | \$125.23 | 4% | \$120.22 |
| 26. | Balance of line item discount for Gunite, Webb, or approved alternate. | | | | |
| MONROE or approved alternate. | | | | | |
| 27. | Front Shocks (International Harvester Corp.) - 66923 | | \$29.81 | 8% | \$27.43 |
| 28. | Front Shocks (Freightliner) - 85006 | | \$43.42 | 5% | \$41.25 |
| 29. | Front C2 Shocks - 65140 | | \$49.17 | 8% | \$45.24 |
| 30. | Rear Shocks (International Harvester Corp.) - 66924 | | \$30.46 | 8% | \$28.02 |
| 31. | Rear Shocks (Freightliner) - 65409 | | \$51.16 | 8% | \$47.07 |
| 32. | Rear Shocks (Freightliner) - 85013 | | \$51.23 | 8% | \$47.13 |
| 33. | Rear C2 Shocks - 65490 | | \$50.64 | 8% | \$46.59 |
| 34. | Balance of line item discount for Monroe or approved alternate. | | | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for Bus Brake Repair Parts - Bid #12-0155

Opened September 28, 2011 at 2:00 p.m.

| All brake linings to be riveted on SBSC brake shoes, OEM factory remanufactured brake shoes, or new brake shoes. | | Fleet Acquisitions dba Fleet Products | | | | Fleet Pride | | | |
|--|---|---------------------------------------|-----------------|------------|----------------|------------------------|-----------------|------------|----------------|
| Item # | Item and Description | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price |
| MIDLAND or approved alternate. | | | | | | | | | |
| 35. | Check Valve - KN23000 | as spec | | 57% | \$18.28 | | \$42.50 | 53% | \$19.98 |
| 36. | Clevis Brake Chamber - KN36470 | Midland CF2 | | 57% | \$3.03 | | \$7.05 | 53% | \$3.31 |
| 37. | Dash Valve - KN20033 | as spec | | 57% | \$23.57 | | \$54.82 | 53% | \$25.77 |
| 38. | Park Brake Valve (International Harvester Corp.) - RKN20031 PP1 | as spec | | 57% | \$23.57 | | \$54.82 | 53% | \$25.77 |
| 39. | Balance of line item discount for Midland or approved alternate. | | | 57% | | | | 53% | |
| NATIONAL or CHICAGO RAWHIDE where indicated or approved alternate. | | | | | | | | | |
| 40. | Front Seal - 35066 Chicago Rawhide | as spec | | 62% | \$26.87 | | \$70.72 | 66% | \$24.04 |
| 41. | Front Seal (International Harvester Corp. and Freightliner) - 370001A National | as spec | | 67% | \$21.61 | | \$65.49 | 60% | \$26.20 |
| 42. | Rear Seal (International Harvester Corp.) - 370023A National | as spec | | 67% | \$27.61 | | \$85.34 | 66% | \$29.02 |
| 43. | Rear Seal (Freightliner) - 370003A National or 47697 Chicago Rawhide | as spec | | 67% | \$27.44 | | \$84.83 | 66% | \$28.84 |
| 44. | Balance of line item discount for National, Chicago Rawhide, or approved alternate. | National Chicago Rawhide | | 67% 62% | | | | | |
| FEDERAL or approved alternate. | | | | | | | | | |
| 45. | Bearings (Freightliner) - 572 | Timken | | 76% | \$12.55 | | \$54.72 | 83% | \$9.30 |
| 46. | Bearings (Freightliner) - 580 | Timken | | 76% | \$20.13 | | \$84.36 | 83% | \$14.34 |
| 47. | Bearings (Freightliner) - 592-A | Timken | | 76% | \$15.32 | | \$67.33 | 83% | \$11.45 |
| 48. | Bearings (Freightliner) - 594-A | Timken | | 76% | \$23.48 | | \$102.10 | 83% | \$17.36 |
| 49. | Bearings (International Harvester Corp.) - 39520 | Timken | | 76% | \$8.34 | | \$35.34 | 82% | \$6.36 |
| 50. | Bearings (International Harvester Corp.) - 39590 | Timken | | 76% | \$14.02 | | \$59.63 | 82% | \$10.73 |
| 51. | Bearings (International Harvester Corp.) - 47620 | Timken | | 76% | \$14.33 | | \$62.65 | 82% | \$11.28 |
| 52. | Bearings (International Harvester Corp.) - 47686 | Timken | | 76% | \$22.30 | | \$96.46 | 82% | \$17.36 |
| 53. | Balance of line item discount for Federal or approved alternate. | Timken | | 76% | | | | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for Bus Brake Repair Parts - Bid #12-0155

Opened September 28, 2011 at 2:00 p.m.

| All brake linings to be riveted on SBSC brake shoes, OEM factory remanufactured brake shoes, or new brake shoes. | | Gary Yeomans Ford | | | | Napa Auto Parts | | | |
|--|---|------------------------|-----------------|------------|----------------|------------------------|-----------------|------------|----------------|
| Item # | Item and Description | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price |
| MIDLAND or approved alternate. | | | | | | | | | |
| 35. | Check Valve - KN23000 | Meritor RKN23000 | \$51.21 | 62% | \$19.46 | as spec | \$29.37 | 27% | \$21.44 |
| 36. | Clevis Brake Chamber - KN36470 | Midland ZZCF2 | \$7.41 | 61% | \$2.89 | CF2 | \$4.87 | 24% | \$3.70 |
| 37. | Dash Valve - KN20033 | Meritor RKN20033 | \$65.59 | 59% | \$26.89 | as spec | \$37.88 | 28% | \$27.27 |
| 38. | Park Brake Valve (International Harvester Corp.) - RKN20031 PP1 | RKN20031 | \$66.78 | 60% | \$26.71 | KN20031 | \$37.88 | 28% | \$27.27 |
| 39. | Balance of line item discount for Midland or approved alternate. | | | 60% | | | | 28% | |
| NATIONAL or CHICAGO RAWHIDE where indicated or approved alternate. | | | | | | | | | |
| 40. | Front Seal - 35066 Chicago Rawhide | as spec | \$42.57 | 38% | \$26.39 | as spec | \$64.94 | 47% | \$34.42 |
| 41. | Front Seal (International Harvester Corp. and Freightliner) - 370001A National | V370001A | \$46.37 | 54% | \$21.33 | as spec | \$57.76 | 57% | \$24.84 |
| 42. | Rear Seal (International Harvester Corp.) - 370023A National | V370023A | \$59.27 | 53% | \$27.86 | as spec | \$69.39 | 57% | \$29.84 |
| 43. | Rear Seal (Freightliner) - 370003A National or 47697 Chicago Rawhide | V370003A | \$58.91 | 53% | \$27.69 | as spec National | \$72.27 | 56% | \$31.80 |
| 44. | Balance of line item discount for National, Chicago Rawhide, or approved alternate. | | | 50% | | | | 57% | |
| FEDERAL or approved alternate. | | | | | | | | | |
| 45. | Bearings (Freightliner) - 572 | | \$24.48 | 29% | \$17.38 | BR572 | \$44.54 | 47% | \$23.61 |
| 46. | Bearings (Freightliner) - 580 | | \$39.21 | 29% | \$27.84 | BR580 | \$71.68 | 47% | \$37.99 |
| 47. | Bearings (Freightliner) - 592-A | | \$30.11 | 29% | \$21.38 | as spec | \$55.19 | 48% | \$28.70 |
| 48. | Bearings (Freightliner) - 594-A | | \$45.65 | 29% | \$32.41 | as spec | \$83.04 | 47% | \$44.01 |
| 49. | Bearings (International Harvester Corp.) - 39520 | | \$15.79 | 28% | \$11.37 | BR39520 | \$30.04 | 47% | \$15.92 |
| 50. | Bearings (International Harvester Corp.) - 39590 | | \$26.67 | 28% | \$19.20 | BR39590 | \$50.22 | 47% | \$26.62 |
| 51. | Bearings (International Harvester Corp.) - 47620 | | \$28.02 | 28% | \$20.17 | BR47620 | \$52.29 | 47% | \$27.71 |
| 52. | Bearings (International Harvester Corp.) - 47686 | | \$43.14 | 28% | \$31.06 | BR47686 | \$81.47 | 47% | \$43.18 |
| 53. | Balance of line item discount for Federal or approved alternate. | | | 29% | | | | 47% | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for Bus Brake Repair Parts - Bid #12-0155

Opened September 28, 2011 at 2:00 p.m.

| All brake linings to be riveted on SBSC brake shoes, OEM factory remanufactured brake shoes, or new brake shoes. | | The Parts House | | | | Power Brake, LLC | | | |
|--|---|-------------------------|-----------------|------------|----------------|------------------------|-----------------|------------|----------------|
| Item # | Item and Description | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price |
| MIDLAND or approved alternate. | | | | | | | | | |
| 35. | Check Valve - KN23000 | as spec | \$42.50 | 58% | \$17.85 | | | | |
| 36. | Clevis Brake Chamber - KN36470 | Replaced by CF-2 | \$7.05 | 58% | \$2.96 | | | | |
| 37. | Dash Valve - KN20033 | as spec | \$54.82 | 58% | \$23.02 | | | | |
| 38. | Park Brake Valve (International Harvester Corp.) - RKN20031 PP1 | KN20031 | \$54.82 | 58% | \$23.02 | | | | |
| 39. | Balance of line item discount for Midland or approved alternate. | Midland Haldex | | 58% | | | | | |
| NATIONAL or CHICAGO RAWHIDE where indicated or approved alternate. | | | | | | | | | |
| 40. | Front Seal - 35066 Chicago Rawhide | | | | | | | | |
| 41. | Front Seal (International Harvester Corp. and Freightliner) - 370001A National | as spec National | \$65.49 | 67% | \$21.61 | | | | |
| 42. | Rear Seal (International Harvester Corp.) - 370023A National | as spec National | \$85.34 | 67% | \$28.16 | | | | |
| 43. | Rear Seal (Freightliner) - 370003A National or 47697 Chicago Rawhide | as spec National | \$84.83 | 67% | \$27.99 | | | | |
| 44. | Balance of line item discount for National, Chicago Rawhide, or approved alternate. | National Seals | | 67% | | | | | |
| FEDERAL or approved alternate. | | | | | | | | | |
| 45. | Bearings (Freightliner) - 572 | | | | | | | | |
| 46. | Bearings (Freightliner) - 580 | | | | | | | | |
| 47. | Bearings (Freightliner) - 592-A | | | | | | | | |
| 48. | Bearings (Freightliner) - 594-A | | | | | | | | |
| 49. | Bearings (International Harvester Corp.) - 39520 | | | | | | | | |
| 50. | Bearings (International Harvester Corp.) - 39590 | | | | | | | | |
| 51. | Bearings (International Harvester Corp.) - 47620 | | | | | | | | |
| 52. | Bearings (International Harvester Corp.) - 47686 | | | | | | | | |
| 53. | Balance of line item discount for Federal or approved alternate. | | | | | | | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for Bus Brake Repair Parts - Bid #12-0155

Opened September 28, 2011 at 2:00 p.m.

| All brake linings to be riveted on SBSC brake shoes, OEM factory remanufactured brake shoes, or new brake shoes. | | Tampa Truck Center | | | |
|--|---|------------------------|-----------------|------------|----------------|
| Item # | Item and Description | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price |
| MIDLAND or approved alternate. | | | | | |
| 35. | Check Valve - KN23000 | | \$23.74 | 6% | \$22.32 |
| 36. | Clevis Brake Chamber - KN36470 | HDX/CF2 | \$3.85 | 6% | \$3.62 |
| 37. | Dash Valve - KN20033 | | \$30.46 | 6% | \$28.63 |
| 38. | Park Brake Valve (International Harvester Corp.) - RKN20031 PP1 | | \$30.02 | 6% | \$28.22 |
| 39. | Balance of line item discount for Midland or approved alternate. | | | | |
| NATIONAL or CHICAGO RAWHIDE where indicated or approved alternate. | | | | | |
| 40. | Front Seal - 35066 Chicago Rawhide | | \$27.17 | 4% | \$26.08 |
| 41. | Front Seal (International Harvester Corp. and Freightliner) - 370001A National | | \$21.68 | 4% | \$20.81 |
| 42. | Rear Seal (International Harvester Corp.) - 370023A National | | \$27.71 | 4% | \$26.60 |
| 43. | Rear Seal (Freightliner) - 370003A National or 47697 Chicago Rawhide | as spec National | \$27.54 | 4% | \$26.44 |
| 44. | Balance of line item discount for National, Chicago Rawhide, or approved alternate. | | | | |
| FEDERAL or approved alternate. | | | | | |
| 45. | Bearings (Freightliner) - 572 | | \$13.01 | 5% | \$12.36 |
| 46. | Bearings (Freightliner) - 580 | | \$21.03 | 5% | \$19.98 |
| 47. | Bearings (Freightliner) - 592-A | | \$16.03 | 5% | \$15.23 |
| 48. | Bearings (Freightliner) - 594-A | | \$24.84 | 5% | \$23.60 |
| 49. | Bearings (International Harvester Corp.) - 39520 | | \$9.51 | 5% | \$9.03 |
| 50. | Bearings (International Harvester Corp.) - 39590 | | \$15.90 | 5% | \$15.11 |
| 51. | Bearings (International Harvester Corp.) - 47620 | | \$16.51 | 5% | \$15.68 |
| 52. | Bearings (International Harvester Corp.) - 47686 | | \$25.86 | 5% | \$24.57 |
| 53. | Balance of line item discount for Federal or approved alternate. | | | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for Bus Brake Repair Parts - Bid #12-0155

Opened September 28, 2011 at 2:00 p.m.

| All brake linings to be riveted on SBSC brake shoes, OEM factory remanufactured brake shoes, or new brake shoes. | | Fleet Acquisitions dba Fleet Products | | | | Fleet Pride | | | |
|--|---|---|-----------------|--------------------------|--|------------------------|-----------------|------------|----------------|
| Item # | Item and Description | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price |
| STEMCO or CHICAGO RAWHIDE where indicated or approved alternate. | | | | | | | | | |
| 54. | Front Gasket (Freightliner) - 453869 Chicago Rawhide | as spec | | 62% | \$1.36 | 330-3024 | \$2.63 | 50% | \$1.32 |
| 55. | Front Hub, Oiler (International Harvester Corp.) - 343-4009 Stemco | as spec | | 53% | \$15.64 | | \$34.20 | 50% | \$17.10 |
| 56. | Front Hub, Oiler (Freightliner) - 343-4024 Stemco | as spec | | 53% | \$26.81 | | \$58.65 | 50% | \$29.33 |
| 57. | Front Hub, Oiler (Freightliner) - 1612 Chicago Rawhide | as spec | | 62% | \$17.98 | | \$47.31 | 50% | \$23.66 |
| 58. | Front Hub Gasket (Freightliner) - 330-3024 Stemco | as spec | | 53% | \$1.20 | | \$2.62 | 50% | \$1.31 |
| 59. | Hub Cap, Oiler - 359-5990 Stemco or 450434 Chicago Rawhide | as spec | | 62% | \$2.51 | | \$5.33 | 50% | \$2.67 |
| 60. | Hub Gasket, Large, Oiler - 330-3009 Stemco | as spec | | 53% | \$1.18 | | \$2.58 | 50% | \$1.29 |
| 61. | Balance of line item discount for Stemco, Chicago Rawhide, or approved alternate. | Stemco Chicago Rawhide | | 53% 62% | | | | 50% | |
| NOTES | | Items 45-53: Made in USA | | | | | | | |
| Contact | Anthony V. Zummo | | | | Andrew Bell | | | | |
| Address | 6510 Golden Groves | | | | 2141 Whitfield Park Loop | | | | |
| | Tampa, FL 33610 | | | | Sarasota, FL 34243 | | | | |
| Phone | 813-621-1734 | | | | 941-758-8282 | | | | |
| Fax | 813-626-2010 | | | | 941-752-3652 | | | | |
| Federal I.D. | 621868964 | | | | 364274919 | | | | |
| Email | azummo@fleetproductsfl.com | | | | andy.bell2@fleetpride.com | | | | |
| | | | | | | | | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for Bus Brake Repair Parts - Bid #12-0155

Opened September 28, 2011 at 2:00 p.m.

| All brake linings to be riveted on SBSC brake shoes, OEM factory remanufactured brake shoes, or new brake shoes. | | Gary Yeomans Ford | | | | Napa Auto Parts | | | |
|--|---|---|-----------------|------------|--|--------------------------------|-----------------|------------|----------------|
| Item # | Item and Description | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price |
| STEMCO or CHICAGO RAWHIDE where indicated or approved alternate. | | | | | | | | | |
| 54. | Front Gasket (Freightliner) - 453869 Chicago Rawhide | as spec | \$1.60 | 29% | \$1.14 | as spec | \$2.66 | 47% | \$1.41 |
| 55. | Front Hub, Oiler (International Harvester Corp.) - 343-4009 Stemco | ZCP3434009 | \$25.69 | 39% | \$15.67 | 1643 | \$31.81 | 47% | \$16.86 |
| 56. | Front Hub, Oiler (Freightliner) - 343-4024 Stemco | ZCP3434024 | \$44.15 | 45% | \$24.28 | 1711 | \$49.19 | 48% | \$25.58 |
| 57. | Front Hub, Oiler (Freightliner) - 1612 Chicago Rawhide | as spec | \$26.31 | 31% | \$18.15 | as spec | \$43.44 | 47% | \$23.02 |
| 58. | Front Hub Gasket (Freightliner) - 330-3024 Stemco | ZCP3303024 | \$1.98 | 41% | \$1.17 | 450755 | \$2.66 | 47% | \$1.41 |
| 59. | Hub Cap, Oiler - 359-5990 Stemco or 450434 Chicago Rawhide | as spec | \$2.26 | 31% | \$1.56 | as spec Chicago Rawhide | \$3.78 | 47% | \$2.00 |
| 60. | Hub Gasket, Large, Oiler - 330-3009 Stemco | ZCP3303009 | \$1.91 | 41% | \$1.13 | 450293 | \$2.43 | 47% | \$1.29 |
| 61. | Balance of line item discount for Stemco, Chicago Rawhide, or approved alternate. | | | 37% | | | | | |
| NOTES | | Can supply price sheets on a USB Drive upon request (very large file, did not want to send 1,000+ pages). | | | | | | | |
| Contact | Ray Grubbs | | | | Dennis Nowak | | | | |
| Address | 1420 North Tomoka Farms Road Daytona Beach, FL 32124 | | | | 1955 Upper Beechwood Sarasota, FL 34232 | | | | |
| Phone | 800-231-6172 | | | | 941-780-7710 | | | | |
| Fax | 386-274-6739 | | | | 941-922-5041 | | | | |
| Federal I.D. | 592164165 | | | | 580254510 | | | | |
| Email | rgrubbs@garyyeomansford.com | | | | nowakdln@aol.com | | | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for Bus Brake Repair Parts - Bid #12-0155

Opened September 28, 2011 at 2:00 p.m.

| All brake linings to be riveted on SBSC brake shoes, OEM factory remanufactured brake shoes, or new brake shoes. | | The Parts House | | | | Power Brake, LLC | | | |
|--|---|------------------------|-----------------|------------|--|------------------------|-----------------|------------|----------------|
| Item # | Item and Description | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price |
| STEMCO or CHICAGO RAWHIDE where indicated or approved alternate. | | | | | | | | | |
| 54. | Front Gasket (Freightliner) - 453869 Chicago Rawhide | | | | | | | | |
| 55. | Front Hub, Oiler (International Harvester Corp.) - 343-4009 Stemco | | | | | | | | |
| 56. | Front Hub, Oiler (Freightliner) - 343-4024 Stemco | | | | | | | | |
| 57. | Front Hub, Oiler (Freightliner) - 1612 Chicago Rawhide | | | | | | | | |
| 58. | Front Hub Gasket (Freightliner) - 330-3024 Stemco | | | | | | | | |
| 59. | Hub Cap, Oiler - 359-5990 Stemco or 450434 Chicago Rawhide | | | | | | | | |
| 60. | Hub Gasket, Large, Oiler - 330-3009 Stemco | | | | | | | | |
| 61. | Balance of line item discount for Stemco, Chicago Rawhide, or approved alternate. | | | | | | | | |
| NOTES | | Item 23: 3647 is OEM. | | | | | | | |
| Contact | Richard Kilpatrick | | | | Tom Cox | | | | |
| Address | 4083 Sawyer Court | | | | 4351B 34th Street North | | | | |
| | Sarasota, FL 34233 | | | | St. Petersburg, FL 33714 | | | | |
| Phone | 941-924-2394 | | | | 727-526-1333 | | | | |
| Fax | 941-924-8621 | | | | 727-526-1306 | | | | |
| Federal I.D. | 611436406 | | | | 223934354 | | | | |
| Email | rkilpatrick@thepartshouse.com | | | | tom@powerbrake1.com | | | | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

Tabulation for Bus Brake Repair Parts - Bid #12-0155

Opened September 28, 2011 at 2:00 p.m.

| All brake linings to be riveted on SBSC brake shoes, OEM factory remanufactured brake shoes, or new brake shoes. | | Tampa Truck Center | | | |
|--|---|-------------------------|-----------------|------------------------------|----------------|
| Item # | Item and Description | Alternate Mfr & Part # | Wholesale Price | % Discount | District Price |
| STEMCO or CHICAGO RAWHIDE where indicated or approved alternate. | | | | | |
| 54. | Front Gasket (Freightliner) - 453869 Chicago Rawhide | | \$1.42 | 6% | \$1.33 |
| 55. | Front Hub, Oiler (International Harvester Corp.) - 343-4009 Stemco | | \$17.95 | 6% | \$16.87 |
| 56. | Front Hub, Oiler (Freightliner) - 343-4024 Stemco | | \$30.58 | 6% | \$28.75 |
| 57. | Front Hub, Oiler (Freightliner) - 1612 Chicago Rawhide | | \$18.54 | 6% | \$17.43 |
| 58. | Front Hub Gasket (Freightliner) - 330-3024 Stemco | | \$1.81 | 6% | \$1.70 |
| 59. | Hub Cap, Oiler - 359-5990 Stemco or 450434 Chicago Rawhide | | \$1.64 | 6% | \$1.54 |
| 60. | Hub Gasket, Large, Oiler - 330-3009 Stemco | | \$1.59 | 6% | \$1.49 |
| 61. | Balance of line item discount for Stemco, Chicago Rawhide, or approved alternate. | | | | |
| NOTES | | | | | |
| Contact | Jeff Ballard | | | | |
| Address | 7528 US Highway 301 North Tampa, FL 33637 | | | | |
| Phone | 813-262-0890, cell 727-534-1353 | | | | |
| Fax | 813-664-1238 | | | | |
| Federal I.D. | 398015193676-8 | | | | |
| Email | jballard@tampaftr.com | | | | |
| | | Recorded by: Peggy Long | | Witnessed by: Joyce E. Haney | |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA
JUSTIFICATION

Bus Brake Parts - Bid #12-0155

Opened: September 28, 2011 at 2:00 p.m.

| Item # | Bidder | Reason For Not Awarding To Other Than Low Bidder |
|--------|---------------------------------------|--|
| 2 | NAPA Auto Parts | Unable to evaluate discount as item bid was not included on submitted price sheets. |
| | Power Brake, LLC | Price sheets were not submitted as required in bid specifications. |
| 3 | NAPA Auto Parts | Unable to evaluate discount as item bid was not included on submitted price sheets. |
| 4 | NAPA Auto Parts | Unable to evaluate discount as item bid was not included on submitted price sheets. |
| 9 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. |
| 19 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. |
| 21 | Power Brake, LLC | Price sheets were not submitted as required in bid specifications. |
| 22 | The Parts House | Vendor qualified bid by giving pricing of pallet vs. each price as requested on the bid form. |
| | Power Brake, LLC | Price sheets were not submitted as required in bid specifications. |
| 23 | Power Brake, LLC | Price sheets were not submitted as required in bid specifications. |
| 24 | Power Brake, LLC | Price sheets were not submitted as required in bid specifications. |
| 25 | Power Brake, LLC | Price sheets were not submitted as required in bid specifications. |
| 26 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. |
| 34 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. |
| 36 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. |
| 39 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. |
| 41 | Fleet Acquisitions dba Fleet Products | Vendor bid discount off list price, but submitted a wholesale jobber price list for this category, unable to evaluate discount. Tie bid was awarded to The Parts House per tie bid specifications. |
| | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. |
| | Tampa Truck Center | Price sheets were not submitted as required in bid specifications. |
| 42 | Fleet Acquisitions dba Fleet Products | Vendor bid discount off list price, but submitted a wholesale jobber price list for this category, unable to evaluate discount. |
| | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. |
| | Tampa Truck Center | Price sheets were not submitted as required in bid specifications. |
| 43 | Fleet Acquisitions dba Fleet Products | Vendor bid discount off list price, but submitted a wholesale jobber price list for this category, unable to evaluate discount. |
| | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. |
| | Tampa Truck Center | Price sheets were not submitted as required in bid specifications. |

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA
JUSTIFICATION

Bus Brake Parts - Bid #12-0155

Opened: September 28, 2011 at 2:00 p.m.

| Item # | Bidder | Reason For Not Awarding To Other Than Low Bidder |
|--------|---------------------------------------|---|
| 44 | Fleet Acquisitions dba Fleet Products | Vendor bid discount off National brand list price, but submitted a wholesale jobber price list for this category, unable to evaluate discount. Tie bid was awarded to The Parts House per tie bid specifications. |
| 54 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. |
| 56 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. |
| 57 | Tampa Truck Center | Price sheets were not submitted as required in bid specifications. |
| 58 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. |
| 59 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. |
| | Tampa Truck Center | Price sheets were not submitted as required in bid specifications. |
| 60 | Gary Yeomans Ford | Price sheets were not submitted as required in bid specifications. |