

Materials Management Purchasing Department 1010Id Venice Road, Osprey, FL 34229 Phone 941-486-2183 • Fax 941-486-2188 SarasotaCountySchools.net

# MEMORANDUM

- TO:Members of the School Board<br/>Dr. Todd Bowden, Superintendent<br/>Mitsi Corcoran, Assistant Superintendent Chief Financial Officer
- FROM: Carol A. Lichon, CPPO, Director of Materials Management

# TITLE: APPROVAL TO AWARD BID #18-01555 BUS BRAKE REPAIR PARTS

Bids to provide 'Bus Brake Repair Parts' were received from nine vendors on September 26, 2017. The bids of Fleet Acquisitions, LLC dba Fleet Products, Fleet Pride, NeoPart Transit, Tampa Spring Company, TPH Holding, LLC dba The Parts House, and Vehicle Maintenance Program, Inc., were the best low bids meeting the advertised specifications. Reasons for not selecting the apparent low bid are included with the bid tabulation. This bid is for a period of three years with an option to renew for two additional one-year periods. The funds for these purchases are contained in the operating budget allocated to the Transportation Department.

Requested by: Ellery Girard "Failure to file a protest within the time prescribed in Section 120.57(3), Florida Statutes, or failure to post the protest bond or other security required by law within the time allowed for filing a bond shall constitute a waiver of proceedings under Chapter 120. Florida Statutes."

Posting Date: 10/10/2017

Fiscal Impact:

Not to exceed \$300,000.00 For a three-year period

**Recommended Motion:** That the bids of Fleet Acquisitions, LLC dba Fleet Products, Fleet Pride, NeoPart Transit, Tampa Spring Company, TPH Holding, LLC dba The Parts House, and Vehicle Maintenance Program, Inc., to provide 'Bus Brake Repair Parts' in an amount not to exceed \$300,000.00 for a three-year period, be approved as presented.

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM emanufacturered brake shoes, or new brake shoes.	FI	eet Acquisit dba Fleet Pr	•		Fleet Pride			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
MERITO	R, MERITOR 312, BENDIX where indicated or approved alternate.								
1	New Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124702QP	as spec	\$187.37	67.92%	\$60.10	as spec	\$187.37	67%	\$61.83
2	New Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124707QP	as spec	\$219.06	67.92%	\$70.27	as spec	\$219.06	67%	\$72.29
3	New Front Heavy Duty Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA2124702QP	as spec	\$278.58	67.92%	\$89.37	as spec	\$278.59	67%	\$91.93
4	Remanufactured Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124702QP	as spec	\$138.45	67.92%	\$44.41	as spec	\$138.45	67%	\$45.69
5	Remanufactured Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124707QP	as spec	\$153.34	67.92%	\$49.19	as spec	\$153.34	67%	\$50.60
6	Front & Rear Brake Pads (Disc Brakes) - Bendix 802078	Bendix K070796	\$377.00	56.82%	\$162.79	Bendix K070796	\$603.20	73%	\$162.86
7	Rear Slack Adjuster - Meritor R801073	Meritor R803110	\$146.21	65.23%	\$50.84	as spec	\$159.77	67%	\$52.72
8	Tapered Roller Hardware Kit - Meritor 8847HDA KIT REJECT	Meritor Kit 8847HDA	\$78.36	60.04%	\$31.31	as spec	\$78.36	60%	\$31.34
9	Tapered Roller Only - Meritor 8847HD   REJECT	Meritor Kit 8847HD	\$31.81	60.01%	\$12.72	as spec	\$31.81	60%	\$12.72
10	Slack Adjuster Replacement Pawl for front and rear slack adjustment assemblies - AY PAWL ASA. Meritor R801700	as spec	\$25.39	59.98%	\$10.16	as spec	25.39	69%	\$7.87
11	Balance of line item discount for all Meritor, Meritor 312, Bendix brake pads or approved alternate.		Perc	entage Disc	ount		Perc	entage Disco	ount
a.	Meritor			60%				60%	
b.	Meritor 312			65%				67%	
C.	Bendix			57%				73%	
d.	Approved alternate: REJECT								
e.	Approved alternate: REJECT								

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM manufacturered brake shoes, or new brake shoes.		NeoPart	Transit		O'Reilly Automotive Stores, Inc., dba O'Reilly Auto Parts				
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price	
MERITOR	R, MERITOR 312, BENDIX where indicated or approved alternate.					Brake Best HD				
1	New Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124702QP	as spec	\$187.37	65%	\$65.58					
2	New Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124707QP	as spec	\$219.06	65%	\$76.67					
3	New Front Heavy Duty Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA2124702QP	as spec	\$278.59	65%	\$97.51					
4	Remanufactured Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124702QP	as spec	\$138.45	65%	\$48.46	BBHPF4702Q P23	\$142.36	41%	\$63.24	
5	Remanufactured Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124707QP	as spec	\$153.34	65%	\$53.67	BBHPF4707Q P23	\$164.39	41%	\$74.14	
6	Front & Rear Brake Pads (Disc Brakes) - Bendix 802078	Meritor MMD 1369AF	\$268.06	65%	\$93.82					
7	Rear Slack Adjuster - Meritor R801073	as spec	\$159.77	65%	\$55.92	BBHRBR8010 73	\$149.14	41%	\$59.45	
8	Tapered Roller Hardware Kit - Meritor 8847HDA KIT REJECT	as spec	\$78.36	65%	\$27.43					
9	Tapered Roller Only - Meritor 8847HD         REJECT	as spec	\$31.81	65%	\$11.13					
10	Slack Adjuster Replacement Pawl for front and rear slack adjustment assemblies - AY PAWL ASA. Meritor R801700	as spec	25.39	65%	\$8.89					
11	Balance of line item discount for all Meritor, Meritor 312, Bendix brake pads or approved alternate.		Perc	entage Disc	count		Perc	entage Disc	ount	
a.	Meritor									
b.	Meritor 312									
C.	Bendix									
d.	Approved alternate: REJECT					Brake Best HD	List le	ess 41% or b	oetter	
e.	Approved alternate: REJECT									

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM manufacturered brake shoes, or new brake shoes.	R	ush Truck Ce	enters		Sun State International			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
MERITOR	R, MERITOR 312, BENDIX where indicated or approved alternate.								
1	New Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124702QP		\$91.05	25%	\$68.29	as spec	\$187.37	65%	\$65.58
2	New Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124707QP		\$106.44	25%	\$79.83	as spec	\$219.06	67%	\$72.29
3	New Front Heavy Duty Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA2124702QP		\$135.95	25%	\$101.96	as spec	\$282.41	67%	\$93.20
4	Remanufactured Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124702QP	Meritor XK3124702QPK RMAN	\$65.48	25%	\$49.11	as spec	\$138.45	65%	\$48.46
5	Remanufactured Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124707QP	Meritor XK3124707QPK RMAN	\$62.44	25%	\$46.83	as spec	\$153.34	70%	\$46.00
6	Front & Rear Brake Pads (Disc Brakes) - Bendix 802078	Bendix K070796BXW	\$377.00	57%	\$162.11	as spec	\$438.61	58%	\$184.22
7	Rear Slack Adjuster - Meritor R801073	Bendix R803110	\$105.28	45%	\$57.90	as spec	\$198.02	60%	\$79.21
8	Tapered Roller Hardware Kit - Meritor 8847HDA KIT REJECT					KIT8847HD	\$31.81	60%	\$12.72
9	Tapered Roller Only - Meritor 8847HD   REJECT					2297T7222	\$4.41	65%	\$1.54
10	Slack Adjuster Replacement Pawl for front and rear slack adjustment assemblies - AY PAWL ASA. Meritor R801700	Meritor	25.39	58%	\$10.66	as spec	\$25.39	57%	\$10.92
11	Balance of line item discount for all Meritor, Meritor 312, Bendix brake pads or approved alternate.		Perce	entage Disc	count		Perc	entage Disc	count
a.	Meritor			25%			National F	leet	
b.	Meritor 312		25%			National F	Fleet		
C.	Bendix		29%			National F	Fleet		
d.	Approved alternate: REJECT	Meritor	25%			National Fleet			
e.	Approved alternate: REJECT	Meritor	25%			National Fleet			

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM manufacturered brake shoes, or new brake shoes.	Та	Tampa Spring Company				TPH Holdings, LLC dba The Parts House				
Item #	Item and Description	Mfr & Part #	Cost	GPM % Markup	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price		
MERITOR	R, MERITOR 312, BENDIX where indicated or approved alternate.										
1	New Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124702QP					as spec	\$187.37	66%	\$63.71		
2	New Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124707QP					as spec	\$219.06	66%	\$74.48		
3	New Front Heavy Duty Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA2124702QP					as spec	\$278.59	66%	\$94.72		
4	Remanufactured Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124702QP					as spec	\$138.45	66%	\$47.07		
5	Remanufactured Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124707QP					as spec	\$153.34	66%	\$52.14		
6	Front & Rear Brake Pads (Disc Brakes) - Bendix 802078					P/N obsolete per Bendix K070796	\$377.00	60%	\$150.80		
7	Rear Slack Adjuster - Meritor R801073					Per Meritor R803110	\$146.21	61%	\$57.02		
8	Tapered Roller Hardware Kit - Meritor 8847HDA KIT REJECT					as spec KIT8847HDA	\$78.36	61%	\$30.56		
9	Tapered Roller Only - Meritor 8847HD   REJECT					as spec KIT8847HD	\$31.81	61%	\$12.41		
10	Slack Adjuster Replacement Pawl for front and rear slack adjustment assemblies - AY PAWL ASA. Meritor R801700					as spec	\$25.39	61%	\$9.90		
11	Balance of line item discount for all Meritor, Meritor 312, Bendix brake pads or approved alternate.		Per	centage Disc	ount		Percer	ntage Disco	ount		
a.	Meritor							59%			
b.	Meritor 312							64%			
c.	Bendix							60%			
d.	Approved alternate: REJECT										
e.	Approved alternate: REJECT										

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

\_

	linings will be riveted on Sarasota School District brake shoes, OEM manufacturered brake shoes, or new brake shoes.	Vehicle Ma	intenance Pr	ogram, Inc.	
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price
MERITOR	R, MERITOR 312, BENDIX where indicated or approved alternate.				
1	New Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124702QP				
2	New Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124707QP				
3	New Front Heavy Duty Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA2124702QP				
4	Remanufactured Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124702QP				
5	Remanufactured Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124707QP				
6	Front & Rear Brake Pads (Disc Brakes) - Bendix 802078				
7	Rear Slack Adjuster - Meritor R801073				
8	Tapered Roller Hardware Kit - Meritor 8847HDA KIT REJECT				
9	Tapered Roller Only - Meritor 8847HD   REJECT				
10	Slack Adjuster Replacement Pawl for front and rear slack adjustment assemblies - AY PAWL ASA. Meritor R801700				
11	Balance of line item discount for all Meritor, Meritor 312, Bendix brake pads or approved alternate.		Perce	entage Disco	unt
a.	Meritor				
b.	Meritor 312		_		
C.	Bendix				
d.	Approved alternate: REJECT				
e.	Approved alternate: REJECT				

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM manufacturered brake shoes, or new brake shoes.		eet Acquisit dba Fleet Pi			Fleet Pride			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
BENDIX,	MERITOR, WABCO where indicated or approved alternate.								
12	Dryer - Bendix 107794X - AD9	as spec	\$58.17	61.17%	\$22.59	as spec	\$52.88	57%	\$22.74
13	Park Brake Valve - Bendix 801315	as spec	\$301.03	56.82%	\$129.99	as spec	\$313.40	58%	\$131.63
14	Purge Valve Kit for AD9 - Bendix #BXM	Bendix 5005037	\$67.68	56.81%	\$29.23	Bendix 800405	\$311.56	58%	\$130.86
15	Front ABS Sensor (Rotors) - Meritor S4410323810	Meritor R955608	\$100.64	59.09%	\$41.17	Meritor R955608	\$127.12	66%	\$43.22
16	Rear ABS Sensor (Rotors) - Meritor S4410321840	Meritor R955604	\$81.06	59.09%	\$33.16	Meritor R955604	\$102.39	66%	\$34.81
17	Front Speed Sensor (Drums) - Bendix 801541	as spec	\$95.82	56.81%	\$41.38		\$99.75	58%	\$41.90
18	Rear Speed Sensor (Drums) - Bendix #BXM	Bendix 801538	\$102.71	56.82%	\$44.35	Bendix 801542	\$116.30	58%	\$48.85
BENDIX,	MERITOR, WABCO where indicated or approved alternate.								
19	Right side Caliper, steer and drive vertical "A" (22A +23) for ADB22X Air Disc Brake - Bendix - K081256	as spec	\$2,372.45	56.82%	\$1,024.47	as spec	\$2,469.95	58%	\$1,037.38
20	Left side Caliper, steer and drive vertical "B" (22A +23) for ADB22X Air Disc Brake - Bendix - K081257	as spec	\$2,372.45	56.82%	\$1,024.47	as spec	\$2,469.95	58%	\$1,037.38
21	Balance of line item discount for Bendix, Meritor, WABCO or approved alternate.		Perc	centage Disc	count		Perc	entage Disc	ount
a.	Bendix			57%				58%	
b.	Meritor			60%				66%	
c.	WABCO			60%					
d.	Approved alternate: REJECT								
e.	Approved alternate: REJECT								

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

	All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufacturered brake shoes, or new brake shoes.		NeoPart	Transit		O'Reilly Automotive Stores, Inc., dba O'Reilly Auto Parts				
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price	
BENDIX,	MERITOR, WABCO where indicated or approved alternate.					Brake Best HD				
12	Dryer - Bendix 107794X - AD9	as spec	\$88.17	35%	\$57.31	BBHRB10779 4	\$96.59	41%	\$38.08	
13	Park Brake Valve - Bendix 801315	as spec	\$301.03	55%	\$135.46					
14	Purge Valve Kit for AD9 - Bendix #BXM					BBH5005037 N	\$116.93	41%	\$47.61	
15	Front ABS Sensor (Rotors) - Meritor S4410323810	as spec	\$79.08	65%	\$27.68					
16	Rear ABS Sensor (Rotors) - Meritor S4410321840	as spec	\$60.49	65%	\$21.17					
17	Front Speed Sensor (Drums) - Bendix 801541	as spec	\$95.82	55%	\$43.12					
18	Rear Speed Sensor (Drums) - Bendix #BXM									
BENDIX,	MERITOR, WABCO where indicated or approved alternate.									
19	Right side Caliper, steer and drive vertical "A" (22A +23) for ADB22X Air Disc Brake - Bendix - K081256	as spec	\$2,372.45	55%	\$1,067.60					
20	Left side Caliper, steer and drive vertical "B" (22A +23) for ADB22X Air Disc Brake - Bendix - K081257	as spec	\$2,372.45	55%	\$1,067.60					
21	Balance of line item discount for Bendix, Meritor, WABCO or approved alternate.		Perc	entage Dis	count		Perc	entage Disc	count	
a.	Bendix			55%						
b.	Meritor			65%						
c.	WABCO			65%						
d.	Approved alternate: REJECT		<u>e</u>			Brake Best HD	List le	ess 41% or l	petter	
e.	Approved alternate: REJECT									

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM manufacturered brake shoes, or new brake shoes.	R	ush Truck Ce	enters		Sun State International			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
BENDIX,	MERITOR, WABCO where indicated or approved alternate.								
12	Dryer - Bendix 107794X - AD9	Bendix	\$58.17	60%	\$23.27	as spec	\$58.17	61%	\$22.69
13	Park Brake Valve - Bendix 801315	Bendix	\$177.71	29%	\$126.17	as spec	\$295.11	48%	\$153.46
14	Purge Valve Kit for AD9 - Bendix #BXM	New Number Bendix 500537BXW	\$67.68	58%	\$28.43	BXM 5005037	\$66.55	42%	\$38.60
15	Front ABS Sensor (Rotors) - Meritor S4410323810	Meritor	\$83.25	60%	\$33.30	R955608	\$100.65	62%	\$38.25
16	Rear ABS Sensor (Rotors) - Meritor S4410321840	Meritor	\$63.67	60%	\$25.47	R955604	\$81.05	55%	\$36.47
17	Front Speed Sensor (Drums) - Bendix 801541	Bendix	\$95.82	58%	\$40.24	as spec	\$95.34	57%	\$41.00
18	Rear Speed Sensor (Drums) - Bendix #BXM	Bendix 801543BXW	\$105.97	58%	\$44.51	BX801538	\$119.60	63%	\$44.25
BENDIX,	MERITOR, WABCO where indicated or approved alternate.								
19	Right side Caliper, steer and drive vertical "A" (22A +23) for ADB22X Air Disc Brake - Bendix - K081256	Bendix	\$2,371.03	59%	\$972.12	as spec	\$2,276.82	46%	\$1,229.48
20	Left side Caliper, steer and drive vertical "B" (22A +23) for ADB22X Air Disc Brake - Bendix - K081257	Bendix	\$2,371.03	59%	\$972.12	as spec	\$2,276.82	46%	\$1,229.48
21	Balance of line item discount for Bendix, Meritor, WABCO or approved alternate.		Perce	entage Disc	count		Perce	entage Dise	count
a.	Bendix			50%			National F	leet	
b.	Meritor		50%				National F	Fleet	
C.	WABCO		50%				National F	Fleet	
d.	Approved alternate: REJECT	Bendix	25%			National Fleet			
e.	Approved alternate: REJECT	Bendix		25%			National F	leet	

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM emanufacturered brake shoes, or new brake shoes.	Та	mpa Spri	ng Compan	у		PH Holdings		
Item #	Item and Description	Mfr & Part #	Cost	GPM % Markup	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
BENDIX	MERITOR, WABCO where indicated or approved alternate.								
12	Dryer - Bendix 107794X - AD9					as spec	\$58.17	64%	\$20.94
13	Park Brake Valve - Bendix 801315					as spec	\$301.03	61%	\$117.40
14	Purge Valve Kit for AD9 - Bendix #BXM					Bendix 5005037	\$67.68	61%	\$26.40
15	Front ABS Sensor (Rotors) - Meritor S4410323810					as spec	\$83.26	61%	\$32.47
16	Rear ABS Sensor (Rotors) - Meritor S4410321840					as spec	\$63.66	61%	\$24.83
17	Front Speed Sensor (Drums) - Bendix 801541					as spec	\$95.82	61%	\$37.37
18	Rear Speed Sensor (Drums) - Bendix #BXM					Bendix 801538	\$102.71	61%	\$40.06
BENDIX	MERITOR, WABCO where indicated or approved alternate.								
19	Right side Caliper, steer and drive vertical "A" (22A +23) for ADB22X Air Disc Brake - Bendix - K081256					as spec	\$2,372.45	60%	\$948.98
20	Left side Caliper, steer and drive vertical "B" (22A +23) for ADB22X Air Disc Brake - Bendix - K081257					as spec	\$2,372.45	60%	\$948.98
21	Balance of line item discount for Bendix, Meritor, WABCO or approved alternate.		Perc	centage Disc	count		Perce	ntage Disco	ount
a.	Bendix							60%	
b.	Meritor							59%	
c.	WABCO								
d.	Approved alternate: REJECT								
e.	Approved alternate: REJECT								

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

\_

	linings will be riveted on Sarasota School District brake shoes, OEM emanufacturered brake shoes, or new brake shoes.	Vehicle M	aintenance Pr	ogram, Inc.	
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price
BENDIX,	MERITOR, WABCO where indicated or approved alternate.				
12	Dryer - Bendix 107794X - AD9				
13	Park Brake Valve - Bendix 801315				
14	Purge Valve Kit for AD9 - Bendix #BXM				
15	Front ABS Sensor (Rotors) - Meritor S4410323810				
16	Rear ABS Sensor (Rotors) - Meritor S4410321840				
17	Front Speed Sensor (Drums) - Bendix 801541				
18	Rear Speed Sensor (Drums) - Bendix #BXM				
BENDIX,	MERITOR, WABCO where indicated or approved alternate.				
19	Right side Caliper, steer and drive vertical "A" (22A +23) for ADB22X Air Disc Brake - Bendix - K081256				
20	Left side Caliper, steer and drive vertical "B" (22A +23) for ADB22X Air Disc Brake - Bendix - K081257				
21	Balance of line item discount for Bendix, Meritor, WABCO or approved alternate.		Perce	entage Disco	unt
21 a.			Perce	entage Disco	unt
	alternate.		Perce	entage Disco	unt
a.	alternate. Bendix		Perce	entage Disco	unt
a. b.	alternate. Bendix Meritor		Perce	entage Disco	unt

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

All brake factory re	linings will be riveted on Sarasota School District brake shoes, OEM emanufacturered brake shoes, or new brake shoes.	FI	leet Acquisit dba Fleet Pi			Fleet Pride			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
GUNITE,	CONMET, WEBB where indicated or approved alternate.								
22	Front Drum - Gunite 3800X or Webb 65548B	ConMet 10009920	\$268.56	71.59%	\$76.30	as spec Webb 65548B	\$533.87	71%	\$154.82
23	Rear Drum - Gunite 3600AX or Webb 66864B	ConMet 10009830	\$269.41	71.59%	\$76.54	as spec Webb 66864B	\$375.25	80%	\$75.05
24	Front & Rear Rotor - ConMet 10020109 or approved alternate	ConMet 10020682	\$327.10	43.18%	\$185.85	as spec	\$619.66	60%	\$247.86
25	Balance of line item discount for Gunite, ConMet, Webb, or approved alternate.		Perc	centage Disc	ount		Percentage Discount		
a.	Gunite			66%					
b.	ConMet			71%			60%		
C.	Webb			67%				76%	
d.	Approved alternate:								
e.	Approved alternate: REJECT								
MONRO	E or approved alternate.								
26	Front C2 Shocks - Monroe 65140	as spec	\$157.02	72.05%	\$43.89	as spec	\$187.30	78%	\$41.21
27	Rear C2 Shocks - Monroe 65490	as spec	\$145.70	72.09%	\$40.66	as spec	\$173.52	78%	\$38.17
28	Balance of line item discount for Monroe or approved alternate.		Perc	centage Disc	ount		Perc	centage Disco	ount
a.	Monroe			68%				78%	
b.	Approved alternate:								
C.	Approved alternate: REJECT								
d.	Approved alternate: REJECT								
e.	Approved alternate: REJECT								

### Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM manufacturered brake shoes, or new brake shoes.		NeoPart	Transit		O'Reilly Automotive Stores, Inc., dba O'Reilly Auto Parts				
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price	
GUNITE,	CONMET, WEBB where indicated or approved alternate.					KIC Holdings Inc				
22	Front Drum - Gunite 3800X or Webb 65548B	Meritor 3219E5803	\$370.52	65%	\$129.68	KIC54214-018	\$350.83	41%	\$138.46	
23	Rear Drum - Gunite 3600AX or Webb 66864B	Meritor 851232070 02	\$260.12	65%	\$91.04	KIC54261-018	\$289.81	41%	\$111.54	
24	Front & Rear Rotor - ConMet 10020109 or approved alternate	Meritor M44DH206 82	\$619.66	65%	\$216.88					
25	Balance of line item discount for Gunite, ConMet, Webb, or approved alternate.		Percentage Discount				Percentage Discount			
a.	Gunite									
b.	ConMet									
C.	Webb									
d.	Approved alternate:	Meritor		65%		KIC Holdings Inc	List le	ess 41% or l	better	
e.	Approved alternate: REJECT									
MONROE	E or approved alternate.									
26	Front C2 Shocks - Monroe 65140	Meritor M85918	\$93.69	65%	\$32.79	as spec	\$157.61	41%	\$75.37	
27	Rear C2 Shocks - Monroe 65490	Meritor M85724	\$112.12	65%	\$39.24	as spec	\$122.02	41%	\$69.82	
28	Balance of line item discount for Monroe or approved alternate.		Perc	entage Dis	count		Perc	entage Disc	count	
a.	Monroe						List le	ess 41% or l	better	
b.	Approved alternate:	Meritor		65%						
C.	Approved alternate: REJECT									
d.	Approved alternate: REJECT									
e.	Approved alternate: REJECT									

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM manufacturered brake shoes, or new brake shoes.	R	ush Truck Ce	enters		Sun State International				
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price	
GUNITE,	CONMET, WEBB where indicated or approved alternate.									
22	Front Drum - Gunite 3800X or Webb 65548B	as spec Gunite 3800X	\$173.54	50%	\$86.77	as spec Gunite ZBR3800X	\$371.28	64.5%	\$131.80	
23	Rear Drum - Gunite 3600AX or Webb 66864B	as spec Gunite 3600AX	\$140.66	50%	\$70.33	as spec Webb WW066864B2 0		40%	\$80.99	
24	Front & Rear Rotor - ConMet 10020109 or approved alternate	New #ConMet CM10020682	\$415.96	40%	\$249.58	Meritor M44DH20682	\$619.66	55%	\$278.85	
25	Balance of line item discount for Gunite, ConMet, Webb, or approved alternate.		Percentage Discount				Perc	entage Disc	count	
a.	Gunite		50%			National Fleet				
b.	ConMet		40%			National Fleet				
C.	Webb		50%			National Fleet				
d.	Approved alternate:	Gunite	40%			National Fleet				
e.	Approved alternate: REJECT	Gunite		40%	National Fleet					
MONRO	or approved alternate.									
26	Front C2 Shocks - Monroe 65140	Monroe	\$94.21	50%	\$47.11	as spec AMS65140	\$141.42	63%	\$52.33	
27	Rear C2 Shocks - Monroe 65490	Monroe	\$87.28	45%	\$48.00	as spec AMS65490	\$129.55	63%	\$47.93	
28	Balance of line item discount for Monroe or approved alternate.		Perce	entage Disc	count		Perc	entage Disc	count	
a.	Monroe		45%			National F	lational Fleet			
b.	Approved alternate:	Gabriel	45%			National F	Fleet			
C.	Approved alternate: REJECT	Gabriel		45%			National F	Fleet		
d.	Approved alternate: REJECT						National F	leet		
e.	Approved alternate: REJECT						National F	leet		

### Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM manufacturered brake shoes, or new brake shoes.	Та	ampa Sprir	ng Company	/	TPH Holdings, LLC dba The Parts House				
Item #	Item and Description	Mfr & Part #	Cost	GPM % Markup	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price	
GUNITE,	CONMET, WEBB where indicated or approved alternate.									
22	Front Drum - Gunite 3800X or Webb 65548B					as spec	\$419.16	69%	\$129.94	
23	Rear Drum - Gunite 3600AX or Webb 66864B					as spec	\$282.94	69%	\$87.71	
24	Front & Rear Rotor - ConMet 10020109 or approved alternate					Meritor M44DH20682	\$619.66	59%	\$254.06	
25	Balance of line item discount for Gunite, ConMet, Webb, or approved alternate.		Perc	centage Disc	ount	Percentage Discount				
a.	Gunite							69%		
b.	ConMet									
C.	Webb							69%		
d.	Approved alternate:					Meritor		59%		
e.	Approved alternate: REJECT									
MONRO	e or approved alternate.									
26	Front C2 Shocks - Monroe 65140	Gabriel 85920	\$78.76	Cost plus 22%	\$35.23	as spec	\$157.02	71%	\$45.54	
27	Rear C2 Shocks - Monroe 65490	Gabriel 85724	\$100.47	Cost plus 22%	\$44.93	as spec	\$145.47	71%	\$42.19	
28	Balance of line item discount for Monroe or approved alternate.		Perc	entage Disc	ount		Perce	ntage Disco	ount	
a.	Monroe					HD shocks = gas-magnum 60 & magnum 70 only at 71%. A other Monroe shocks at 60%				
b.	Approved alternate:	Gabriel	С	ost plus 229	%					
с.	Approved alternate: REJECT									
d.	Approved alternate: REJECT									
e.	Approved alternate: REJECT									

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM emanufacturered brake shoes, or new brake shoes.	Vehicle M	aintenance Pr	ogram, Inc.	
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	Distric Price
GUNITE,	CONMET, WEBB where indicated or approved alternate.				
22	Front Drum - Gunite 3800X or Webb 65548B				
23	Rear Drum - Gunite 3600AX or Webb 66864B				
24	Front & Rear Rotor - ConMet 10020109 or approved alternate				
25	Balance of line item discount for Gunite, ConMet, Webb, or approved alternate.		Perce	entage Disco	unt
a.	Gunite				
b.	ConMet				
с.	Webb				
d.	Approved alternate:				
e.	Approved alternate: REJECT				
MONRO	E or approved alternate.				
26	Front C2 Shocks - Monroe 65140				
27	Rear C2 Shocks - Monroe 65490				
28	Balance of line item discount for Monroe or approved alternate.		Perce	entage Disco	unt
a.	Monroe				
b.	Approved alternate:				
с.	Approved alternate: REJECT				
d.	Approved alternate: REJECT				
e.	Approved alternate: REJECT				

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM manufacturered brake shoes, or new brake shoes.	F	leet Acquisit dba Fleet P				Fleet	Pride	
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
NATIONA alternate.	L, STEMCO or CHICAGO RAWHIDE where indicated or approved								
29	Front Seal - National Seal 370001A	as spec	\$69.50	69.78%	\$21.00	as spec	\$59.68	67%	\$19.69
30	Rear Seal - National 370003A or Chicago Rawhide 47697	as spec National 370003A	\$90.00	70.71%	\$26.36	as spec National 370003A	\$77.29	67%	\$25.51
31	Front Gasket - Chicago Rawhide 453869	as spec	\$3.38	69.23%	\$1.04	Stemco 330- 3024	\$3.55	67%	\$1.17
32	Front Hub, Oiler - Stemco 343-4024	as spec	\$65.45	59.09%	\$26.77	as spec	\$74.40	67%	\$24.55
NATIONA alternate.	L, STEMCO or CHICAGO RAWHIDE where indicated or approved								
33	Front Hub, Oiler - Chicago Rawhide 1612	as spec	\$55.31	69.16%	\$17.06	as spec	\$50.74	65%	\$17.76
34	Front Hub Gasket - Stemco 330-3024	as spec	\$3.13	59.11%	\$1.28	as spec	\$3.55	67%	\$1.17
35	Hub Cap, Oiler - Stemco 359-5990 or Chicago Rawhide 450434	as spec Chicago Rawhide	\$4.68	69.23%	\$1.44	as spec Stemco 359- 5990	\$7.33	67%	\$2.42
36	Hub Gasket, Large, Oiler - Stemco 330-3009	as spec	\$3.08	59.09%	\$1.26	as spec	\$3.50	67%	\$1.16
37	Balance of line item discount for National, Stemco, Chicago Rawhide, or approved alternate.		Perc	centage Disc	ount		Percentage Discount		
a.	National			65%				67%	
b.	Stemco			57%				67%	
c.	Chicago Rawhide			66%				65%	
d.	Approved alternate:								
e.	Approved alternate: REJECT								

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM manufacturered brake shoes, or new brake shoes.		NeoPart	Transit			eilly Automotiv dba O'Reilly A		C.,
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
NATIONA alternate.	L, STEMCO or CHICAGO RAWHIDE where indicated or approved								
29	Front Seal - National Seal 370001A					as spec	\$50.83	41%	\$20.36
30	Rear Seal - National 370003A or Chicago Rawhide 47697					as spec	\$71.17	41%	\$28.50
31	Front Gasket - Chicago Rawhide 453869					National GKT024	\$8.46	41%	\$3.14
32	Front Hub, Oiler - Stemco 343-4024					National 343- 024	\$77.95	41%	\$31.22
NATIONA alternate.	L, STEMCO or CHICAGO RAWHIDE where indicated or approved								
33	Front Hub, Oiler - Chicago Rawhide 1612								
34	Front Hub Gasket - Stemco 330-3024					National GKT024	\$8.46	41%	\$3.14
35	Hub Cap, Oiler - Stemco 359-5990 or Chicago Rawhide 450434					National B299	\$6.76	41%	\$2.30
36	Hub Gasket, Large, Oiler - Stemco 330-3009					National GKT009	\$8.46	41%	\$2.30
37	Balance of line item discount for National, Stemco, Chicago Rawhide, or approved alternate.		Perc	entage Disc	count		Perc	entage Disc	ount
a.	National						List le	ess 41% or I	oetter
b.	Stemco								
C.	Chicago Rawhide								
d.	Approved alternate:								
e.	Approved alternate: REJECT								

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM emanufacturered brake shoes, or new brake shoes.	R	ush Truck Ce	enters		Sun State International				
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price	
NATION/ alternate	AL, STEMCO or CHICAGO RAWHIDE where indicated or approved									
29	Front Seal - National Seal 370001A	National	\$35.96	43%	\$20.50	as spec V370001A	\$52.11	59%	\$21.37	
30	Rear Seal - National 370003A or Chicago Rawhide 47697	National	\$33.25	22%	\$25.94	as spec V370003A	\$68.42	64%	\$24.63	
31	Front Gasket - Chicago Rawhide 453869	Chicago	\$2.38	43%	\$1.36	as spec CR453869-8	\$1.55	31%	\$1.07	
32	Front Hub, Oiler - Stemco 343-4024	Stemco	\$60.32	59%	\$24.73	as spec 343-4024	\$58.38	40%	\$35.03	
NATION/ alternate	AL, STEMCO or CHICAGO RAWHIDE where indicated or approved									
33	Front Hub, Oiler - Chicago Rawhide 1612	Chicago	\$35.93	49%	\$18.32	as spec CR1612B-100	\$21.32	20%	\$17.06	
34	Front Hub Gasket - Stemco 330-3024	Stemco	\$2.89	63%	\$1.07	as spec 330-3024	\$2.46	40%	\$1.48	
35	Hub Cap, Oiler - Stemco 359-5990 or Chicago Rawhide 450434	Stemco	\$2.36	20%	\$1.89	as spec CR4504344	\$3.27	27%	\$2.39	
36	Hub Gasket, Large, Oiler - Stemco 330-3009	Stemco	\$2.83	63%	\$1.05	as spec 330-3009	\$2.36	40%	\$1.42	
37	Balance of line item discount for National, Stemco, Chicago Rawhide, or approved alternate.		Perce	entage Disc	count		Perce	entage Disc	count	
a.	National			40%			National F	Fleet		
b.	Stemco			40%			National F	Fleet		
C.	Chicago Rawhide		40%				National F	Fleet		
d.	Approved alternate:			40%			National F	leet		
e.	Approved alternate: REJECT			40%			National F	Fleet		

### Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM emanufacturered brake shoes, or new brake shoes.	Та	impa Spri	ng Company	/	TPH Holdings, LLC dba The Parts House				
Item #	Item and Description	Mfr & Part #	Cost	GPM % Markup	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price	
NATION/ alternate	AL, STEMCO or CHICAGO RAWHIDE where indicated or approved									
29	Front Seal - National Seal 370001A	Timken 10S35000	\$46.17	Cost plus 22%	\$17.73	Timken 10S35000T	\$52.99	66%	\$18.02	
30	Rear Seal - National 370003A or Chicago Rawhide 47697	Timken 11S47670	\$59.63	Cost plus 22%	\$22.90	Timken 11S47670T	\$66.99	66%	\$22.78	
31	Front Gasket - Chicago Rawhide 453869	Timken 61024R	10.84 4 pack	Cost plus 22%	3.47 4 pack	Stemco 330-3024	\$3.13	55%	\$1.41	
32	Front Hub, Oiler - Stemco 343-4024	Timken 80024	\$40.13	Cost plus 22%	\$15.41	Timken HU024A	\$53.99	66%	\$18.36	
NATION/ alternate	AL, STEMCO or CHICAGO RAWHIDE where indicated or approved									
33	Front Hub, Oiler - Chicago Rawhide 1612	Timken 80024	\$40.13	Cost plus 22%	\$15.41	as spec	\$55.31	64%	\$19.91	
34	Front Hub Gasket - Stemco 330-3024	Timken 61024R	10.84 4 pack	Cost plus 22%	3.47 4 pack	as spec	\$3.13	55%	\$1.41	
35	Hub Cap, Oiler - Stemco 359-5990 or Chicago Rawhide 450434	Timken 64999R	10.52 4 pack	Cost plus 22%	3.37 4 pack	as spec	\$6.45	55%	\$2.90	
36	Hub Gasket, Large, Oiler - Stemco 330-3009	Timken 61009R	10.72 4 pack	Cost plus 22%	3.43 4 pack	Timken 733067	\$2.99	66%	\$1.02	
37	Balance of line item discount for National, Stemco, Chicago Rawhide, or approved alternate.		Per	centage Disc	ount		Perce	ntage Disco	ount	
a.	National							67%		
b.	Stemco							55%		
C.	Chicago Rawhide							64%		
d.	Approved alternate:	Timken	C	Cost plus 22º	%	Timken		66%		
e.	Approved alternate: REJECT									

# Tabulation for Bus Brake Repair Parts - Bid #18-0155

\_

	linings will be riveted on Sarasota School District brake shoes, OEM emanufacturered brake shoes, or new brake shoes.	Vehicle Mai	intenance Pr	ogram, Inc.	
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price
NATION/ alternate	AL, STEMCO or CHICAGO RAWHIDE where indicated or approved				
29	Front Seal - National Seal 370001A	Chicago Rawhide SKF35066	\$80.21	80.4%	\$15.72
30	Rear Seal - National 370003A or Chicago Rawhide 47697	Chicago Rawhide SKF47697	\$102.28	77.5%	\$23.01
31	Front Gasket - Chicago Rawhide 453869	Chicago Rawhide SKF453869	\$3.38	71.3%	\$0.97
32	Front Hub, Oiler - Stemco 343-4024	Chicago Rawhide SKF1612	\$55.31	81.8%	\$10.07
NATION/ alternate	AL, STEMCO or CHICAGO RAWHIDE where indicated or approved				
33	Front Hub, Oiler - Chicago Rawhide 1612	Chicago Rawhide SKF1612	\$55.31	81.8%	\$10.07
34	Front Hub Gasket - Stemco 330-3024	National GKT024	\$1.68	41.1%	\$0.99
35	Hub Cap, Oiler - Stemco 359-5990 or Chicago Rawhide 450434	Chicago Rawhide SKF450434	\$4.68	72.6%	\$1.28
36	Hub Gasket, Large, Oiler - Stemco 330-3009	National GKT009	\$1.68	41.1%	\$0.99
37	Balance of line item discount for National, Stemco, Chicago Rawhide, or approved alternate.		Perce	entage Disco	unt
a.	National		#44	0-SB (9-14-1 40%	5)
b.	Stemco				
C.	Chicago Rawhide		Chicago Rawhide SKF (July 2017 List) #457312 / #457303 68.9%		
d.	Approved alternate:				
e.	Approved alternate: REJECT				

### Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM emanufacturered brake shoes, or new brake shoes.	FI	leet Acquisit dba Fleet Pi			Fleet Pride				
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price	
TIMKEN	or approved alternate.									
38	Bearings - Timken 572	as spec	\$68.90	82.45%	\$12.09	as spec	\$38.14	68%	\$12.20	
39	Bearings - Timken 580	as spec	\$110.55	82.37%	\$19.49	as spec	\$48.18	70%	\$14.45	
40	Bearings - Timken 592-A	as spec	\$84.14	82.18%	\$14.99	as spec	\$34.61	69%	\$10.73	
41	Bearings - Timken 594-A	as spec	\$128.93	82.50%	\$22.56	as spec	\$53.86	69%	\$16.70	
42	Balance of line item discount for Timken or approved alternate.		Perc	centage Disc	ount		Perc	centage Disco	ount	
a.	Timken			75%				69%		
b.	Approved alternate:									
C.	Approved alternate: REJECT									
d.	Approved alternate: REJECT									
CONMET	r or approved alternate									
43	Rotor Bearings Rear, Outer Cone - ConMet 103600	Timken NP 840302	\$164.74	69.86%	\$49.64	Timken Set	\$146.67	68%	\$46.93	
44	Rotor Bearings Rear, Outer Cup - ConMet 103601	Timken NP 053874	\$112.19	69.86%	\$33.81	430	φ140.07	0078	φ <del>-</del> 0.55	
45	Rotor Bearings Rear, Inner Cone - ConMet 103598	Timken NP 034946	\$211.51	69.86%	\$63.75	Timken Set	\$190.65	64%	\$68.63	
46	Rotor Bearings Rear, Inner Cup - ConMet 103599	Timken NP 363298	\$126.13	80.98%	\$23.99	429	\$190.05	04 /0	<b>400.03</b>	
47	Rotor Bearings Front, Outer Cone - ConMet 103594	Timken NP 874005	\$101.35	69.86%	\$30.54	Timken Set	\$89.53	68%	\$28.65	
48	Rotor Bearings Front, Outer Cup - ConMet 103595	Timken NP 435398	\$53.02	69.86%	\$15.98	428	<b>409.00</b>	00 /0	<b>\$20.0</b> 5	
49	Rotor Bearings Front, Inner Cone - ConMet 103596	Timken NP 899357	\$140.37	69.86%	\$42.30	Timken Set	\$126.99	68%	\$40.64	
50	Rotor Bearings Front, Inner Cup - ConMet 103597	Timken NP 026773	\$86.94	69.86%	\$26.20	427	<b>⊅</b> 1 <b>⊼0</b> .99	00%	<b>ቅ40.64</b>	
51	Balance of line item discount for ConMet or approved alternate.		Percentage Discount				Perc	centage Disco	ount	
a.	ConMet									
b.	Approved alternate:	Timken		60%		Timken		68%		
C.	Approved alternate: REJECT									
	Notes:	k	*Extension co	orrections		*Extensi	on correction	is & brands ir	luded	

### Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM manufacturered brake shoes, or new brake shoes.		NeoPart	Transit		O'Reilly Automotive Stores, Inc., dba O'Reilly Auto Parts				
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price	
IMKEN	or approved alternate.					BCA-Federal Mogul				
38	Bearings - Timken 572	Meritor MER572	\$20.30			BCA HD211	\$89.81	41%	\$42.39	
39	Bearings - Timken 580	Meritor MER580	\$41.55			1BCA 580	\$42.36	41%	\$19.99	
40	Bearings - Timken 592-A	Meritor MER592A	\$20.96			BCA HD203	\$96.59	41%	\$45.59	
41	Bearings - Timken 594-A	Meritor MER594A	\$42.65			BCA 594A	\$62.69	41%	\$29.59	
42	Balance of line item discount for Timken or approved alternate.		Percentage Discount				Percentage Discount			
a. b.	Timken Approved alternate:	Meritor	65%			BCA-Federal Mogul	List less 41% or better			
C.	Approved alternate: REJECT									
d.	Approved alternate: REJECT									
ONMET	or approved alternate									
43	Rotor Bearings Rear, Outer Cone - ConMet 103600									
44	Rotor Bearings Rear, Outer Cup - ConMet 103601									
45	Rotor Bearings Rear, Inner Cone - ConMet 103598									
46	Rotor Bearings Rear, Inner Cup - ConMet 103599									
47	Rotor Bearings Front, Outer Cone - ConMet 103594									
48	Rotor Bearings Front, Outer Cup - ConMet 103595									
49	Rotor Bearings Front, Inner Cone - ConMet 103596									
50	Rotor Bearings Front, Inner Cup - ConMet 103597						_			
51	Balance of line item discount for ConMet or approved alternate.		Perc	entage Disc	count		Perc	entage Disc	ount	
a. b.	ConMet Approved alternate:									
D. C.	Approved alternate: REJECT									
0.	Notes:		*Extension of				ated 41% = lis	at loop 440/	or b c ++	

### Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM manufacturered brake shoes, or new brake shoes.	R	ush Truck Ce	enters		Sun State International				
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price	
TIMKEN	or approved alternate.									
38	Bearings - Timken 572	Timken	\$20.12	44%	\$11.27	as spec TM 572	\$22.43	39%	\$13.68	
39	Bearings - Timken 580	Timken	\$32.42	44%	\$18.16	as spec TM 580	\$36.19	39%	\$22.08	
40	Bearings - Timken 592-A	Timken	\$20.96	44%	\$11.74	as spec TM 592A	\$27.83	39%	\$16.98	
41	Bearings - Timken 594-A	Timken	\$37.52	44%	\$21.01	as spec TM 594A	\$41.83	39%	\$25.52	
42	Balance of line item discount for Timken or approved alternate.		Perce	entage Disc	count		Perc	entage Dise	count	
a.	Timken			44%			National F	Fleet		
b.	Approved alternate:	National	40%				National I	Fleet		
C.	Approved alternate: REJECT	Stemco		40%		National Fleet				
d.	Approved alternate: REJECT					National Fleet				
CONMET	or approved alternate									
43	Rotor Bearings Rear, Outer Cone - ConMet 103600	ConMet	\$33.96	32%	\$23.09	Hyatt Bearing HYT580PS	\$49.78	25%	\$37.34	
44	Rotor Bearings Rear, Outer Cup - ConMet 103601	ConMet	\$39.64	34%	\$26.16	Hyatt Bearing HYT572	\$20.24	25%	\$15.18	
45	Rotor Bearings Rear, Inner Cone - ConMet 103598	ConMet	\$38.19	32%	\$25.97	Hyatt Bearing HYT594A	\$32.52	25%	\$24.39	
46	Rotor Bearings Rear, Inner Cup - ConMet 103599	ConMet	\$40.72	32%	\$27.69	Hyatt Bearing HYT592A	\$21.69	31%	\$14.97	
47	Rotor Bearings Front, Outer Cone - ConMet 103594	np874005	\$43.75	48%	\$22.75	Hyatt Bearing HYT3782	\$17.50	32%	\$11.90	
48	Rotor Bearings Front, Outer Cup - ConMet 103595	np435398	\$22.88	28%	\$16.47	Hyatt Bearing HYT3720	\$9.90	25%	\$7.43	
49	Rotor Bearings Front, Inner Cone - ConMet 103596	np899357trb	\$60.59	32%	\$41.20	Hyatt Bearing HYTHM212049	\$26.37	25%	\$19.78	
50	Rotor Bearings Front, Inner Cup - ConMet 103597	np026773	\$37.53	33%	\$25.15	Hyatt Bearing HYTHM212011	\$14.15	25%	\$10.61	
51	Balance of line item discount for ConMet or approved alternate.		Perce	entage Disc	count			entage Disc	count	
a.	ConMet		32%				National F			
b.	Approved alternate:	Timken		32%		National Fleet				
C.	Approved alternate: REJECT	Stemco	corrected &	32%		National Fleet				

### Tabulation for Bus Brake Repair Parts - Bid #18-0155

	linings will be riveted on Sarasota School District brake shoes, OEM emanufacturered brake shoes, or new brake shoes.	Та	impa Spri	ng Company	/	TPH Holdings, LLC dba The Parts House					
Item #	Item and Description	Mfr & Part #	Cost	GPM % Markup	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price		
TIMKEN	or approved alternate.										
38	Bearings - Timken 572	as spec	\$35.47	Cost plus 22%	\$13.62	as spec	\$43.99	73%	\$11.88		
39	Bearings - Timken 580	as spec	\$57.17	Cost plus 22%	\$21.95	as spec	\$68.99	73%	\$18.63		
40	Bearings - Timken 592-A	as spec	\$43.97	Cost plus 22%	\$16.88	as spec	\$51.99	73%	\$14.04		
41	Bearings - Timken 594-A	as spec	\$66.20	Cost plus 22%	\$25.42	as spec	\$77.99	73%	\$21.06		
42	Balance of line item discount for Timken or approved alternate.		Per	centage Disc	ount		Perce	ntage Disco	ount		
a.	Timken		C	Cost plus 22	%			66%			
b.	Approved alternate:										
C.	Approved alternate: REJECT										
d.	Approved alternate: REJECT										
CONMET	Γ or approved alternate										
43	Rotor Bearings Rear, Outer Cone - ConMet 103600					Timken NP840302	\$98.99	66%	\$33.66		
44	Rotor Bearings Rear, Outer Cup - ConMet 103601					Timken NP053874	\$67.99	66%	\$23.12		
45	Rotor Bearings Rear, Inner Cone - ConMet 103598					Timken NP034946	\$123.99	66%	\$42.16		
46	Rotor Bearings Rear, Inner Cup - ConMet 103599					Timken NP363298	\$76.99	66%	\$26.18		
47	Rotor Bearings Front, Outer Cone - ConMet 103594					Timken NP874005	\$62.99	66%	\$21.42		
48	Rotor Bearings Front, Outer Cup - ConMet 103595					Timken NP435398	\$33.99	66%	\$11.56		
49	Rotor Bearings Front, Inner Cone - ConMet 103596					Timken NP899357	\$83.99	66%	\$28.56		
50	Rotor Bearings Front, Inner Cup - ConMet 103597					Timken NP026773	\$53.99	66%	\$18.36		
51	Balance of line item discount for ConMet or approved alternate.		Per	centage Disc	ount		Perce	ntage Disco	ount		
a.	ConMet					<b></b>		000/			
b.	Approved alternate:					Timken		66%			
С.	Approved alternate: REJECT										

### Tabulation for Bus Brake Repair Parts - Bid #18-0155

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufacturered brake shoes, or new brake shoes.		Vehicle Maintenance Program, Inc.			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	Distric Price
TIMKEN	or approved alternate.			•	
38	Bearings - Timken 572				
39	Bearings - Timken 580				
40	Bearings - Timken 592-A				
41	Bearings - Timken 594-A				
42	Balance of line item discount for Timken or approved alternate.         Percentage Disc		unt		
a.	Timken				
b.	Approved alternate:				
c.	Approved alternate: REJECT				
d.	Approved alternate: REJECT				
CONMET	Γ or approved alternate				
43	Rotor Bearings Rear, Outer Cone - ConMet 103600				
44	Rotor Bearings Rear, Outer Cup - ConMet 103601				
45	Rotor Bearings Rear, Inner Cone - ConMet 103598				
46	Rotor Bearings Rear, Inner Cup - ConMet 103599				
47	Rotor Bearings Front, Outer Cone - ConMet 103594				
48	Rotor Bearings Front, Outer Cup - ConMet 103595				
49	Rotor Bearings Front, Inner Cone - ConMet 103596				
50	Rotor Bearings Front, Inner Cup - ConMet 103597				
51	Balance of line item discount for ConMet or approved alternate.		Perc	entage Disco	unt
a.	ConMet				
b.	Approved alternate:				
с.	Approved alternate: REJECT				
	Notes:	*Extensions corrections			

Tabulation for Bus Brake Repair Parts - Bid #18-0155

Company	Fleet Acquisitions, LLC dba Fleet Products	Fleet Pride	NeoPart Transit	
Contact	John Stace Williams	Amanda DeLaney	Mitch Smucker	
Address	6510 Golden Groves Lane Tampa, FL 33610	2141 Whitfield Park Loop Sarasota, FL 34243	5 Dutch Court Reading, PA 19608	
Phone	813-621-1734	941-758-8282	888-332-2606 x115	
Fax	813-626-2010	941-752-3652	610-518-7551	
Federal I.D.	62-1868964	63-0681070	36-4830017	
Email	swilliams@fleetproductsfl.com	amanda.delaney@fleetpride.com	msmucker@neoparttransit.com	
Company	O'Reilly Automotive Stores, Inc., dba O'Reilly Auto Parts	Rush Truck Centers	Sun State International	
Contact	Vanessa Creech	David Rye	Debbie Hall	
Address	233 South Patterson Springfield, MO 65802	8111 Adamo Drive Tampa, FL 33619	8247 15th Street East Sarasota, FL 34243	
Phone	417-829-5879	800-757-7383	813-335-6265 or 941-355-7681	
Fax	800-925-0899	813-559-2399	941-351-9108	
Federal I.D.	44-0618012	06-1672108	59-3750718	
Email	probids@oreillyauto.com	ryed@rushenterprises.com	debbie.hall@sunstateintl.com	
Company	Tampa Spring Company	TPH Holdings, LLC dba The Parts House	Vehicle Maintenance Program, Inc	
Contact	John Messina, Jr.	Richard Kilpatrick	Lindi Brooks	
Address	4653 19th Street Court East Bradenton, FL 34203	2704 63rd Avenue East Bradenton, FL 34203	3595 North Dixie Highway, Bay #7 Boca Raton, FL 33431	
Phone	941-727-1400	941-238-6799	561-362-6080	
Fax	941-727-1406	941-746-4023	561-362-7994	
Federal I.D.	59-1198637	85-4550535	52-1574660	
Email	jmessina@tampaspringco.com	rkilpatrick@thepartshouse.com	lindi@vmpparts.com	
	Recorded by: JoAnn Joyce	Witnessed by: Joy	rce Haney	

#### THE SCHOOL BOARD OF SARASOTA COUNTY JUSTIFICATION

Item #	Bidder	Reason For Not Awarding To Other Than Low Bidder	
5	Rush Truck Centers	Award as overall low for category to Fleet Acquisitions, LLC dba Fleet Products.	
	Sun State International		
6	NeoPart Transit	Unable to evaluate product bid, award to TPH Holdings, LLC dba The Parts House.	
8 & 9	Reject Item	Unclear specifications. Reject item.	
11 a-e	Rush Truck Centers	Vendor was not awarded any items in category or balance of line.	
11 d	O'Reilly Automotive Stores, Inc., dba O'Reilly Auto Parts	Vendor non-responsive. Vendor changed pricing terms from 36 months to 12 months. District will not use Brake Best HD brand.	
11 d & e	Reject Item		
21 a-e	Rush Truck Centers	Vendor was not awarded any items in category or balance of line.	
21 d	O'Reilly Automotive Stores, Inc., dba O'Reilly Auto Parts	Vendor non-responsive. Vendor changed pricing terms from 36 months to 12 months. District will not use Brake Best HD brand.	
21 d & e	Reject Item		
23	Rush Truck Centers	Award as overall low as group to Fleet Acquisitions, LLC dba Fleet Products.	
25 a-c	Rush Truck Centers	Vendor was not awarded any items in category or balance of line.	
25 d	O'Reilly Automotive Stores, Inc., dba O'Reilly Auto Parts	Vendor non-responsive. Vendor changed pricing terms from 36 months to 12 months. District will not use KIC brand.	
25 e	Reject Item		
27	Fleet Pride	Award as overall low as group to NeoPart Transit for the category of shock aborbers.	
28 a-c	Rush Truck Centers	Vendor was not awarded any items in category or balance of line.	
28 c, d & e	Reject Item		
	Tampa Spring Company		
29 & 30	TPH Holdings, LLC dba The Parts House	Award as overall low as group to Fleet Pride for as specific brand 'National Seal' as the Transportation	
20 0 00	Sun State International	Department uses the National Seal driver to install these seals.	
	Vehicle Maintenance Program, Inc.		
33	Vehicle Maintenance Program, Inc.	Award as overall low as group to Tampa Spring Company for category of gaskets.	
37 а-е	Rush Truck Centers	Vendor was not awarded any items in category or balance of line.	
37 e	Reject Item		
	Fleet Acquisitions, LLC dba Fleet Products	Award overall low as group to Fleet Pride for category of bearing sets.	
38	Rush Truck Centers		
	TPH Holdings, LLC dba The Parts House		
42 a-c	Rush Truck Centers	Vendor was not awarded any items in category or balance of line.	
42 c & d	Reject Item		
42 b	O'Reilly Automotive Stores, Inc., dba O'Reilly Auto Parts	Vendor non-responsive. Vendor changed pricing terms from 36 months to 12 months. District will not use BCA brand.	

# Bus Brake Repair Parts - Bid #18-0155

#### THE SCHOOL BOARD OF SARASOTA COUNTY JUSTIFICATION

44-50	Sun State International	Unable to evaluate product bid, award overall low as group to Fleet Pride.	
45 & 46	Rush Truck Centers		
	TPH Holdings, LLC	Award overall low as group to Fleet Pride for category of rotor bearing sets.	
	dba The Parts House		
51 a-c	Rush Truck Centers	Vendor was not awarded any items in category or balance of line.	
51 c	Reject Item		