



THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA
MATERIALS MANAGEMENT DEPARTMENT
101 OLD VENICE ROAD • OSPREY, FLORIDA 34229
TELEPHONE (941) 486-2183 • FAX (941) 486-2188

MEMORANDUM

TO: Members of the School Board
Lori White, Superintendent
Mitsi Corcoran, Chief Financial Officer

FROM: Pat Black, CPPB, Director of Materials Management

TITLE: APPROVAL TO AWARD BID #15-0155 FOR BUS BRAKE REPAIR PARTS

Bids to provide 'Bus Brake Repair Parts' were received from nine vendors on September 25, 2014. The bids of Fleet Acquisitions, LLC, Fleet Pride, Rush Truck Centers of Florida dba Rush Truck Center of Tampa, Sun State International, and The Parts House were the best low bids meeting the advertised specifications. Reasons for not selecting the apparent low bid are included with the bid tabulation. This bid is for a period of one year with the option to renew for two additional one-year periods. The funds for these purchases are contained in the operating budget allocated to the Transportation Department.

Requested by:
Pat Black

"Failure to file a protest within the time prescribed in Section 120.57(3), Florida Statutes, or failure to post the protest bond or other security required by law within the time allowed for filing a bond shall constitute a waiver of proceedings under Chapter 120, Florida Statutes."

Posting Date: 10/14/2014

Fiscal Impact:

Not to exceed
\$115,000.00

Recommended Motion: That the bids of Fleet Acquisitions, LLC, Fleet Pride, Rush Truck Centers of Florida dba Rush Truck Center of Tampa, Sun State International, and The Parts House, to provide 'Bus Brake Repair Parts' in an amount not to exceed \$115,000.00, be approved as presented.

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		Fleet Acquisitions, LLC				Fleet Pride			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
MERITOR, MERITOR 312, BENDIX where indicated or approved alternate.									
1	New Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124702QP	As spec	\$156.15	65%	\$54.65	As spec	\$156.15	65%	\$54.65
2	New Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124707QP	As spec	\$218.07	65%	\$76.32	As spec	\$218.07	60%	\$87.23
3	Remanufactured Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124702QP	As spec	\$142.04	65%	\$49.71	As spec	\$142.04	60%	\$56.82
4	Remanufactured Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124707QP	As spec	\$151.06	67%	\$49.85	As spec	\$151.06	60%	\$60.42
5	Front & Rear Brake Pads (Disc Brakes) - Bendix 802078	Bendix K070796	\$417.71	59%	\$171.26	New # K070796	\$417.71	50%	\$208.86
6	Rear Slack Adjuster - Meritor R801073	As spec	\$195.52	60%	\$78.21	As spec	\$195.52	61%	\$76.25
7	Tapered Roller Hardware Kit - Meritor 8847HDA KIT	As spec - Kit 8847HDA	\$77.20	60%	\$30.88	As spec	\$77.20	56%	\$33.97
8	Tapered Roller Only - Meritor 8847HD	As spec Kit 8847HD	\$31.03	60%	\$12.41	As spec	\$77.20	56%	\$33.97
9	Slack Adjuster Replacement Pawl for front and rear slack adjustment assemblies - AY PAWL ASA. Meritor R801700	As spec	\$24.77	60%	\$9.91	As spec	\$24.77	50%	\$12.39
10	Balance of line item discount for all Meritor, Meritor 312, Bendix brake pads or approved alternate.	Bendix Meritor Meritor 312		58% 58% 64%				55%	
BENDIX, WABCO where indicated or approved alternate.									
11	Dryer - Bendix 107794X - AD9	As spec	\$56.59	64%	\$20.37	As spec	\$51.45	50%	\$25.73
12	Governor - Bendix D2 - OR 275491	OR 275491X	\$30.39	59%	\$12.46	As spec	\$29.78	50%	\$14.89
13	Park Brake Valve - Bendix 800142	As spec	\$202.76	59%	\$83.13	As spec	\$202.76	50%	\$101.38
14	Park Brake Valve - Bendix 801315	As spec	\$283.63	59%	\$116.29	As spec	\$283.63	45%	\$156.00

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		Gary Yeomans Ford				Suncoast Auto Parts dba Napa			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
MERITOR, MERITOR 312, BENDIX where indicated or approved alternate.									
1	New Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124702QP				\$58.87				
2	New Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124707QP				\$87.03				
3	Remanufactured Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124702QP				\$55.04				
4	Remanufactured Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124707QP				\$56.75				
5	Front & Rear Brake Pads (Disc Brakes) - Bendix 802078				\$191.71	As spec	\$274.00		\$210.45
6	Rear Slack Adjuster - Meritor R801073				\$61.40	As spec	\$136.69		\$88.52
7	Tapered Roller Hardware Kit - Meritor 8847HDA KIT				\$27.97				
8	Tapered Roller Only - Meritor 8847HD				\$14.34				
9	Slack Adjuster Replacement Pawl for front and rear slack adjustment assemblies - AY PAWL ASA. Meritor R801700				\$10.56				
10	Balance of line item discount for all Meritor, Meritor 312, Bendix brake pads or approved alternate.				\$563.67				
BENDIX, WABCO where indicated or approved alternate.									
11	Dryer - Bendix 107794X - AD9				\$20.54				
12	Governor - Bendix D2 - OR 275491				\$31.68	As spec	\$19.49		\$14.55
13	Park Brake Valve - Bendix 800142				\$104.47	As spec	\$144.00		\$102.14
14	Park Brake Valve - Bendix 801315				\$146.12	As spec	\$194.00		\$142.90

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		Rush Truck Centers of Florida dba Rush Truck Center, Tampa				Sun State International			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
MERITOR, MERITOR 312, BENDIX where indicated or approved alternate.									
1	New Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124702QP	Meritor	\$156.15	66%	\$53.09	As spec	\$71.86	30%	\$50.30
2	New Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124707QP	Meritor	\$218.07	66%	\$74.14	As spec	\$94.49	25%	\$70.87
3	Remanufactured Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124702QP	Meritor	\$142.04	65%	\$49.71	As spec	\$63.32	30%	\$44.32
4	Remanufactured Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124707QP	Meritor	\$151.06	68%	\$48.34	As spec	\$60.63	25%	\$45.47
5	Front & Rear Brake Pads (Disc Brakes) - Bendix 802078	Meritor K070796BXW	\$417.71	57%	\$179.62	BXK070796	\$266.69	30%	\$186.68
6	Rear Slack Adjuster - Meritor R801073	Meritor	\$195.52	65%	\$68.43	As spec	\$86.17	30%	\$60.32
7	Tapered Roller Hardware Kit - Meritor 8847HDA KIT	Meritor	\$77.19	60%	\$30.88	As spec	\$34.25	20%	\$27.40
8	Tapered Roller Only - Meritor 8847HD	Meritor	\$31.03	60%	\$12.41	As spec	\$17.61	20%	\$14.09
9	Slack Adjuster Replacement Pawl for front and rear slack adjustment assemblies - AY PAWL ASA. Meritor R801700	Meritor	\$24.78	61%	\$9.66	As spec	\$14.16	25%	\$10.62
10	Balance of line item discount for all Meritor, Meritor 312, Bendix brake pads or approved alternate.	Meritor		63%		Meritor		20%	
BENDIX, WABCO where indicated or approved alternate.									
11	Dryer - Bendix 107794X - AD9	Bendix	\$56.59	61%	\$22.07	As spec	\$28.00	25%	\$21.00
12	Governor - Bendix D2 - OR 275491	Bendix	\$30.39	61%	\$11.85	As spec	\$18.88	30%	\$13.22
13	Park Brake Valve - Bendix 800142	Bendix-#BXM	\$202.76	61%	\$79.08	As spec	\$138.87	30%	\$97.21
14	Park Brake Valve - Bendix 801315	Bendix-#BXM	\$283.63	61%	\$110.62	As spec	\$197.54	30%	\$138.28

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		Tampa Spring Co.				Tampa Truck Center, LLC			
Item #	Item and Description	Mfr & Part #	Cost	GPM % Markup	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
MERITOR, MERITOR 312, BENDIX where indicated or approved alternate.									
1	New Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124702QP	Stemco 187-2102	\$47.23	20%	\$56.68				
2	New Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124707QP	Stemco187-3017	\$54.79	20%	\$65.75				
3	Remanufactured Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124702QP	Meritor/Frasle K523-4702	\$28.00	20%	\$33.60	As spec	\$66.03	20%	\$52.82
4	Remanufactured Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124707QP	Meritor/Frasle K523-4707	\$28.50	20%	\$34.20	As spec	\$69.65	20%	\$55.72
5	Front & Rear Brake Pads (Disc Brakes) - Bendix 802078	Dayton parts D1369-CB	\$188.00	20%	\$225.60	K070796	\$279.92	33%	\$187.55
6	Rear Slack Adjuster - Meritor R801073	Automann 139.2831	\$34.41	20%	\$41.29		\$99.30	33%	\$66.53
7	Tapered Roller Hardware Kit - Meritor 8847HDA KIT	Dayton Parts 08-108847	\$7.03	20%	\$8.44				
8	Tapered Roller Only - Meritor 8847HD	Dayton Parts 01-234	\$1.78	20%	\$2.14	As spec	\$16.71	20%	\$13.37
9	Slack Adjuster Replacement Pawl for front and rear slack adjustment assemblies - AY PAWL ASA. Meritor R801700	Automann 139.1700	\$7.38	20%	\$8.86	As spec	\$14.34	20%	\$11.47
10	Balance of line item discount for all Meritor, Meritor 312, Bendix brake pads or approved alternate.	Stemco Meritor/Frasle Dayton Parts Automann		Cost + 20% (GPM)				28%	
BENDIX, WABCO where indicated or approved alternate.									
11	Dryer - Bendix 107794X - AD9	Automann 170.107796	\$21.50	20%	\$25.80	As spec	\$33.52	25%	\$25.14
12	Governor - Bendix D2 - OR 275491	Automann 170.275491	\$7.75	20%	\$9.30		\$16.21	20%	\$12.97
13	Park Brake Valve - Bendix 800142	As spec	\$97.00	20%	\$116.40		\$113.92	20%	\$91.14
14	Park Brake Valve - Bendix 801315	As spec	\$135.00	20%	\$162.00		\$159.35	20%	\$127.48

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		The Parts House			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price
MERITOR, MERITOR 312, BENDIX where indicated or approved alternate.					
1	New Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124702QP	As spec	\$156.15	62%	\$59.34
2	New Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor KSMA3124707QP	As spec	\$218.07	62%	\$82.87
3	Remanufactured Front Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124702QP	As spec	\$142.04	62%	\$53.98
4	Remanufactured Rear Shoe Kit, includes 2 shoes and hardware Kit - Meritor XK3124707QP	As spec	\$151.06	62%	\$57.40
5	Front & Rear Brake Pads (Disc Brakes) - Bendix 802078	As spec	\$417.71	56%	\$183.79
6	Rear Slack Adjuster - Meritor R801073	As spec	\$195.52	56%	\$86.03
7	Tapered Roller Hardware Kit - Meritor 8847HDA KIT	As spec	\$77.20	56%	\$33.97
8	Tapered Roller Only - Meritor 8847HD	As spec	\$31.03	56%	\$13.65
9	Slack Adjuster Replacement Pawl for front and rear slack adjustment assemblies - AY PAWL ASA. Meritor R801700	As spec	\$24.77	56%	\$10.90
10	Balance of line item discount for all Meritor, Meritor 312, Bendix brake pads or approved alternate.	Meritor Meritor 312 Bendix		56%	
BENDIX, WABCO where indicated or approved alternate.					
11	Dryer - Bendix 107794X - AD9	As spec	\$56.59	56%	\$24.90
12	Governor - Bendix D2 - OR 275491	As spec	\$30.39	56%	\$13.37
13	Park Brake Valve - Bendix 800142	As spec	\$202.76	56%	\$89.21
14	Park Brake Valve - Bendix 801315	As spec	\$283.63	56%	\$124.80

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		Fleet Acquisitions, LLC				Fleet Pride			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
BENDIX, WABCO where indicated or approved alternate. (continued)									
15	Purge Valve Kit for AD9 - Bendix 5005037	As spec	\$63.47	59%	\$26.02	As spec	\$63.47	50%	\$31.74
16	Front ABS Sensor (Rotors) - WABCO WAB441-032-381-0	Meritor S4410323810	\$80.91	60%	\$32.36	As spec	\$57.12	50%	\$28.56
17	Rear ABS Sensor (Rotors) - WABCO WAB441-032-184-0	Meritor S4410321840	\$63.11	60%	\$25.24	As spec	\$63.11	50%	\$31.56
18	Front Speed Sensor (Drums) - Bendix 801541	As spec	\$92.55	59%	\$37.95	As spec	\$92.55	45%	\$50.90
19	Rear Speed Sensor (Drums) - Bendix 801538	As spec	\$101.11	59%	\$41.46	As spec	\$101.21	50%	\$50.61
20	Balance of line item discount for Bendix, WABCO or approved alternate.	Bendix Meritor/Wabco		58%				50%	
GUNITE, CONMET, WEBB where indicated or approved alternate.									
21	Front Drum - Gunite 3800X or Webb 65548B	As spec - Gunite 3800X	\$429.16	68%	\$137.33	As spec - Webb 65548B	\$462.33	65%	\$161.82
22	Rear Drum - Gunite 3600AX or Webb 66864B	As spec - Gunite 3600AX	\$320.83	68%	\$102.67	As spec - Webb 66864B	\$324.90	60%	\$129.96
23	Front & Rear Rotor - ConMet 10020109 or approved alternate meeting specifications listed on Addendum #1. REJECT	ConMet 10020682	\$416.33	42.5%	\$239.39				
24	Balance of line item discount for Gunite, ConMet, Webb, or approved alternate.	ConMet Gunite Webb		42.5% 67% 67%				55%	
MONROE or approved alternate.									
25	Front Shocks - Monroe 65482	As spec	\$166.03	70%	\$49.81	As spec	\$198.05	70%	\$59.42
26	Front C2 Shocks - Monroe 65140	As spec	\$143.64	70%	\$43.09	As spec	\$171.35	70%	\$51.41
27	Rear Shocks - Monroe 65409	As spec	\$149.60	70%	\$44.88	As spec	\$178.31	70%	\$53.49
28	Rear Shocks - Monroe 65401	As spec	\$147.64	70%	\$44.29	As spec	\$176.10	70%	\$52.83
29	Rear C2 Shocks - Monroe 65490	As spec	\$137.07	70%	\$41.12	As spec	\$163.50	70%	\$49.05

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		Gary Yeomans Ford				Suncoast Auto Parts dba Napa			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
BENDIX, WABCO where indicated or approved alternate. (continued)									
15	Purge Valve Kit for AD9 - Bendix 5005037				\$29.03	As spec	\$39.99		\$29.79
16	Front ABS Sensor (Rotors) - WABCO WAB441-032-381-0				\$32.31				
17	Rear ABS Sensor (Rotors) - WABCO WAB441-032-184-0				\$25.27				
18	Front Speed Sensor (Drums) - Bendix 801541				\$43.32	As spec	\$59.99		\$46.64
19	Rear Speed Sensor (Drums) - Bendix 801538				\$51.63	As spec	\$65.99		\$50.98
20	Balance of line item discount for Bendix, WABCO or approved alternate.				\$484.37				
GUNITE, CONMET, WEBB where indicated or approved alternate.									
21	Front Drum - Gunite 3800X or Webb 65548B				\$165.87		\$244.00		\$168.29
22	Rear Drum - Gunite 3600AX or Webb 66864B				\$228.76		149.44		\$119.07
23	Front & Rear Rotor - ConMet 10020109 or approved alternate meeting specifications listed on Addendum #1. REJECT								
24	Balance of line item discount for Gunite, ConMet, Webb, or approved alternate.				\$394.63				
MONROE or approved alternate.									
25	Front Shocks - Monroe 65482				\$55.04	As spec	\$90.69		\$49.75
26	Front C2 Shocks - Monroe 65140				\$47.62	As spec	\$78.39		\$43.04
27	Rear Shocks - Monroe 65409				\$47.56	As spec	\$81.69		\$44.78
28	Rear Shocks - Monroe 65401				\$48.94	As spec	\$80.69		\$44.23
29	Rear C2 Shocks - Monroe 65490				\$43.63	As spec	\$74.69		\$41.06

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		Rush Truck Centers of Florida dba Rush Truck Center, Tampa				Sun State International			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
BENDIX, WABCO where indicated or approved alternate. (continued)									
15	Purge Valve Kit for AD9 - Bendix 5005037	Bendix-#BXM	\$63.47	61%	\$24.75	As spec	\$36.90	30%	\$25.83
16	Front ABS Sensor (Rotors) - WABCO WAB441-032-381-0	Wabco-S#	\$202.76	58%	\$85.16	As spec	\$38.89	20%	\$31.11
17	Rear ABS Sensor (Rotors) - WABCO WAB441-032-184-0	Wabco-S#	\$63.11	49%	\$32.19	As spec	\$30.40	20%	\$24.32
18	Front Speed Sensor (Drums) - Bendix 801541	Bendix-#BXM	\$101.55	61%	\$39.60	As spec	\$57.43	25%	\$43.07
19	Rear Speed Sensor (Drums) - Bendix 801538	Bendix-#BXM	\$95.75	61%	\$37.34	As spec	\$66.01	30%	\$46.21
20	Balance of line item discount for Bendix, WABCO or approved alternate.	Bendix		59%		Bendix		25%	
GUNITE, CONMET, WEBB where indicated or approved alternate.									
21	Front Drum - Gunite 3800X or Webb 65548B	As spec - Gunite 3800X	\$188.59	26%	\$139.56	As spec	\$169.74	25%	\$127.31
22	Rear Drum - Gunite 3600AX or Webb 66864B	As spec - Webb 66864B	\$198.82	48%	\$103.39	As spec	\$126.13	25%	\$94.60
23	Front & Rear Rotor - ConMet 10020109 or approved alternate meeting specifications listed on Addendum #1. REJECT	As spec - ConMet	\$220.58	30%	\$154.41	Freightliner only CM10020682	N/A	N/A	\$265.71
24	Balance of line item discount for Gunite, ConMet, Webb, or approved alternate.	Webb		35%		Gunite		25%	
MONROE or approved alternate.									
25	Front Shocks - Monroe 65482	Gabriel 85006GBL	\$51.68	29%	\$36.69	As spec	\$77.00	25%	\$57.75
26	Front C2 Shocks - Monroe 65140	Gabriel 85918	\$59.07	31%	\$40.76	As spec	\$66.62	25%	\$49.97
27	Rear Shocks - Monroe 65409	Gabriel 85003GBL	\$62.23	40%	\$37.34	As spec	\$66.54	25%	\$49.91
28	Rear Shocks - Monroe 65401	Gabriel 85013ACO	\$56.02	33%	\$37.53	As spec	\$68.43	25%	\$51.32
29	Rear C2 Shocks - Monroe 65490	Gabriel 85024	\$59.65	25%	\$44.74	As spec	\$61.02	25%	\$45.77

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		Tampa Spring Co.				Tampa Truck Center, LLC			
Item #	Item and Description	Mfr & Part #	Cost	GPM % Markup	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
BENDIX, WABCO where indicated or approved alternate. (continued)									
15	Purge Valve Kit for AD9 - Bendix 5005037	Automann 170.107798	\$18.90	20%	\$22.68		\$40.17	30%	\$28.12
16	Front ABS Sensor (Rotors) - WABCO WAB441-032-381-0						\$42.28	20%	\$33.82
17	Rear ABS Sensor (Rotors) - WABCO WAB441-032-184-0						\$32.98	18%	\$27.04
18	Front Speed Sensor (Drums) - Bendix 801541	As spec	\$44.00	20%	\$52.80		\$58.05	26%	\$42.96
19	Rear Speed Sensor (Drums) - Bendix 801538	As spec	\$48.50	20%	\$58.20		\$63.48	26%	\$46.98
20	Balance of line item discount for Bendix, WABCO or approved alternate.	Bendix Automann		Cost + 20% (GPM)				27%	
GUNITE, CONMET, WEBB where indicated or approved alternate.									
21	Front Drum - Gunite 3800X or Webb 65548B	Dayton Parts HD17M	\$90.20	20%	\$108.24		201.23	40%	\$120.74
22	Rear Drum - Gunite 3600AX or Webb 66864B	Dayton Parts HD1M	\$77.70	20%	\$93.24		144.79	21%	\$114.38
23	Front & Rear Rotor - ConMet 10020109 or approved alternate meeting specifications listed on Addendum #1. REJECT					10020682	261.77	25.3%	\$195.54
24	Balance of line item discount for Gunite, ConMet, Webb, or approved alternate.	Dayton Parts Gunite Webb		Cost + 20% (GPM)				28.7%	
MONROE or approved alternate.									
25	Front Shocks - Monroe 65482	Gabriel 85006	\$28.50	28%	\$36.48		\$76.24	40%	\$45.74
26	Front C2 Shocks - Monroe 65140	Gabriel 85918	\$29.55	28%	\$37.82		\$65.96	35%	\$42.87
27	Rear Shocks - Monroe 65409	Gabriel 85003	\$28.27	28%	\$36.19		\$68.64	35%	\$44.62
28	Rear Shocks - Monroe 65401	Gabriel 85013	\$32.00	28%	\$40.96		\$67.79	35%	\$44.06
29	Rear C2 Shocks - Monroe 65490	Gabriel 85724	\$34.19	28%	\$43.76		\$62.93	35%	\$40.90

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		The Parts House			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price
BENDIX, WABCO where indicated or approved alternate. (continued)					
15	Purge Valve Kit for AD9 - Bendix 5005037	As spec	\$63.47	56%	\$27.93
16	Front ABS Sensor (Rotors) - WABCO WAB441-032-381-0	As spec	\$80.91	56%	\$35.60
17	Rear ABS Sensor (Rotors) - WABCO WAB441-032-184-0	As spec	\$63.11	56%	\$27.77
18	Front Speed Sensor (Drums) - Bendix 801541	As spec	\$92.55	56%	\$40.72
19	Rear Speed Sensor (Drums) - Bendix 801538	As spec	\$101.21	56%	\$44.53
20	Balance of line item discount for Bendix, WABCO or approved alternate.	Bendix Wabco		54%	
GUNITE, CONMET, WEBB where indicated or approved alternate.					
21	Front Drum - Gunite 3800X or Webb 65548B	As spec - Gunite 3800X	429.16	65%	\$150.21
22	Rear Drum - Gunite 3600AX or Webb 66864B	As spec - Gunite 3600AX	320.83	65%	\$112.29
23	Front & Rear Rotor - ConMet 10020109 or approved alternate meeting specifications listed on Addendum #1. REJECT				
24	Balance of line item discount for Gunite, ConMet, Webb, or approved alternate.	Gunite		60%	
MONROE or approved alternate.					
25	Front Shocks - Monroe 65482	As spec	\$166.03	58%	\$69.73
26	Front C2 Shocks - Monroe 65140	As spec	\$143.64	58%	\$60.33
27	Rear Shocks - Monroe 65409	As spec	\$149.49	58%	\$62.79
28	Rear Shocks - Monroe 65401	As spec	\$147.64	58%	\$62.01
29	Rear C2 Shocks - Monroe 65490	As spec	\$137.07	58%	\$57.57

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		Fleet Acquisitions, LLC				Fleet Pride			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
MONROE or approved alternate. (continued)									
30	Balance of line item discount for Monroe or approved alternate.	Monroe		68%				70%	
NATIONAL, STEMCO or CHICAGO RAWHIDE where indicated or approved alternate.									
31	Front Seal - Chicago Rawhide 35066	As spec - SKF	\$75.06	63%	\$27.77	As spec	\$73.56	60%	\$29.42
32	Rear Seal - National 370003A or Chicago Rawhide 47697	As spec - National 370003A	\$40.91	27%	\$29.86	As spec - National 370003A	\$86.09	66%	\$29.27
33	Front Gasket - Chicago Rawhide 453869	Chicago Rawhide 453869-8 SKF	\$95.69	63%	\$35.41	Stemco 330-3024	\$3.47	50%	\$1.74
34	Front Hub, Oiler - Stemco 343-4024	As spec	\$55.31	53%	\$26.00	As spec	\$69.86	60%	\$27.94
35	Front Hub, Oiler - Chicago Rawhide 1612	As spec - SKF	\$51.74	63%	\$19.14	As spec	\$41.93	50%	\$20.97
36	Front Hub Gasket - Stemco 330-3024	As spec	\$2.48	53%	\$1.17	As spec	\$3.47	50%	\$1.74
37	Hub Cap, Oiler - Stemco 359-5990 or Chicago Rawhide 450434	Chicago Rawhide SKF 450434-4	\$4.37	63%	\$1.62	As spec	\$7.04	59%	\$2.89
38	Hub Gasket, Large, Oiler - Stemco 330-3009	As spec	\$2.43	53%	\$1.14	As spec	\$3.41	59%	\$1.40
39	Balance of line item discount for National, Stemco, Chicago Rawhide, or approved alternate.	National Stemco SKF		27% 53% 63%				55%	

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		Gary Yeomans Ford				Suncoast Auto Parts dba Napa			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
MONROE or approved alternate. (continued)									
30	Balance of line item discount for Monroe or approved alternate.				\$242.79				
NATIONAL, STEMCO or CHICAGO RAWHIDE where indicated or approved alternate.									
31	Front Seal - Chicago Rawhide 35066				\$27.57		\$46.99		\$24.18
32	Rear Seal - National 370003A or Chicago Rawhide 47697				\$35.14	National C.R.	National \$32.99 Chicago Rawhide \$59.95		National \$29.18 Chicago Rawhide \$30.83
33	Front Gasket - Chicago Rawhide 453869				\$1.17		\$15.69		\$8.03
34	Front Hub, Oiler - Stemco 343-4024				\$28.67		\$37.49		\$30.17
35	Front Hub, Oiler - Chicago Rawhide 1612				\$19.14		\$32.49		\$16.67
36	Front Hub Gasket - Stemco 330-3024				\$1.25		\$2.69		\$1.50
37	Hub Cap, Oiler - Stemco 359-5990 or Chicago Rawhide 450434				\$2.49	Stemco C.R.	Stemco - \$3.69 Chicago Rawhide - \$10.99		Stemco - \$2.75 Chicago Rawhide - \$5.69
38	Hub Gasket, Large, Oiler - Stemco 330-3009				\$1.19		\$2.49		\$1.48
39	Balance of line item discount for National, Stemco, Chicago Rawhide, or approved alternate.				\$116.62				

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		Rush Truck Centers of Florida dba Rush Truck Center, Tampa				Sun State International			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
MONROE or approved alternate. (continued)									
30	Balance of line item discount for Monroe or approved alternate.	Gabriel		32%		Monroe		25%	
NATIONAL, STEMCO or CHICAGO RAWHIDE where indicated or approved alternate.									
31	Front Seal - Chicago Rawhide 35066	As spec - Chicago Rawhide	\$50.06	53%	\$23.53	As spec	\$34.52	25%	\$25.89
32	Rear Seal - National 370003A or Chicago Rawhide 47697	As spec - Chicago Rawhide	\$63.84	53%	\$30.00	As spec	\$44.03	25%	\$33.02
33	Front Gasket - Chicago Rawhide 453869	As spec - Chicago Rawhide 453869-8CHR	\$2.29	53%	\$1.08	As spec	\$1.43	25%	\$1.07
34	Front Hub, Oiler - Stemco 343-4024	As spec - Stemco	\$56.62	53%	\$26.61	As spec	\$40.21	25%	\$30.16
35	Front Hub, Oiler - Chicago Rawhide 1612	Stemco 343-4024	\$56.62	53%	\$26.61	As spec	\$22.84	25%	\$17.13
36	Front Hub Gasket - Stemco 330-3024	As spec Stemco	\$2.77	53%	\$1.30	As spec	\$1.85	25%	\$1.39
37	Hub Cap, Oiler - Stemco 359-5990 or Chicago Rawhide 450434	As spec - Stemco 359-5990	\$5.62	53%	\$2.64	As spec	\$1.90	25%	\$1.43
38	Hub Gasket, Large, Oiler - Stemco 330-3009	Chicago Rawhide 453795-8CHR	\$2.48	53%	\$1.17	As spec	\$1.89	25%	\$1.42
39	Balance of line item discount for National, Stemco, Chicago Rawhide, or approved alternate.	Chicago Rawhide		53%		National Chicago Rawhide		25%	

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		Tampa Spring Co.				Tampa Truck Center, LLC			
Item #	Item and Description	Mfr & Part #	Cost	GPM % Markup	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
MONROE or approved alternate. (continued)									
30	Balance of line item discount for Monroe or approved alternate.	Gabriel Gabriel Monroe		Cost + 28% (GPM)				36%	
NATIONAL, STEMCO or CHICAGO RAWHIDE where indicated or approved alternate.									
31	Front Seal - Chicago Rawhide 35066	Triseal 65263U	\$13.68	28%	\$17.51		\$34.77	19%	\$28.16
32	Rear Seal - National 370003A or Chicago Rawhide 47697	Triseal 65156U	\$17.67	28%	\$22.62		\$34.87	20%	\$27.90
33	Front Gasket - Chicago Rawhide 453869	Triseal 61024	\$0.70	28%	\$0.90		\$1.74	30%	\$1.22
34	Front Hub, Oiler - Stemco 343-4024	Triseal 81024	\$13.08	28%	\$16.74		\$38.04	26.6%	\$27.92
35	Front Hub, Oiler - Chicago Rawhide 1612	Triseal 80024	\$11.89	28%	\$15.22		\$23.97	17%	\$19.90
36	Front Hub Gasket - Stemco 330-3024	Triseal 61024	\$0.70	28%	\$0.90		\$2.70	26%	\$2.00
37	Hub Cap, Oiler - Stemco 359-5990 or Chicago Rawhide 450434	Triseal 64999	\$1.30	28%	\$1.66	As spec - Stemco 359- 5990	\$5.01	26.6%	\$3.68
38	Hub Gasket, Large, Oiler - Stemco 330-3009	Triseal 61009	\$0.69	28%	\$0.88		\$2.55	25.6%	\$1.90
39	Balance of line item discount for National, Stemco, Chicago Rawhide, or approved alternate.	Triseal		Cost + 28% (GPM)					

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		The Parts House			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price
MONROE or approved alternate. (continued)					
30	Balance of line item discount for Monroe or approved alternate.	Monroe		58%	
NATIONAL, STEMCO or CHICAGO RAWHIDE where indicated or approved alternate.					
31	Front Seal - Chicago Rawhide 35066	National Seal 370001A	\$69.50	65%	\$24.33
32	Rear Seal - National 370003A or Chicago Rawhide 47697	As spec	\$90.00	65%	\$31.50
33	Front Gasket - Chicago Rawhide 453869				
34	Front Hub, Oiler - Stemco 343-4024	As spec	\$61.45	54%	\$28.27
35	Front Hub, Oiler - Chicago Rawhide 1612				
36	Front Hub Gasket - Stemco 330-3024	As spec	\$2.75	54%	\$1.27
37	Hub Cap, Oiler - Stemco 359-5990 or Chicago Rawhide 450434	As spec	\$5.58	54%	\$2.57
38	Hub Gasket, Large, Oiler - Stemco 330-3009	As spec	\$2.70	54%	\$1.24
39	Balance of line item discount for National, Stemco, Chicago Rawhide, or approved alternate.	National Stemco		62% 50%	

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		Fleet Acquisitions, LLC				Fleet Pride			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
FEDERAL or approved alternate.									
40	Bearings - Federal 572	Timken 572	\$27.56	59%	\$11.30	As spec	\$56.03	75%	\$14.01
41	Bearings - Federal 580	Timken 580	\$44.22	59%	\$18.13	As spec	\$89.78	75%	\$22.45
42	Bearings - Federal 592-A	Timken 592-A	\$33.65	59%	\$13.80	As spec	\$134.10	60%	\$53.64
43	Bearings - Federal 594-A	Timken 594-A	\$51.57	59%	\$21.14	As spec	\$10.54	76%	\$2.53
44	Balance of line item discount for Federal or approved alternate.	Timken		50%					
CONMET or approved alternate									
45	Rotor Bearings Rear, Outer Cone - ConMet 103600	Timken NP840302	\$65.89	25%	\$49.42				
46	Rotor Bearings Rear, Outer Cup - ConMet 103601	Timken NP053874	\$44.88	25%	\$33.66				
47	Rotor Bearings Rear, Inner Cone - ConMet 103598	Timken NP034946	\$84.61	25%	\$63.46				
48	Rotor Bearings Rear, Inner Cup - ConMet 103599	Timken NP363298	\$50.45	25%	\$37.84				
49	Rotor Bearings Front, Outer Cone - ConMet 103594	Timken NP874005	\$40.45	25%	\$30.34				
50	Rotor Bearings Front, Outer Cup - ConMet 103595	Timken NP435398	\$21.21	25%	\$15.91				
51	Rotor Bearings Front, Inner Cone - ConMet 103596	Timken NP899357	\$56.16	25%	\$42.12				
52	Rotor Bearings Front, Inner Cup - ConMet 103597	Timken NP026773	\$34.78	25%	\$26.09				
53	Balance of line item discount for ConMet or approved alternate.	Timken NP Series		25%					
NOTES: Ring Power submitted decline to bid letter		*Extension corrections				*Extension corrections			

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		Gary Yeomans Ford				Suncoast Auto Parts dba Napa			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
FEDERAL or approved alternate.									
40	Bearings - Federal 572				\$18.59				
41	Bearings - Federal 580				\$28.90				
42	Bearings - Federal 592-A				\$22.88				
43	Bearings - Federal 594-A				\$33.67				
44	Balance of line item discount for Federal or approved alternate.				\$104.04				
CONMET or approved alternate									
45	Rotor Bearings Rear, Outer Cone - ConMet 103600	Fleetrite FP580			\$12.58				
46	Rotor Bearings Rear, Outer Cup - ConMet 103601	Fleetrite FP572			\$9.62				
47	Rotor Bearings Rear, Inner Cone - ConMet 103598	Fleetrite FP594A			\$17.97				
48	Rotor Bearings Rear, Inner Cup - ConMet 103599	Fleetrite FP592A			\$11.93				
49	Rotor Bearings Front, Outer Cone - ConMet 103594	Fleetrite FP3782			\$9.61				
50	Rotor Bearings Front, Outer Cup - ConMet 103595	Fleetrite FP3720			\$4.83				
51	Rotor Bearings Front, Inner Cone - ConMet 103596	Fleetrite FPHM212049			\$13.12				
52	Rotor Bearings Front, Inner Cup - ConMet 103597	Fleetrite FPHM212011			\$7.46				
53	Balance of line item discount for ConMet or approved alternate.				87.12				
NOTES: Ring Power submitted decline to bid letter						*Extension corrections			

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		Rush Truck Centers of Florida dba Rush Truck Center, Tampa				Sun State International			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
FEDERAL or approved alternate.									
40	Bearings - Federal 572	Timken 572TRB	\$43.25	73%	\$11.68	As spec	\$24.14	23%	\$18.59
41	Bearings - Federal 580	Timken 580TRB	\$69.73	73%	\$18.83	As spec	\$37.55	23%	\$28.91
42	Bearings - Federal 592-A	Timken 592ATRB	\$53.63	73%	\$14.48	As spec	\$29.72	23%	\$22.88
43	Bearings - Federal 594-A	Timken 594ATRB	\$80.69	73%	\$21.79	As spec	\$43.73	23%	\$33.67
44	Balance of line item discount for Federal or approved alternate.	Timken		73%		Federal Timken		23%	
CONMET or approved alternate									
45	Rotor Bearings Rear, Outer Cone - ConMet 103600	As spec ConMet	\$32.98	30%	\$23.09	As spec	\$37.55	23%	\$28.91
46	Rotor Bearings Rear, Outer Cup - ConMet 103601	As spec ConMet	\$35.17	30%	\$24.62	As spec	\$24.14	23%	\$18.59
47	Rotor Bearings Rear, Inner Cone - ConMet 103598	As spec ConMet	\$37.10	30%	\$25.97	As spec	\$43.73	23%	\$33.67
48	Rotor Bearings Rear, Inner Cup - ConMet 103599	As spec ConMet	\$39.55	30%	\$27.69	As spec	\$29.72	23%	\$22.88
49	Rotor Bearings Front, Outer Cone - ConMet 103594	Timken NP874005TRB	\$69.36	72%	\$19.42	As spec	\$22.61	23%	\$17.41
50	Rotor Bearings Front, Outer Cup - ConMet 103595	Timken NP435398TRB	\$32.77	72%	\$9.18	As spec	\$10.54	23%	\$8.12
51	Rotor Bearings Front, Inner Cone - ConMet 103596	Timken NP899357TRB	\$96.32	72%	\$26.97	As spec	\$31.07	23%	\$23.92
52	Rotor Bearings Front, Inner Cup - ConMet 103597	Timken NP026773TRB	\$54.52	72%	\$15.27	As spec	\$17.41	23%	\$13.41
53	Balance of line item discount for ConMet or approved alternate.	Timken		51%		Federal Timken		23%	
NOTES: Ring Power submitted decline to bid letter		*Extension corrections and brands included				*Extension corrections			

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		Tampa Spring Co.				Tampa Truck Center, LLC			
Item #	Item and Description	Mfr & Part #	Cost	GPM % Markup	District Price	Mfr & Part #	Wholesale Price	% Discount	District Price
FEDERAL or approved alternate.									
40	Bearings - Federal 572	DT Components 572	\$16.75	28%	\$21.44		\$17.79		\$14.26
41	Bearings - Federal 580	DT Components 580	\$28.74	28%	\$36.79		\$28.63		\$22.96
42	Bearings - Federal 592-A	DT Components 592-A	\$20.07	28%	\$25.69		\$22.04		\$17.68
43	Bearings - Federal 594-A	DT Components 594-A	\$31.38	28%	\$40.17		\$33.17		\$26.60
44	Balance of line item discount for Federal or approved alternate.	DT Components		Cost + 28% (GPM)				25%	
CONMET or approved alternate									
45	Rotor Bearings Rear, Outer Cone - ConMet 103600	DT Components NP840302	\$41.18	28%	\$52.71	NP840302TRB	\$53.76	25%	\$40.32
46	Rotor Bearings Rear, Outer Cup - ConMet 103601	DT Components NP053874	\$28.05	28%	\$35.90	NP053874TRB	\$36.14	25%	\$27.11
47	Rotor Bearings Rear, Inner Cone - ConMet 103598	DT Components NP034946	\$47.82	28%	\$61.21	NP034946TRB	\$62.01	25%	\$46.51
48	Rotor Bearings Rear, Inner Cup - ConMet 103599	DT Components NP363298	\$26.59	28%	\$34.04	NP363298TRB	\$44.92	25%	\$33.69
49	Rotor Bearings Front, Outer Cone - ConMet 103594	DT Components NP874005	\$20.95	28%	\$26.82	NP874005TRB	\$30.12	25%	\$22.59
50	Rotor Bearings Front, Outer Cup - ConMet 103595	DT Components NP435398	\$11.99	28%	\$15.35	NP435398TRB	\$15.76	25%	\$11.82
51	Rotor Bearings Front, Inner Cone - ConMet 103596	DT Components NP899357	\$35.09	28%	\$44.92		\$29.68	25%	\$22.26
52	Rotor Bearings Front, Inner Cup - ConMet 103597	DT Components NP026773	\$15.16	28%	\$19.40	NP026773TRB	\$22.88	25%	\$17.16
53	Balance of line item discount for ConMet or approved alternate.	DT Components		Cost + 28% (GPM)					
NOTES: Ring Power submitted decline to bid letter		*All pricing is cost with GPM % mark-up * Extension corrections				*Extension corrections			

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

All brake linings will be riveted on Sarasota School District brake shoes, OEM factory remanufactured brake shoes, or new brake shoes.		The Parts House			
Item #	Item and Description	Mfr & Part #	Wholesale Price	% Discount	District Price
FEDERAL or approved alternate.					
40	Bearings - Federal 572	Timken 572	\$60.99	75%	\$15.25
41	Bearings - Federal 580	Timken 580	\$94.99	75%	\$23.75
42	Bearings - Federal 592-A	Timken 592A	\$72.99	75%	\$18.25
43	Bearings - Federal 594-A	Timken 594A	\$108.99	75%	\$27.25
44	Balance of line item discount for Federal or approved alternate.	Timken		70%	
CONMET or approved alternate					
45	Rotor Bearings Rear, Outer Cone - ConMet 103600				
46	Rotor Bearings Rear, Outer Cup - ConMet 103601				
47	Rotor Bearings Rear, Inner Cone - ConMet 103598				
48	Rotor Bearings Rear, Inner Cup - ConMet 103599				
49	Rotor Bearings Front, Outer Cone - ConMet 103594	Timken NP874005	\$87.99	70%	\$26.40
50	Rotor Bearings Front, Outer Cup - ConMet 103595	Timken NP455398	\$47.99	70%	\$14.40
51	Rotor Bearings Front, Inner Cone - ConMet 103596	Timken NP899357	\$115.99	70%	\$34.80
52	Rotor Bearings Front, Inner Cup - ConMet 103597	Timken NP026773	\$74.99	70%	\$22.50
53	Balance of line item discount for ConMet or approved alternate.	Timken		65%	
NOTES: Ring Power submitted decline to bid letter		*Extension corrections and brands included			

THE SCHOOL BOARD OF SARASOTA COUNTY, FLORIDA

TABULATION FOR BUS BRAKE REPAIR PARTS - BID #15-0155

OPENED SEPTEMBER 25, 2014 AT 2:00 P.M.

Company	Fleet Acquisitions, LLC	Fleet Pride
Contact	Anthony V. Zummo	Victor L. Russell
Address	6510 Golden Groves Lane	2141 Whitfield Park Loop
	Tampa, FL 33610	Sarasota, FL 34243
Phone	813-621-1734	941-758-8282
Fax	813-626-2010	941-752-3652
Federal I.D.	621868964	630681070
Email	azummo@fleetproductsfl.com	vic.russell@fleetpride.com
Company	Gary Yeomans Ford	Suncoast Auto Parts dba Napa
Contact	Ray Grubbs	Rick Roberts
Address	1420 North Tomoka Farms Road	5310 McIntosh Road
	Daytona Beach, FL 32124	Sarasota, FL 34233
Phone	386-253-6579	513-846-4007
Fax	386-274-6739	941-922-5041
Federal I.D.	592164165	270504819
Email	rgrubbs@anewford.com	rroberts.napa@gmail.com
Company	Rush Truck Centers of Florida dba Rush Truck Center,	Sun State International
Contact	David Rye	Paul Dearth
Address	8111 East Adamo Drive	8247 15th Street East
	Tampa, FL 33619	Sarasota, FL 34243
Phone	813-664-1441	941-355-7681
Fax	813-739-1682	941-351-9108
Federal I.D.	061672108	593750718
Email	harrisc@rushenterprises.com	paul.dearth@sunstateintl.com
Company	Tampa Spring Co.	Tampa Truck Center, LLC
Contact	John Messina, Jr.	Jeff Ballard
Address	2930 63rd Avenue East	7528 US Highway 301 North
	Bradenton, FL 34203	Tampa, FL 33637
Phone	941-727-1400	813-262-0890
Fax	813-933-2805	813-664-1238
Federal I.D.	591198637	270850894
Email	jmessina@tampaspringco.com	jballard@tampaftrl.com
Company	The Parts House	
Contact	David C. Manderscheid	
Address	4083 Sawyer Court	
	Sarasota, FL 34233	
Phone	941-924-2394	
Fax	941-924-8621	
Federal I.D.	611436406	
Email	dmanderscheid@thepartshouse.com	
Recorded by: Sydney Manas		Witnessed by: Joyce Haney

THE SCHOOL BOARD OF SARASOTA COUNTY
JUSTIFICATION

Bus Brake Repair Parts - Bid #15-0155

Opened September 25, 2014 at 2:00 p.m.

Item #	Bidder	Reason For Not Awarding To Other Than Low Bidder
2	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
3	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
4	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
6	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
7	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	Sun State International	Unable to evaluate discount as item bid was not included on submitted price sheets.
	Gary Yeomans Ford	Price sheets were not submitted as required in bid specifications.
	Rush Truck Centers of Florida dba Rush Truck Center, Tampa	Unable to evaluate discount as roller hardware kit bid was not included on submitted price sheets.
8	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	Rush Truck Centers of Florida dba Rush Truck Center, Tampa	Unable to evaluate discount as tapered roller bid was not included on submitted price sheets.
9	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
10	Fleet Pride	Vendor was not awarded in any items in category or balance of line.
	Sun State International	
	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	Tampa Truck Center, LLC	Price sheets were not submitted as required in bid specifications.
	The Parts House	Vendor was not awarded any items in category or balance of line.
12	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
14	Rush Truck Centers of Florida dba Rush Truck Center, Tampa	Unable to evaluate discount as item bid was not included on submitted price sheets.
15	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
16	Fleet Pride	Unable to evaluate discount as item bid was not included on submitted price sheets.
	Sun State International	
	Gary Yeomans Ford	Price sheets were not submitted as required in bid specifications.

THE SCHOOL BOARD OF SARASOTA COUNTY
JUSTIFICATION

Bus Brake Repair Parts - Bid #15-0155

Opened September 25, 2014 at 2:00 p.m.

17	Sun State International	Unable to evaluate discount as item bid was not included on submitted price sheets.
20	Fleet Pride	Vendor was not awarded any items in category or balance of line.
	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	Tampa Truck Center, LLC	Price sheets were not submitted as required in bid specifications.
	The Parts House	Vendor was not awarded any items in category or balance of line.
21	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	Tampa Truck Center, LLC	Price sheets were not submitted as required in bid specifications.
22	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
23	Rush Truck Centers of Florida dba Rush Truck Center, Tampa	Reject Item. Price sheets were not submitted for ConMet rotors as required in bid specifications. No other bids received.
	Tampa Truck Center, LLC	
	Fleet Acquisitions, LLC	
	Sun State International	
24	Fleet Acquisitions, LLC	Vendor was not awarded any items in category or balance of line.
	Fleet Pride	Vendor did not indicate brand for balance of line discount and was not awarded any items in category.
	Rush Truck Centers of Florida dba Rush Truck Center, Tampa	Vendor was not awarded any items in category or balance of line.
	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	Tampa Truck Center, LLC	Price sheets were not submitted as required in bid specifications.
	The Parts House	Vendor was not awarded any items in category or balance of line.

THE SCHOOL BOARD OF SARASOTA COUNTY
JUSTIFICATION

Bus Brake Repair Parts - Bid #15-0155

Opened September 25, 2014 at 2:00 p.m.

25	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	Tampa Truck Center, LLC	Price sheets were not submitted as required in bid specifications.
	Rush Truck Centers of Florida dba Rush Truck Center, Tampa	Unable to evaluate discount as shock category bid was not included on submitted price sheets.
	Suncoast Auto Parts dba Napa	Vendor provided a secure website vs CD, flash drive, or printed sheets as required in bid specifications.
26	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	Tampa Truck Center, LLC	Price sheets were not submitted as required in bid specifications.
	Rush Truck Centers of Florida dba Rush Truck Center, Tampa	Unable to evaluate discount as shock category bid was not included on submitted price sheets.
	Suncoast Auto Parts dba Napa	Vendor provided a secure website vs CD, flash drive, or printed sheets as required in bid specifications.
27	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	Tampa Truck Center, LLC	Price sheets were not submitted as required in bid specifications.
	Rush Truck Centers of Florida dba Rush Truck Center, Tampa	Unable to evaluate discount as shock category bid was not included on submitted price sheets.
	Suncoast Auto Parts dba Napa	Vendor provided a secure website vs CD, flash drive, or printed sheets as required in bid specifications.
28	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	Tampa Truck Center, LLC	Price sheets were not submitted as required in bid specifications.
	Rush Truck Centers of Florida dba Rush Truck Center, Tampa	Unable to evaluate discount as shock category bid was not included on submitted price sheets.
	Suncoast Auto Parts dba Napa	Vendor provided a secure website vs CD, flash drive, or printed sheets as required in bid specifications.
29	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	Tampa Truck Center, LLC	Price sheets were not submitted as required in bid specifications.
	Rush Truck Centers of Florida dba Rush Truck Center, Tampa	Unable to evaluate discount as shock category bid was not included on submitted price sheets.
	Suncoast Auto Parts dba Napa	Vendor provided a secure website vs CD, flash drive, or printed sheets as required in bid specifications.

THE SCHOOL BOARD OF SARASOTA COUNTY
JUSTIFICATION

Bus Brake Repair Parts - Bid #15-0155

Opened September 25, 2014 at 2:00 p.m.

30	Fleet Pride	Vendor did not indicate brand for balance of line discount and was not awarded any items in category.
	Rush Truck Centers of Florida dba Rush Truck Center, Tampa	Vendor was not awarded any items in category or balance of line.
	Sun State International	
	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	Tampa Truck Center, LLC	Price sheets were not submitted as required in bid specifications.
	The Parts House	Vendor was not awarded any items in category or balance of line.
31	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	Rush Truck Centers of Florida dba Rush Truck Center, Tampa	Unable to evaluate discount as item bid was not included on submitted price sheets.
	Suncoast Auto Parts dba Napa	Vendor provided a secure website vs CD, flash drive, or printed sheets as required in bid specifications.
32	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	Tampa Truck Center, LLC	Price sheets were not submitted as required in bid specifications.
	Suncoast Auto Parts dba Napa	Vendor provided a secure website vs CD, flash drive, or printed sheets as required in bid specifications.
33	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
34	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
35	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	Suncoast Auto Parts dba Napa	Vendor provided a secure website vs CD, flash drive, or printed sheets as required in bid specifications.
36	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
38	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.

THE SCHOOL BOARD OF SARASOTA COUNTY
JUSTIFICATION

Bus Brake Repair Parts - Bid #15-0155

Opened September 25, 2014 at 2:00 p.m.

39	Fleet Pride	Vendor did not indicate brand for balance of line discount and was not awarded any items in category.
	Rush Truck Centers of Florida dba Rush Truck Center, Tampa	Vendor was not awarded in category or balance of line for the Chicago Rawhide, National, Stemco brands.
	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	The Parts House	Vendor was not awarded in category or balance of line for the Stemco brand.
43	Fleet Pride	Vendor withdrew bid pricing.
44	Sun State International	Vendor was not awarded in category or balance of line.
	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	Tampa Truck Center, LLC	Price sheets were not submitted as required in bid specifications.
	The Parts House	Vendor was not awarded in category or balance of line.
45	Gary Yeomans Ford	Price sheets were not submitted as required in bid specifications.
	Rush Truck Centers of Florida dba Rush Truck Center, Tampa	Unable to evaluate discount as item bid was not included on submitted price sheets.
46	Gary Yeomans Ford	Price sheets were not submitted as required in bid specifications.
47	Gary Yeomans Ford	Price sheets were not submitted as required in bid specifications.
	Rush Truck Centers of Florida dba Rush Truck Center, Tampa	Unable to evaluate discount as item bid was not included on submitted price sheets.
48	Gary Yeomans Ford	Price sheets were not submitted as required in bid specifications.
49	Gary Yeomans Ford	Price sheets were not submitted as required in bid specifications.
50	Gary Yeomans Ford	Price sheets were not submitted as required in bid specifications.
51	Gary Yeomans Ford	Price sheets were not submitted as required in bid specifications.
	Tampa Truck Center, LLC	Price sheets were not submitted as required in bid specifications.
52	Gary Yeomans Ford	Price sheets were not submitted as required in bid specifications.
53	Fleet Acquisitions, LLC	Vendor did not indicate brand for balance of line discount and was not awarded any items in category.
	Rush Truck Centers of Florida dba Rush Truck Center, Tampa	Vendor was not awarded in category or balance of line.
	Tampa Spring Company	Vendor submitted a blank flash drive, price sheets were not submitted as required in bid specifications.
	The Parts House	Vendor was not awarded in category or balance of line.